

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
HD57002RQ	Acura MDX, 07-13	Fender R	Cobra King	10/14A	60210STXA90ZZ	AC1241119
CV-10104AQ-LH	Chevrolet Avalanche, 07-09	Fender L	Tong Yang	01/15A	15243561	GM1240333
CV-10104AQ-LH	Chevrolet Avalanche, 07-09	Fender L	Tong Yang	01/15A	25825296	GM1240333
CV-10104AQ-LH	Chevrolet Avalanche, 07-10	Fender L	Tong Yang	01/15A	20774897	GM1240333
CV-10104AQ-LH	Chevrolet Avalanche, 07-12	Fender L	Tong Yang	01/15A	25992404	GM1240333
CV-10104AQ-LH	Chevrolet Avalanche, 07-13	Fender L	Tong Yang	01/15A	22977475	GM1240333
CVMB09FL1	Chevrolet Malibu Hybrid, 09-10	Fender L	Gordon	12/14A	25949347	GM1240356
CVMB09FR1	Chevrolet Malibu, 09-12	Fender R	Gordon	10/14A	25949346	GM1241356
CVMB09FL1	Chevrolet Malibu, 09-12	Fender L	Gordon	12/14A	25949347	GM1240356
CV-10104AQ-LH	Chevrolet Suburban, 07-09	Fender L	Tong Yang	01/15A	15243561	GM1240333
CV-10104AQ-LH	Chevrolet Suburban, 07-09	Fender L	Tong Yang	01/15A	25825296	GM1240333
CV-10104AQ-LH	Chevrolet Suburban, 07-10	Fender L	Tong Yang	01/15A	20774897	GM1240333
CV-10104AQ-LH	Chevrolet Suburban, 07-12	Fender L	Tong Yang	01/15A	25992404	GM1240333
CV-10104AQ-LH	Chevrolet Suburban, 07-14	Fender L	Tong Yang	01/15A	22977475	GM1240333
CV-10104AQ-LH	Chevrolet Tahoe Hybrid, 08-09	Fender L	Tong Yang	01/15A	15243561	GM1240333
CV-10104AQ-LH	Chevrolet Tahoe Hybrid, 08-09	Fender L	Tong Yang	01/15A	25825296	GM1240333
CV-10104AQ-LH	Chevrolet Tahoe Hybrid, 08-10	Fender L	Tong Yang	01/15A	20774897	GM1240333
CV-10104AQ-LH	Chevrolet Tahoe Hybrid, 08-12	Fender L	Tong Yang	01/15A	25992404	GM1240333
CV-10104AQ-LH	Chevrolet Tahoe Hybrid, 08-13	Fender L	Tong Yang	01/15A	22977475	GM1240333
CV-10104AQ-LH	Chevrolet Tahoe, 07-09	Fender L	Tong Yang	01/15A	15243561	GM1240333
CV-10104AQ-LH	Chevrolet Tahoe, 07-09	Fender L	Tong Yang	01/15A	25825296	GM1240333
CV-10104AQ-LH	Chevrolet Tahoe, 07-10	Fender L	Tong Yang	01/15A	20774897	GM1240333
CV-10104AQ-LH	Chevrolet Tahoe, 07-12	Fender L	Tong Yang	01/15A	25992404	GM1240333
CV-10104AQ-LH	Chevrolet Tahoe, 07-14	Fender L	Tong Yang	01/15A	22977475	GM1240333
DG9310150-000C	Dodge Full Size Pickup, 09-10	Hood	AP	07/15A	55372034AA	CH1230275
DG9310150-000C	Dodge Full Size Pickup, 09-10	Hood	AP	07/15A	55372034AC	CH1230275
DG9310150-000C	Dodge Full Size Pickup, 09-11	Hood	AP	07/15A	55372034AD	CH1230275
DG9310150-000C	Dodge Full Size Pickup, 09-12	Hood	AP	07/15A	68160234AB	CH1230275
DG9310150-000C	Dodge Full Size Pickup, 09-12	Hood	AP	07/15A	68160234AC	CH1230275
DG9310150-000C	Dodge Full Size Pickup, 09-15	Hood	AP	07/15A	68160234AD	CH1230275
FD-20100AQ	Ford Escape HEV, 05-07	Hood	Tong Yang	05/15A	5L8Z16612AA	FO1230202
S0197H000AS	Ford Escape HEV, 05-07	Hood	Jui Li	05/15A	5L8Z16612AA	FO1230202
FD-20100AQ	Ford Escape, 01-07	Hood	Tong Yang	05/15A	5L8Z16612AA	FO1230202
S0197H000AS	Ford Escape, 01-07	Hood	Jui Li	05/15A	5L8Z16612AA	FO1230202
FDP04HD1	Ford F150 Pickup, 04-08 (New Style)	Hood	Gordon	01/15A	4L3Z16612AA	FO1230240
S1055F100AS	GMC Terrain, 10	Fender L	Jui Li	08/15A	20826781	GM1240366
S1055F100AS	GMC Terrain, 10-11	Fender L	Jui Li	08/15A	20888071	GM1240366
S1055F100AS	GMC Terrain, 10-15	Fender L	Jui Li	08/15A	22846919	GM1240366
S1027F200AS	Honda Accord Hybrid, 14-15	Fender R	Jui Li	11/14A	60211T2FA90ZZ	HO1241185
S1027F100AS	Honda Accord Hybrid, 14-15	Fender L	Jui Li	03/15A	60261T2FA90ZZ	HO1240185
S1027F200AS	Honda Accord Sedan, 13-15	Fender R	Jui Li	11/14A	60211T2FA90ZZ	HO1241185
S1027F100AS	Honda Accord Sedan, 13-15	Fender L	Jui Li	03/15A	60261T2FA90ZZ	HO1240185
HD0900150-000C	Honda Civic Coupe, 06-11	Hood	AP	ALL	60100SVAA90ZZ	HO1230149
S0743H000AS	Honda Civic Coupe, 06-11	Hood	Jui Li	ALL	60100SVAA90ZZ	HO1230149
S0733H000AS	Honda Civic Hybrid, 06-08	Hood	Jui Li	05/15A	60100SNEA90ZZ	HO1230148
S0733H000AS	Honda Civic Hybrid, 06-11	Hood	Jui Li	05/15A	60100SNEA91ZZ	HO1230148
S0733H000AS	Honda Civic Sedan, 06-10	Hood	Jui Li	05/15A	60100SNEA90ZZ	HO1230148
S0733H000AS	Honda Civic Sedan, 06-11	Hood	Jui Li	05/15A	60100SNEA91ZZ	HO1230148
HD7500150-200C	Honda Fit, 07-08	Hood	AP	07/15A	60100SLNA90ZZ	HO1230153
HD0D11HD1	Honda Odyssey, 10-14	Hood	Gordon	06/15A	60100TK8A90ZZ	HO1230164
FDP04HD1	Lincoln Mark LT, 06-08	Hood	Gordon	01/15A	4L3Z16612AA	FO1230240
FD-20100AQ	Mercury Mariner HEV, 06-07	Hood	Tong Yang	05/15A	5L8Z16612AA	FO1230202
S0197H000AS	Mercury Mariner HEV, 06-07	Hood	Jui Li	05/15A	5L8Z16612AA	FO1230202



MONTHLY RECALL REPORT

January 2016*

[Report: P8]
Monthly

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
FD-20100AQ	Mercury Mariner, 05-07	Hood	Tong Yang	05/15A	5L8Z16612AA	FO1230202
S0197H000AS	Mercury Mariner, 05-07	Hood	Jui Li	05/15A	5L8Z16612AA	FO1230202
NSS6703A	Nissan Murano, 09-13	Radiator Support	Auto Power	02/15A	625001AA0A	NI1225186
TY-20128AQ	Scion tC, 05-10	Hood	Tong Yang	07/15A	5330121040	SC1230103
TYCA07FL1	Toyota Camry Hybrid, 07-09	Fender L	Gordon	01/15A	5380233170	TO1240211
TYCA07FL1	Toyota Camry Hybrid, 07-09	Fender L	Gordon	02/15A	5380233170	TO1240211
TYCA07FL1	Toyota Camry Hybrid, 07-09	Fender L	Gordon	04/15B	5380233170	TO1240211
TYCA07FL1	Toyota Camry Hybrid, 07-11	Fender L	Gordon	01/15A	5380206120	TO1240211
TYCA07FL1	Toyota Camry Hybrid, 07-11	Fender L	Gordon	02/15A	5380206120	TO1240211
TYCA07FL1	Toyota Camry Hybrid, 07-11	Fender L	Gordon	04/15B	5380206120	TO1240211
TY3810150-000C	Toyota Camry Hybrid, 07-11 (USA)	Hood	AP	12/14A	5330106090	TO1230206
WL-453AQ	Toyota Camry Hybrid, 07-11 (USA)	Hood	William	12/14A	5330106090	TO1230206
TYCA07FL1	Toyota Camry, 07-09	Fender L	Gordon	01/15A	5380233170	TO1240211
TYCA07FL1	Toyota Camry, 07-09	Fender L	Gordon	02/15A	5380233170	TO1240211
TYCA07FL1	Toyota Camry, 07-09	Fender L	Gordon	04/15B	5380233170	TO1240211
TYCA07FL1	Toyota Camry, 07-11	Fender L	Gordon	01/15A	5380206120	TO1240211
TYCA07FL1	Toyota Camry, 07-11	Fender L	Gordon	02/15A	5380206120	TO1240211
TYCA07FL1	Toyota Camry, 07-11	Fender L	Gordon	04/15B	5380206120	TO1240211
TY3810150-000C	Toyota Camry, 07-11 (USA)	Hood	AP	12/14A	5330106090	TO1230206
WL-453AQ	Toyota Camry, 07-11 (USA)	Hood	William	12/14A	5330106090	TO1230206
TY-20230AQ	Toyota Corolla, 14-15	Hood	Tong Yang	05/15S	5330102270	TO1230232
TY-10263AQ-RH	Toyota Prius Plug In, 12-14	Fender R	Tong Yang	01/15A	5380147040	TO1241232
TY-10263AQ-RH	Toyota Prius, 10-15	Fender R	Tong Yang	01/15A	5380147040	TO1241232
TYR406HD1	Toyota RAV-4, 06-12	Hood	Gordon	01/14A	533010R020	TO1230204
S0739H000AS	Toyota Tacoma, 05-09, w/o scoop	Hood	Jui Li	05/15A	5330104130	TO1230200
TY-20133AQ	Toyota Tacoma, 05-09, w/o scoop	Hood	Tong Yang	05/15A	5330104130	TO1230200
S0739H000AS	Toyota Tacoma, 05-11, w/o scoop	Hood	Jui Li	05/15A	5330104120	TO1230200
TY-20133AQ	Toyota Tacoma, 05-11, w/o scoop	Hood	Tong Yang	05/15A	5330104120	TO1230200
S0739H000AS	Toyota Tacoma, 05-11, w/o scoop	Hood	Jui Li	05/15A	5330104160	TO1230200
TY-20133AQ	Toyota Tacoma, 05-11, w/o scoop	Hood	Tong Yang	05/15A	5330104160	TO1230200
TY-20206AQ	Toyota Yaris Hatchback, 12-14, Japan built	Hood	Tong Yang	06/15A	5330152320	TO1230227
VW-10072AQ-LH	Volkswagen GLI Sedan, 11-15	Fender L	Tong Yang	04/15A	5C6821105	VW1240142
VW-10072AQ-RH	Volkswagen GLI Sedan, 11-15	Fender R	Tong Yang	04/15A	5C6821106	VW1241142
VW-10072AQ-LH	Volkswagen Jetta Hybrid, 13-15	Fender L	Tong Yang	04/15A	5C6821105	VW1240142
VW-10072AQ-RH	Volkswagen Jetta Hybrid, 13-15	Fender R	Tong Yang	04/15A	5C6821106	VW1241142
VW-10072AQ-LH	Volkswagen Jetta Sedan, 11-15	Fender L	Tong Yang	04/15A	5C6821105	VW1240142
VW-10072AQ-RH	Volkswagen Jetta Sedan, 11-15	Fender R	Tong Yang	04/15A	5C6821106	VW1241142
VW-03005AQ	Volkswagen Passat, 06-10	Radiator Support	Tong Yang	04/15A	3C0805588J	VW1225126

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
Y-GMBP338CA	Chevrolet Avalanche, 07-13, w/o off road pkg	Bumper Cover, Front	Y.C.C.	05/15A	25814570	GM1000817
Y-GMBP338CA	Chevrolet Suburban, 07-14, w/o off road pkg	Bumper Cover, Front	Y.C.C.	05/15A	25814570	GM1000817
Y-GMBP338CA	Chevrolet Tahoe, 07-14, w/o off road pkg	Bumper Cover, Front	Y.C.C.	05/15A	25814570	GM1000817
GMCTRAI-F02FLNEW	Chevrolet Trailblazer, 02-05, w/fog lamps	Bumper Cover, Front	Micro Rim	6614J	88943617	GM1000672
CR-04060BBQ	Chrysler 200 Sedan, 11-14	Bumper Cover, Rear	Tong Yang	07/15A	68082030AD	CH1100964
Y-CRBP037CA	Chrysler PT Cruiser, 03-05	Bumper Cover, Front	Y.C.C.	06/15A	5093640AA	CH1000373

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
Y-CRBP043CA	Chrysler PT Cruiser, 06-10	Bumper Cover, Front	Y.C.C.	12/14A	5179104AA	CH1000959
Y-CRBP043CA	Chrysler PT Cruiser, 06-10	Bumper Cover, Front	Y.C.C.	12/14A	5179104AB	CH1000864
Y-CRBP043CA	Chrysler PT Cruiser, 06-10	Bumper Cover, Front	Y.C.C.	12/14A	68166405AA	CH1000864
CR4710870-100C	Chrysler Sebring Sedan, 07-10, w/single exhaust	Bumper Cover, Rear	AP-Procom	05/15A	68004596AD	CH1100892
Y-CRBP035CA	Chrysler Town & Country LXi/Limited, 01-04	Bumper Cover, Front	Y.C.C.	06/15A	5018610AA	CH1000319
Y-CRBP052CA	Chrysler Town & Country, 05-07, 119 in WB w/o fog lamps	Bumper Cover, Front	Y.C.C.	06/15A	5139120AA	CH1000434
Y-CRBP067CA	Dodge Ram R1500 Pick-Up, 13-14	Fascia, Upper	Y.C.C.	05/15A	68197697AA	CH1014108
Y-FDBP108CA	Ford Focus Coupe, 09-10 (from 9-3-08)	Bumper Cover, Rear	Y.C.C.	06/15A	9S4Z17K835BAPTM	FO1100643
Y-FDBP108CA	Ford Focus SES, 10-11	Bumper Cover, Rear	Y.C.C.	06/15A	9S4Z17K835BAPTM	FO1100643
FD-04346BBQ	Ford Mustang, 10-12	Bumper Cover, Front	Tong Yang	09/15A	AR3Z17D957AA	FO1000652
Y-HDBP143CA	Honda Accord Coupe, 03-05, (6cyl) w/man. trans.	Bumper Cover, Front	Y.C.C.	07/15A	04711SDPA90ZZ	HO1000212
HD-04249BBQ	Honda Accord Sedan, 13-15	Bumper Cover, Front	Tong Yang	07/15A	04711T2AA90ZZ	HO1000288
HD-04249BBQ	Honda Accord Sedan, 13-15	Bumper Cover, Front	Tong Yang	09/14A	04711T2AA90ZZ	HO1000288
HD0910000-300C	Honda Civic Hybrid, 13-15	Bumper Cover, Front	AP-Procom	04/15A	04711TR3A70ZZ	HO1000290
HD0910000-300C	Honda Civic Sedan, 13-15	Bumper Cover, Front	AP-Procom	04/15A	04711TR3A70ZZ	HO1000290
Y-HYBP021CA	Hyundai Elantra Sedan, 11-12 (USA)	Bumper Cover, Rear	Y.C.C.	07/15A	866113Y000	HY1100180
Y-HYBP021CA	Hyundai Elantra, 11-13, From 5-14-12, USA built	Bumper Cover, Rear	Y.C.C.	07/15A	866113Y001	HY1100180
DS-04224BBQ	Infiniti G35 Coupe, 03-07	Bumper Cover, Front	Tong Yang	08/15B	62022AM840	IN1000122
DGB074NDO	Jeep Grand Cherokee Laredo/Limited/Overland, 11-15, w/parking sensor, w/o blind spot detection	Bumper Cover, Rear	Pro Fortune	07/13A	1VQ66TZZAA	CH1100954
DGB074NDO	Jeep Grand Cherokee, 11-12, w/parking sensor, w/o blind spot detection	Bumper Cover, Rear	Pro Fortune	07/13A	68085679AA	CH1100954
DGB074NDO	Jeep Grand Cherokee, 11-12, w/parking sensor, w/o blind spot detection	Bumper Cover, Rear	Pro Fortune	07/13A	68085679AB	CH1100954
DGB074NDO	Jeep Grand Cherokee, 11-12, w/parking sensor, w/o blind spot detection	Bumper Cover, Rear	Pro Fortune	07/13A	68085679AC	CH1100954
Y-AMAR015ARC	Jeep Patriot, 11-15, w/o Chrome trim w/o Tow Hooks	Bumper Cover, Front	Y.C.C.	07/15A	68091523AA	CH1015111
Y-KABP013CA	Kia Rio Sedan, 12-15	Bumper Cover, Front	Y.C.C.	05/15A	865111W000	KI1000159
TY-04275BBQ	Lexus RX 330, 04-06	Bumper Cover, Rear	Tong Yang	04/15B	521590E900	LX1100121
TY-04275BBQ	Lexus RX 350, 07-09	Bumper Cover, Rear	Tong Yang	04/15B	521590E900	LX1100121
TY-04275BBQ	Lexus RX 400h, 06-07	Bumper Cover, Rear	Tong Yang	04/15B	521590E900	LX1100121
DS-04344BEQ	Nissan Pathfinder, 13-15, w/Object sensor w/o Towing hitch	Bumper Cover, Rear	Tong Yang	08/14B	850223KA1H	NI1100290
DS-04306BBQ	Nissan Rogue S/SL/SV, 11-14	Bumper Cover, Front	Tong Yang	01/15B	620221VK0H	NI1000277
Y-TYBP270HAC	Toyota Camry Hybrid, 07-11, (USA)	Bumper Cover, Rear	Y.C.C.	07/14A	5215906952	TO1100274
TYB111NBQ	Toyota Camry Hybrid, 12-14	Bumper Cover, Front	Pro Fortune	07/15A	5211906974	TO1000378
TYB111NBQ	Toyota Camry L/LE/XLE, 12-14	Bumper Cover, Front	Pro Fortune	07/15A	5211906974	TO1000378
TY-04403BCQ	Toyota Camry L/LE/XLE/Hybrid, 12-14	Bumper Cover, Rear	Tong Yang	06/15A	5215906961	TO1100296
Y-TYBP252CA	Toyota Corolla S, 03-08	Bumper Cover, Rear	Y.C.C.	10/14A	5215902912	TO1100209
Y-TYBP252CA	Toyota Corolla XRS, 05-06	Bumper Cover, Rear	Y.C.C.	10/14A	5215902912	TO1100209
Y-TYBP293CA	Toyota Prius Plug In, 12-15, Halogen	Bumper Cover, Front	Y.C.C.	07/15A	5211947934	TO1000394
Y-TYBP293CA	Toyota Prius, 12-15, w/o headlamp washers	Bumper Cover, Front	Y.C.C.	07/15A	5211947934	TO1000394
TY-04447BAQ	Toyota RAV-4, 13-15, w/o Parking sensors	Bumper Cover, Rear	Tong Yang	07/15A	521500R110	TO1100306
TY-04447BAQ	Toyota RAV-4, 13-15, w/o Parking sensors	Bumper Cover, Rear	Tong Yang	08/15B	521500R110	TO1100306
VW-04152BBQ	Volkswagen Jetta Hybrid, 13-15	Bumper Cover, Front	Tong Yang	06/15B	5C6807217DGRU	VW1000190
VW-04152BBQ	Volkswagen Jetta Sedan, 11-14, w/o Headlamp Washer, w/o Parking Assist	Bumper Cover, Front	Tong Yang	06/15B	5C6807217DGRU	VW1000190
VW-04152BBQ	Volkswagen Jetta Sedan, 11-14, w/o Headlamp Washer, w/o Parking Assist	Bumper Cover, Front	Tong Yang	06/15B	5C6807217GRU	VW1000190



MONTHLY RECALL REPORT January 2016*

[Report: P8]
Monthly

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
K30-1155R-AC	Ford Escape, 13-15	Headlamp Assy, R	DEPO	20150420	CJ5Z13008C	FO2503309
K30-1155L-AC	Ford Escape, 13-15	Headlamp Assy, L	DEPO	20150420	CJ5Z13008D	FO2502309

CAPA 501 STANDARD - BUMPER PARTS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

*This report includes all decertifications from December 1, 2015 through December 31, 2015.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.