

### NEW PARTS CAPA 101 STANDARD - METALS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Dodge Dart, 13-14	Fender R	DG1K002RQ	Cobra King	68082972AA	CH1241280
Dodge Dart, 13-14	Fender R	DG1K002RQ	Cobra King	68082972AB	CH1241280
Dodge Dart, 13-16	Fender R	DG1K002RQ	Cobra King	68082972AC	CH1241280
Ford Escape Hybrid, 08-12	Fender Brace, R	CR-317ARQ	Chang Jung	8L8Z16A023A	FO1245102
Ford Escape Hybrid, 08-12	Fender Brace, L	CR-317ALQ	Chang Jung	8L8Z16A024A	FO1244102
Ford Escape, 08-12	Fender Brace, R	CR-317ARQ	Chang Jung	8L8Z16A023A	FO1245102
Ford Escape, 08-12	Fender Brace, L	CR-317ALQ	Chang Jung	8L8Z16A024A	FO1244102
Mercury Mariner Hybrid, 08-11	Fender Brace, R	CR-317ARQ	Chang Jung	8L8Z16A023A	FO1245102
Mercury Mariner Hybrid, 08-11	Fender Brace, L	CR-317ALQ	Chang Jung	8L8Z16A024A	FO1244102
Mercury Mariner, 08-11	Fender Brace, R	CR-317ARQ	Chang Jung	8L8Z16A023A	FO1245102
Mercury Mariner, 08-11	Fender Brace, L	CR-317ALQ	Chang Jung	8L8Z16A024A	FO1244102
Mitsubishi Lancer Sportback, 09-15, w/o Turbo	Bar, Upper Tie	MBS6508A	Auto Power	5256A607	MI1225143
Mitsubishi Lancer, 08-15, w/o Turbo	Bar, Upper Tie	MBS6508A	Auto Power	5256A607	MI1225143

### NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
BMW 5-Series 528i Standard Sedan, 14-15, w/o M pkg, w/o Park distance control	Bumper Cover, Rear	BMB056NCQ	Pro Fortune	51127332761	BM1100321
BMW 5-Series 535d/535i Standard Sedan, 14-15, w/o M pkg, w/o Park distance control	Bumper Cover, Rear	BMB054NCQ	Pro Fortune	51127332762	BM1100327
BMW 5-Series F10 Sedan M pkg, 11-13, w/o Park Distance Control	Bumper Cover, Front	BMB039NGQ	Pro Fortune	51118058994	BM1000311
BMW 5-Series F10 Sedan M pkg, 11-13, w/Park Distance Control w/o Side View Camera	Bumper Cover, Front	BMB039NIQ	Pro Fortune	51118058996	BM1000312
BMW 5-Series F10 Sedan M pkg, 11-13, w/Park Distance Control w/Side View Camera	Bumper Cover, Front	BMB039NHQ	Pro Fortune	51118058998	BM1000313
BMW 5-Series F10H Hybrid M pkg, 12-15, w/o Park Distance Control	Bumper Cover, Front	BMB039NGQ	Pro Fortune	51118058994	BM1000311
BMW 5-Series F10H Hybrid M pkg, 12-15, w/Park Distance Control w/o Side View Camera	Bumper Cover, Front	BMB039NIQ	Pro Fortune	51118058996	BM1000312
BMW 5-Series F10H Hybrid M pkg, 12-15, w/Park Distance Control w/Side View Camera	Bumper Cover, Front	BMB039NHQ	Pro Fortune	51118058998	BM1000313
Chevrolet Impala, Eco, 14	Grille, Lower	CV-07251GAQ	Tong Yang	22941696	GM1036164
Chevrolet Impala, 14-16, LS LT Model	Grille, Lower	CV-07251GAQ	Tong Yang	22941696	GM1036164
Chevrolet Malibu ECO, 14	Grille, Lower	CV-07272GAQ	Tong Yang	22995179	GM1200675
Chevrolet Malibu LS/LT/LTZ, 14-16	Grille, Lower	CV-07272GAQ	Tong Yang	22995179	GM1200675
Mercedes-Benz M-Class, ML320 BLUETEC, 09, w/o Sport Pkg w/o Parktronic w/o H/Lamp Washers	Bumper Cover, Front	BZB057NCQ	Pro Fortune	1648857225	MB1000290
Mercedes-Benz M-Class, ML320 BLUETEC, 09, w/o Sport Pkg w/o Parktronic w/o H/Lamp Washers	Bumper Cover, Front	BZB057NCQ	Pro Fortune	16488572259999	MB1000290
Mercedes-Benz M-Class, ML320 BLUETEC, 09, w/o Sport Pkg w/Parktronic w/o H/Lamp Washers	Bumper Cover, Front	BZB057NDQ	Pro Fortune	1648803240	MB1000292
Mercedes-Benz M-Class, ML320 BLUETEC, 09, w/o Sport Pkg w/Parktronic w/o H/Lamp Washers	Bumper Cover, Front	BZB057NDQ	Pro Fortune	16488032409999	MB1000292
Mercedes-Benz M-Class, ML320, 09, BLUETEC w/o Sport Pkg w/o Parktronic w/ H/Lamp Washers	Bumper Cover, Front	BZB057NEQ	Pro Fortune	1648803140	MB1000291
Mercedes-Benz M-Class, ML320, 09, BLUETEC w/o Sport Pkg w/o Parktronic w/ H/Lamp Washers	Bumper Cover, Front	BZB057NEQ	Pro Fortune	16488031409999	MB1000291
Mercedes-Benz M-Class, ML350 BLUETEC, 10-11, w/o Sport Pkg w/o Parktronic w/ H/Lamp Washers	Bumper Cover, Front	BZB057NEQ	Pro Fortune	1648803140	MB1000291
Mercedes-Benz M-Class, ML350 BLUETEC, 10-11, w/o Sport Pkg w/o Parktronic w/ H/Lamp Washers	Bumper Cover, Front	BZB057NEQ	Pro Fortune	16488031409999	MB1000291
Mercedes-Benz M-Class, ML350 BLUETEC, 10-11, w/o Sport Pkg w/o Parktronic w/o H/Lamp Washers	Bumper Cover, Front	BZB057NCQ	Pro Fortune	1648857225	MB1000290
Mercedes-Benz M-Class, ML350 BLUETEC, 10-11, w/o Sport Pkg w/o Parktronic w/o H/Lamp Washers	Bumper Cover, Front	BZB057NCQ	Pro Fortune	16488572259999	MB1000290

**NEW PARTS CAPA 201 STANDARD - PLASTICS**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Mercedes-Benz M-Class, ML350 BLUETEC, 10-11, w/o Sport Pkg w/Parktronic w/o H/Lamp Washers	Bumper Cover, Front	BZB057NDQ	Pro Fortune	1648803240	MB1000292
Mercedes-Benz M-Class, ML350 BLUETEC, 10-11, w/o Sport Pkg w/Parktronic w/o H/Lamp Washers	Bumper Cover, Front	BZB057NDQ	Pro Fortune	16488032409999	MB1000292
Mercedes-Benz M-Class, ML350, 09, w/o Sport Pkg w/Parktronic w/o H/Lamp Washers	Bumper Cover, Front	BZB057NDQ	Pro Fortune	1648803240	MB1000292
Mercedes-Benz M-Class, ML350, 09, w/o Sport Pkg w/Parktronic w/o H/Lamp Washers	Bumper Cover, Front	BZB057NDQ	Pro Fortune	16488032409999	MB1000292
Mercedes-Benz M-Class, ML350, 09-11, w/o Sport Pkg w/o Parktronic w/o H/Lamp Washers	Bumper Cover, Front	BZB057NCQ	Pro Fortune	1648857225	MB1000290
Mercedes-Benz M-Class, ML350, 09-11, w/o Sport Pkg w/o Parktronic w/o H/Lamp Washers	Bumper Cover, Front	BZB057NCQ	Pro Fortune	16488572259999	MB1000290
Mercedes-Benz M-Class, ML350, 09-11, w/o Sport Pkg w/o Parktronic w/ H/Lamp Washers	Bumper Cover, Front	BZB057NEQ	Pro Fortune	1648803140	MB1000291
Mercedes-Benz M-Class, ML350, 09-11, w/o Sport Pkg w/o Parktronic w/ H/Lamp Washers	Bumper Cover, Front	BZB057NEQ	Pro Fortune	16488031409999	MB1000291
Mercedes-Benz M-Class, ML450 Hybrid, 10-11, w/Parktronic w/o H/Lamp Washers	Bumper Cover, Front	BZB057NDQ	Pro Fortune	1648803240	MB1000292
Mercedes-Benz M-Class, ML450 Hybrid, 10-11, w/Parktronic w/o H/Lamp Washers	Bumper Cover, Front	BZB057NDQ	Pro Fortune	16488032409999	MB1000292
Mercedes-Benz M-Class, ML450 Hybrid, 10-11, w/o Parktronic w/ H/Lamp Washers	Bumper Cover, Front	BZB057NEQ	Pro Fortune	1648803140	MB1000291
Mercedes-Benz M-Class, ML450 Hybrid, 10-11, w/o Parktronic w/ H/Lamp Washers	Bumper Cover, Front	BZB057NEQ	Pro Fortune	16488031409999	MB1000291
Mercedes-Benz M-Class, ML550, 09-11, w/o Sport Pkg w/o Parktronic w/ H/Lamp Washers	Bumper Cover, Front	BZB057NEQ	Pro Fortune	1648803140	MB1000291
Mercedes-Benz M-Class, ML550, 09-11, w/o Sport Pkg w/o Parktronic w/ H/Lamp Washers	Bumper Cover, Front	BZB057NEQ	Pro Fortune	16488031409999	MB1000291
Mercedes-Benz M-Class, ML550, 09-11, w/o Sport Pkg w/Parktronic w/o H/Lamp Washers	Bumper Cover, Front	BZB057NDQ	Pro Fortune	1648803240	MB1000292
Mercedes-Benz M-Class, ML550, 09-11, w/o Sport Pkg w/Parktronic w/o H/Lamp Washers	Bumper Cover, Front	BZB057NDQ	Pro Fortune	16488032409999	MB1000292
Mercedes-Benz, ML450 Hybrid, 10-11, w/o Sport Pkg w/o Parktronic w/o H/Lamp Washers	Bumper Cover, Front	BZB057NCQ	Pro Fortune	1648857225	MB1000290
Mercedes-Benz, ML450 Hybrid, 10-11, w/o Sport Pkg w/o Parktronic w/o H/Lamp Washers	Bumper Cover, Front	BZB057NCQ	Pro Fortune	16488572259999	MB1000290
Mercedes-Benz, ML550, 09-11, w/o Sport Pkg w/o Parktronic w/o H/Lamp Washers	Bumper Cover, Front	BZB057NCQ	Pro Fortune	1648857225	MB1000290
Mercedes-Benz, ML550, 09-11, w/o Sport Pkg w/o Parktronic w/o H/Lamp Washers	Bumper Cover, Front	BZB057NCQ	Pro Fortune	16488572259999	MB1000290
Mini Cooper R60 Countryman, 11-15, w/Chrome	Bumper Cover, Front	MN04-9901-WH	Tran Hung	51119807196	MC1000115
Mini Cooper R61 Paceman, 13-15, w/Chrome	Bumper Cover, Front	MN04-9901-WH	Tran Hung	51119807196	MC1000115
Nissan Altima Hybrid, 07-11	Moulding, Rocker Panel R	NSR065RBO	Pro Fortune	76850JA000	NI1607100
Nissan Altima Sedan, 07-12	Moulding, Rocker Panel R	NSR065RBO	Pro Fortune	76850JA000	NI1607100

**NEW PARTS CAPA 301 STANDARD - LIGHTING**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Chevrolet Silverado 1500 LT W/T, 14-15	Headlamp Assy, L	K35-1171L-AC1	DEPO	23172782	GM2502410
Chevrolet Silverado 1500 LT W/T, 14-15	Headlamp Assy, R	K35-1171R-AC1	DEPO	23172783	GM2503410
Chevrolet Silverado 1500 LT W/T, 14-15	Headlamp Assy, L	K35-1171L-AC1	DEPO	23223255	GM2502410
Chevrolet Silverado 1500 LT W/T, 14-15	Headlamp Assy, R	K35-1171R-AC1	DEPO	23223256	GM2503410
Chevrolet Silverado 1500 LT W/T, 14-15	Headlamp Assy, L	K35-1171L-AC1	DEPO	23380550	GM2502410
Chevrolet Silverado 1500 LT W/T, 14-15	Headlamp Assy, R	K35-1171R-AC1	DEPO	23380551	GM2503410
Chevrolet Silverado, 14-15	Taillamp L	K35-1964L-AC	DEPO	23141274	GM2800261
Chevrolet Silverado, 14-15	Taillamp R	K35-1964R-AC	DEPO	23141275	GM2801261

**NEW PARTS CAPA 301 STANDARD - LIGHTING**

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Chevrolet Silverado, 14-15	Taillamp L	K35-1964L-AC	DEPO	23431875	GM2800261
Chevrolet Silverado, 14-15	Taillamp R	K35-1964R-AC	DEPO	23431876	GM2801261
Chrysler 200, 15	Taillamp L	17-5516-00-9	TYC Brother	68110363AA	CH2803107
Chrysler 200, 15	Taillamp R	17-5515-00-9	TYC Brother	68110364AA	CH2802107
Chrysler PT Cruiser, 06-08	Lamp, Back Up R	17-5253-00-9	TYC Brother	5116068AC	CH2883102
Chrysler PT Cruiser, 06-08	Lamp, Back Up L	17-5254-00-9	TYC Brother	5116069AC	CH2882102
Chrysler PT Cruiser, 06-10	Lamp, Back Up R	17-5253-00-9	TYC Brother	5116068AD	CH2883102
Chrysler PT Cruiser, 06-10	Lamp, Back Up L	17-5254-00-9	TYC Brother	5116069AD	CH2882102
Ford Fiesta Hatchback SE, 12-13, w/Appearance pkg	Headlamp Assy, R	K30-1149R-AC2	DEPO	CE8Z13008A	FO2503300
Ford Fiesta Hatchback SE, 12-13, w/Appearance Pkg	Headlamp Assy, L	K30-1149L-AC2	DEPO	CE8Z13008B	FO2502300
Ford Fiesta Sedan SE, 12-13, w/Appearance pkg	Headlamp Assy, R	K30-1149R-AC2	DEPO	CE8Z13008A	FO2503300
Ford Fiesta Sedan SE, 12-13, w/Appearance Pkg	Headlamp Assy, L	K30-1149L-AC2	DEPO	CE8Z13008B	FO2502300
Honda Fit, 09-11	Lamp, Fog R	19-5939-00-9	TYC Brother	33901TK6305	HO2593122
Honda Fit, 09-11	Lamp, Fog L	19-5940-00-9	TYC Brother	33951TK6305	HO2592122
Kia Forte Sedan, 10-13	Taillamp L	323-1934L-AC	DEPO	924011M010	KI2804101
Kia Forte Sedan, 10-13	Taillamp R	323-1934R-AC	DEPO	924021M010	KI2805101
Mitsubishi Eclipse Coupe, 08-12	Headlamp Assy, L	314-1136L-AC1	DEPO	8301B135	MI2502159
Mitsubishi Eclipse Coupe, 08-12	Headlamp Assy, R	314-1136R-AC1	DEPO	8301B136	MI2503159
Mitsubishi Eclipse Spyder, 07-11, From 1-07, 2.4L Eng	Headlamp Assy, L	314-1136L-AC1	DEPO	8301B135	MI2502159
Mitsubishi Eclipse Spyder, 07-11, From 1-07, 2.4L Eng	Headlamp Assy, R	314-1136R-AC1	DEPO	8301B136	MI2503159

**NEW PARTS CAPA 501 STANDARD - BUMPERS**

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Ford Crown Victoria, 98-11	Reinf., Bumper Rear	FO1106208DSC	PBSI-DS	3W7Z17906AA	FO1106208
Lincoln Town Car, 03-11	Reinf., Bumper Rear	FO1106227DSC	PBSI-DS	6W1Z17906B	FO1106227
Mercury Grand Marquis/Maruder, 03-11	Reinf., Bumper Rear	FO1106208DSC	PBSI-DS	3W7Z17906AA	FO1106208

**DECERTIFICATIONS**

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

**CAPA 101 STANDARD - METALS**

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
HD2810150-200C	Honda Accord Sedan, 08-09, (6 cyl)	Hood	AP 10/14A	60100TA6A90ZZ	HO1230154
HD2810150-200C	Honda Accord Sedan, 08-09, 6 cyl, USA built	Hood	AP 10/14A	60100TA6A91ZZ	HO1230154
HD2810150-200C	Honda Accord Sedan, 10-12, 6 Cyl	Hood	AP 10/14A	60100TA6A91ZZ	HO1230154
MZA506HD1	Mazda 5, 06-07	Hood	Gordon 09/15A	CCY35231X	MA1230162
MZA506HD1	Mazda 5, 06-07	Hood	Gordon 09/15A	CDY35231X	MA1230162
MZA506HD1	Mazda 5, 06-10	Hood	Gordon 09/15A	CCY35231XA	MA1230162
S0739H000BS	Toyota Tacoma, 05-09, w/scoop	Hood	Jui Li 09/15A	5330104140	TO1230201
TY-20133BQ	Toyota Tacoma, 05-09, w/scoop	Hood	Tong Yang 09/15A	5330104140	TO1230201
S0739H000BS	Toyota Tacoma, 05-11, w/Scoop	Hood	Jui Li 09/15A	5330104150	TO1230201
TY-20133BQ	Toyota Tacoma, 05-11, w/Scoop	Hood	Tong Yang 09/15A	5330104150	TO1230201
S0739H000BS	Toyota Tacoma, 05-11, w/scoop	Hood	Jui Li 09/15A	5330104170	TO1230201
TY-20133BQ	Toyota Tacoma, 05-11, w/scoop	Hood	Tong Yang 09/15A	5330104170	TO1230201

**CAPA 201 STANDARD - PLASTICS**

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
LX4610000-210C	Lexus RX 350, 10-12, w/o Premium Pkg; w/Parking Assist	Bumper Cover, Front	AP-Procom 01/15A	521190E907	LX1000191

**DECERTIFICATIONS**

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

**CAPA 301 STANDARD - LIGHTING**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
332-1199R-ACN	Chevrolet Impala, 04-05, from 2/6/04	Headlamp Assy, R	DEPO	20150925	10356098	GM2503248

**CAPA 501 STANDARD - BUMPERS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

**DELETED PARTS CAPA 101 STANDARD - METALS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

**DELETED PARTS CAPA 201 STANDARD - PLASTICS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

**DELETED PARTS CAPA 301 STANDARD - LIGHTING**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

**DELETED PARTS CAPA 501 STANDARD - BUMPERS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

\*This report includes all new, decertified and deleted parts from February 15, 2016 through February 19, 2016.

All CAPA reports including the weekly update are available on the CAPA website at [www.capacertified.org](http://www.capacertified.org).

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at [debbie@capacertified.org](mailto:debbie@capacertified.org)