

### NEW PARTS CAPA 101 STANDARD - METALS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Buick Encore, 13-15	Hood	BKEC13HD1	Gordon	94536914	GM1230416
Buick Encore, 13-15	Hood	BKEC13HD1	Gordon	95143268	GM1230416
Buick Encore, 13-16	Hood	BKEC13HD1	Gordon	42341565	GM1230416
Dodge Charger, 15	Fender R	S1045F200AS	Jui Li	68213060AC	CH1241282
Dodge Charger, 15	Fender L	S1045F100AS	Jui Li	68213061AC	CH1240282
Dodge Charger, 15, Standard non-functional hood scoop	Hood	S1045H000AL	Jui Li	68265445AA	CH1230305
Mazda CX-5, 13-16	Hood	MZX513HD1	Gordon	KDY35231XA	MA1230171
Volkswagen Golf Gen 7, 14-15, Mexico built	Hood	VWGF15HD1	Gordon	5G0823031J	VW1230146
Volkswagen Golf Gen 7, 15	Hood	VWGF15HD1	Gordon	5G0823031J	VW1230146

### NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
BMW 5-Series F10 Sedan, 14-16, w/o M pkg, w/o Active cruise control	Grille, Center Bumper	BM-07098GAQ	Tong Yang	51117331724	BM1036149
BMW 5-Series F10H Hybrid, 14-16, w/o M pkg, w/o Active cruise control	Grille, Center Bumper	BM-07098GAQ	Tong Yang	51117331724	BM1036149
Buick Encore, 13-16, w/o Side Object Sensor L	Fascia, L	BK-04052PALQ	Tong Yang	95352037	GM1116104
Buick Encore, 13-16, w/o Side Object Sensor R	Fascia, R	BK-04052PARQ	Tong Yang	95352038	GM1117104
Chevrolet Silverado 2500/3500, 15, w/Fog lamps, w/o Parking aid sensors	Filler, Front	CV-04305MAQ	Tong Yang	23156745	GM1087252
Chevrolet Silverado 2500/3500, 15-16, w/Fog lamps w/Parking aid sensors	Filler, Front	CV-04305MBQ	Tong Yang	23476442	GM1087252
Chevrolet Silverado 2500/3500, 15-16, w/Fog lamps, w/o Parking aid sensors	Filler, Front	CV-04305MAQ	Tong Yang	23476441	GM1087252
Dodge Challenger, 15	Crossmember, Upper	DG-03011AQ	Tong Yang	68144972AE	
Dodge Challenger, 15	Crossmember, Upper	DG-03011AQ	Tong Yang	68174972AD	
Dodge Challenger, 15	Crossmember, Upper	DG-03011AQ	Tong Yang	68174972AE	
Ford Flex Titanium, 11-12	Reinf, Grille Opng	FD-07378GAQ	Tong Yang	BA8Z8A284AA	FO1223123
Hyundai Elantra Sedan, 14-15, Chrome	Grille	HN-07080GAQ	Tong Yang	863503X700	HY1200173
Hyundai Elantra Sedan, 14-15, Korea built	Bumper Cover, Rear	Y-HYBP031CA	Y.C.C.	866113X700	HY1100202
Kia Optima, 14-15, USA built	Bumper Cover, Front	Y-KABP019CA	Y.C.C.	865114C500	KI1000168
Kia Rio Sedan, 06-11, Paint to match	Bumper Cover, Rear	KA-04079BBQ	Tong Yang	866111G000	KI1100129
Kia Sportage, 14-15, 2.4L Eng	Grille	KA-07056GAQ	Tong Yang	863503W500	KI1200162
Mercedes-Benz E-Class Hybrid Sedan, 14, w/o AMG styling pkg, w/Parktronic, w/o Insert	Bumper Cover, Front	BZ-04122BDQ	Tong Yang	21288025479999	MB1000428
Mercedes-Benz E-Class Sedan, 14, w/o AMG styling pkg, w/Parktronic, w/o Insert	Bumper Cover, Front	BZ-04122BDQ	Tong Yang	21288025479999	MB1000428
Mercedes-Benz E-Class Wagon, 14, w/o AMG styling pkg, w/Parktronic, w/o Insert	Bumper Cover, Front	BZ-04122BDQ	Tong Yang	21288025479999	MB1000428

### NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Cadillac CTS Sedan, 14-15	Reflector, Cover L	332-2904L-UC	DEPO	23856325	GM1184111
Cadillac CTS Sedan, 14-16	Reflector, Cover L	332-2904L-UC	DEPO	22856325	GM1184111
Cadillac CTS Sedan, 14-16	Reflector, Cover R	332-2904R-UC	DEPO	22856326	GM1185111
Ford C-Max Energi, 13-16	Headlamp Assy, R	20-9557-00-9	TYC Brother	DM5Z13008C	FO2503314
Ford C-Max Energi, 13-16	Headlamp Assy, L	20-9558-00-9	TYC Brother	DM5Z13008D	FO2502314
Ford C-Max Hybrid, 13-16	Headlamp Assy, R	20-9557-00-9	TYC Brother	DM5Z13008C	FO2503314
Ford C-Max Hybrid, 13-16	Headlamp Assy, L	20-9558-00-9	TYC Brother	DM5Z13008D	FO2502314
Hyundai Elantra Sedan, 14-16, w/o LED position (USA Built)	Headlamp Assy, L	20-9640-00-9	TYC Brother	921013Y500	HY2502187
Hyundai Elantra Sedan, 14-16, w/o LED position (USA built)	Headlamp Assy, R	20-9639-00-9	TYC Brother	921023Y500	HY2503187
Mazda 3 Hatchback, 14-15	Lamp, Fog R	19-6089-00-9	TYC Brother	TK2151680A	MA2593125
Mazda 3 Hatchback, 14-15	Lamp, Fog L	19-6090-00-9	TYC Brother	TK2151690A	MA2592125
Mazda 3 Sedan, 14-15	Lamp, Fog R	19-6089-00-9	TYC Brother	TK2151680A	MA2593125

### NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Mazda 3 Sedan, 14-15	Lamp, Fog L	19-6090-00-9	TYC Brother	TK2151690A	MA2592125
Mazda 6 Sedan, 14-16	Headlamp, Lens/Housing R	20-9427-01-9	TYC Brother	GJR9510K0C	MA2519160
Mazda 6 Sedan, 14-16	Headlamp, Lens/Housing L	20-9428-01-9	TYC Brother	GJR9510L0C	MA2518160
Mazda 6, 11-15	Lamp, Fog R	19-6089-00-9	TYC Brother	TK2151680A	MA2593125
Mazda 6, 11-15	Lamp, Fog L	19-6090-00-9	TYC Brother	TK2151690A	MA2592125
Mazda CX-5, 13-15	Lamp, Fog R	19-6089-00-9	TYC Brother	TK2151680A	MA2593125
Mazda CX-5, 13-15	Lamp, Fog L	19-6090-00-9	TYC Brother	TK2151690A	MA2592125
Mazda CX-9, 13-14	Lamp, Fog R	19-6089-00-9	TYC Brother	TK2151680A	MA2593125
Mazda CX-9, 13-14	Lamp, Fog L	19-6090-00-9	TYC Brother	TK2151690A	MA2592125
Mazda MX-5 Miata, 13-15	Lamp, Fog R	19-6089-00-9	TYC Brother	TK2151680A	MA2593125
Mazda MX-5 Miata, 13-15	Lamp, Fog L	19-6090-00-9	TYC Brother	TK2151690A	MA2592125
Mitsubishi Eclipse Coupe, 06 to 1-1-07	Headlamp Assy, R	314-1136R-ACD7	DEPO	8301A508	MI2503138
Mitsubishi Eclipse Spyder, 07, 2.4L/3.8L Eng	Headlamp Assy, R	314-1136R-ACD7	DEPO	8301A508	MI2503138
Subaru Forester, 14	Lamp, Fog	19-6063-00-9	TYC Brother	84501AJ060	SU2592122
Subaru Impreza Sedan, 14	Headlamp Assy, R	320-1123R-ACN2	DEPO	84001FJ081	SU2503154
Subaru Impreza Sedan, 14	Headlamp Assy, L	320-1123L-ACN2	DEPO	84001FJ091	SU2502154
Subaru Impreza Wagon, 14	Headlamp Assy, R	320-1123R-ACN2	DEPO	84001FJ081	SU2503154
Subaru Impreza Wagon, 14	Headlamp Assy, L	320-1123L-ACN2	DEPO	84001FJ091	SU2502154
Subaru Legacy, 13-14	Lamp, Fog	19-6063-00-9	TYC Brother	84501AJ060	SU2592122
Subaru XV Crosstrek Hybrid, 14-15	Headlamp Assy, R	320-1123R-ACN2	DEPO	84001FJ081	SU2503154
Subaru XV Crosstrek Hybrid, from 9/13-15	Headlamp Assy, L	320-1123L-ACN2	DEPO	84001FJ091	SU2502154
Subaru XV Crosstrek, from 9/13-15	Headlamp Assy, R	320-1123R-ACN2	DEPO	84001FJ081	SU2503154
Subaru XV Crosstrek, from 9/13-15	Headlamp Assy, L	320-1123L-ACN2	DEPO	84001FJ091	SU2502154
Toyota Corolla S/XRS, 09-10	Headlamp Assy, R	20-6993-90-9	TYC Brother	8111002680	TO2503183
Toyota Corolla S/XRS, 09-10	Headlamp Assy, L	20-6994-90-9	TYC Brother	8115002680	TO2502183
Volkswagen Beetle, 06-10	Headlamp Assy, L	20-6868-00-9	TYC Brother	1C0941029N	VW2518109
Volkswagen Beetle, 06-10	Headlamp Assy, R	20-6867-00-9	TYC Brother	1C0941030N	VW2519109

### NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Ford F150 Pickup, 15, Crew/Regular, Extended Cab	Bracket, Bumper R	FD45151ARH	Hui Yih	FL3Z17B984A	FO1067194
Ford F150 Pickup, 15, Crew/Regular/Extended Cab	Bracket, Bumper L	FD45151ALH	Hui Yih	FL3Z17B985A	FO1066194
Honda Civic Hybrid, 09-11	Absorber, Impact	HD01079A	Auto Power	71170SNAA50	HO1070150
Honda Civic Sedan, 09-11	Absorber, Impact	HD01079A	Auto Power	71170SNAA50	HO1070150
Nissan Altima Hybrid, 10-11	Absorber, Impact	NS01107A	Auto Power	62090ZX00A	NI1070147
Nissan Altima Sedan, 10-12	Absorber, Impact	NS01107A	Auto Power	62090ZX00A	NI1070147

### DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

### CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
HD-10082AQ-RH	Acura TL, 04-08	Fender R	Tong Yang	08/15A	04620SEPA90ZZ	AC1241114
S0807F200AS	Acura TL, 04-08	Fender R	Jui Li	08/15A	04620SEPA90ZZ	AC1241114
HD-10082AQ-RH	Acura TL, 04-08	Fender R	Tong Yang	08/15A	04620SEPA91ZZ	AC1241114
S0807F200AS	Acura TL, 04-08	Fender R	Jui Li	08/15A	04620SEPA91ZZ	AC1241114
CV-10124AQ-LH	Chevrolet Camaro Convertible, 11-15	Fender L	Tong Yang	12/15A	20943621	GM1240365
CV-10124AQ-LH	Chevrolet Camaro Coupe, 10-15	Fender L	Tong Yang	12/15A	20943621	GM1240365
CV-10124AQ-LH	Chevrolet Camaro, 10-11	Fender L	Tong Yang	12/15A	92220523	GM1240365
CV9300150-000C	Chevrolet Silverado 1500/2500 Series, 01-02	Hood	AP	12/14A	12477524	GM1230234
S0149H000AS	Chevrolet Silverado 1500/2500 Series, 01-02	Hood	Jui Li	12/14A	12477524	GM1230234

**DECERTIFICATIONS**

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

**CAPA 101 STANDARD - METALS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
S0149H000AS	Chevrolet Silverado, 99-00	Hood	Jui Li	12/14A	12477524	GM1230234
CV9300150-000C	Chevrolet Suburban, 00-04	Hood	AP	12/14A	12477524	GM1230234
S0149H000AS	Chevrolet Suburban, 00-04	Hood	Jui Li	12/14A	12477524	GM1230234
CV9300150-000C	Chevrolet Tahoe, 00-06	Hood	AP	12/14A	12477524	GM1230234
S0149H000AS	Chevrolet Tahoe, 00-06	Hood	Jui Li	12/14A	12477524	GM1230234
CR-20019AQ	Chrysler 200 Convertible, 11	Hood	Tong Yang	06/15A	68079056AC	CH1230290
CR-20019AQ	Chrysler 200 Convertible, 11	Hood	Tong Yang	06/15A	68079056AD	CH1230290
CR-20019AQ	Chrysler 200 Convertible, 11-14	Hood	Tong Yang	06/15A	68079056AE	CH1230290
CR-20019AQ	Chrysler 200 Sedan, 11	Hood	Tong Yang	06/15A	68079056AC	CH1230290
CR-20019AQ	Chrysler 200 Sedan, 11	Hood	Tong Yang	06/15A	68079056AD	CH1230290
CR-20019AQ	Chrysler 200 Sedan, 11-12	Hood	Tong Yang	06/15A	68079056AE	CH1230290
DG-20055AQ	Dodge Journey, 09-11	Hood	Tong Yang	09/15A	5076777AC	CH1230282
DG-20055AQ	Dodge Journey, 09-11	Hood	Tong Yang	11/15A	5076777AC	CH1230282
DG-20055AQ	Dodge Journey, 09-15	Hood	Tong Yang	09/15A	5076777AE	CH1230282
DG-20055AQ	Dodge Journey, 09-15	Hood	Tong Yang	11/15A	5076777AE	CH1230282
AM-20014AQ	Jeep Liberty, 02	Hood	Tong Yang	11/15A	55177200AB	CH1230220
S0229H000AS	Jeep Liberty, 02	Hood	Jui Li	11/15A	55177200AB	CH1230220
AM-20014AQ	Jeep Liberty, 02-03	Hood	Tong Yang	11/15A	55177200AC	CH1230220
S0229H000AS	Jeep Liberty, 02-03	Hood	Jui Li	11/15A	55177200AC	CH1230220
AM-20014AQ	Jeep Liberty, 02-04	Hood	Tong Yang	11/15A	55177200AD	CH1230220
S0229H000AS	Jeep Liberty, 02-04	Hood	Jui Li	11/15A	55177200AD	CH1230220
NIRG08HD1	Nissan Rogue, 08-15	Hood	Gordon	10/15A	FEA0MJM0MA	NI1230176
S0669H000AS	Nissan Rogue, 08-15	Hood	Jui Li	10/15A	FEA0MJM0MA	NI1230176

**CAPA 201 STANDARD - PLASTICS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
CV05025VDQ	Chevrolet Silverado, 03-07, w/o tow hooks or fog lamps	Deflector, Front Air	TYG Products	15/12/22	10367211	GM1092175
CV05025VDQ	Chevrolet Silverado, 03-07, w/o tow hooks or fog lamps	Deflector, Front Air	TYG Products	15/12/22	10397998	GM1092206
DG-04110BBQ	Dodge Avenger, 11-14	Bumper Cover, Front	Tong Yang	07/15A	68081991AB	CH1000996
LSB008NDQ	Lexus IS 250, 06-08, w/o park distance sensors	Bumper Cover, Rear	Pro Fortune	08/15A	5215953905	LX1100129
LSB008NDQ	Lexus IS 250, 06-08, w/o park distance sensors	Bumper Cover, Rear	Pro Fortune	11/15A	5215953905	LX1100129
LSB008NDQ	Lexus IS 350, 06-08, w/o park distance sensors	Bumper Cover, Rear	Pro Fortune	08/15A	5215953905	LX1100129
LSB008NDQ	Lexus IS 350, 06-08, w/o park distance sensors	Bumper Cover, Rear	Pro Fortune	11/15A	5215953905	LX1100129

**CAPA 301 STANDARD - LIGHTING**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
335-1142L-AC	GMC Yukon Hybrid, 08	Headlamp Assy, L	DEPO	20141124	15861025	GM2502265
335-1142L-AC	GMC Yukon Hybrid, 08	Headlamp Assy, L	DEPO	20150223	15861025	GM2502265
335-1142R-AC	GMC Yukon Hybrid, 08	Headlamp Assy, R	DEPO	20141124	15861026	GM2503265
335-1142L-AC	GMC Yukon Hybrid, 08-13	Headlamp Assy, L	DEPO	20141124	20969894	GM2502265
335-1142L-AC	GMC Yukon Hybrid, 08-13	Headlamp Assy, L	DEPO	20150223	20969894	GM2502265
335-1142R-AC	GMC Yukon Hybrid, 08-13	Headlamp Assy, R	DEPO	20141124	20969895	GM2503265

**DECERTIFICATIONS**

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

**CAPA 301 STANDARD - LIGHTING**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
335-1142L-AC	GMC Yukon XL, 07-08	Headlamp Assy, L	DEPO	20141124	15861025	GM2502265
335-1142L-AC	GMC Yukon XL, 07-08	Headlamp Assy, L	DEPO	20150223	15861025	GM2502265
335-1142R-AC	GMC Yukon XL, 07-08	Headlamp Assy, R	DEPO	20141124	15861026	GM2503265
335-1142L-AC	GMC Yukon XL, 07-13	Headlamp Assy, L	DEPO	20141124	20969894	GM2502265
335-1142L-AC	GMC Yukon XL, 07-13	Headlamp Assy, L	DEPO	20150223	20969894	GM2502265
335-1142R-AC	GMC Yukon XL, 07-13	Headlamp Assy, R	DEPO	20141124	20969895	GM2503265
335-1142L-AC	GMC Yukon, 07-08	Headlamp Assy, L	DEPO	20141124	15861025	GM2502265
335-1142L-AC	GMC Yukon, 07-08	Headlamp Assy, L	DEPO	20150223	15861025	GM2502265
335-1142R-AC	GMC Yukon, 07-08	Headlamp Assy, R	DEPO	20141124	15861026	GM2503265
335-1142L-AC	GMC Yukon, 07-14	Headlamp Assy, L	DEPO	20141124	20969894	GM2502265
335-1142L-AC	GMC Yukon, 07-14	Headlamp Assy, L	DEPO	20150223	20969894	GM2502265
335-1142R-AC	GMC Yukon, 07-14	Headlamp Assy, R	DEPO	20141124	20969895	GM2503265

**CAPA 501 STANDARD - BUMPERS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

**DELETED PARTS CAPA 101 STANDARD - METALS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

**DELETED PARTS CAPA 201 STANDARD - PLASTICS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

**DELETED PARTS CAPA 301 STANDARD - LIGHTING**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

**DELETED PARTS CAPA 501 STANDARD - BUMPERS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

\*This report includes all new, decertified and deleted parts from April 18, 2016 through April 22, 2016.  
All CAPA reports including the weekly update are available on the CAPA website at [www.capacertified.org](http://www.capacertified.org).  
If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at [debbie@capacertified.org](mailto:debbie@capacertified.org)