

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
NONE						

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
CR-04053BBQ	Chrysler 300, 05-10, 3.5L Eng	Bumper Cover, Rear	Tong Yang	02/15B	4805777AC	CH1100320
HD04107BBQ	Honda Accord Sedan, 01-02	Bumper Cover, Front	TYG Products	15/06/08	04711S84A91ZZ	HO1000196
HD04103BBQ	Honda Civic Coupe/Sedan, 01-03	Bumper Cover, Front	TYG Products	15/02/09	04711S5PA90ZZ	HO1000197
HD-04104BBQ	Honda Civic Hybrid, 03	Bumper Cover, Rear	Tong Yang	11/14A	04715S5AA90ZZ	HO1100200
HD04193BBQ	Honda Civic Hybrid, 06-08	Bumper Cover, Front	TYG Products	15/03/27	04711SNEA90ZZ	HO1000239
HD-04104BBQ	Honda Civic Sedan, 01-03	Bumper Cover, Rear	Tong Yang	11/14A	04715S5AA90ZZ	HO1100200
HD04193BBQ	Honda Civic Sedan, 06-08, 1.8L eng	Bumper Cover, Front	TYG Products	15/03/27	04711SNEA90ZZ	HO1000239
INJ1002A1-C	Infiniti JX35, 13, w/o Premium pkg	Bumper Cover, Front	Great Bestcam	08/14A	620223JA0H	IN1000251
INJ1002A1-C	Infiniti JX35, 13, w/o Premium pkg	Bumper Cover, Front	Great Bestcam	08/14A	FBM223JAMH	IN1000251
INJ1002A1-C	Infiniti QX60 Hybrid, 14, w/o Object Sensors	Bumper Cover, Front	Great Bestcam	08/14A	FBM223JAMH	IN1000251
INJ1002A1-C	Infiniti QX60 Hybrid, 14-15, w/o Object Sensors	Bumper Cover, Front	Great Bestcam	08/14A	620223JA0H	IN1000251
INJ1002A1-C	Infiniti QX60, 14, w/o Object Sensors	Bumper Cover, Front	Great Bestcam	08/14A	FBM223JAMH	IN1000251
INJ1002A1-C	Infiniti QX60, 14-15, w/o Object Sensors	Bumper Cover, Front	Great Bestcam	08/14A	620223JA0H	IN1000251
AM-04053BDQ	Jeep Grand Cherokee Laredo/Limited/ Overland/Summit, 14-15, w/Parking Assist	Bumper Cover, Front Upper	Tong Yang	06/14A	68214172AA	CH1014109
CHRJEEP-F11NEW	Jeep Grand Cherokee, 11, w/o Headlamp Washer	Bumper Cover, Front Upper	Micro Rim	J7714	68078268AA	CH1000979
CHRJEEP-F11NEW	Jeep Grand Cherokee, 11-13, w/o Headlamp Washer	Bumper Cover, Front Upper	Micro Rim	J7714	68078268AB	CH1000979
LX1310870-000C	Lexus ES 350, 07-12, w/Parking Sensors	Bumper Cover, Rear	AP-Procom	07/15A	5215933923	LX1100130
LX4610000-210C	Lexus RX 350, 10-12, w/o Premium Pkg; w/Parking	Bumper Cover, Front	AP-Procom	09/15A	521190E907	LX1000191
DS-04333BBQ	Nissan Altima, 13-15	Bumper Cover, Front	Tong Yang	09/15A	620223TA0H	NI1000285
DT3540000-010C	Nissan Maxima, 09-14	Bumper Cover, Front	AP-Procom	07/15A	620229N00H	NI1000258
DS-04329BBQ	Nissan Maxima, 09-14	Bumper Cover, Rear	Tong Yang	08/15B	850229N00H	NI1100264
DS-04287BAQ	Nissan Versa Sedan, 07-11, w/o Spoiler	Bumper Cover, Rear	Tong Yang	09/15A	HEM229EG0J	NI1100272
DS-04287BAQ	Nissan Versa Sedan, 07-11, w/o Spoiler	Bumper Cover, Rear	Tong Yang	09/15A	HEM22EM40J	NI1100272
TY-04330BCQ	Toyota Corolla Base/CE/LE/XLE, 09-10, (USA)	Bumper Cover, Rear	Tong Yang	06/15A	5215902963	TO1100264
TY8030000-500C	Toyota RAV-4 Base, 09-12	Bumper Cover, Front	AP-Procom	03/15A	5211942970	TO1000349
TOYSIEN-F11NEW	Toyota Sienna Base/L/LE, 11-15, 3.5L Eng	Bumper Cover, Front	Micro Rim	10/14B	5211908904	TO1000369
TOYSIEN-F11SNEW	Toyota Sienna Limited, 11-15, 3.5L Eng	Bumper Cover, Front	Micro Rim	09/14B	5211908902	TO1000368
TOYSIEN-F11NEW	Toyota Sienna XLE, 11-15, 3.5L Eng, w/o Limited pkg	Bumper Cover, Front	Micro Rim	10/14B	5211908904	TO1000369
TOYSIEN-F11SNEW	Toyota Sienna XLE, 11-15, w/Limited pkg 3.5L Eng	Bumper Cover, Front	Micro Rim	09/14B	5211908902	TO1000368
TY7520870-000C	Toyota Sienna, 04-10, w/o Park Assist Sensors	Bumper Cover, Rear	AP-Procom	05/15A	52159AE900	TO1100229
TY7520870-000C	Toyota Sienna, 04-10, w/o Park Assist Sensors	Bumper Cover, Rear	AP-Procom	07/15A	52159AE900	TO1100229
TY7520870-100C	Toyota Sienna, 04-10, w/Park Assist Sensor	Bumper Cover, Rear	AP-Procom	06/15A	52159AE902	TO1100228
TOYSIEN-F11NEW	Toyota Sienna, 11-12, 2.7L Eng	Bumper Cover, Front	Micro Rim	10/14B	5211908904	TO1000369

CAPA 301 STANDARD - LIGHTING

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
20-9494-00-9	Toyota Corolla, 14-15	Headlamp Assy, L	TYC Brother	7151510	8115002E60	TO2502216

CAPA 501 STANDARD - BUMPER PARTS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
NONE						

*This report includes all decertifications from March 1, 2016 through March 31, 2016.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.