

### NEW PARTS CAPA 101 STANDARD - METALS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Chevrolet Silverado 1500, 14-15, US built	Hood	GM1230419DSC	PBSI-DS	23203557	GM1230419
Chevrolet Silverado 1500, 14-15, USA/Mexico built	Hood	GM1230419DSC	PBSI-DS	23271756	GM1230419
Dodge Caliber, 07-12	Crossmember, Lower	JP30070AOH	Hui Yih	5115402AH	CH1225226
Ford F150 Pickup, 09-14	Bracket, Grille R	FD7E079RQ	Cobra King	9L3Z8182A	FO1207125
Ford F150 Pickup, 09-14	Bracket, Grille L	FD7E079LQ	Cobra King	9L3Z8182B	FO1207124
Honda Accord Sedan, 08-09, (6 cyl)	Hood	DJ-AC08401	Da Juane	60100TA6A90ZZ	HO1230154
Honda Accord Sedan, 08-09, 6 cyl, USA built	Hood	DJ-AC08401	Da Juane	60100TA6A91ZZ	HO1230154
Honda Accord Sedan, 10-12, 6 Cyl	Hood	DJ-AC08401	Da Juane	60100TA6A91ZZ	HO1230154
Jeep Compass, 07-16	Crossmember, Lower	JP30070AOH	Hui Yih	5115402AH	CH1225226
Jeep Patriot, 07-16	Crossmember, Lower	JP30070AOH	Hui Yih	5115402AH	CH1225226
Nissan Altima Sedan, 13-15	Support, Side R	NS58122RQ	Cobra King	F25123TAMA	NI1225205
Nissan Altima Sedan, 13-15	Support, Side L	NS58122LQ	Cobra King	F25133TAMA	NI1225204
Nissan Versa Sedan, 12-15	Radiator Support	DSS001AWK	Sa. Tai - H	F25303ANAH	NI1225197

### NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
BMW 5-Series F10 Sedan, 14-15, w/o M Pkg, w/ Park Distance Control, w/o Side View Camera	Bumper Cover, Front	BMB053NEQ	Pro Fortune	51117332680	BM1000309
BMW 5-Series F10 Sedan, 14-15, w/o M Pkg, w/o Park Distance control	Bumper Cover, Front	BMB053NDQ	Pro Fortune	51117332679	BM1000308
BMW 5-Series F10 Sedan, 14-15, w/o M Pkg, w/Park Distance Control, w/Side View Camera	Bumper Cover, Front	BMB053NFQ	Pro Fortune	51117332681	BM1000310
BMW 5-Series F10H Hybrid, 14-15, w/o M Pkg, w/ Park Distance Control, w/o Side View Camera	Bumper Cover, Front	BMB053NEQ	Pro Fortune	51117332680	BM1000309
BMW 5-Series F10H Hybrid, 14-15, w/o M Pkg, w/Park Distance Control, w/Side View Camera	Bumper Cover, Front	BMB053NFQ	Pro Fortune	51117332681	BM1000310
BMW 5-Series Gran Turismo F07, 10-13, w/Side View Camera	Bumper Cover, Front	BMB051NCQ	Pro Fortune	51117248039	BM1000319
BMW 5-Series Hybrid F10H, 14-15, w/o M Pkg, w/o Park Distance Control	Bumper Cover, Front	BMB053NDQ	Pro Fortune	51117332679	BM1000308
GMC Sierra 1500 Argent, 14-15	Cover, License Plate Mounting	CV-04268MAQ	Tong Yang	22877652	GM1068150
Hyundai Sonata, 15	Radiator Support	HN-03024AQ	Tong Yang	64101C2000	HY1225179
Hyundai Sonata, 15	Grille, Lower	HN-07087GAQ	Tong Yang	86561C2000	HY1036127
Kia Sportage, 11-15	Bumper Cover, Front	Y-KABP024CA	Y.C.C.	865113W000	KI1000152
Kia Sportage, 14-16	Grille, Bumper	KA-07060GAQ	Tong Yang	865613W500	KI036128
Lexus IS 250, 14-15, w/o F sport pkg	Extension, Grille	LXIS214GB1	Gordon	5210253020	LX1201100
Lexus IS 350, 14-15, w/o F sport pkg	Extension, Grille	LXIS214GB1	Gordon	5210253020	LX1201100
Mercedes-Benz GLK-Class, 10-12, w/o HL washer	Bumper Cover, Front	BZ-04140BJQ	Tong Yang	2048851425	MB1000331
Mercedes-Benz GLK-Class, 10-12, w/o Parktronic, w/o HL washer, w/o Off road pkg	Bumper Cover, Front	BZ-04140BJQ	Tong Yang	20488514259999	MB1000331
Mercedes-Benz GLK-Class, 10-12, w/ Parktronic, w/o HL washers, w/o Off road pkg	Bumper Cover, Front	BZ-04140BMQ	Tong Yang	2048804340	MB1000300
Mercedes-Benz GLK-Class, 10-12, w/o AMG styling, w/o Optical off road pkg, w/Parktronic, w/HL washer	Bumper Cover, Front	BZ-04140BCQ	Tong Yang	2048804540	MB1000364
Mercedes-Benz GLK-Class, 10-12, w/o AMG styling, w/o Optical off road pkg, w/Parktronic, w/HL washer	Bumper Cover, Front	BZ-04140BCQ	Tong Yang	20488045409999	MB1000364
Mercedes-Benz GLK-Class, 10-12, w/o AMG styling, w/o Optical off road, w/o Parktronic, w/HL washers	Bumper Cover, Front	BZ-04140BKQ	Tong Yang	20488044409999	MB1000365
Mercedes-Benz GLK-Class, 10-12, w/o HL washers	Bumper Cover, Front	BZ-04140BMQ	Tong Yang	20488043409999	MB1000300
Mercedes-Benz GLK-Class, 13-15, w/o Sport, w/o Parktronic	Bumper Cover, Rear	BZ-04143BDQ	Tong Yang	2048800849	MB1100305
Mercedes-Benz GLK-Class, 13-15, w/o Sport, w/o Park	Bumper Cover, Rear	BZ-04143BDQ	Tong Yang	20488008499999	MB1100305
Mercedes-Benz GLK-Class, 10-12, w/o AMG styling, w/o Optical off road, w/HL washers, w/o Object Sensors	Bumper Cover, Front	BZ-04140BKQ	Tong Yang	2048804440	MB1000365
Mercedes-Benz GLK-Class, 13-15, w/Parktronic	Bumper Cover, Rear	BZ-04143BBQ	Tong Yang	2048800949	MB1100306

### NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Mercedes-Benz GLK-Class, 13-15, w/Parktronic	Bumper Cover, Rear	BZ-04143BBQ	Tong Yang	20488009499999	MB1100306
Nissan Juke Nismo RS, 11-15	Liner, Fender R	NSJ1014BR-C	Great Bestcam	638423YW0A	NI1249140
Nissan Juke Nismo RS, 11-15	Liner, Fender L	NSJ1014BL-C	Great Bestcam	638433YW0A	NI1248140
Nissan Juke Nismo, 13-15, From 1-13	Liner, Fender R	NSJ1014BR-C	Great Bestcam	638423YW0A	NI1249140
Nissan Juke Nismo, 13-15, From 1-13	Liner, Fender L	NSJ1014BL-C	Great Bestcam	638433YW0A	NI1248140
Nissan Juke S/SL/SV, 15	Liner, Fender R	NSJ1014BR-C	Great Bestcam	638423YW0A	NI1249140
Nissan Juke S/SL/SV, 15	Liner, Fender L	NSJ1014BL-C	Great Bestcam	638433YW0A	NI1248140
Toyota Yaris Hatchback, 14, France built	Liner, Fender R	TYI041RAQ	Pro Fortune	538750D430	TO1249193
Toyota Yaris Hatchback, 14, France built	Liner, Fender L	TYI041LAQ	Pro Fortune	538760D430	TO1248193
Toyota Yaris Hatchback, 15, France built	Liner, Fender R	TYI041RBQ	Pro Fortune	538750D170	TO1249197
Toyota Yaris Hatchback, 15, France built	Liner, Fender L	TYI041LBQ	Pro Fortune	538760D170	TO1248197
Volvo XC60, 10-13, T6 R Design, R Design Model w/o H/Lamp Washer Paint to Match	Bumper Cover, Front	VV27-9904	Tran Hung	398549469	VO1000188
Volvo XC60, 10-13, T6 Model w/ H/Lamp Washer Paint to Match	Bumper Cover, Front	VV27-9904	Tran Hung	398549469	VO1000188
Volvo XC60, 10-13, T6 R Design, R Design Model w/ H/Lamp Washer Paint to Match	Bumper Cover, Front	VV27-9904	Tran Hung	398549469	VO1000188
Volvo XC60, 10-13, T6 R Design, R Design Model w/o H/Lamp Washer Paint to Match	Bumper Cover, Front	VV27-9904	Tran Hung	398549469	VO1000188

### NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Dodge Full Size Pickup, 07-09 (New Style)	Headlamp Assy, R	334-1122R-AC	DEPO	68003124AB	CH2503180
Dodge Full Size Pickup, 07-09 (New Style)	Headlamp Assy, L	334-1122L-AC	DEPO	68003125AB	CH2502180
Dodge Pickup, 07-08	Headlamp Assy, R	334-1122R-AC	DEPO	68003124AD	CH2503180
Dodge Pickup, 07-08, New Style	Headlamp Assy, L	334-1122L-AC	DEPO	68003125AD	CH2502180
Dodge R1500 MEGA/R2500/R3500 Pickup, 07-09	Headlamp Assy, R	334-1122R-AC	DEPO	68003124AD	CH2503180
Dodge R1500 MEGA/R2500/R3500 Pickup, 07-09	Headlamp Assy, L	334-1122L-AC	DEPO	68003125AD	CH2502180
Ford Fiesta S/SE Hatchback, 14	Headlamp Assy, L	K30-1159L-AC2	DEPO	D2BZ13008B	FO2503324
Ford Fiesta S/SE Hatchback, 14	Headlamp Assy, R	K30-1159R-AC2	DEPO	D2BZ13008D	FO2502324
Ford Fiesta S/SE Hatchback, 14-15	Headlamp Assy, R	K30-1159R-AC2	DEPO	D2BZ13008F	FO2502324
Ford Fiesta S/SE Hatchback, 14-15	Headlamp Assy, L	K30-1159L-AC2	DEPO	D2BZ13008H	FO2503324
Ford Fiesta S/SE Hatchback, 15-16, from 7/8/15	Headlamp Assy, R	K30-1159R-AC2	DEPO	D2BZ13008J	FO2502324
Ford Fiesta S/SE Hatchback, 15-16, from 7/8/15	Headlamp Assy, L	K30-1159L-AC2	DEPO	D2BZ13008L	FO2502324
Ford Fiesta S/SE Sedan, 14	Headlamp Assy, L	K30-1159L-AC2	DEPO	D2BZ13008B	FO2503324
Ford Fiesta S/SE Sedan, 14	Headlamp Assy, R	K30-1159R-AC2	DEPO	D2BZ13008D	FO2502324
Ford Fiesta S/SE Sedan, 14-15	Headlamp Assy, R	K30-1159R-AC2	DEPO	D2BZ13008F	FO2502324
Ford Fiesta S/SE Sedan, 14-15	Headlamp Assy, L	K30-1159L-AC2	DEPO	D2BZ13008H	FO2503324
Ford Fiesta S/SE Sedan, 15-16, from 7/8/15	Headlamp Assy, R	K30-1159R-AC2	DEPO	D2BZ13008J	FO2502324
Ford Fiesta S/SE Sedan, 15-16, from 7/8/15	Headlamp Assy, L	K30-1159L-AC2	DEPO	D2BZ13008L	FO2502324
Ford Fiesta ST, 14	Headlamp Assy, L	K30-1159L-AC2	DEPO	D2BZ13008B	FO2503324
Ford Fiesta ST, 14	Headlamp Assy, R	K30-1159R-AC2	DEPO	D2BZ13008D	FO2502324
Ford Fiesta ST, 14-15	Headlamp Assy, R	K30-1159R-AC2	DEPO	D2BZ13008F	FO2502324
Ford Fiesta ST, 14-15	Headlamp Assy, L	K30-1159L-AC2	DEPO	D2BZ13008H	FO2503324
Ford Fiesta ST, 15-16, from 7/8/15	Headlamp Assy, R	K30-1159R-AC2	DEPO	D2BZ13008J	FO2502324
Ford ST Fiesta, 15-16, from 7/8/15	Headlamp Assy, L	K30-1159L-AC2	DEPO	D2BZ13008L	FO2502324
Honda CR-V EX/EX-L, 15	Headlamp Assy, R	20-9621-90-9	TYC Brother	33100T1WA01	HO2503161
Honda CR-V EX/EX-L, 15	Headlamp Assy, L	20-9622-90-9	TYC Brother	33150T1WA01	HO2502161
Subaru Legacy, 15-16, w/o Driver Assist System	Lamp, Fog L	312-2030L-ACN	DEPO	84501AL01A	SU2592124
Toyota RAV-4 Sport, 09-12 (USA)	Headlamp Assy, R	312-11B2R-ACN7	DEPO	811100R020	TO2503206
Toyota RAV-4 Sport, 09-12 (USA)	Headlamp Assy, L	312-11B2L-ACN7	DEPO	811500R020	TO2502206

### NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Cadillac CTS, 08-13	Absorber, Impact	CD01145A	Auto Power	22880978	GM1070260
Hyundai Elantra, 04-06	Bar, Impact	HY1006119DSC	PBSI-DS	865302D500	HY1006119
Toyota Camry Hybrid, 07-11, Japan built	Bar, Reinforcement	TO1006206DSC	PBSI-DS	5202133150	TO1006206
Toyota Camry, 07-11, Japan built	Bar, Reinforcement	TO1006206DSC	PBSI-DS	5202133150	TO1006206

### DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

### CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
CH1230221DSC	Dodge Pickup (New Style), 04-08, w/o hood scoop	Hood	PBSI-DS	15273	55275733AF	CH1230221
CH1230221DSC	Dodge Pickup R1500 Mega Cab/R2500/R3500, 05-09, w/o Power Bulge	Hood	PBSI-DS	15273	55275733AF	CH1230221
CH1230221DSC	Dodge Pickup, 02	Hood	PBSI-DS	15273	55275733AA	CH1230221
CH1230221DSC	Dodge Pickup, 02-03 (New Style)	Hood	PBSI-DS	15273	55275733AF	CH1230221
CH1230221DSC	Dodge Pickup, 03	Hood	PBSI-DS	15273	55275733AB	CH1230221
CH1230221DSC	Dodge Pickup, 04, w/o hood scoop	Hood	PBSI-DS	15273	55275733AD	CH1230221
CH1230221DSC	Dodge Pickup, 05, w/o hood scoop	Hood	PBSI-DS	15273	55275733AE	CH1230221
DS-20103AQ	Nissan Altima Coupe, 08-09	Hood	Tong Yang	12/14A	65100JA030	NI1230173
DS-20103AQ	Nissan Altima Hybrid, 07-09	Hood	Tong Yang	12/14A	65100JA00D	NI1230173
DS-20103AQ	Nissan Altima Sedan, 07-09	Hood	Tong Yang	12/14A	65100JA00D	NI1230173
DS-20103AQ	Nissan Altima Sedan/Hybrid, 07-09	Hood	Tong Yang	12/14A	65100JA030	NI1230173
NS58002RQ	Nissan Altima, 13-15	Fender R	Cobra King	09/15A	631003TA0A	NI1241205
TYTM05F11	Toyota Tacoma Prerunner, 05-11, (2WD), w/wheel opng flare	Fender L	Gordon	11/14A	5380204100	TO1240208
TYTM05F11	Toyota Tacoma Prerunner, 05-15, (2WD), w/wheel opng flare	Fender L	Gordon	11/14A	5381204100	TO1240208
TYTM05F11	Toyota Tacoma, 05-11, (4WD)	Fender L	Gordon	11/14A	5380204100	TO1240208
TYTM05F11	Toyota Tacoma, 05-15, (4WD)	Fender L	Gordon	11/14A	5381204100	TO1240208

### CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Y-GMBP340CA	Chevrolet Camaro LS/LT, 10-13	Bumper Cover, Front	Y.C.C.	11/15A	92236548	GM1000906
CV-04185BBO	Chevrolet Equinox, 10-11	Bumper Cover, Front	Tong Yang	12/15A	20896097	GM1000907
CV-04185BBO	Chevrolet Equinox, 10-15	Bumper Cover, Front	Tong Yang	12/15A	20983230	GM1000907
Y-FDBP075CA	Ford Mustang Deluxe/Premium, 05-09	Bumper Cover, Rear	Y.C.C.	01/15A	5R3Z17K835AAA	FO1100387
Y-HDBP185CA	Honda Civic Hybrid, 12	Bumper Cover, Rear	Y.C.C.	10/15A	04715TR3A90ZZ	HO1100272
Y-HDBP185CA	Honda Civic Sedan, 12, 1.8L eng (USA, Canada, Japan)	Bumper Cover, Rear	Y.C.C.	10/15A	04715TR3A90ZZ	HO1100272
ING1003B1-C	Infiniti G35 Coupe, 03-07	Bumper Cover, Rear	Great Bestcam	09/15A	85022AM840	IN1100117
LSB037NDO	Lexus RX 350, 13-15, w/o F Sport pkg	Bumper Cover, Front	Pro Fortune	01/16A	521190E916	LX1000248
LSB037NDO	Lexus RX 450h, 10-15, w/o F Sport pkg, w/Parking assist	Bumper Cover, Front	Pro Fortune	01/16A	521190E916	LX1000248
Y-SCBP405CA	Scion xB, 11-15	Bumper Cover, Front	Y.C.C.	12/15A	5211912959	SC1000107
Y-TYBP269ACA	Toyota Camry Base, 08-09, (USA)	Bumper Cover, Front	Y.C.C.	08/15B	5211906919	TO1000329
Y-TYBP269ACA	Toyota Camry Base, 08-09, (USA)	Bumper Cover, Front	Y.C.C.	11/15B	5211906919	TO1000329
Y-TYBP269ACA	Toyota Camry CE, 07 (USA)	Bumper Cover, Front	Y.C.C.	08/15B	5211906919	TO1000329

**DECERTIFICATIONS**

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

**CAPA 201 STANDARD - PLASTICS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Y-TYBP269ACA	Toyota Camry CE, 07 (USA)	Bumper Cover, Front	Y.C.C.	11/15B	5211906919	TO1000329
Y-TYBP269ACA	Toyota Camry Hybrid, 07-09 (USA)	Bumper Cover, Front	Y.C.C.	08/15B	5211906919	TO1000329
Y-TYBP269ACA	Toyota Camry Hybrid, 07-09 (USA)	Bumper Cover, Front	Y.C.C.	11/15B	5211906919	TO1000329
Y-TYBP269ACA	Toyota Camry LE/XLE, 07-09, (USA)	Bumper Cover, Front	Y.C.C.	08/15B	5211906919	TO1000329
Y-TYBP269ACA	Toyota Camry LE/XLE, 07-09, (USA)	Bumper Cover, Front	Y.C.C.	11/15B	5211906919	TO1000329
TYB116NCQ	Toyota Corolla Base/CE/L/LE, 11-13 (NA)	Bumper Cover, Rear	Pro Fortune	09/15C	5215902977	TO1100287
VW-04131BCQ	Volkswagen Tiguan, 09-11, w/o Headlamp Washer	Bumper Cover, Front	Tong Yang	04/15A	5N0807217FGRU	VW1000173

**CAPA 301 STANDARD - LIGHTING**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

**CAPA 501 STANDARD - BUMPERS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

**DELETED PARTS CAPA 101 STANDARD - METALS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

**DELETED PARTS CAPA 201 STANDARD - PLASTICS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

**DELETED PARTS CAPA 301 STANDARD - LIGHTING**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

**DELETED PARTS CAPA 501 STANDARD - BUMPERS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

\*This report includes all new, decertified and deleted parts from April 25, 2016 through April 29, 2016.

All CAPA reports including the weekly update are available on the CAPA website at [www.capacertified.org](http://www.capacertified.org).

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at [debbie@capacertified.org](mailto:debbie@capacertified.org)