

### NEW PARTS CAPA 101 STANDARD - METALS

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Ford Taurus Police model, 13-16	Fender R	FD-10218AQ-RH	Tong Yang	DG1Z16005B	FO1241277
Ford Taurus Police model, 13-16	Fender L	FD-10218AQ-LH	Tong Yang	DG1Z16006B	FO1240277
Ford Taurus SHO, 10-16	Fender R	FD-10218AQ-RH	Tong Yang	DG1Z16005B	FO1241277
Ford Taurus SHO, 10-16	Fender L	FD-10218AQ-LH	Tong Yang	DG1Z16006B	FO1240277
Ford Taurus, 10-11	Fender R	FD-10218AQ-RH	Tong Yang	AG1Z16005A	FO1241277
Ford Taurus, 10-11	Fender L	FD-10218AQ-LH	Tong Yang	AG1Z16006A	FO1240277
Ford Taurus, 10-16	Fender R	FD-10218AQ-RH	Tong Yang	DG1Z16005B	FO1241277
Ford Taurus, 10-16	Fender L	FD-10218AQ-LH	Tong Yang	DG1Z16006B	FO1240277

### NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Cadillac SRX, 10-15	Grille, Lower Center	CDG012NDQ	Pro Fortune	25778326	GM1036129
Chrysler 200 Sedan, 15-16, Black Type 1	Bumper Cover, Applique Center	CR-07043MAQ	Tong Yang	68203036AB	CH1044119
Hyundai Tucson, 10-15	Bumper Cover, Front Lower	HN5010130-000C	AP-Procom	865122S000	HY1095100
Jeep Grand Cherokee Laredo/Limited/Overland/Summit, 14-15, w/Parking Assist	Bumper Cover, Front Upper	JP8210000-600C	AP-Procom	68214172AA	CH1014109
Jeep Grand Cherokee, 11-14	Filler, Bumper R	JP52004RQ	Cobra King	68078296AA	CH1089100
Jeep Grand Cherokee, 11-14	Filler, Bumper L	JP52004LQ	Cobra King	68078297AA	CH1088100
Subaru Legacy, 13-14	Grille	SB-07055GAQ	Tong Yang	91121AJ13A	SU1200157
Toyota 4Runner SR5 Premium, 14-16, w/o Chrome trim	Bumper Cover, Rear	TYB136NCQ	Pro Fortune	5215935922	TO1100312
Toyota 4Runner Trail Premium, 14-16, w/o Chrome trim	Bumper Cover, Rear	TYB136NDQ	Pro Fortune	5215935923	TO1100313
Toyota 4Runner Trail, 14-16, w/o Chrome trim	Bumper Cover, Rear	TYB136NDQ	Pro Fortune	5215935923	TO1100313
Toyota 4Runner TRD Pro, 14-16, w/o Chrome trim	Bumper Cover, Rear	TYB136NDQ	Pro Fortune	5215935923	TO1100313
Toyota 4Runner, 14-16, SR5, w/o Chrome trim	Bumper Cover, Rear	TYB136NCQ	Pro Fortune	5215935922	TO1100312
Toyota Sienna SE, 11-15, w/o Park Assist	Bumper Cover, Rear	TY20-8525	Tran Hung	5215908905	TO1100284
Volkswagen Passat, 12-15	Liner, Fender R	VWP1014FR-C	Great Bestcam	561805912D9B9	VW1249123

### NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Chevrolet 1500 LS Silverado, 14-15	Headlamp, L	20-9576-00-9	TYC Brother	20933722	GM2502395
Chevrolet 1500 LS Silverado, 14-15	Headlamp, R	20-9575-00-9	TYC Brother	20933723	GM2503395
Chevrolet 1500 LS Silverado, 14-15	Headlamp, R	20-9575-00-9	TYC Brother	23223258	GM2503395
Chevrolet 1500 LS Silverado, 14-15	Headlamp, R	20-9575-00-9	TYC Brother	23380553	GM2503395
Chevrolet Impala, 06-09	Taillamp R	11-6179-00-9	TYC Brother	15873297	GM2801193
Chevrolet Impala, 06-09	Taillamp L	11-6180-00-9	TYC Brother	15873298	GM2800193
Chevrolet Impala, 06-13	Taillamp L	11-6180-00-9	TYC Brother	25971597	GM2800193
Chevrolet Impala, 06-13	Taillamp R	11-6179-00-9	TYC Brother	25971598	GM2801193
Chevrolet Silverado 1500 LS, 14-15	Headlamp, L	20-9576-00-9	TYC Brother	23223257	GM2502395
Chevrolet Silverado 1500 LS, 14-15	Headlamp, L	20-9576-00-9	TYC Brother	23380552	GM2502395
Ford Fiesta S/SE Hatchback, 14	Headlamp Assy, L	20-9532-00-9	TYC Brother	D2BZ13008B	FO2503324
Ford Fiesta S/SE Hatchback, 14-15	Headlamp Assy, L	20-9532-00-9	TYC Brother	D2BZ13008H	FO2503324
Ford Fiesta S/SE Hatchback, 14-16, from 7/8/15	Headlamp Assy, L	20-9532-00-9	TYC Brother	D2BZ13008L	FO2502324
Ford Fiesta S/SE Sedan, 14	Headlamp Assy, L	20-9532-00-9	TYC Brother	D2BZ13008B	FO2503324
Ford Fiesta S/SE Sedan, 14-15	Headlamp Assy, L	20-9532-00-9	TYC Brother	D2BZ13008H	FO2503324
Ford Fiesta S/SE Sedan, 14-16, from 7/8/15	Headlamp Assy, L	20-9532-00-9	TYC Brother	D2BZ13008L	FO2502324
Ford Fiesta ST, 14	Headlamp Assy, L	20-9532-00-9	TYC Brother	D2BZ13008B	FO2503324
Ford Fiesta ST, 14-15	Headlamp Assy, L	20-9532-00-9	TYC Brother	D2BZ13008H	FO2503324
Ford ST Fiesta, 14-16, from 7/8/15	Headlamp Assy, L	20-9532-00-9	TYC Brother	D2BZ13008L	FO2502324
Hyundai Elantra Sedan, 11-13	Reflector, Bumper Rear L	321-2905L-UC	DEPO	924053X000	HY1184103
Hyundai Elantra Sedan, 11-13	Reflector, Bumper Rear R	321-2905R-UC	DEPO	924063X000	HY1185103
Hyundai Elantra Sedan, 11-13 (USA)	Headlamp Assy, L	20-12552-00-9	TYC Brother	921013Y000	HY2502161
Hyundai Elantra Sedan, 11-13 (USA)	Headlamp Assy, R	20-12551-00-9	TYC Brother	921023Y000	HY2503161

### NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Hyundai Elantra Sedan, 14-16	Reflector, Bumper Rear L	17-5538-00-9	TYC Brother	924053X200	HY1184114
Hyundai Elantra Sedan, 14-16	Reflector, Bumper Rear R	17-5537-00-9	TYC Brother	924063X200	HY1185114
Hyundai Elantra Sedan, 14-16, on body (USA built)	Taillamp L	321-1960L-ACN	DEPO	924013Y500	HY2804131
Kia Sportage, 13-16, w/o LED Accent Light	Headlamp Assy, L	323-1134L-ACD2	DEPO	921013W720	KI2502184
Kia Sportage, 13-16, w/o LED Accent Light	Headlamp Assy, R	323-1134R-ACD2	DEPO	921023W720	KI2503184
Lexus GX 470, 03-09	Reflector, Bumper Rear R	312-2902R-UC	DEPO	8191008010	LX2831100
Lexus GX 470, 03-09	Reflector, Bumper Rear L	312-2902L-UC	DEPO	8192008010	LX2830100
Lexus IS F, 08-14	Reflector, Bumper Rear R	312-2902R-UC	DEPO	8191008010	LX2831100
Lexus IS F, 08-14	Reflector, Bumper Rear L	312-2902L-UC	DEPO	8192008010	LX2830100
Lexus RX 300, 99-03	Reflector, Bumper Rear R	312-2902R-UC	DEPO	8191008010	LX2831100
Lexus RX 300, 99-03	Reflector, Bumper Rear L	312-2902L-UC	DEPO	8192008010	LX2830100
Mazda 3 Hatchback, 14-16, Japan Built, on Liftgate	Taillamp L	316-1309L-AC	DEPO	B45C513G0B	MA2802114
Subaru Outback, 10-14, on liftgate	Taillamp R	17-5501-01-9	TYC Brother	84912AJ07A	SU2803101
Subaru Outback, 10-14, on liftgate	Taillamp L	17-5502-01-9	TYC Brother	84912AJ08A	SU2802101
Toyota Avalon Hybrid, 13-15	Reflector, Bumper Rear R	312-2902R-UC	DEPO	8191008010	LX2831100
Toyota Avalon Hybrid, 13-15	Reflector, Bumper Rear L	312-2902L-UC	DEPO	8192008010	LX2830100
Toyota Avalon, 13-15	Reflector, Bumper Rear R	312-2902R-UC	DEPO	8191008010	LX2831100
Toyota Avalon, 13-15	Reflector, Bumper Rear L	312-2902L-UC	DEPO	8192008010	LX2830100
Toyota Matrix, 09-14	Reflector, Bumper Rear R	312-2902R-UC	DEPO	8191008010	LX2831100
Toyota Matrix, 09-14	Reflector, Bumper Rear L	312-2902L-UC	DEPO	8192008010	LX2830100
Toyota Sienna, 11-15	Reflector, Bumper Rear R	312-2902R-UC	DEPO	8191008010	LX2831100
Toyota Sienna, 11-15	Reflector, Bumper Rear L	312-2902L-UC	DEPO	8192008010	LX2830100
Toyota Venza, 09-14	Reflector, Bumper Rear R	312-2902R-UC	DEPO	8191008010	LX2831100
Toyota Venza, 09-14	Reflector, Bumper Rear L	312-2902L-UC	DEPO	8192008010	LX2830100
Volvo XC90, 03-14	Headlamp Assy, L	20-6564-00-9	TYC Brother	312768096	VO2502112
Volvo XC90, 03-14	Headlamp Assy, R	20-6563-00-9	TYC Brother	312768104	VO2503112

### NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Toyota Corolla, 03-08	Absorber, Impact	TA14613Q	Cobra King	5261502060	TO1170120

### DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

### CAPA 101 STANDARD - METALS

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
VW-10072AQ-LH	Volkswagen GLI Sedan, 11-15	Fender L	Tong Yang	11/15A	5C6821105	VW1240142
VW-10072AQ-LH	Volkswagen Jetta Hybrid, 13-15	Fender L	Tong Yang	11/15A	5C6821105	VW1240142
VW-10072AQ-LH	Volkswagen Jetta Sedan, 11-15	Fender L	Tong Yang	11/15A	5C6821105	VW1240142

### CAPA 201 STANDARD - PLASTICS

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
CLB064NCQ	Chevrolet Cruze, 11-16, w/o RS Pkg, w/o Rear Object Sensor	Bumper Cover, Rear	Pro Fortune	11/15B	95016694	GM1100876
CV-04173BCQ	Chevrolet Tahoe, 07-11, w/o Off Road pkg, w/o object sensor	Bumper Cover, Rear	Tong Yang	09/15A	25830549	GM1100785
CV-04173BCQ	Chevrolet Tahoe, 07-14, w/o Off Road pkg, w/o object sensor	Bumper Cover, Rear	Tong Yang	09/15A	20951794	GM1100785

**DECERTIFICATIONS**

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

**CAPA 201 STANDARD - PLASTICS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
CV-04173BCQ	GMC Yukon, 07-11, w/o object sensor	Bumper Cover, Rear	Tong Yang	09/15A	25830549	GM1100785
CV-04173BCQ	GMC Yukon, 07-14, w/o object sensor	Bumper Cover, Rear	Tong Yang	09/15A	20951794	GM1100785
TY-04259BBQ	Scion tC, 05-10	Bumper Cover, Front	Tong Yang	04/15A	5211921906	SC1000103
TY-04259BBQ	Scion tC, 05-10	Bumper Cover, Front	Tong Yang	11/15A	5211921906	SC1000103
Y-TYBP283HCA	Toyota Prius V, 12-14, w/LED HLamps and Pre-Collision System	Bumper Cover, Front	Y.C.C.	11/13A	5211947925	TO1000387

**CAPA 301 STANDARD - LIGHTING**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

**CAPA 501 STANDARD - BUMPERS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

**DELETED PARTS CAPA 101 STANDARD - METALS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

**DELETED PARTS CAPA 201 STANDARD - PLASTICS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

**DELETED PARTS CAPA 301 STANDARD - LIGHTING**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

**DELETED PARTS CAPA 501 STANDARD - BUMPERS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

\*This report includes all new, decertified and deleted parts from May 23, 2016 through May 27, 2016.  
All CAPA reports including the weekly update are available on the CAPA website at [www.capacertified.org](http://www.capacertified.org).  
If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at [debbie@capacertified.org](mailto:debbie@capacertified.org)