

NEW PARTS CAPA 101 STANDARD - METALS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|---|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Chevrolet Silverado 1500, 14-15 (USA), w/o Camera | Tailgate | CVSR14TG1 | Gordon | 23190796 | GM1900127 |
| Chevrolet Silverado 1500, 14-15 (USA), w/o Camera | Tailgate | CVSR14TG1 | Gordon | 23418939 | GM1900127 |
| Chevrolet Silverado 1500, 14-15, w/camera | Tailgate | CVSR14T11 | Gordon | 23205798 | GM1900128 |
| Chevrolet Silverado 1500, 14-15, w/camera | Tailgate | CVSR14T11 | Gordon | 23418940 | GM1900128 |
| Chevrolet Silverado 2500/3500, 15 (USA), w/o Camera | Tailgate | CVSR14TG1 | Gordon | 23190796 | GM1900127 |
| Chevrolet Silverado 2500/3500, 15 (USA), w/o Camera | Tailgate | CVSR14TG1 | Gordon | 23418939 | GM1900127 |
| Chevrolet Silverado 2500/3500, 15, w/camera | Tailgate | CVSR14T11 | Gordon | 23205798 | GM1900128 |
| Chevrolet Silverado 2500/3500, 15, w/camera | Tailgate | CVSR14T11 | Gordon | 23418940 | GM1900128 |
| GMC Sierra 1500, 14-15 (USA), w/o Camera | Tailgate | CVSR14TG1 | Gordon | 23190796 | GM1900127 |
| GMC Sierra 1500, 14-15 (USA), w/o Camera | Tailgate | CVSR14TG1 | Gordon | 23418939 | GM1900127 |
| GMC Sierra 1500, 14-15, w/camera | Tailgate | CVSR14T11 | Gordon | 23205798 | GM1900128 |
| GMC Sierra 1500, 14-15, w/camera | Tailgate | CVSR14T11 | Gordon | 23418940 | GM1900128 |
| GMC Sierra 2500/3500, 15 (USA), w/o Camera | Tailgate | CVSR14TG1 | Gordon | 23190796 | GM1900127 |
| GMC Sierra 2500/3500, 15 (USA), w/o Camera | Tailgate | CVSR14TG1 | Gordon | 23418939 | GM1900127 |
| GMC Sierra 2500/3500, 15, w/camera | Tailgate | CVSR14T11 | Gordon | 23205798 | GM1900128 |
| GMC Sierra 2500/3500, 15, w/camera | Tailgate | CVSR14T11 | Gordon | 23418940 | GM1900128 |
| Honda Civic Coupe, 06-11 | Hood | HD0900150-000C | AP | 60100SVAA90ZZ | HO1230149 |
| Honda Civic Coupe, 06-11 | Hood | S0743H000AS | Jui Li | 60100SVAA90ZZ | HO1230149 |
| Subaru Legacy, 15-16 | Hood | SB-20030AQ | Tong Yang | 57229AL00B9P | SU1230147 |
| Subaru Outback, 15-16 | Hood | SB-20030AQ | Tong Yang | 57229AL00B9P | SU1230147 |

NEW PARTS CAPA 201 STANDARD - PLASTICS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--|---------------------------|----------------------------|---------------------|-------------------|-------------------------|
| BMW 5-Series F10 Sedan, 14-15, w/o M Pkg, w/ Park Distance Control, w/o Side View Camera | Bumper Cover, Front | BM-04125BEQ | Tong Yang | 51117332680 | BM1000309 |
| BMW 5-Series F10 Sedan, 14-15, w/o M Pkg, w/o Park Distance control, w/o Side View Camera | Bumper Cover, Front | BM-04125BDQ | Tong Yang | 51117332679 | BM1000308 |
| BMW 5-Series F10 Sedan, 14-15, w/o M Pkg, w/Park Distance Control, w/Side View Camera | Bumper Cover, Front | BM-04125BFQ | Tong Yang | 51117332681 | BM1000310 |
| BMW 5-Series F10H Hybrid, 14-15, w/o M Pkg, w/ Park Distance Control, w/o Side View Camera | Bumper Cover, Front | BM-04125BEQ | Tong Yang | 51117332680 | BM1000309 |
| BMW 5-Series F10H Hybrid, 14-15, w/o M Pkg, w/Park Distance Control, w/Side View Camera | Bumper Cover, Front | BM-04125BFQ | Tong Yang | 51117332681 | BM1000310 |
| BMW 5-Series Hybrid F10H, 14-15, w/o M Pkg, w/o Park Distance Control | Bumper Cover, Front | BM-04125BDQ | Tong Yang | 51117332679 | BM1000308 |
| BMW X5 E70, 35i/35i Sport/35d/35i Premium, 11-13, w/o Park distance control | Bumper Cover, Rear | BM-04099BCQ | Tong Yang | 51127227762 | BM1100251 |
| BMW X5 E70, 35i/35i Sport/35d/35i Premium, 11-13, w/Park distance control | Bumper Cover, Rear | BM-04099BDQ | Tong Yang | 51127227787 | BM1100252 |
| Ford Focus, 08-11 | Cover, Reinforcement R | FD8N121RQ | Cobra King | 8S4Z17C947A | FO1033102 |
| Honda CR-V, 15-16 | Moulding, Grille Lower | HD-07200MAQ | Tong Yang | 71125T1WA01 | HO1216114 |
| Honda CR-V, 15-16, LX Model | Moulding, Bumper Front | HD-04295MAQ | Tong Yang | 71110T1WA11 | HO1095121 |
| Honda HR-V, 16 | Trim, Grille | HD-07205MARQ | Tong Yang | 71123T7A000 | HO1213113 |
| Honda HR-V, 16 | Trim, Grille | HD-07205MALQ | Tong Yang | 71128T7A000 | HO1212113 |
| Honda Pilot EX/EX-L/LX/SE, 12-15 | Bumper Cover, Rear | Y-HDBP192CA | Y.C.C. | 04715SZAA70ZZ | HO1100274 |
| Honda Pilot Touring, 12-15 | Bumper Cover, Rear | Y-HDBP192HCA | Y.C.C. | 04715SZAA60ZZ | HO1100275 |
| Hyundai Sonata, 15, 2.4L Eng, Dual Exhaust | Bumper Cover, Rear Lower | HYP028NAQ | Pro Fortune | 86612C2200 | HY1195104 |
| Hyundai Sonata, 15, Dual Exhaust 2.0L Engine | Bumper Cover, Front Lower | HYP027NAQ | Pro Fortune | 86612C2300 | HY1195105 |
| Jeep Liberty, 02-07 | Bumper Pad, Rear R | JP58021ARH | Hui Yih | 55155996AD | CH1191109 |
| Jeep Liberty, 02-07 | Bumper Pad, Rear L | JP58021ALH | Hui Yih | 55155997AD | CH1191108 |
| Mercedes-Benz E-Class E300/E350/E550 Sedan Hybrid, 14-15, w/AMG styling | Bumper Cover, Front | BZ-04142BDQ | Tong Yang | 212885273888 | MB1000411 |
| Mercedes-Benz E-Class E300/E350/E550 Sedan Hybrid, 14-15, w/AMG styling | Bumper Cover, Front | BZ-04142BDQ | Tong Yang | 21288527389999 | MB1000411 |
| Mercedes-Benz E-Class Sedan (212), 14-16, w/Parktronic | Bumper Cover, Front | BZ-04142BDQ | Tong Yang | 212885273888 | MB1000411 |
| Mercedes-Benz E-Class Sedan (212), 14-16, w/Parktronic | Bumper Cover, Front | BZ-04142BDQ | Tong Yang | 21288527389999 | MB1000411 |
| Mercedes-Benz E-Class Wagon, 14,16, w/Parktronic | Bumper Cover, Front | BZ-04142BDQ | Tong Yang | 212885273888 | MB1000411 |
| Mercedes-Benz E-Class Wagon, 14,16, w/Parktronic | Bumper Cover, Front | BZ-04142BDQ | Tong Yang | 21288527389999 | MB1000411 |
| Mercedes-Benz GLK-Class, 10-15, w/aluminum trim | Grille | BZ-07111GAQ | Tong Yang | 20488008839776 | MB1200161 |

NEW PARTS CAPA 201 STANDARD - PLASTICS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|---|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Mercedes-Benz M-Class ML350/ML350 Blutec/ML550, 12-15, w/Parktronic | Bumper Cover, Rear | BZB068NDQ | Pro Fortune | 166885062580 | MB1100296 |
| Mercedes-Benz M-Class ML350/ML350 Blutec/ML550, 12-15, w/Parktronic | Bumper Cover, Rear | BZB068NDQ | Pro Fortune | 16688506259999 | MB1100296 |
| Scion iC, 14-16 | Cover, Fog Lamp Opnq, L | TY-99268CALQ | Tong Yang | 5243821040 | SC1038102 |
| Toyota Camry Hybrid, 15-16, w/o Park Assist | Bumper Cover, Rear | TY-04517BCQ | Tong Yang | 5215906989 | TO1100315 |
| Toyota Camry, 15-16, w/o Park Assist | Bumper Cover, Rear | TY-04517BCQ | Tong Yang | 5215906989 | TO1100315 |
| Toyota, Scion, iC, 14-16 | Grille, Lower Cover R | TY-99264CARQ | Tong Yang | 5212721080 | SC1039103 |
| Toyota, Scion, iC, 14-16 | Cover, Bumper Hole | TY-99264CALQ | Tong Yang | 5212821080 | SC1038103 |
| Toyota, Scion, iC, 14-16 | Cover, Fog Lamp Opnq, R | TY-99268CARQ | Tong Yang | 5243721040 | SC1039102 |

NEW PARTS CAPA 301 STANDARD - LIGHTING

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Dodge Charger, 15-16 | Lamp, Side Marker R | 18-6163-00-9 | TYC Brother | 68214404AA | CH22551133 |
| Dodge Charger, 15-16 | Lamp, Side Marker L | 18-6164-00-9 | TYC Brother | 68214405AA | CH2550133 |
| GMC Acadia, 07-12 | Taillamp R | 335-1941R-AC | DEPO | 20912756 | GM2801216 |
| GMC Acadia, 07-12 | Taillamp L | 335-1941L-AC | DEPO | 20912757 | GM2800216 |
| Honda Accord EX-L/Touring, 13-15, On body | Taillamp R | 11-6623-00-9 | TYC Brother | 33500T2AA12 | HO2805103 |
| Honda Accord EX-L/Touring, 13-15, On body | Taillamp L | 11-6624-00-9 | TYC Brother | 33500T2AA12 | HO2804103 |
| Honda Pilot, 16 | Taillamp R | 11-6829-00-9 | TYC Brother | 33500TG7A01 | HO2805107 |
| Honda Pilot, 16 | Taillamp L | 11-6830-00-9 | TYC Brother | 33500TG7A01 | HO2804107 |
| Hyundai Santa Fe Sport, 13-16 | Headlamp Assy, L | 321-1146L-AC | DEPO | 921014Z010 | HY2502169 |
| Hyundai Santa Fe Sport, 13-16 | Headlamp Assy, R | 321-1146R-AC | DEPO | 921024Z010 | HY2503169 |
| Hyundai Sonata, 15-16, LED | Taillamp L | 321-1316L-AC | DEPO | 92403C2100 | HY2802125 |
| Kia Sedona, 15-16 | Taillamp L | 11-6764-00-9 | TYC Brother | 92401A9020 | KI2804117 |
| Kia Sedona, 15-16 | Taillamp R | 11-6763-00-9 | TYC Brother | 92402A9020 | KI2805117 |
| Kia Sorento, 14-15 | Headlamp Assy, L | 20-9450-90-9 | TYC Brother | 921011U600 | KI2502165 |
| Kia Sorento, 14-15 | Headlamp Assy, R | 20-9449-90-9 | TYC Brother | 921021U600 | KI2503165 |
| Mazda Pickup, 01-10 | Taillamp R | 316-1912R-UC | DEPO | 1F2051150 | MA2801114 |
| Mazda Pickup, 01-10 | Taillamp L | 316-1912L-UC | DEPO | 1F2051160 | MA2800114 |
| Nissan Maxima, 09-11 | Taillamp R | 11-6581-00-9 | TYC Brother | 265509N00B | NI2801193 |
| Nissan Maxima, 09-11 | Taillamp L | 11-6582-00-9 | TYC Brother | 265559N00B | NI2800193 |
| Toyota 4Runner, 14 | Headlamp, L | 20-9512-01-9 | TYC Brother | 8117035570 | TO2518150 |
| Toyota 4Runner, 14-15 | Headlamp, R | 20-9511-01-9 | TYC Brother | 8113035540 | TO2519150 |
| Toyota 4Runner, 14-16 | Headlamp, R | 20-9511-01-9 | TYC Brother | 8113035541 | TO2519150 |
| Toyota 4Runner, 14-16 | Headlamp, L | 20-9512-01-9 | TYC Brother | 8117035571 | TO2518150 |
| Toyota Sienna Base/LE/XLE/Limited, 10-14, From 10-11 | Lamp, Back Up R | 312-1318R-AC | DEPO | 8158008011 | TO2803125 |
| Toyota Sienna Base/LE/XLE/Limited, 11-14, From 10-11 | Lamp, Back Up L | 312-1318L-AC | DEPO | 8159008011 | TO2802125 |
| Toyota Sienna L, 13-14 | Lamp, Back Up R | 312-1318R-AC | DEPO | 8158008011 | TO2803125 |
| Toyota Sienna L, 13-14 | Lamp, Back Up L | 312-1318L-AC | DEPO | 8159008011 | TO2802125 |
| Volkswagen Jetta, 15 | Taillamp L | 17-5562-00-9 | TYC Brother | 5C6945093D | VW2802112 |
| Volkswagen Jetta, 15 | Taillamp R | 17-5561-00-9 | TYC Brother | 5C6945094D | VW2803112 |

NEW PARTS CAPA 501 STANDARD - BUMPERS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--------------------------------|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--|-------------------------|---------------------|------------|-------------------|-------------------------|
| FDPU09FL1 | Ford F150 Pickup, 09-10, w/o wheel opng mldg | Fender L | Gordon | 12/15A | 9L3Z16006A | FO1240272 |
| FDPU09FL1 | Ford F150 Pickup, 09-14, w/o wheel opng mldg | Fender L | Gordon | 12/15A | BL3Z16006A | FO1240272 |
| S0703H000AS | Ford Focus, 08-11 | Hood | Jui Li | 03/16A | 8S4Z16612A | FO1230272 |
| NS58002LQ | Nissan Altima, 13-15 | Fender L | Cobra King | 04/16A | 631013TA0A | NI1240205 |

CAPA 201 STANDARD - PLASTICS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|---|--------------------------|---------------------|------------|-------------------|-------------------------|
| DG04087BBQ | Dodge Grand Caravan, 08-10, w/headlamp washer | Bumper Cover, Front | TYG Products | 15/11/11 | 1AG02TZZAA | CH1000931 |
| DG04087BBQ | Dodge Grand Caravan, 08-10, w/headlamp washer | Bumper Cover, Front | TYG Products | 15/11/11 | 1AG02TZZAB | CH1000931 |
| Y-DSBP223CA | Nissan Versa Hatchback, 07-11, w/o Sport | Bumper Cover, Front | Y.C.C. | 03/16A | FBM22EM30J | NI1000245 |
| Y-DSBP223CA | Nissan Versa Hatchback, 07-12, w/o Sport | Bumper Cover, Front | Y.C.C. | 03/16A | FBM229EG0J | NI1000245 |
| Y-DSBP223CA | Nissan Versa Sedan, 07-11 | Bumper Cover, Front | Y.C.C. | 03/16A | FBM229EG0J | NI1000245 |
| Y-DSBP223CA | Nissan Versa Sedan, 07-11 | Bumper Cover, Front | Y.C.C. | 03/16A | FBM22EM30J | NI1000245 |
| TY-04330BCQ | Toyota Corolla Base/CE/L, 09-10, (USA) | Bumper Cover, Rear | Tong Yang | 09/15B | 5215902963 | TO1100264 |
| TY-04330BCQ | Toyota Corolla Base/CE/L, 09-10, (USA) | Bumper Cover, Rear | Tong Yang | 12/15A | 5215902963 | TO1100264 |
| TY-04393BBQ | Toyota Highlander, 11-13 | Bumper Cover, Rear Upper | Tong Yang | 02/16A | 521590E907 | TO1100289 |

CAPA 301 STANDARD - LIGHTING

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| NONE | | | | | | |

CAPA 501 STANDARD - BUMPERS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| NONE | | | | | | |

DELETED PARTS CAPA 101 STANDARD - METALS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| HD3510150-000C | Honda Insight, 10-14 | Hood | AP | 60100TM8A90ZZ | HO1230160 |

DELETED PARTS CAPA 201 STANDARD - PLASTICS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| | | | | | |

DELETED PARTS CAPA 301 STANDARD - LIGHTING

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

DELETED PARTS CAPA 501 STANDARD - BUMPERS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |



WEEKLY PARTS UPDATE

August 29, 2016

[Report: P6]
Weekly

CORRECTION

The following part was listed as decertified on the July 18, 2016 Weekly Parts Update.
Upon further review, this part was not decertified during the period covered by that report.

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| 312-1186R-AC7 | Toyota Tacoma, 05-11, Type 1 | Headlamp Assy, R | DEPO | 20150601 | 8111004173 | TO2503181 |

*This report includes all new, decertified and deleted parts from August 22, 2016 through August 26, 2016.

All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org