

NEW PARTS CAPA 101 STANDARD - METALS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Honda Civic Sedan, 16	Beam, Bumper	HD46161AH	Hui Yih	71150TBAA00	HO1031105
Mercury Mariner Hybrid, 08-09	Fender R	CR-902BRQ	Chang Jung	8E6Z16005A	FO1241262
Mercury Mariner Hybrid, 10-11	Fender R	CR-902ARQ	Chang Jung	AE6Z16005A	FO1241280
Mercury Mariner, 08-09	Fender R	CR-902BRQ	Chang Jung	8E6Z16005A	FO1241262
Mercury Mariner, 10-11	Fender R	CR-902ARQ	Chang Jung	AE6Z16005A	FO1241280
Toyota Tundra, 14-16	Radiator Support	TYS6868A	Auto Power	532010C090	TO1225325

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
BMW 3-Series F30 Sedan, 12-14, w/o M sport line, w/HL washer, w/PDC, w/o PA, w/Camera	Bumper Cover, Front	BM-04126BKQ	Tong Yang	51117327279	BM1000269
BMW 3-Series F30 Sedan, 12-15, w/o M sport line, w/HL washer, w/o PDC	Bumper Cover, Front	BM-04126BEQ	Tong Yang	51117293093	BM1000271
BMW 3-Series F30 Sedan, 12-15, w/o M sport line, w/o HL washer, w/PDC, w/PA, w/Camera	Bumper Cover, Front	BM-04126BDQ	Tong Yang	51117293089	BM1000272
BMW 3-Series F30 Sedan, 12-15, w/o M sport line, w/o HL washer, w/PDC, w/PA, w/o Camera	Bumper Cover, Front	BM-04126BCQ	Tong Yang	51117293087	BM1000273
BMW 3-Series F30H Hybrid Sedan, 13-14, w/o M Sport Line, w/HL washer, w/PDC, w/o PA, w/Camera	Bumper Cover, Front	BM-04126BKQ	Tong Yang	51117327279	BM1000269
BMW 3-Series F30H Hybrid Sedan, 13-15, w/o M Sport Line, w/HL washer, w/o PDC	Bumper Cover, Front	BM-04126BEQ	Tong Yang	51117293093	BM1000271
BMW 3-Series F30H Hybrid Sedan, 13-15, w/o M Sport Line, w/o HL washer, w/PDC, w/PA, w/Camera	Bumper Cover, Front	BM-04126BDQ	Tong Yang	51117293089	BM1000272
BMW 3-Series F30H Hybrid Sedan, 13-15, w/o M Sport Line, w/o HL washer, w/PDC, w/PA, w/o Camera	Bumper Cover, Front	BM-04126BCQ	Tong Yang	51117293087	BM1000273
BMW 3-Series F31 Wagon, 14, w/o M sport line, w/HL washer, w/PDC, w/o PA, w/Camera	Bumper Cover, Front	BM-04126BKQ	Tong Yang	51117327279	BM1000269
BMW 3-Series F31 Wagon, 14-15, w/o M sport line, w/HL washer, w/o PDC	Bumper Cover, Front	BM-04126BEQ	Tong Yang	51117293093	BM1000271
BMW 3-Series F31 Wagon, 14-15, w/o M sport line, w/o HL washer, w/PDC, w/PA, w/Camera	Bumper Cover, Front	BM-04126BDQ	Tong Yang	51117293089	BM1000272
BMW 3-Series F31 Wagon, 14-15, w/o M sport line, w/o HL washer, w/PDC, w/PA, w/o Camera	Bumper Cover, Front	BM-04126BCQ	Tong Yang	51117293087	BM1000273
BMW 3-Series Sedan F30, 12-15, Modern/Luxury/Sport Line, w/o H/L Washer, w/o PDC	Bumper Cover, Front	BM-04126BAQ	Tong Yang	51117293085	BM1000276
BMW 3-Series Sedan Hybrid F30H, 13-15, Modern/Luxury/Sport Line, w/o H/L Washer, w/o PDC	Bumper Cover, Front	BM-04126BAQ	Tong Yang	51117293085	BM1000276
BMW 3-Series Wagon F31, 14-15, Modern/Luxury/Sport Line, w/o H/L Washer, w/o PDC	Bumper Cover, Front	BM-04126BAQ	Tong Yang	51117293085	BM1000276
Chrysler 200, 15-17, Sedan, w/o Parallel Park Assist, w/ Parking Sensors	Bumper Cover, Front	CR-04068BFQ	Tong Yang	5SH88TZAA	CH1000A17
Chrysler Town & Country, 11-14, w/o Blind spot sensor	Bumper Cover, Rear	CR-04065BCQ	Tong Yang	68125726AA	CH1100968
Chrysler Town & Country, 11-16, w/o Blind Spot Sensor	Bumper Cover, Rear	CR-04065BCQ	Tong Yang	68125726AB	CH1100968
Dodge Challenger, 08-14	Shield, Splash R	DGC3014AR-C	Great Bestcam	5028750AF	CH1249150
Dodge Challenger, 08-14	Shield, Splash L	DGC3014AL-C	Great Bestcam	5028751AF	CH1248150
Dodge Charger, 11-14	Liner, Fender Assy R	DGC4014BR-C	Great Bestcam	68083028AH	CH1249154
Dodge Charger, 11-14	Liner, Fender Assy L	DGC4014BL-C	Great Bestcam	68083029AH	CH1248154
Dodge Grand Caravan, 11-16, w/o Blind Spot Sensor	Bumper Cover, Rear	CR-04065BCQ	Tong Yang	68125726AB	CH1100968
Ford Focus, 15-16, w/o Fog Lamps L	Grille, Outer Bumper L	FD8T083LQ	Cobra King	F1EZ17B814B	FO1038150
Ford Focus, 15-16, w/o Fog Lamps R	Grille, Outer Bumper R	FD8T083RQ	Cobra King	F1EZ17B814A	FO1039150
Honda Civic Coupe, 14-15	Bumper Cover, Rear	HDB102NBQ	Pro Fortune	71501TS8A50ZZ	HO1100288
Honda Civic Coupe, 14-15, 1.8L Eng	Grille	HD-07186GAQ	Tong Yang	71120TS8A51	HO1200221
Honda Pilot, 09-11	Cover, Fog Lamp Opng R	HD1C083RQ	Cobra King	71102SZAA00ZZ	HO1039101
Honda Pilot, 09-11	Cover, Fog Lamp Opng L	HD1C083LQ	Cobra King	71107SZAA00ZZ	HO1038101
Kia Sedona, 15-16, Black w/o Auto Cruise	Grille	KA-07066GAQ	Tong Yang	86352A9500	KI1200178
Kia Sedona, 15-16, Chrome w/o Auto Cruise	Grille	KA-07066GBQ	Tong Yang	86352A9520	KI1200179
Kia Sorento, 14-15	Bumper Cover, Rear Lower	Y-KAAR023RCA	Y.C.C.	866121U500	KI1115102
Subaru Outback, 15-16	Grille	SB-07059GAQ	Tong Yang	91121AL05A	SU1200159
Toyota 4Runner SR5 Premium, 14-16, w/o Chrome trim	Bumper Cover, Rear	TY-04508BCQ	Tong Yang	5215935922	TO1100312
Toyota 4Runner Trail Premium, 14-16, w/o Chrome trim	Bumper Cover, Rear	TY-04508BDQ	Tong Yang	5215935923	TO1100313

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Toyota 4Runner Trail, 14-16, w/o Chrome trim	Bumper Cover, Rear	TY-04508BDQ	Tong Yang	5215935923	TO1100313
Toyota 4Runner TRD Pro, 14-16, w/o Chrome trim	Bumper Cover, Rear	TY-04508BDQ	Tong Yang	5215935923	TO1100313
Toyota 4Runner, 14-16, SR5, w/o Chrome trim	Bumper Cover, Rear	TY-04508BCQ	Tong Yang	5215935922	TO1100312
Toyota Prius Plug-In, 12-15	Bumper Cover, Front Upper	TAOK106Q	Cobra King	5328947033	TO1224101
Toyota Prius, 10-15	Bumper Cover, Front Upper	TAOK106Q	Cobra King	5328947033	TO1224101
Toyota Tacoma, 12-15	Filler, Headlamp R	TA8B004ARQ	Cobra King	5250204900	TO1089118
Toyota Tacoma, 12-15	Filler, Headlamp L	TA8B004ALQ	Cobra King	5250304900	TO1088118
Volkswagen Tiguan, 12-15	Grille	VW-07136GAQ	Tong Yang	5N0853651H9B9	VW1200160
Volkswagen Tiguan, 12-16	Grille	VW-07136GAQ	Tong Yang	5N0853651J9B9	VW1200160

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Dodge Dakota Pickup, 08-11, w/o Black bezel	Headlamp Assy, R	334-1129R-AC1	DEPO	55112244AE	CH2519128
Dodge Dakota Pickup, 08-11, w/o Black bezel	Headlamp Assy, L	334-1129L-AC1	DEPO	55112245AE	CH2518128
GMC Sierra, 14-15	Headlamp Assy, L	K35-1172L-AC	DEPO	23130717	GM2502394
GMC Sierra, 14-15	Headlamp Assy, R	K35-1172R-AC	DEPO	23130718	GM2503394
Kia Optima, 12-13, On body, USA built	Taillamp L	11-6410-90-9	TYC Brother	924014C000	KI2804108
Kia Optima, 12-13, On body, USA built	Taillamp R	11-6409-90-9	TYC Brother	924024C000	KI2805108
Kia Sorento, 14-15	Headlamp Assy, L	20-9450-00-9	TYC Brother	921011U500	KI2502164
Kia Sorento, 14-15	Headlamp Assy, R	20-9449-00-9	TYC Brother	921021U500	KI2503164
Subaru Impreza, 06	Headlamp Assy, R	320-1117R-AC7	DEPO	84001FE680	SU2503131
Subaru Outback, 06	Headlamp Assy, R	320-1117R-AC7	DEPO	84001FE680	SU2503131
Toyota Camry Special Edition, 15-16	Taillamp R	312-19C4R-AC2	DEPO	8155006830	TO2805126
Toyota Camry Special Edition, 15-16	Taillamp L	312-19C4L-AC2	DEPO	8156006830	TO2804126
Toyota Tacoma Limited, 16	Taillamp R	312-19ACR-AC-C	DEPO	8155004190	TO2801199
Toyota Tacoma Limited, 16	Taillamp L	312-19ACL-AC-C	DEPO	8156004190	TO2800199

NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Chevrolet 2500/3500 HD Silverado, 07-10, w/o Rear Object sensors	Bumper, Rear Assembly	GM1103150DSC	PBSI-DS	GM1103150	GM1103150
Chevrolet 2500/3500 HD Silverado, 07-10, w/Rear Object sensors	Bumper, Rear Assembly	GM1103151DSC	PBSI-DS	GM1103151	GM1103151
Chevrolet 2500/3500 HD Silverado, 11, w/Rear Object sensor, w/o Sensor Components	Bumper, Rear Assembly	GM1103161DSC	PBSI-DS	GM1103161	GM1103161
Chevrolet 2500/3500HD Silverado, 11-12, w/o Rear Object sensor	Bumper, Rear Assembly	GM1103164DSC	PBSI-DS	GM1103164	GM1103164
Chevrolet 3500 HD Silverado, 07-10, w/Dual Rear Wheels, w/o Rear Object sensors	Bumper, Rear Assembly	GM1103153DSC	PBSI-DS	GM1103153	GM1103153
Chevrolet 3500 HD Silverado, 07-10, w/Dual Rear Wheels, w/Rear Object Sensor, w/o Sensor Components	Bumper, Rear Assembly	GM1103154DSC	PBSI-DS	GM1103154	GM1103154
Chevrolet Silverado 1500 Hybrid, 09-11, w/o Rear Object sensor	Bumper, Rear Assembly	GM1103159DSC	PBSI-DS	GM1103159	GM1103159
Chevrolet Silverado 1500, 09-11, w/o Rear Object sensor	Bumper, Rear Assembly	GM1103159DSC	PBSI-DS	GM1103159	GM1103159
Chevrolet Silverado 2500/3500HD, 11, w/Rear Object sensor, w/o Sensor components	Bumper, Rear Assembly	GM1103165DSC	PBSI-DS	GM1103165	GM1103165
Chevrolet Silverado Hybrid, 09-13, w/o Rear Object Sensors	Bumper, Rear Assembly	GM1103147DSC	PBSI-DS	GM1103147	GM1103147
Chevrolet Silverado Hybrid, 09-13, w/Rear Object Sensors, w/o Sensor components	Bumper, Rear Assembly	GM1103148DSC	PBSI-DS	GM1103148	GM1103148
Chevrolet Silverado, 07-13, w/o Rear Object Sensors	Bumper, Rear Assembly	GM1103147DSC	PBSI-DS	GM1103147	GM1103147
Chevrolet Silverado, 07-13, w/Rear Object Sensors	Bumper, Rear Assembly	GM1103149DSC	PBSI-DS	GM1103149	GM1103149
Chevrolet Silverado, 07-13, w/Rear Object Sensors, w/o Sensor components	Bumper, Rear Assembly	GM1103148DSC	PBSI-DS	GM1103148	GM1103148
Dodge RAM R1500 Pickup, 13-16, w/single piece bumper	Absorber, Impact	DG01177A	Auto Power	68145441AC	CH1070834
GMC 1500 Sierra, 09-11, w/o Rear Object sensor	Bumper, Rear Assembly	GM1103159DSC	PBSI-DS	GM1103159	GM1103159
GMC 2500/3500 HD Sierra, 07-10, w/o Rear Object sensors	Bumper, Rear Assembly	GM1103150DSC	PBSI-DS	GM1103150	GM1103150
GMC 2500/3500 HD Sierra, 07-10, w/Rear Object sensors	Bumper, Rear Assembly	GM1103151DSC	PBSI-DS	GM1103151	GM1103151
GMC 2500/3500 HD Sierra, 11, w/Rear Object sensor, w/o Sensor Components	Bumper, Rear Assembly	GM1103161DSC	PBSI-DS	GM1103161	GM1103161
GMC 2500/3500HD Sierra, 11-12, w/o Rear Object sensor	Bumper, Rear Assembly	GM1103164DSC	PBSI-DS	GM1103164	GM1103164
GMC 3500 HD Sierra, 07-10, w/Dual Rear Wheels, w/o Rear Object sensors	Bumper, Rear Assembly	GM1103153DSC	PBSI-DS	GM1103153	GM1103153

NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
GMC 3500 HD Sierra, w/Dual Rear Wheels, w/Rear Object Sensor, w/o Sensor Components	Bumper, Rear Assembly	GM1103154DSC	PBSI-DS	GM1103154	GM1103154
GMC Sierra 1500 Hybrid, 09-11, w/o Rear Object sensor	Bumper, Rear Assembly	GM1103159DSC	PBSI-DS	GM1103159	GM1103159
GMC Sierra 2500/3500HD, 11, w/Rear Object sensor, w/o Sensor components	Bumper, Rear Assembly	GM1103165DSC	PBSI-DS	GM1103165	GM1103165
GMC Sierra Hybrid, 09-13, w/o Rear Object Sensors	Bumper, Rear Assembly	GM1103147DSC	PBSI-DS	GM1103147	GM1103147
GMC Sierra Hybrid, 09-13, w/Rear Object Sensors, w/o Sensor components	Bumper, Rear Assembly	GM1103148DSC	PBSI-DS	GM1103148	GM1103148
GMC Sierra, 07-13, w/o Rear Object Sensors	Bumper, Rear Assembly	GM1103147DSC	PBSI-DS	GM1103147	GM1103147
GMC Sierra, 07-13, w/Rear Object Sensors	Bumper, Rear Assembly	GM1103149DSC	PBSI-DS	GM1103149	GM1103149
GMC Sierra, 07-13, w/Rear Object sensors, w/o Sensor components	Bumper, Rear Assembly	GM1103148DSC	PBSI-DS	GM1103148	GM1103148
Kia Optima, 14-15 (USA Built)	Bar, Impact	KAR8055A	Auto Power	866314C500	KI1106128
Kia Soul, 10-11	Absorber, Energy	KA0C124Q	Cobra King	865202K005	KI1070123
Nissan Altima Coupe, 10-13	Absorber, Impact	NS01185A	Auto Power	62090ZX10A	NI1070146
Toyota Camry Hybrid, 12-14, To 12-13	Bar, Reinforcement	TYR2517A	Auto Power	5213106101	TO1006226
Toyota Camry, 12-14, To 12-13	Bar, Reinforcement	TYR2517A	Auto Power	5213106101	TO1006226
Toyota Solara, 04-06	Absorber, Impact	TA4A124Q	Cobra King	52611AA060	TO1070145

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

DELETED PARTS CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					



WEEKLY PARTS UPDATE

October 24, 2016

[Report: P6]
Weekly

DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

*This report includes all new, decertified and deleted parts from October 17, 2016 through October 21, 2016.

All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org