

NEW PARTS CAPA 101 STANDARD - METALS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
BMW 2-Series F22 Coupe, 14-16	Panel, Upper Support	BMS6805A	Auto Power	51647245786	BM1225136
BMW 3-Series F30 Sedan, 12-16	Panel, Upper Support	BMS6805A	Auto Power	51647245786	BM1225136
BMW #-Series F31 Wagon, 14-16	Panel, Upper Support	BMS6805A	Auto Power	51647245786	BM1225136
BMW 4-Series F36 Gran Coupe, 15-16	Panel, Upper Support	BMS6805A	Auto Power	51647245786	BM1225136
Cadillac CTS Sedan, 14-16	Hood	CD49001Q	Cobra King	22788387	GM1230436
Chevrolet Silverado 1500, 07-13	Bracket, Center Bumper	CV9F104Q	Cobra King	25811768	GM1225316
Chevrolet Silverado 2500/3500, 07-14	Bracket, Center Bumper	CV9F104Q	Cobra King	25811768	GM1225316
Ford Pickup F150 (New Style), 04-08	Bracket, Support	FD1B007Q	Cobra King	5L3Z16864AA	FO1225175
Ford Pickup F150, 09	Bracket, Support	FD1B007Q	Cobra King	5L3Z16864AA	FO1225175
Ford Pickup F150, 10, 4.6L/5.4L Eng	Bracket, Support	FD1B007Q	Cobra King	5L3Z16864AA	FO1225175
Ford Pickup Mark LT, 06-08	Bracket, Support	FD1B007Q	Cobra King	5L3Z16864AA	FO1225175
GMC Sierra 1500, 07-13	Bracket, Center Bumper	CV9F104Q	Cobra King	25811768	GM1225316
GMC Sierra 2500/3500, 07-14	Bracket, Center Bumper	CV9F104Q	Cobra King	25811768	GM1225316
Subaru Legacy, 15-16	Brace, Cover	SB45004Q	Cobra King	57705AL02A	SU1041100
Subaru Outback, 15-16	Brace, Cover	SB45004Q	Cobra King	57705AL02A	SU1041100

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Chevrolet Avalanche, 07-13	Filler, Bumper L	CVT143AL	Auto Power	21996230	GM1088171
Chevrolet Cruze, 11-16	Cover, Lower	LT-CVB001A	Liantuoh	95212249	GM1228149
Chevrolet Equinox, 10-12	Support Assy, Front Cover	CV-07198CAQ	Tong Yang	20824645	GM1041121
Chevrolet Equinox, 10-12	Support Assy, Front Cover	CV-07198CAQ	Tong Yang	22802304	GM1041121
Chevrolet Equinox, 10-12	Support Assy, Front Cover	CV-07198CAQ	Tong Yang	25798731	GM1041121
Chevrolet Equinox, 10-15	Support Assy, Front Cover	CV-07198CAQ	Tong Yang	23106653	GM1041121
Chevrolet Equinox, 10-16	Support Assy, Front Cover	CV-07198CAQ	Tong Yang	23507949	GM1041121
Chevrolet Malibu, 14-15	Deflector, Front Air	CLM144NAQ	Pro Fortune	22995175	GM1218102
Chevrolet Suburban, 07-14	Filler, Bumper L	CVT143AL	Auto Power	21996230	GM1088171
Chevrolet Tahoe, 07-14	Filler, Bumper L	CVT143AL	Auto Power	21996230	GM1088171
Ford C-Max Energi, 13-14, w/o Front tow hook	Bumper Cover, Front	FD-04438BBQ	Tong Yang	DM5Z17D957APTM	FO1000689
Ford C-Max Hybrid, 13-14, w/o Front tow hook	Bumper Cover, Front	FD-04438BBQ	Tong Yang	DM5Z17D957APTM	FO1000689
Ford Fusion Hybrid, 13-16	Valance, Lower Bumper	FD-05110VAQ	Tong Yang	DS7Z17810AA	FO1195125
Ford Fusion, 13-16	Valance, Lower Bumper	FD-05110VAQ	Tong Yang	DS7Z17810AA	FO1195125
Ford Transit Connect Van, 14-15, to 8/18/14	Grille	FD-07402GAQ	Tong Yang	DT1Z8200B	FO1200558
Ford Transit Connect Wagon, 14-15, to 8/18/14	Grille	FD-07402GAQ	Tong Yang	DT1Z8200B	FO1200558
Ford Transit Connect, 14-15, Van, w/o Honeycomb Mesh	Grille	FD-07401GAQ	Tong Yang	DT1Z8200A	FO1200557
Ford Transit Connect, 14-15, Wagon, w/o Honeycomb Mesh	Grille	FD-07401GAQ	Tong Yang	DT1Z8200A	FO1200557
GMC 2500/3500 HD/Denali Sierra, 15	Plate, Skid	CV-04310MAQ	Tong Yang	23178964	GM1053103
GMC 2500/3500 SLT Sierra, 15	Plate, Skid	CV-04310MAQ	Tong Yang	23178964	GM1053103
GMC Terrain, 10-12	Support Assy, Front Cover	CV-07198CAQ	Tong Yang	20824645	GM1041121
GMC Terrain, 10-12	Support Assy, Front Cover	CV-07198CAQ	Tong Yang	22802304	GM1041121
GMC Terrain, 10-12	Support Assy, Front Cover	CV-07198CAQ	Tong Yang	25798731	GM1041121
GMC Terrain, 10-15	Support Assy, Front Cover	CV-07198CAQ	Tong Yang	23106653	GM1041121
GMC Terrain, 10-16	Support Assy, Front Cover	CV-07198CAQ	Tong Yang	23507949	GM1041121
GMC Terrain, 13-15	Support Assy, Front Cover	CV-07198CAQ	Tong Yang	23106653	GM1041121
GMC Terrain, 13-16	Support Assy, Front Cover	CV-07198CAQ	Tong Yang	23507949	GM1041121
GMC Yukon XL 1500, 07-14	Filler, Bumper L	CVT192AL	Auto Power	10376175	GM1088179
GMC Yukon XL 1500, 07-15	Filler, Bumper R	CVT192AR	Auto Power	10376176	GM1089179
GMC Yukon, 07-14	Filler, Bumper L	CVT192AL	Auto Power	10376175	GM1088179
GMC Yukon, 07-14	Filler, Bumper R	CVT192AR	Auto Power	10376176	GM1089179
Honda CR-V, 15	Bumper Cover, Rear Upper	HD6710870-300C	AP-Procom	04715T1WA91ZZ	HO1114103
Kia Sedona, 15-16	Bumper Cover, Rear Lower	KA-04110BBQ	Tong Yang	86612A9000	KI1115108
Mercedes-Benz CLA-Class, 14-16, w/o AMG Styling, w/o Active Park Assist	Bumper Cover, Front	MD1300000-500C	AP-Procom	117880004080	MB1000440
Mercedes-Benz CLA-Class, 14-16, w/o AMG Styling, w/o Active Park Assist	Bumper Cover, Front	MD1300000-500C	AP-Procom	11788000409999	MB1000440

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Mercedes-Benz CLA-Class, 14-16, w/o AMG Styling; w/Active Park Assist	Bumper Cover, Front	MD1300000-000C	AP-Procom	117880084080	MB1000441
Mercedes-Benz CLA-Class, 14-16, w/o AMG Styling; w/Active Park Assist	Bumper Cover, Front	MD1300000-000C	AP-Procom	11788008409999	MB1000441
Mercedes-Benz R-Class, 11-13 w/ H/Lamp Washers, w/Parktronic	Bumper Cover, Front Assy	BZB061NCQ	Pro Fortune	25188003479999	MB1000399
Toyota Highlander Hybrid, 14-16	Cover, Engine Under	TYE032NAQ	Pro Fortune	514410E091	TO1228187
Toyota Highlander, 11-13	Cover, Engine Under	TYE034NAQ	Pro Fortune	514410E060	TO1228183
Toyota Highlander, 14-16	Cover, Engine Under	TYE032NAQ	Pro Fortune	514410E091	TO1228187
Volkswagen Jetta Sedan, 15-16	Grille Assy, Front	VW-07146GAQ	Tong Yang	5C6853651AJZLL	VW1200165

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Cadillac ATS Sedan, 15-16	Lamp, Side Marker L	18-6168-00-9	TYC Brother	23169181	GM2550200
Cadillac ATS Sedan, 15-16	Lamp, Side Marker R	18-6167-00-9	TYC Brother	23169182	GM2551200
Cadillac CTS Sedan, 14-16	Lamp, Side Marker L	18-6168-00-9	TYC Brother	23169181	GM2550200
Cadillac CTS Sedan, 14-16	Lamp, Side Marker R	18-6167-00-9	TYC Brother	23169182	GM2551200
Chevrolet Camaro Convertible/Coupe, 16-17	Lamp, Side Marker L	18-6168-00-9	TYC Brother	23169181	GM2550200
Chevrolet Camaro Convertible/Coupe, 16-17	Lamp, Side Marker R	18-6167-00-9	TYC Brother	23169182	GM2551200
Chevrolet Cruze, 11-14	Taillamp L	11-6358-00-9	TYC Brother	96828250	GM2804107
Chevrolet Cruze, 11-14	Taillamp R	11-6357-00-9	TYC Brother	96828251	GM2805107
Chevrolet Cruze, 11-15	Taillamp L	11-6358-00-9	TYC Brother	95384046	GM2804107
Chevrolet Cruze, 11-16	Taillamp L	11-6358-00-9	TYC Brother	94540776	GM2804107
Chevrolet Cruze, 11-16	Taillamp R	11-6357-00-9	TYC Brother	95384047	GM2805107
Chrysler 300 Base/C/S/Luxury/SRT-8 Sedan, 13-14, Chrome	Taillamp R	333-1962R-ACN	DEPO	68154602AC	CH2819134
Chrysler 300 Base/C/S/Luxury/SRT-8 Sedan, 13-14, Chrome	Taillamp L	333-1962L-ACN	DEPO	68154603AC	CH2818134
Chrysler 300 Platinum, 12-14, From 3-19-12	Taillamp R	333-1962R3ACN	DEPO	68154606AC	CH2819135
Chrysler 300 Platinum, 12-14, From 3-19-12	Taillamp L	333-1962L3ACN	DEPO	68154607AC	CH2818135
Subaru Impreza, 06	Headlamp Assy, L	320-1117L-AC7	DEPO	84001FE690	SU2502131
Subaru Outback, 06	Headlamp Assy, L	320-1117L-AC7	DEPO	84001FE690	SU2502131

NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Lexus RX 350, 10-12	Absorber, Impact	LE08124Q	Cobra King	526110E020	LX1070118
Lexus RX 450h, 10-12	Absorber, Impact	LE08124Q	Cobra King	526110E020	LX1070118

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
TYS6488A	Toyota Sequoia, 08	Radiator Support	Auto Power	01/16A	532010C070	TO1225275
TYS6488A	Toyota Sequoia, 08-16	Radiator Support	Auto Power	01/16A	532010C071	TO1225275
TYS6488A	Toyota Tundra, 07-09	Radiator Support	Auto Power	01/16A	532010C070	TO1225275
TYS6488A	Toyota Tundra, 07-10	Radiator Support	Auto Power	01/16A	532010C071	TO1225275

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
HD04104BBQ	Honda Civic Hybrid, 03	Bumper Cover, Rear	TYG Products	150925	04715S5AA90ZZ	HO1100200
HD04104BBQ	Honda Civic Sedan, 01-03	Bumper Cover, Rear	TYG Products	150925	04715S5AA90ZZ	HO1100200

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

DELETED PARTS CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

*This report includes all new, decertified and deleted parts from October 31, 2016 through November 4, 2016.

All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org