

NEW PARTS CAPA 101 STANDARD - METALS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Audi A3 Cabrio, 15-16	Fender L	ADA315FL1	Gordon	8V5821105A	AU1240136
Audi A3 Cabrio, 15-16	Fender R	ADA315FR1	Gordon	8V5821106A	AU1241136
Audi A3 Sedan, 15-16	Fender L	ADA315FL1	Gordon	8V5821105A	AU1240136
Audi A3 Sedan, 15-16	Fender R	ADA315FR1	Gordon	8V5821106A	AU1241136
Audi S3 Sedan, 15-16	Fender L	ADA315FL1	Gordon	8V5821105A	AU1240136
Audi S3 Sedan, 15-16	Fender R	ADA315FR1	Gordon	8V5821106A	AU1241136
Scion xB, 08-15	Radiator Support Assy	TYS6628A	Auto Power	5320112905	SC1225104

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Chevrolet 1500 Silverado, 14-15	Insert, Front Bumper R	CV9N020RQ	Cobra King	22944875	GM2603102
Chevrolet 1500 Silverado, 14-15	Insert, Front Bumper L	CV9N020LQ	Cobra King	22944876	GM2602102
Chevrolet Camaro Convertible, 14-15, w/Object Sensor	Bumper Cover, Rear	CVCAM14RB2	Gordon	23164145	GM1114107
Chevrolet Camaro Coupe, 14-15, w/Object Sensor	Bumper Cover, Rear	CVCAM14RB2	Gordon	23164145	GM1114107
Chevrolet Camaro LS/LT Coupe, 10-13	Moulding, Bumper Rear	CVCAM10RB1	Gordon	92218168	GM1195122
Chevrolet Camaro LT Convertible, 11	Moulding, Bumper Rear	CVCAM10RB1	Gordon	92218168	GM1195122
Chevrolet Camaro LT Convertible, 12-13, w/o Tow hook	Moulding, Bumper Rear	CVCAM10RB1	Gordon	92218168	GM1195122
Chevrolet Camaro LT Covertible, 12-13, w/Tow hook, w/o Rear camera	Moulding, Bumper Rear	CVCAM10RB1	Gordon	92218168	GM1195122
Chevrolet Camaro SS, 10-13	Moulding, Bumper Rear	CVCMO10RV1	Gordon	92218169	GM1195123
Chevrolet Impala LTZ, 14-15, w/Blind spot sensor	Bumper Cover, Rear	CV-04264BBQ	Tong Yang	23119743	GM1100919
Chevrolet Impala, 14, w/Blind spot sensor	Bumper Cover, Rear	CV-04264BBQ	Tong Yang	22934642	GM1100919
Chrysler 200 Sedan, 15-16, w/o Exhaust opening no. 1	Cover, Lower	CR-05003VAQ	Tong Yang	68103925AC	CH1195121
Chrysler 200 Sedan, 15-16, w/o Exhaust Opening, w/o Parallel Park Assist, w/o Parking Sensors	Bumper Cover, Rear	CR-04069BFQ	Tong Yang	1UW74TZZAD	CH1100990
Ford Fusion Energi, 13-16	Reinf, Front Panel	FD-03043AQ	Tong Yang	DS7Z8A284A	FO1227103
Ford Fusion Hybrid, 13-16	Reinf, Front Panel	FD-03043AQ	Tong Yang	DS7Z8A284A	FO1227103
Ford Fusion, 13-16	Reinf, Front Panel	FD-03043AQ	Tong Yang	DS7Z8A284A	FO1227103
Honda Civic Sedan, 16	Garnish, Rear Bumper	HD-05030VAQ	Tong Yang	71502TBAA00	HO1195110
Hyundai Sonata, 15-16, Standard-Non sport	Bumper Cover, Front	Y-HYPB027CA	Y.C.C.	86511C2000	HY1000205
Kia Forte 5, 14-15	Radiator Support	KAS6880A	Auto Power	64101A7001	KI1225161
Kia Forte Koup, 14-15	Radiator Support	KAS6880A	Auto Power	64101A7001	KI1225161
Kia Forte Sedan, 14-15	Radiator Support	KAS6880A	Auto Power	64101A7001	KI1225161
Lexus IS 250, 06-08	Cover, Grille	LSN007NAQ	Pro Fortune	5311253010	LX1202100
Lexus IS 350, 06-08	Cover, Grille	LSN007NAQ	Pro Fortune	5311253010	LX1202100
Lincoln MKZ Hybrid, 13-16	Reinf, Front Panel	FD-03043AQ	Tong Yang	DS7Z8A284A	FO1227103
Lincoln MKZ, 13-16	Reinf, Front Panel	FD-03043AQ	Tong Yang	DS7Z8A284A	FO1227103
Mercedes-Benz GL-Class, 13-16, w/o AMG Styling	Trim, Bumper	BZ-04178MAQ	Tong Yang	1668852825	MB1044128
Toyota Yaris Hatchback, 15-17	Guard, Rear Bumper	TY-05083VAQ	Tong Yang	524530D040	TO1195102

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Chevrolet Equinox LS/LT, 10-12	Headlamp Assy, L	20-9096-00-9	TYC Brother	20997472	GM2502338
Chevrolet Equinox LS/LT, 10-12	Headlamp Assy, R	20-9095-00-9	TYC Brother	20997473	GM2503338
Chevrolet Equinox LS/LT, 10-15	Headlamp Assy, L	20-9096-00-9	TYC Brother	22915376	GM2502338
Chevrolet Equinox LS/LT, 10-15	Headlamp Assy, R	20-9095-00-9	TYC Brother	22915377	GM2503338
Chevrolet Equinox LS/LT, 10-15	Headlamp Assy, L	20-9096-00-9	TYC Brother	23308253	GM2502338
Chevrolet Equinox LS/LT, 10-15	Headlamp Assy, R	20-9095-00-9	TYC Brother	23308254	GM2503338
Chrysler 200 Convertible LX/Limited/Touring, 11-14	Headlamp Assy, R	20-9197-00-9	TYC Brother	5182590AC	CH2519140
Chrysler 200 Convertible LX/Limited/Touring, 11-14	Headlamp Assy, L	20-9198-00-9	TYC Brother	5182591AC	CH2518140
Chrysler 200 LX/Limited/Touring Sedan, 11-14	Headlamp Assy, R	20-9197-00-9	TYC Brother	5182590AC	CH2519140
Chrysler 200 Sedan LX/Limited/Touring, 11-14	Headlamp Assy, L	20-9198-00-9	TYC Brother	5182591AC	CH2518140
Dodge Dart, 13-15, Halogen, Chrome	Headlamp, R	334-1136R-AC1	DEPO	68081388AK	CH2519143
Dodge Dart, 13-15, Halogen, Chrome	Headlamp, R	334-1136R-AC1	DEPO	68081388AL	CH2519143
Dodge Dart, 13-15, Halogen, Chrome	Headlamp, L	334-1136L-AC1	DEPO	68081389AK	CH2518143
Dodge Dart, 13-15, Halogen, Chrome	Headlamp, L	334-1136L-AC1	DEPO	68081389AL	CH2518143
Ford Taurus, 13-14, to 2-6-14, Halogen	Headlamp Assy, L	K30-1154L-AC	DEPO	DG1Z13008C	FO2502310
Ford Taurus, 13-14, to 2/6/14, Halogen	Headlamp Assy, R	K30-1154R-AC	DEPO	DG1Z13008A	FO2503336

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Kia Sorento, 16	Taillamp L	11-6780-00-9	TYC Brother	92401C6000	KI2804119
Kia Sorento, 16	Taillamp R	11-6779-00-9	TYC Brother	92402C6000	KI2805119
Lexus ES 350, 10-12	Lamp, Fog R	19-5983-01-9	TYC Brother	8121133220	LX2595105
Lexus ES 350, 10-12	Lamp, Fog L	19-5984-01-9	TYC Brother	8122133220	LX259105
Subaru Impreza Sedan/Wagon, 15-16	Headlamp Assy, R	20-9303-90-9	TYC Brother	84001FJ320	SU2503155
Subaru Impreza Sedan/Wagon, 15-16	Headlamp Assy, L	20-9304-90-9	TYC Brother	84001FJ330	SU2502155

NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Cadillac ATS-V, 16-17	Absorber, Impact	CD01206A	Auto Power	23288932	GM1070297
Chevrolet Impala, 14-16	Reinforcement, Bumper Front	GM1006678DSC	PBSI-DS	23124168	GM1106678
Chevrolet Malibu Hybrid, 13-14	Reinforcement, Bumper Rear	GM1106690DSC	PBSI-DS	22835198	GM1106690
Chevrolet Malibu Limited, 16	Reinforcement, Bumper Rear	GM1106690DSC	PBSI-DS	22835198	GM1106690
Chevrolet Malibu, 13-15	Reinforcement, Bumper Rear	GM1106690DSC	PBSI-DS	22835198	GM1106690
Chevrolet Silverado 1500, 16	Bracket, Front Bumper L	CVT211AL	Auto Power	84029810	GM1062114
Chevrolet Silverado 1500, 16	Bracket, Front Bumper R	CVT211AR	Auto Power	84029811	GM1063114
Chevrolet Silverado 1500, 16, w/o Fog lamps	Bracket, Bumper L	CVT212AL	Auto Power	84029797	GM1062115
Chevrolet Silverado 1500, 16, w/o Fog lamps	Bracket, Bumper R	CVT212AR	Auto Power	84029798	GM1063115
Dodge Charger, 15-16	Bar, Reinforcement	CH1106222DSC	PBSI-DS	68209675AA	CH1106222
Hyundai Sonata, 15	Bar, Reinforcement	HNR8057A	Auto Power	86631C2100	HY1106155

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
HN2720000-000C	Hyundai Elantra Sedan, 11-13 (USA)	Bumper Cover, Front	AP-Procom	07/16A	865113Y000	HY1000185
TY8040870-100C	Toyota RAV-4, 13-15, w/o Parking sensors	Bumper Cover, Rear	AP-Procom	10/16A	521500R110	TO1100306
TY8040870-100C	Toyota RAV-4, 13-15, w/o Parking sensors	Bumper Cover, Rear	AP-Procom	11/16A	521500R110	TO1100306

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

DELETED PARTS CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
FD9300110-000C	Ford Bronco, 92-96	Deflector Stone	AP	F2TZ17779A	FO1087122
FD9300110-000C	Ford Pickup, 92-98	Deflector Stone	AP	F2TZ17779A	FO1087122



WEEKLY PARTS UPDATE

March 20, 2017

[Report: P6]
Weekly

DELETED PARTS CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

*This report includes all new, decertified and deleted parts from March 13, 2017 through March 17, 2017.

All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org