

NEW PARTS CAPA 101 STANDARD - METALS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Chevrolet Silverado 2500 HD, 11-14	Radiator Support	CVS6787A	Auto Power	22825905	GM1225299
GMC Sierra 2500 HD/3500 HD, 11-14	Radiator Support	CVS6787A	Auto Power	22825905	GM1225299
Hyundai Tucson, 16-17	Fender L	HY0K002LQ	Cobra King	66311D3000	HY1240165
Hyundai Tucson, 16-17	Fender R	HY0K002RQ	Cobra King	66321D3000	HY1241165
Kia Rio Sedan, 16, from 5/13/15	Radiator Support Assy	KA-03012CQ	Tong Yang	641011W003	KI1225179
Suzuki Grand Vitara, 06-13	Tie Bar, Upper Side R	SZS6497AR	Auto Power	5824165J01	SZ1225146
Suzuki Grand Vitara, 06-13	Tie Bar, Upper Side L	SZS6497AL	Auto Power	5824265J01	SZ1225145

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Acura RDX, 16-17	Grille	HD-07201GAQ	Tong Yang	71121TX4A51	AC1200128
Audi A3 Cabrio, 15-16, w/o Headlamp washer, w/o Parking aid	Bumper Cover, Front	AU0710000-100C	AP-Procom	8V5807065GRU	AU1000218
Audi A3 Cabrio, 15-16, w/o Headlamp washer, w/Parking aid, w/o Parallel park assist	Bumper Cover, Front	AU0710000-000C	AP-Procom	8V5807065BGRU	AU1000219
Audi A3 Sedan, 15-16, w/o Headlamp washer, w/o Parking aid	Bumper Cover, Front	AU0710000-100C	AP-Procom	8V5807065GRU	AU1000218
Audi A3 Sedan, 15-16, w/o Headlamp washer, w/Parking aid, w/o Parallel park assist	Bumper Cover, Front	AU0710000-000C	AP-Procom	8V5807065BGRU	AU1000219
Audi Q3, 15	Joint, Connector	AD-04057BBQ	Tong Yang	8U0807663GRU	AU1087103
Audi Q5, 09-17, w/o S-Line pkg	Bumper Cover, Rear	AD-04052BBQ	Tong Yang	8R0807303GRU	AU1100186
Audi Q5, 13-16, Hybrid	Bumper Cover, Rear	AD-04052BBQ	Tong Yang	8R0807303GRU	AU1100186
Chevrolet Camaro Convertible, 14-15, w/o Object Sensor	Bumper Cover, Rear	CVCAM14RB1	Gordon	23164146	GM1114106
Chevrolet Camaro Coupe, 14-15, w/o Object Sensor	Bumper Cover, Rear	CVCAM14RB1	Gordon	23164146	GM1114106
Chrysler Town & Country, 08-10	Dam, Air	DG05021VAQ	TYG Products	5113133AC	CH1090144
Chrysler Town & Country, 11-16	Dam, Air	DG05021VAQ	TYG Products	5113133AC	CH1090144
Dodge Challenger, 15-17, w/Fog Lamps	Bumper Cover, Front	DG3620000-000C	AP-Procom	68258730AB	CH1000A20
Dodge Charger R/T, R/T Road & Track, 15-16	Bumper Cover, Rear Lower	DGP100NAQ	Pro Fortune	68226556AA	CH1195116
Dodge Charger SE/SXT, 15-16	Bumper Cover, Rear Lower	DGP100NAQ	Pro Fortune	68226556AA	CH1195116
Dodge Grand Caravan, 08-10	Dam, Air	DG05021VAQ	TYG Products	5113133AC	CH1090144
Dodge Grand Caravan, 08-17	Dam, Air	DG05021VAQ	TYG Products	68320463AA	CH1090144
Dodge Grand Caravan, 11-16	Dam, Air	DG05021VAQ	TYG Products	5113133AC	CH1090144
Dodge Town & Country, 08-17	Dam, Air	DG05021VAQ	TYG Products	68320463AA	CH1090144
Honda Civic Sedan, 16, 1.5L eng	Grille, Bumper	HD-07218GAQ	Tong Yang	71102TBAA00	HO1036123
Honda CR-V, 02-04	Bumper Cover, Front	Y-HDBP138ACA	Y.C.C.	04711S9AA90	HO1000202
Honda HR-V, 16-17	Grille, Bumper Lower	HDN107NAQ	Pro Fortune	71103T7JH00	HO1036122
Hyundai Accent Hatchback, 15-16	Grille	HYG010NAQ	Pro Fortune	863511R510	HY1200184
Hyundai Accent Sedan, 15-16	Grille	HYG010NAQ	Pro Fortune	863511R510	HY1200184
Hyundai Santa Fe, 10-12	Cover, Lower	HN-05017VAQ	Tong Yang	865250W700	HY1095104
Hyundai Santa Fe, 13-16	Bumper Cover, Front	HN-04153BBQ	Tong Yang	86511B8000	HY1000199
Mercedes-Benz C-Class C300/C400, 15-17, w/AMG styling pkg, w/o Parktronic	Bumper Cover, Rear	BZB072NCQ	Pro Fortune	20588559389999	MB1100367
Mercedes-Benz C-Class C63, 15-17, w/o Parktronic	Bumper Cover, Rear	BZB072NCQ	Pro Fortune	20588559389999	MB1100367
Nissan Juke, 15-16, S, SL, SV Model, w/Around View Monitor	Grille, Assy	DS-07353GBQ	Tong Yang	620703YM1B	NI1200276
Subaru Impreza Sedan, 15-16	Grille	SBG007NAQ	Pro Fortune	91122FJ040	SU1200163
Subaru Impreza Wagon, 15-16	Grille	SBG007NAQ	Pro Fortune	91122FJ040	SU1200163
Subaru XV Crosstrak Hybrid, 15-16	Grille	SBG007NAQ	Pro Fortune	91122FJ040	SU1200163
Toyota RAV-4, 16, North American Built	Bumper Cover, Rear	TY-04558BBQ	Tong Yang	521590R914	TO1114102
Toyota Tacoma, 16-17	Spoiler, Lower	TY-05090VAQ	Tong Yang	5385104070	
Volkswagen Passat, 16, Single Exhaust	Valance, Lower Bumper	VW-05051VAQ	Tong Yang	561807521D9B9	VW1195113

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Dodge Dart, 13-15, Black trim	Headlamp, R	334-1136R-AC2	DEPO	68085140AK	CH2503240
Dodge Dart, 13-15, Black trim	Headlamp, R	334-1136R-AC2	DEPO	68085140AL	CH2503240
Dodge Dart, 13-15, Black trim	Headlamp, L	334-1136L-AC2	DEPO	68085141AK	CH2502240
Dodge Dart, 13-15, Black trim	Headlamp, L	334-1136L-AC2	DEPO	68085141AL	CH2502240
GMC Sierra, 14-15	Headlamp Assy, L	K35-1172L-AC	DEPO	23130717	GM2502394
GMC Sierra, 14-15	Headlamp Assy, R	K35-1172R-AC	DEPO	23130718	GM2503394
Hyundai Accent, 03-06	Headlamp Assy, L	20-6528-00-9	TYC Brother	9210125550	HY2502128
Hyundai Accent, 03-06	Headlamp Assy, R	20-6527-00-9	TYC Brother	9210225550	HY2503128

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application</u>	<u>Part</u>	<u>Manufacturer</u>	<u>OEM</u>	<u>PartsLink</u>
<u>Description</u>	<u>Description</u>	<u>Number</u>	<u>Number</u>	<u>Number</u>
Kia Rio Sedan, 12-16, Std lamp	Taillamp L	323-1942L-AC	DEPO 924011W000	KI2804109
Kia Rio Sedan, 12-16, Std lamp	Taillamp R	323-1942R-AC	DEPO 924021W000	KI2805109
Kia Rio5, 12-15	Reflector, Bumper L	323-4001L-UC	DEPO 924051W210	KI1184109
Kia Rio5, 12-15	Reflector, Bumper R	323-4001R-UC	DEPO 924061W200	KI1185109
Kia Sedona Limited/SXL, 15-16	Reflector, Bumper Rear R	323-2911R-UC	DEPO 92405A9250	KI1185108
Kia Sedona Limited/SXL, 15-16	Reflector, Bumper Rear L	323-2911L-UC	DEPO 92406A9250	KI1184108
Lexus ES 300, 02-03, w/HID	Headlamp Assy, R	312-1172R-UCH7	DEPO 8114533461	LX2503117
Lexus ES 300, 02-03, w/HID	Headlamp Assy, L	312-1172L-UCH7	DEPO 8118533461	LX2502117
Lexus ES 330, 04, w/HID	Headlamp Assy, R	312-1172R-UCH7	DEPO 8114533461	LX2503117
Lexus ES 330, 04, w/HID	Headlamp Assy, L	312-1172L-UCH7	DEPO 8118533461	LX2502117
Mazda Pickup, 01-10	Headlamp, R	316-1125R-AC	DEPO 1FAA51030	MA2503117
Mazda Pickup, 01-10	Headlamp, L	316-1125L-AC	DEPO 1FAA51040	MA2502117
Nissan Maxima, 16-17	Lamp, Back Up R	315-1311R-AC	DEPO 265404RA0A	NI2803105
Nissan Maxima, 16-17	Lamp, Back Up L	315-1311L-AC	DEPO 265454RA0A	NI2802105
Toyota Avalon, 05-07, on body	Taillamp R	312-1971R-AC	DEPO 81550AC090	TO2805100
Toyota Avalon, 05-07, on body	Taillamp L	312-1971L-AC	DEPO 81560AC090	TO2804100
Toyota Avalon, 08-09	Taillamp R	312-1971R-AC2	DEPO 8155007050	TO2805122
Toyota Avalon, 08-09	Taillamp L	312-1971L-AC2	DEPO 8156007050	TO2804122
Toyota Avalon, 10, on body	Taillamp R	312-1971R-AC	DEPO 81550AC090	TO2805100
Toyota Avalon, 10, on body	Taillamp L	312-1971L-AC	DEPO 81560AC090	TO2804100
Toyota Corolla CE/L/LE/LE Eco, 17	Taillamp R	312-19B8R-AC-PR	DEPO 8155002B00	TO2805130
Toyota Corolla CE/L/LE/LE Eco, 17	Taillamp L	312-19B8L-AC-PR	DEPO 8156002B00	TO2804130
Toyota Corolla SE/XLE/XSE, 17	Taillamp R	312-19B8R-AC-R	DEPO 8155002B10	TO2805131
Toyota Corolla SE/XLE/XSE, 17	Taillamp L	312-19B8L-AC-R	DEPO 8156002B10	TO2804131
Toyota Tacoma, 16-17	Headlamp Assy, R	20-9749-00-9	TYC Brother 8111004250	TO2503242
Toyota Tacoma, 16-17	Headlamp Assy, L	20-9750-00-9	TYC Brother 8115004250	TO2502242
Volkswagen Jetta, 15	Taillamp L	11-6784-00-9	TYC Brother 5C6945095F	VW2804112
Volkswagen Jetta, 15	Taillamp R	11-6783-00-9	TYC Brother 5C6945096F	VW2805112

NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application</u>	<u>Part</u>	<u>Manufacturer</u>	<u>OEM</u>	<u>PartsLink</u>
<u>Description</u>	<u>Description</u>	<u>Number</u>	<u>Number</u>	<u>Number</u>
Buick LaCrosse, 14-16	Reinf., Bumper Rear	GM1106692DSC	PBSI-DS 23164201	GM1106692
Cadillac XTS, 13-17	Reinf., Bumper Rear	GM1106692DSC	PBSI-DS 23164201	GM1106692
Chevrolet Impala, 14-17	Reinf., Bumper Rear	GM1106692DSC	PBSI-DS 23164201	GM1106692
Chrysler 300 Sedan, 15-17, w/o SRT-8 model	Bar, Reinforcement	CH1106221DSC	PBSI-DS 68207359AB	CH1106221
Dodge Challenger, 15-16	Bar, Reinforcement	CH1106221DSC	PBSI-DS 68207359AB	CH1106221
Ford Fusion Hybrid, 10-12	Bar, Impact	FDR3341A	Auto Power AE5Z17757A	FO1006256
Ford Fusion S/SE/SEL/Sport, 10-12	Bar, Impact	FDR3341A	Auto Power AE5Z17757A	FO1006256
Lexus ES 300h, 13-16	Absorber, Impact	LE18613Q	Cobra King 5261506170	LX1170103
Lexus ES 350, 13-16	Absorber, Impact	LE18613Q	Cobra King 5261506170	LX1170103
Lincoln MKZ Hybrid, 11-12	Bar, Impact	FDR3341A	Auto Power AE5Z17757A	FO1006256
Lincoln MKZ, 10-12	Bar, Impact	FDR3341A	Auto Power AE5Z17757A	FO1006256
Mercury Milan Hybrid, 10-11	Bar, Impact	FDR3341A	Auto Power AE5Z17757A	FO1006256
Mercury Milan, 10-11	Bar, Impact	FDR3341A	Auto Power AE5Z17757A	FO1006256
Nissan Sentra SR, 10-12, 2.0L Eng	Absorber, Energy	NS01197A	Auto Power 62090ET80B	NI1070144
Nissan Sentra, 07-12, 2.5L Eng	Absorber, Energy	NS01197A	Auto Power 62090ET80B	NI1070144
Nissan Sentra, 10-12	Absorber, Impact	NS28613Q	Cobra King 85090ZE80B	NI1170138
Toyota Tundra, 07-09, w/Rear sensors	Bumper, Rear Assembly	TO1103116DSC	PBSI-DS TO1103116	TO1103116
Toyota Tundra, 07-10, w/o Parking aids, w/o Rock Warrior pkg, Chrome	Bumper, Rear Assembly	TO1103117DSC	PBSI-DS TO1103117	TO1103117

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

<u>Manufacturer</u>	<u>Application</u>	<u>Part</u>	<u>OEM</u>	<u>PartsLink</u>
<u>Number</u>	<u>Description</u>	<u>Description</u>	<u>Number</u>	<u>Number</u>
HNS6662-1A	Hyundai Sonata, 11-14	Radiator Support	Auto Power 08/16A 641013Q200	HY1225164

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
BKB029NBQ	Buick Regal eASSIST, 12-13	Bumper Cover, Front	Pro Fortune	09/16A	13243355	GM1000923
BKB029NBQ	Buick Regal, 11-13	Bumper Cover, Front	Pro Fortune	09/16A	13243355	GM1000923
STB012NCQ	Chevrolet Captiva Sport LT/LTZ, 13-15	Bumper Cover, Rear	Pro Fortune	08/16A	19167514	GM1100807
STB012NCQ	Chevrolet Captiva Sport LT/LTZ, 13-15	Bumper Cover, Rear	Pro Fortune	08/16A	22949863	GM1100807
DT6620000-000C	Nissan Rogue, 14-15	Bumper Cover, Front	AP-Procom	08/16A	620224BA0H	NI1000293
STB012NCQ	Saturn Vue Hybrid, , 08-09, 2.4L eng	Bumper Cover, Rear	Pro Fortune	08/16A	19167514	GM1100807
STB012NCQ	Saturn Vue Hybrid, 08-10, 2.4L eng	Bumper Cover, Rear	Pro Fortune	08/16A	22949863	GM1100807
STB012NCQ	Saturn Vue XR, 08-09	Bumper Cover, Rear	Pro Fortune	08/16A	19167514	GM1100807
STB012NCQ	Saturn Vue XR, 08-10	Bumper Cover, Rear	Pro Fortune	08/16A	22949863	GM1100807
TY6030870-000C	Toyota Highlander Hybrid, 14-16, w/Rear Object Sensors	Bumper Cover, Rear Upper	AP-Procom	05/16A	521590E912	TO1114101
TY6030870-000C	Toyota Highlander, 14-16, w/Rear Object Sensors	Bumper Cover, Rear Upper	AP-Procom	05/16A	521590E912	TO1114101
TY-07539GAQ	Toyota Venza, 13-16	Grille	Tong Yang	03/16A	531010T020	TO1200359

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

DELETED PARTS CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

*This report includes all new, decertified and deleted parts from March 20, 2017 through March 24, 2017.

All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org