

**NEW PARTS CAPA 101 STANDARD - METALS**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Mercedes-Benz GLC-Coupe 253, 17	Crossmember, Front Strut	BZS60081A	Auto Power	2536201000	MB1225188
Mercedes-Benz GLC-SUV 253, 16-17	Crossmember, Front Strut	BZS60081A	Auto Power	2536201000	MB1225188
Toyota Tacoma, 16-17, w/Hood Scoop	Hood	TY-20248BQ	Tong Yang	5330104230	TO1230240
Toyota Tacoma, 16-17, w/o Hood Scoop	Hood	TY-20248AQ	Tong Yang	5330104220	TO1230239

**NEW PARTS CAPA 201 STANDARD - PLASTICS**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
BMW 7-Series F04/F02 Hybrid, 11-12, w/o M Pkg, w/o Park Distance Control	Bumper Cover, Rear	BMB024NCQ	Pro Fortune	51127209924	BM1100328
BMW 7-Series F04/F02 Hybrid, 11-12, w/o M Pkg, w/Park Distance Control	Bumper Cover, Rear	BMB024NDQ	Pro Fortune	51127209926	BM1100198
BMW 7-Series, 09-12, w/o M Sport	Bumper Cover, Rear	BMB024NDQ	Pro Fortune	51127209926	BM1100198
BMW X3 F25, 15-17, w/o M Pkg, w/Active Cruise Control	Grille, Lower	BM33-9777	Tran Hung	51117347971	BM1036164
BMW X3 F25, 15-17, w/o M Pkg, w/o Active Cruise Control	Grille, Lower	BM33-9776	Tran Hung	51117338476	BM1036163
BMW X5 F15, 14-16, w/HL washer, w/Night vision, w/o Park assist, w/o Surround view	Bumper Cover, Front	BM-04136BXQ	Tong Yang	51117378601	BM1000397
BMW X5 F15, 14-16, w/HL washer, w/Night vision, w/o Park assist, w/ Surround view	Bumper Cover, Front	BM-04136BWQ	Tong Yang	51117378559	BM1000399
BMW X5 F15, 14-16, w/HL washer, w/Night vision, w/Park assist, w/o Surround view	Bumper Cover, Front	BM-04136BVQ	Tong Yang	51117379416	BM1000401
BMW X5 F15, 14-16, w/HL washer, w/o Night vision, w/o Park assist, w/o Surround view	Bumper Cover, Front	BM-04136BACQ	Tong Yang	51117378600	BM1000333
BMW X5 F15, 14-16, w/HL washer, w/o Night vision, w/o Park assist, w/ Surround view	Bumper Cover, Front	BM-04136BABQ	Tong Yang	51117378558	BM1000405
BMW X5 F15, 14-16, w/HL washer, w/o Night vision, w/Park assist, w/o Surround view	Bumper Cover, Front	BM-04136BAAQ	Tong Yang	51117379415	BM1000400
BMW X5 F15, 14-16, w/HL washer, w/o Night vision, w/Park assist, w/ Surround view	Bumper Cover, Front	BM-04136BYQ	Tong Yang	51117378554	BM1000402
BMW X5 F15, 14-16, w/o HL washer, w/Night vision	Bumper Cover, Front	BM-04136BFQ	Tong Yang	51117378617	BM1000396
BMW X5 F15, 14-16, w/o HL washer, w/o Night vision, w/Park assist, w/o Surround view	Bumper Cover, Front	BM-04136BADQ	Tong Yang	51117378613	BM1000394
BMW X5 F15, 14-16, w/o HL washer, w/o Night vision, w/o Park assist, w/ Surround view	Bumper Cover, Front	BM-04136BAEQ	Tong Yang	51117379609	BM1000393
BMW X5 F15, 14-17, w/o HL washer, w/o Night vision, w/o Park assist, w/ Surround view	Bumper Cover, Front	BM-04136BAEQ	Tong Yang	51117378609	BM1000393
Chevrolet Volt, 11-15, w/o Rear view camera	Bumper Cover, Rear	CLB074NCQ	Pro Fortune	23174782	GM1100884
Chevrolet Volt, 11-15, w/Rear view camera	Bumper Cover, Rear	CLB074NDQ	Pro Fortune	23174756	GM1100883
Chrysler 200 Sedan, 15-16, w/o Exhaust Opening, w/o Parallel Park Assist, w/o Parking Sensors	Bumper Cover, Rear	CR4730870-200C	AP-Procom	1UW74TZZAD	CH1100990
Chrysler 200 Sedan, 15-16, w/o Exhaust opening, w/o Park assist w/Parking sensors	Bumper Cover, Rear	CR4730870-100C	AP-Procom	1UW73TZZAD	CH1100991
Chrysler 200, Sedan, 15-16, w/o Exhaust Opening w/Park Assist System	Bumper Cover, Rear	CR4730870-000C	AP-Procom	5NH88TZZAD	CH1100992
Kia Optima, 14-15, USA built	Bumper Cover, Front	KA3520000-200C	AP-Procom	865114C500	KI1000168
Lincoln MKZ Hybrid, 13-15, w/o Rear object sensors	Bumper Cover, Rear	FMCMKZ-R13NEW	Micro Rim	DP5Z17K835CBPTM	FO1100698
Lincoln MKZ, 13-15, w/o Rear object sensors	Bumper Cover, Rear	FMCMKZ-R13NEW	Micro Rim	DP5Z17K835CBPTM	FO1100698
Toyota RAV-4, 16-17, North America built, w/o Parking sensors	Bumper Cover, Front	Y-TYBP321ACA	Y.C.C.	521190R914	TO1014105
Toyota RAV-4, 16-17, North America built, w/Parking sensors	Bumper Cover, Front	Y-TYBP321CA	Y.C.C.	521190R915	TO1014106
Toyota Tundra, 07-13, w/o parking assist	Bumper Cover, Rear	TY04469BBQ	TYG Products	521590C903	TO1100256
Toyota Tundra, 07-13, w/parking assist	Bumper Cover, Rear	TY04469BDQ	TYG Products	521590C904	TO1100257

**NEW PARTS CAPA 301 STANDARD - LIGHTING**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Kia Optima, 13-15, LED Type, from 10/3/13	Taillamp L	323-1311L-AC	DEPO	924032T620	KI2802105
Kia Optima, 13-15, LED Type, From 10/3/13	Taillamp R	323-1311R-AC	DEPO	924042T620	KI2803105
Mazda 3 Hatchback, 14-17, Japan Built, on liftgate, LED	Taillamp R	316-1308R-AC	DEPO	B45D513F0C	MA2803113
Mazda 3 Hatchback, 14-17, Japan Built, on liftgate, LED	Taillamp R	316-1308R-AC	DEPO	B45D513F0D	MA2803113
Mazda 3 Hatchback, 14-17, Japan Built, on liftgate, LED	Taillamp L	316-1308L-AC	DEPO	B45D513G0C	MA2802113
Nissan Altima, 16-17	Taillamp R	11-6887-00-9	TYC Brother	265509HS0A	NI2805106
Nissan Altima, 16-17	Taillamp L	11-6888-00-9	TYC Brother	265559HS0A	NI2804106
Nissan Juke, 15-16	Headlamp Assy, R	20-9697-00-9	TYC Brother	260103YM2A	NI2503236
Nissan Juke, 15-16	Headlamp Assy, L	20-9698-00-9	TYC Brother	260603YM2A	NI2502236
Nissan Sentra, 16-17, on body	Taillamp R	315-1990R-AC	DEPO	265503YU0A	NI2805108

**NEW PARTS CAPA 301 STANDARD - LIGHTING**

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Nissan Sentra, 16-17, on body	Taillamp L	315-1990L-AC	DEPO	265553YU0A	NI2804108
Toyota Prius c, 15-16	Lamp, Signal R	312-1657R-UC	DEPO	8151152070	TO2533120
Toyota Prius c, 15-16	Lamp, Signal L	312-1657L-UC	DEPO	8152152070	TO2532120
Toyota Tacoma, 16-17, Halogen, w/LED DRL, Black bezel	Headlamp Assy, R	312-11AER-ACN2	DEPO	8111004270	TO2503244
Toyota Tacoma, 16-17, Halogen, w/LED DRL, Black bezel	Headlamp Assy, L	312-11AEL-ACN2	DEPO	8115004270	TO2502244
Volkswagen Jetta, 15-17	Lamp, Fog L	19-6124-00-9	TYC Brother	5C7941699P	VW2592126
Volkswagen Jetta, 15-17	Lamp, Fog R	19-6123-00-9	TYC Brother	5C7941700P	VW2593126

**NEW PARTS CAPA 501 STANDARD - BUMPERS**

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Chrysler 300 Sedan, 15-17, w/o SRT-8 model	Bar, Reinforcement	CRR3457A	Auto Power	68207359AB	CH1106221
Dodge Challenger, 15-16	Bar, Reinforcement	CRR3457A	Auto Power	68207359AB	CH1106221
Dodge Charger, 15-16	Bar, Reinforcement	DGR3452A	Auto Power	68209675AA	CH1106222
Lexus RX 350, 16-17	Absorber, Impact	LX01200A	Auto Power	526110E110	LX1070153
Lexus RX 350, 16-17, Canada built	Absorber, Impact	LX01200A	Auto Power	526110E110	LX1070153
Lexus RX 450h, 16-17	Absorber, Impact	LX01200A	Auto Power	526110E110	LX1070153
Mazda CX-3, 16-17	Absorber, Impact	MZ01215A	Auto Power	DB4F50111A	MA1070115

**DECERTIFICATIONS**

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

**CAPA 101 STANDARD - METALS**

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
TYS6612A	Toyota Venza, 09-11	Radiator Support	Auto Power	06/15A	532100T010	TO1225293
TYS6612A	Toyota Venza, 09-11	Radiator Support	Auto Power	06/15A	532100T011	TO1225293
TYS6612A	Toyota Venza, 09-16	Radiator Support	Auto Power	06/15A	532100T012	TO1225293

**CAPA 201 STANDARD - PLASTICS**

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Y-HDBP141CA	Honda Accord Hybrid, 05	Bumper Cover, Rear	Y.C.C.	09/16B	04715SDAA90ZZ	HO1100208
Y-HDBP141CA	Honda Accord Sedan, 03-05	Bumper Cover, Rear	Y.C.C.	09/16B	04715SDAA90ZZ	HO1100208
Y-HDBP162HCA	Honda Accord Sedan, 08-09, (6 cyl)	Bumper Cover, Rear	Y.C.C.	11/16A	04715TA1A90ZZ	HO1100245
Y-HDBP162HCA	Honda Accord Sedan, 08-12 (6 cyl)	Bumper Cover, Rear	Y.C.C.	11/16A	04715TA1A91ZZ	HO1100245
HD6710130-100C	Honda CR-V, 15-16	Cover, Lower	AP-Procom	11/16A	04712T1WA91	HO1015111
LX2110870-100C	Lexus IS 200t, 14-16, w/o Park distance sensors	Bumper Cover, Rear	AP-Procom	03/16A	5215953940	LX1100168
LX2110870-100C	Lexus IS 250 Sedan, 14-16, w/o Park Distance Sensors	Bumper Cover, Rear	AP-Procom	03/16A	5215953940	LX1100168
LX2110870-100C	Lexus IS 300, 14-16, w/o Park distance sensors	Bumper Cover, Rear	AP-Procom	03/16A	5215953940	LX1100168
LX2110870-100C	Lexus IS 350, 14-16, w/o Park distance sensors	Bumper Cover, Rear	AP-Procom	03/16A	5215953940	LX1100168

**CAPA 301 STANDARD - LIGHTING**

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
NONE						

**CAPA 501 STANDARD - BUMPERS**

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
NONE						

**DELETED PARTS CAPA 101 STANDARD - METALS**

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
NONE					



# WEEKLY PARTS UPDATE

## June 5, 2017

[Report: P6]  
Weekly

### DELETED PARTS CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

### DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

### DELETED PARTS CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

\*This report includes all new, decertified and deleted parts from May 29, 2017 through June 2, 2017.

All CAPA reports including the weekly update are available on the CAPA website at [www.capacertified.org](http://www.capacertified.org).

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at [debbie@capacertified.org](mailto:debbie@capacertified.org)