

**NEW PARTS CAPA 101 STANDARD - METALS**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Jeep Wrangler, 07-13, w/o Power bulge, 1 Nozzle	Hood	AM-20018AQ	Tong Yang	68002350AB	CH1230256
Jeep Wrangler, 07-16	Hood	AM-20018AQ	Tong Yang	68170741AB	CH1230304

**NEW PARTS CAPA 201 STANDARD - PLASTICS**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Honda Accord Coupe, 16-17, w/Parking Sensors	Bumper Cover, Front	HD-04321BDQ	Tong Yang	71100T3LA60ZZ	HO1000305
Honda Accord Sedan, 16-17	Garnish, Front Bumper	HD-07211MAQ	Tong Yang	71151T2FA51	HO1044106
Honda Pilot, 16	Bumper Cover, Rear	Y-HDBP203CA	Y.C.C.	04715TG7A90ZZ	HO1114104
Jeep Cherokee, 14-17, w/Advanced park assist, w/Trailer hitch	Bumper Cover, Rear	JP7720870-000C	AP-Procom	68232317AB	CH1100988
Jeep Cherokee, 14-17, w/Advanced park assist, w/Trailer hitch	Bumper Cover, Rear	JP7720870-000C	AP-Procom	68232317AD	CH1100988
Jeep Cherokee, 14-17, w/o Advanced park assist, w/o Parking sensor, w/o Trailer hitch	Bumper Cover, Rear	JP7720870-100C	AP-Procom	68203261AD	CH1100987
Jeep Renegade, 15	Bumper Cover, Rear Upper, R	DGS104RBQ	Pro Fortune	5VW86TZZAA	CH1117103
Jeep Renegade, 15	Bumper Cover, Rear Upper, L	DGS104LBQ	Pro Fortune	5VW88TZZAA	CH1116103
Kia Optima, 14-15, w/o Park assist system, USA built	Bumper Cover, Rear	KA3520870-300C	AP-Procom	866114C500	KI1100180
Kia Sportage, 11, 2.4L Eng, w/Parking sensor, To 2-11-11	Bumper Cover, Rear	KA-04058BBQ	Tong Yang	866123W010	KI1100158
Lexus ES 300h, 13-15, w/HID H/Lamps	Seal, Upper	LXES3513FG1	Gordon	5329533090	LX1224102
Lexus ES 350, 13-15, w/HID H/Lamps	Seal, Upper	LXES3513FG1	Gordon	5329533090	LX1224102
Lexus GS 300, 08-11, w/o Parking assist	Bumper Cover, Rear	LX20-8528-OSH	Tran Hung	5215930942	LX1100135
Lexus GS 300, 08-11, w/Parking assist	Bumper Cover, Rear	LX20-8528-WSH	Tran Hung	5215930943	LX1100136
Lexus GS 350, 08-11, w/o Parking assist	Bumper Cover, Rear	LX20-8528-OSH	Tran Hung	5215930942	LX1100135
Lexus GS 350, 08-11, w/Parking assist	Bumper Cover, Rear	LX20-8528-WSH	Tran Hung	5215930943	LX1100136
Lexus GS 430, 08-11, w/o Parking assist	Bumper Cover, Rear	LX20-8528-OSH	Tran Hung	5215930942	LX1100135
Lexus GS 430, 08-11, w/Parking assist	Bumper Cover, Rear	LX20-8528-WSH	Tran Hung	5215930943	LX1100136
Lexus GS 450h, 08-11, w/o Parking assist	Bumper Cover, Rear	LX20-8528-OSH	Tran Hung	5215930942	LX1100135
Lexus GS 450h, 08-11, w/Parking assist	Bumper Cover, Rear	LX20-8528-WSH	Tran Hung	5215930943	LX1100136
Lexus GS 460, 08-11, w/o Parking assist	Bumper Cover, Rear	LX20-8528-OSH	Tran Hung	5215930942	LX1100135
Lexus GS 460, 08-11, w/Parking assist	Bumper Cover, Rear	LX20-8528-WSH	Tran Hung	5215930943	LX1100136
Lexus IS 250, 14-16, w/o Headlamp washer w/o Park distance sensors	Bumper Cover, Front	LX2110000-300C	AP-Procom	521195E904	LX1000262
Lexus IS 350, 14-16, w/o Headlamp washer w/o Park distance sensors	Bumper Cover, Front	LX2110000-300C	AP-Procom	521195E904	LX1000262
Lincoln MKZ Hybrid, 13-15, w/Rear object sensors, w/o Active park assist	Bumper Cover, Rear	FMCMKZ-R13SNEW	Micro Rim	EP5Z17K835APTM	FO1100699
Lincoln MKZ, 13-15, w/Rear object sensors, w/o Active park assist	Bumper Cover, Rear	FMCMKZ-R13SNEW	Micro Rim	EP5Z17K835APTM	FO1100699
Mini Cooper Hardtop 4 Door F55, 15-17, w/o Park Distance Control, w/o John Cooper Works pkg	Bumper Cover, Rear	AT-04041BCQ	Tong Yang	51127380023	MC1100162
Mini Cooper Hardtop 4 Door F55, 15-17, w/Park Distance Control, w/o John Cooper Works pkg	Bumper Cover, Rear	AT-04041BDQ	Tong Yang	51127380024	MC1100163
Toyota RAV-4, 16-17, Non painted, North America built	Guard, Rear Bumper	TYP152NAQ	Pro Fortune	524530R010	TO1195107
Toyota RAV-4, 16-17, North America built, w/o Parking sensors	Bumper Cover, Front	TYB151NCQ	Pro Fortune	521190R914	TO1014105
Toyota RAV-4, 16-17, North America built, w/Parking sensors	Bumper Cover, Front	TYB151NDQ	Pro Fortune	521190R915	TO1014106
Toyota RAV-4, 16-17, North American Built	Bumper Cover, Rear	TYB152NBQ	Pro Fortune	521590R914	TO1114102
Toyota Tacoma, 16-17	Liner, Fender R	TYT2014HR-C	Great Bestcam	5387504080	TO1249205
Toyota Tacoma, 16-17	Liner, Fender L	TYT2014HL-C	Great Bestcam	5387604080	TO1248205

**NEW PARTS CAPA 301 STANDARD - LIGHTING**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Chevrolet Suburban, 15	Taillamp L	K35-1972L-AC	DEPO	22783101	GM2800264
Chevrolet Suburban, 15	Taillamp L	K35-1972L-AC	DEPO	23476137	GM2800264
Chevrolet Suburban, 15-16	Taillamp L	K35-1972L-AC	DEPO	23407432	GM2800264
Chevrolet Tahoe, 15	Taillamp L	K35-1972L-AC	DEPO	22783101	GM2800264
Chevrolet Tahoe, 15	Taillamp L	K35-1972L-AC	DEPO	23476137	GM2800264
Chevrolet Tahoe, 15-16	Taillamp L	K35-1972L-AC	DEPO	23407432	GM2800264
Chrysler 200, 15	Taillamp L	A33-1308L-AC	DEPO	68110363AA	CH2803107
Chrysler 200, 15	Taillamp R	A33-1308R-AC	DEPO	68110364AA	CH2802107
Chrysler 200, 15-16	Taillamp L	A33-1308L-AC	DEPO	68110363AC	CH2803107
Chrysler 200, 15-16	Taillamp R	A33-1308R-AC	DEPO	68110364AB	CH2802107
Kia Sedona, 15-17, Halogen, w/o LED Position lamp	Headlamp Assy, L	323-1145L-AC2	DEPO	92101A9110	KI2502181
Kia Sedona, 15-17, Halogen, w/o LED Position Lamp	Headlamp Assy, R	323-1145R-AC2	DEPO	92102A9110	KI2503181
Nissan Sentra, 16-17, on luggage lid	Taillamp R	17-5671-00-9	TYC Brother	265503YU5A	NI2803111
Nissan Sentra, 16-17, on luggage lid	Taillamp L	17-5672-00-9	TYC Brother	265553YU5A	NI2802111

**NEW PARTS CAPA 501 STANDARD - BUMPERS**

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Chevrolet Astro, 95-05	Bar, Front Bumper Impact	GM1006359DSC	PBSI-DS	15677873	GM1006359
Ford Fusion Energi, 13-16, w/o Towing Hook	Bar, Impact	FD44138BH	Hui Yih	DG9Z17757A	FO1006263
Ford Fusion Energi, 13-16, w/Towing Hook	Bar, Impact	FD44138AH	Hui Yih	DG9Z5410852A	FO1006262
Ford Fusion Hybrid, 13-16, w/o Towing Hook	Bar, Impact	FD44138BH	Hui Yih	DG9Z17757A	FO1006263
Ford Fusion Hybrid, 13-16, w/Towing Hook	Bar, Impact	FD44138AH	Hui Yih	DG9Z5410852A	FO1006262
Ford Fusion, 13-16, w/o Towing Hook	Bar, Impact	FD44138BH	Hui Yih	DG9Z17757A	FO1006263
Ford Fusion, 13-16, w/Towing Hook	Bar, Impact	FD44138AH	Hui Yih	DG9Z5410852A	FO1006262
GMC Safari, 95-05	Bar, Front Bumper Impact	GM1006359DSC	PBSI-DS	15677873	GM1006359
Kia Optima, 12-13, USA built	Bar, Impact	KAR8060A	Auto Power	866314C010	KI1106125

**DECERTIFICATIONS**

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

**CAPA 101 STANDARD - METALS**

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
BM-20014AQ	BMW 5-Series Sedan, 04-10	Hood	Tong Yang	05/16A	41617111385	BM1230116
BM-20014AQ	BMW 5-Series Wagon, 06-10	Hood	Tong Yang	05/16A	41617111385	BM1230116

**CAPA 201 STANDARD - PLASTICS**

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
DS-04357BBO	Nissan Rogue, 14-15	Bumper Cover, Front	Tong Yang	12/15A	620224BA0H	NI1000293

**CAPA 301 STANDARD - LIGHTING**

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
NONE						

**CAPA 501 STANDARD - BUMPERS**

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
NONE						

**DELETED PARTS CAPA 101 STANDARD - METALS**

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
NONE					

**DELETED PARTS CAPA 201 STANDARD - PLASTICS**

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
NONE					

**DELETED PARTS CAPA 301 STANDARD - LIGHTING**

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
NONE					

**DELETED PARTS CAPA 501 STANDARD - BUMPERS**

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
NONE					

\*This report includes all new, decertified and deleted parts from June 5, 2017 through June 9, 2017.

All CAPA reports including the weekly update are available on the CAPA website at [www.capacertified.org](http://www.capacertified.org).

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at [debbie@capacertified.org](mailto:debbie@capacertified.org)