

NEW PARTS CAPA 101 STANDARD - METALS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Ford Escape, 13-16	Radiator Support	FD30131AOH	Hui Yih	CV6Z7810812A	FO1225215
Ford Escape, 17	Support, Lower Rad Support	FD34171AOH	Hui Yih	GV6Z7810812A	FO1225238
Kia Sedona, 15-16	Radiator Support	KA-03022AQ	Tong Yang	64101A9000	KI1225172
Lincoln MKC, 15-16	Radiator Support	FD30131AOH	Hui Yih	CV6Z7810812A	FO1225215
Toyota Tacoma, 16-17, w/Wheel Opng Mldg	Fender R	TY-10354BQ-RH	Tong Yang	5381104120	TO1241262
Toyota Tacoma, 16-17, w/Wheel Opng Mldg	Fender L	TY-10354BQ-LH	Tong Yang	5381204120	TO1240262

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Acura RDX, 16-17, w/o Parking Sensors	Bumper Cover, Front	HD-04297BCQ	Tong Yang	04711TX4A50ZZ	AC1000190
Acura RDX, 16-17, w/Parking Sensors	Bumper Cover, Front	HD-04297BDQ	Tong Yang	04711TX4A60ZZ	AC1000191
BMW 3-Series (F30) Sedan, 16-17, Luxury Line, w/o M Sport Line, w/o Headlamp Washer	Bumper Cover, Front	BM33-9968-OHOSH	Tran Hung	51117445131	BM1000427
BMW 3-Series Hybrid (F30), 16-17, Luxury Line, w/o M Sport Line, w/o Headlamp Washer	Bumper Cover, Front	BM33-9968-OHOSH	Tran Hung	51117445131	BM1000427
BMW 3-Series Hybrid (F30), 16-17, Sport Line, w/o M Sport Line, w/Headlamp Washer	Bumper Cover, Front	BM33-9967-WHOSH	Tran Hung	51117445141	BM1000456
BMW 3-Series Hybrid (F30), 16-17, Sport Line, w/o M Sport Line, w/o Headlamp Washer	Bumper Cover, Front	BM33-9967-OHOSH	Tran Hung	51117445137	BM1000455
BMW 3-Series Hybrid (F30), 16-17, Standard, w/o M Sport Line, w/o Headlamp Washer	Bumper Cover, Front	BM33-9966-OHOSH	Tran Hung	51117445105	BM1000425
BMW 3-Series Hybrid (F30), 16-17, w/o M Sport Line, w/Headlamp Washer	Bumper Cover, Front	BM33-9966-WHOSH	Tran Hung	51117445106	BM1000426
BMW 3-Series Hybrid F30), 16-17, Luxury Line, w/o M Sport Line, w/Headlamp Washer	Bumper Cover, Front	BM33-9968-WHOSH	Tran Hung	51117445133	BM1000428
BMW 3-Series Sedan (F30), 16-17, Luxury Line, w/o M Sport Line, w/Headlamp Washer	Bumper Cover, Front	BM33-9968-WHOSH	Tran Hung	51117445133	BM1000428
BMW 3-Series Sedan (F30), 16-17, Sport Line, w/o M Sport Line, w/Headlamp Washer	Bumper Cover, Front	BM33-9967-WHOSH	Tran Hung	51117445141	BM1000456
BMW 3-Series Sedan (F30), 16-17, Sport Line, w/o M Sport Line, w/o Headlamp Washer	Bumper Cover, Front	BM33-9967-OHOSH	Tran Hung	51117445137	BM1000455
BMW 3-Series Sedan (F30), 16-17, Standard, w/o M Sport Line, w/Headlamp Washer	Bumper Cover, Front	BM33-9966-WHOSH	Tran Hung	51117445106	BM1000426
BMW 3-Series Sedan (F30), 16-17, Standard, w/o M Sport Line, w/o Headlamp Washer	Bumper Cover, Front	BM33-9966-OHOSH	Tran Hung	51117445105	BM1000425
BMW 3-Series Wagon (F31), 16-17, Luxury Line, w/o M Sport Line, w/o Headlamp Washer	Bumper Cover, Front	BM33-9968-OHOSH	Tran Hung	51117445131	BM1000427
BMW 3-Series Wagon (F31), 16-17, Sport Line, w/o M Sport Line, w/Headlamp Washer	Bumper Cover, Front	BM33-9967-WHOSH	Tran Hung	51117445141	BM1000456
BMW 3-Series Wagon (F31), 16-17, Sport Line, w/o M Sport Line, w/o Headlamp Washer	Bumper Cover, Front	BM33-9967-OHOSH	Tran Hung	51117445137	BM1000455
BMW 3-Series Wagon (F31), 16-17, Standard, w/o M Sport Line, w/Headlamp Washer	Bumper Cover, Front	BM33-9966-WHOSH	Tran Hung	51117445106	BM1000426
BMW 3-Series Wagon (F31), 16-17, Standard, w/o M Sport Line, w/o Headlamp Washer	Bumper Cover, Front	BM33-9966-OHOSH	Tran Hung	51117445105	BM1000425
BMW 3-Series Wagon {F31}, 16-17, Luxury Line, w/o M Sport Line, w/Headlamp Washer	Bumper Cover, Front	BM33-9968-WHOSH	Tran Hung	51117445133	BM1000428
BMW X3 F25, 11-17, w/Fog Lamps, w/o Parking Assist, w/Surround View	Bumper Cover, Front	BM-04143BPQ	Tong Yang	51117389901	BM1000352
BMW X3 F25, 11-17, w/Fog Lamps, w/Parking Assist, w/o Surround View	Bumper Cover, Front	BM-04143BNQ	Tong Yang	51117389899	BM1000353
BMW X3 F25, 11-17, w/Fog Lamps, w/Parking Assist, w/Surround View	Bumper Cover, Front	BM-04143BGQ	Tong Yang	51117389903	BM1000354
BMW X3 F25, 11-17, w/o Fog Lamps, w/o Parking Assist, w/Surround View	Bumper Cover, Front	BM-04143BSQ	Tong Yang	51117389900	BM1000348
BMW X3 F25, 11-17, w/o Fog Lamps, w/Parking Assist, w/Surround View	Bumper Cover, Front	BM-04143BHQ	Tong Yang	51117389902	BM1000350
BMW X3, 11-17, w/o Fog Lamps, w/Parking Assist, w/o Surround View	Bumper Cover, Front	BM-04143BRQ	Tong Yang	51117389898	BM1000349
BMW X3, F25, 11-17, w/o Fog Lamps, w/o Parking Assist, w/o Surround View	Bumper Cover, Front	BM-04143BEQ	Tong Yang	51117389897	BM1000351
BMW X5 F15, 14-16, w/o HL washer, w/o Night vision, w/o Park assist, w/o Surround view	Bumper Cover, Front	BM-04136BHQ	Tong Yang	51117379596	BM1000392

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
BMW X5 F15, 14-16, w/o HL washer, w/o Night vision, w/o Park assist, w/o Surround view., w/o LED	Bumper Cover, Front	BM-04136BHQ	Tong Yang	51117378596	BM1000392
BMW X5 F15, 14-17, w/o HL washer, w/o Night vision, w/Park assist, w/Surround view, w/o LED	Bumper Cover, Front	BM-04136BGO	Tong Yang	51117378616	BM1000395
Buick Regal, 11-13, w/o parking assist	Bumper Cover, Rear	BK-04048BCQ	Tong Yang	13243346	GM1100871
Buick Regal, 11-13, w/parking assist	Bumper Cover, Rear	BK-04048BDQ	Tong Yang	20971893	GM1100872
Chevrolet Silverado 2500 HD, 15, w/Chrome, w/o Skid plate	Deflector, Lower Air	CV-05087VAQ	Tong Yang	22978557	GM1092252
Dodge Ram Pick-Up R2500, 10-17	Liner, Fender R	LT-DGV001AR	Liantuoh	68148310AD	CH1249164
Dodge Ram Pickup R3500, 10-17	Liner, Fender L	LT-DGV001AL	Liantuoh	68148311AC	CH1248164
Dodge Ram R2500 Pick-Up, 14-17	Liner, Fender L	LT-DGV001AL	Liantuoh	68148311AC	CH1248164
Dodge Ram R3500 Pick-Up, 14-17	Liner, Fender R	LT-DGV001AR	Liantuoh	68148310AD	CH1249164
Ford Focus S/SE, Sedan, 15-16	Grille Assy, Front	FD-07405GAQ	Tong Yang	F1EZ8200B	FO1200575
Ford Focus SE, Hatchback, 15-16	Grille Assy, Front	FD-07405GAQ	Tong Yang	F1EZ8200B	FO1200575
Honda Civic Sedan, 16-17, 1.5L eng	Grille, Bumper	HDN111NAQ	Pro Fortune	71102TBAA00	HO1036123
Honda Civic, 16-17, 2.0L Eng	Grille, Bumper	HDN112NAQ	Pro Fortune	71102TBAA10	HO1036124
Toyota RAV-4, 13-15	Seal, Rear Bumper Side R	TA5H612RQ	Cobra King	525910R030	TO1163102
Toyota RAV-4, 13-15	Seal, Rear Bumper Side L	TA5H612LQ	Cobra King	525920R030	TO1162102

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Chrysler 200 Sedan, 15-16, halogen, w/black trim	Headlamp Assy, L	A33-1196L-ACN2	DEPO	68284786AA	CH2502261
Chrysler 200 Sedan, 15-16, halogen, w/black trim	Headlamp Assy, R	A33-1196R-ACN2	DEPO	68284787AA	CH2503261
Chrysler 200 Sedan, 15-16, w/LED DRL, chrome	Headlamp Assy, L	A33-1196L-ACN1	DEPO	68284782AA	CH2502262
Chrysler 200 Sedan, 15-16, w/LED DRL, chrome	Headlamp Assy, R	A33-1196R-ACN1	DEPO	68284783AA	CH2503262
Dodge Charger, 15-16	Taillamp R	11-6797-00-9	TYC Brother	68213144AC	CH2801208
Dodge Charger, 15-16	Taillamp L	11-6798-00-9	TYC Brother	68213145AC	CH2800208
Ford Transit Cargo Van, 15-16, w/Chrome Trim	Headlamp Assy, R	20-9607-00-9	TYC Brother	CK4Z13008CA	FO2503329
Ford Transit Cargo Van, 15-16, w/Chrome Trim	Headlamp Assy, L	20-9608-00-9	TYC Brother	CK4Z13008DA	FO2502329
Ford Transit Passenger Van, 15-16, w/Chrome trim	Headlamp Assy, R	20-9607-00-9	TYC Brother	CK4Z13008CA	FO2503329
Ford Transit Passenger Van, 15-16, w/Chrome Trim	Headlamp Assy, L	20-9608-00-9	TYC Brother	CK4Z13008DA	FO2502329
Mazda 3 Sedan, 14-15, Mexico built	Taillamp R	316-1942R-ACN	DEPO	BJT151150A	MA2805123
Mazda 3 Sedan, 14-15, Mexico built	Taillamp L	316-1942L-ACN	DEPO	BJT151160A	MA2804123
Toyota Corolla SE/XLE/XSE, 17	Taillamp R	11-6639-80-9	TYC Brother	8155002B10	TO2805131
Toyota Corolla SE/XLE/XSE, 17	Taillamp L	11-6640-80-9	TYC Brother	8156002B10	TO2804131

NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Hyundai Tucson, 16-17	Absorber, Impact	HN01198A	Auto Power	86520D3010	HY1070162

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
AM-10020AQ-RH	Jeep Wrangler, 07-08	Fender R	Tong Yang	10/15A	68002398AC	CH1241257
AM-10020AQ-RH	Jeep Wrangler, 07-11	Fender R	Tong Yang	10/15A	68002398AD	CH1241257
AM-10020AQ-RH	Jeep Wrangler, 07-12	Fender R	Tong Yang	10/15A	68002398AE	CH1241257
AM-10020AQ-RH	Jeep Wrangler, 07-16	Fender R	Tong Yang	10/15A	68029992AB	CH1241257
MZ-03001AQ	Mazda 3, 04-09	Radiator Support	Tong Yang	08/16A	BP4K53110H	MA1225127
MZ-03001AQ	Mazda 3, 04-09	Radiator Support	Tong Yang	08/16A	BP4K53110J	MA1225127
VW0940090-200C	Volkswagen Passat, 12-15	Radiator Support	AP-Procom	09/16A	561805588B9B9	VW1225138

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
CV-04173BDQ	Chevrolet Tahoe, 07-11, w/o Off Road pkg, w/object sensor	Bumper Cover, Rear	Tong Yang	05/16B	25830551	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-11, w/o Off Road pkg, w/object sensor	Bumper Cover, Rear	Tong Yang	07/16A	25830551	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-11, w/o Off Road pkg, w/object sensor	Bumper Cover, Rear	Tong Yang	08/16A	25830551	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-11, w/Off Road pkg, (RPO-BPH)	Bumper Cover, Rear	Tong Yang	05/16B	25830551	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-11, w/Off Road pkg, (RPO-BPH)	Bumper Cover, Rear	Tong Yang	07/16A	25830551	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-11, w/Off Road pkg, (RPO-BPH)	Bumper Cover, Rear	Tong Yang	08/16A	25830551	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-14, w/o Off Road pkg, w/object sensor	Bumper Cover, Rear	Tong Yang	05/16B	20951793	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-14, w/o Off Road pkg, w/object sensor	Bumper Cover, Rear	Tong Yang	07/16A	20951793	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-14, w/o Off Road pkg, w/object sensor	Bumper Cover, Rear	Tong Yang	08/16A	20951793	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-14, w/Off Road pkg, (RPO-BPH)	Bumper Cover, Rear	Tong Yang	05/16B	20951793	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-14, w/Off Road pkg, (RPO-BPH)	Bumper Cover, Rear	Tong Yang	07/16A	20951793	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-14, w/Off Road pkg, (RPO-BPH)	Bumper Cover, Rear	Tong Yang	08/16A	20951793	GM1100783
CV-04173BDQ	GMC Yukon, 07-11, w/object sensor	Bumper Cover, Rear	Tong Yang	05/16B	25830551	GM1100783
CV-04173BDQ	GMC Yukon, 07-11, w/object sensor	Bumper Cover, Rear	Tong Yang	07/16A	25830551	GM1100783
CV-04173BDQ	GMC Yukon, 07-11, w/object sensor	Bumper Cover, Rear	Tong Yang	08/16A	25830551	GM1100783
CV-04173BDQ	GMC Yukon, 07-14, w/object sensor	Bumper Cover, Rear	Tong Yang	05/16B	20951793	GM1100783
CV-04173BDQ	GMC Yukon, 07-14, w/object sensor	Bumper Cover, Rear	Tong Yang	07/16A	20951793	GM1100783
CV-04173BDQ	GMC Yukon, 07-14, w/object sensor	Bumper Cover, Rear	Tong Yang	08/16A	20951793	GM1100783
TY04253BBQ	Toyota Camry, 02-06, (USA)	Bumper Cover, Rear	TYG Products	15/02/06	52159AA903	TO1100203
TY04253BBQ	Toyota Camry, 02-06, (USA)	Bumper Cover, Rear	TYG Products	16/07/21	52159AA903	TO1100203
Y-TYBP271ACA	Toyota Corolla Base/CE/L, 09-10, (USA)	Bumper Cover, Rear	Y.C.C.	11/16A	5215902963	TO1100264
Y-TYBP271HCA	Toyota Corolla, 09-10, (Japan)	Bumper Cover, Rear	Y.C.C.	08/16A	5215912934	TO1100268

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

DELETED PARTS CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					



WEEKLY PARTS UPDATE

June 26, 2017

[Report: P6]
Weekly

DELETED PARTS CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

*This report includes all new, decertified and deleted parts from June 18, 2017 through June 24, 2017.

All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org