

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
S1027H000BS	Honda Accord Sedan, 13-14, 6 Cyl	Hood	Jui Li	10/16A	60100T2AA80ZZ	HO1230170
S1027H000BS	Honda Accord Sedan, 13-16, 6 Cyl	Hood	Jui Li	10/16A	60100T2GA90ZZ	HO1230170
HN-10028AQ-LH	Hyundai Santa Fe, 07-09	Fender L	Tong Yang	06/16A	663100W260	HY1240139
JP8210150-000C	Jeep Grand Cherokee, 11-12	Hood	AP	11/16A	55369587AC	CH1230283
JP8210150-000C	Jeep Grand Cherokee, 11-14	Hood	AP	11/16A	55369587AD	CH1230283
JP8210150-000C	Jeep Grand Cherokee, 11-17	Hood	AP	11/16A	55369587AG	CH1230283
DJ-CA12401	Toyota Camry Hybrid, 12-14	Hood	Da Juane	01/16A	5330106150	TO1230225
DJ-CA12401	Toyota Camry Hybrid, 12-14	Hood	Da Juane	02/14A	5330106150	TO1230225
DJ-CA12401	Toyota Camry Hybrid, 12-14	Hood	Da Juane	02/15A	5330106150	TO1230225
DJ-CA12401	Toyota Camry Hybrid, 12-14	Hood	Da Juane	03/17A	5330106150	TO1230225
DJ-CA12401	Toyota Camry Hybrid, 12-14	Hood	Da Juane	04/16A	5330106150	TO1230225
DJ-CA12401	Toyota Camry Hybrid, 12-14	Hood	Da Juane	04/17A	5330106150	TO1230225
DJ-CA12401	Toyota Camry Hybrid, 12-14	Hood	Da Juane	05/14A	5330106150	TO1230225
DJ-CA12401	Toyota Camry Hybrid, 12-14	Hood	Da Juane	06/15A	5330106150	TO1230225
DJ-CA12401	Toyota Camry Hybrid, 12-14	Hood	Da Juane	06/16A	5330106150	TO1230225
DJ-CA12401	Toyota Camry Hybrid, 12-14	Hood	Da Juane	07/15A	5330106150	TO1230225
DJ-CA12401	Toyota Camry Hybrid, 12-14	Hood	Da Juane	08/14A	5330106150	TO1230225
DJ-CA12401	Toyota Camry Hybrid, 12-14	Hood	Da Juane	09/15A	5330106150	TO1230225
DJ-CA12401	Toyota Camry Hybrid, 12-14	Hood	Da Juane	09/16A	5330106150	TO1230225
DJ-CA12401	Toyota Camry Hybrid, 12-14	Hood	Da Juane	10/16A	5330106150	TO1230225
DJ-CA12401	Toyota Camry Hybrid, 12-14	Hood	Da Juane	11/15A	5330106150	TO1230225
DJ-CA12401	Toyota Camry Hybrid, 12-14	Hood	Da Juane	11/15B	5330106150	TO1230225
DJ-CA12401	Toyota Camry Hybrid, 12-14	Hood	Da Juane	11/16A	5330106150	TO1230225
DJ-CA12401	Toyota Camry Hybrid, 12-14	Hood	Da Juane	12/14A	5330106150	TO1230225
DJ-CA12401	Toyota Camry Hybrid, 12-14	Hood	Da Juane	12/16A	5330106150	TO1230225
DJ-CA12401	Toyota Camry Hybrid, 12-14	Hood	Da Juane	ALL	5330106150	TO1230225
DJ-CA12401	Toyota Camry, 12-14	Hood	Da Juane	01/16A	5330106150	TO1230225
DJ-CA12401	Toyota Camry, 12-14	Hood	Da Juane	02/14A	5330106150	TO1230225
DJ-CA12401	Toyota Camry, 12-14	Hood	Da Juane	02/15A	5330106150	TO1230225
DJ-CA12401	Toyota Camry, 12-14	Hood	Da Juane	03/17A	5330106150	TO1230225
DJ-CA12401	Toyota Camry, 12-14	Hood	Da Juane	04/16A	5330106150	TO1230225
DJ-CA12401	Toyota Camry, 12-14	Hood	Da Juane	04/17A	5330106150	TO1230225
DJ-CA12401	Toyota Camry, 12-14	Hood	Da Juane	05/14A	5330106150	TO1230225
DJ-CA12401	Toyota Camry, 12-14	Hood	Da Juane	06/15A	5330106150	TO1230225
DJ-CA12401	Toyota Camry, 12-14	Hood	Da Juane	06/16A	5330106150	TO1230225
DJ-CA12401	Toyota Camry, 12-14	Hood	Da Juane	07/15A	5330106150	TO1230225
DJ-CA12401	Toyota Camry, 12-14	Hood	Da Juane	08/14A	5330106150	TO1230225
DJ-CA12401	Toyota Camry, 12-14	Hood	Da Juane	09/15A	5330106150	TO1230225
DJ-CA12401	Toyota Camry, 12-14	Hood	Da Juane	09/16A	5330106150	TO1230225
DJ-CA12401	Toyota Camry, 12-14	Hood	Da Juane	10/16A	5330106150	TO1230225
DJ-CA12401	Toyota Camry, 12-14	Hood	Da Juane	11/15A	5330106150	TO1230225
DJ-CA12401	Toyota Camry, 12-14	Hood	Da Juane	11/15B	5330106150	TO1230225
DJ-CA12401	Toyota Camry, 12-14	Hood	Da Juane	11/16A	5330106150	TO1230225
DJ-CA12401	Toyota Camry, 12-14	Hood	Da Juane	12/14A	5330106150	TO1230225
DJ-CA12401	Toyota Camry, 12-14	Hood	Da Juane	12/16A	5330106150	TO1230225
DJ-CA12401	Toyota Camry, 12-14	Hood	Da Juane	ALL	5330106150	TO1230225
TY8040150-000C	Toyota RAV-4, 13-15, North America Built	Hood	AP	08/16A	533010R050	TO1230229



MONTHLY RECALL REPORT

June 2017*

[Report: P8]
Monthly

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
ADA409RB1	Audi A4 Sedan, 09-12, w/S-Line pkg, w/o Parking aid	Bumper Cover, Rear	Gordon	11/15A	8K5807303BGRU	AU1100184
ADA409RB1	Audi S4 Sedan, 10-12, w/o Parking aid	Bumper Cover, Rear	Gordon	11/15A	8K5807303BGRU	AU1100184
DG-04088BAQ	Dodge Nitro, 07-09, Black w/o fog lamps	Bumper Cover, Front	Tong Yang	12/14A	1FU08CD7AA	CH1000886
HN-04071BBQ	Hyundai Santa Fe, 07-09	Bumper Cover, Rear	Tong Yang	10/14A	866112B020	HY1100153
AM-04028BDQ	Jeep Liberty, 06-07, Body Color w/o tow hooks	Bumper Cover, Front	Tong Yang	09/14A	5JJ07TZZAD	CH1000869
MD5700000-E00C	Mercedes-Benz E Class, 07-09, E320/E350/E550, w/o AMG Styling, Sport, Headlamp Washer, & Parktronic	Bumper Cover, Front	AP-Procom	02/16A	2118802340	MB1000271
DS-04333BBQ	Nissan Altima, 13-15	Bumper Cover, Front	Tong Yang	10/16A	620223TA0H	NI1000285
NSB113NBQ	Nissan Altima, 13-15	Bumper Cover, Front	Pro Fortune	12/16B	620223TA0H	NI1000285
DS-04204BBQ	Nissan Murano, 03-05	Bumper Cover, Front	Tong Yang	05/16A	62022CA026	NI1000209
DS-04368BBQ	Nissan Versa Sedan, 15-17	Bumper Cover, Rear	Tong Yang	09/16A	HEM229KM0J	NI1100297
TY-04242BBQ	Toyota Prius, 04-09	Bumper Cover, Front	Tong Yang	01/16B	5211947903	TO1000274
TY04304BCQ	Toyota Sienna, 06-10, w/o park assist sensors	Bumper Cover, Front	TYG Products	16/06/20	52119AE904	TO1000323

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 501 STANDARD - BUMPER PARTS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

*This report includes all decertifications from May 1, 2017 through May 31, 2017.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.