

**NEW PARTS CAPA 101 STANDARD - METALS**

<b>Application Description</b>	<b>Part Description</b>	<b>Manufacturer Number</b>	<b>Manufacturer</b>	<b>OEM Number</b>	<b>PartsLink Number</b>
Chevrolet Trax, 13-16	Hood	CVTX15HD1	Gordon	42599227	GM1230428
Chevrolet Trax, 13-16	Hood	CVTX15HD1	Gordon	95143271	GM1230428
Ford Explorer, 16-17	Hood	FDEP16HD1	Gordon	FB5Z16612A	FO1230315
Mercedes-Benz GLK-Class, 10-15	Hood	BZ-20034AQ	Tong Yang	2048800557	MB1230132
Volkswagen Golf, 15-17	Bracket, H/Lamp Mounting L	VG47156ALH	Hui Yih	5GM805931	VW2508101
Volkswagen Golf, 15-17	Bracket, H/Lamp Mounting R	VG47156ARH	Hui Yih	5GM805932	VW2509101

**NEW PARTS CAPA 201 STANDARD - PLASTICS**

<b>Application Description</b>	<b>Part Description</b>	<b>Manufacturer Number</b>	<b>Manufacturer</b>	<b>OEM Number</b>	<b>PartsLink Number</b>
Acura RDX, 16-17, w/o parking sensors	Bumper Cover, Rear	HD-04301BBQ	Tong Yang	04715TX4A50ZZ	AC1114101
BMW X1 F48, 16-17, Chrome w/o M Pkg	Grille	BM-07124GALQ	Tong Yang	51137354823	BM1200290
BMW X1 F48, 16-17, Chrome w/o M Pkg	Grille	BM-07124GARQ	Tong Yang	51137354824	BM1200289
Chevrolet Camaro LS/LT, 14-15, w/Tow hook	Grille, Bumper Lower	CVCAM14FG1	Gordon	22829524	GM1036165
Chevrolet Camaro SS Coupe/Convertible, 14-15	Grille, Bumper Lower	CVCAM14FG1	Gordon	22829524	GM1036165
Honda Accord Sedan, 16-17	Moulding, Lower	HD-07216MAQ	Tong Yang	71124T2FA51	HO1216116
Honda Pilot, 16-17, w/o Chrome Trim	Cover, Lower	HD-04324BAQ	Tong Yang	71110TG7A00	HO1015113
Hyundai Sonata, 14	Liner, Fender L	HYS1014FL-C	Great Bestcam	868113Q700	HY1248135
Hyundai Sonata, 14	Liner, Fender R	HYS1014FR-C	Great Bestcam	868123Q700	HY1249135
Infiniti Q50 Red Sport 400/Sport, 14-17, w/Object sensors	Bumper Cover, Front	IFB005NDQ	Pro Fortune	620224HE0H	IN1000259
Infiniti Q50 Hybrid Sport, 14-15, w/o Object sensors	Bumper Cover, Front	IFB005NCQ	Pro Fortune	620224HD0H	IN1000258
Infiniti Q50 Hybrid Sport, 14-15, w/Object sensors	Bumper Cover, Front	IFB005NDQ	Pro Fortune	620224HE0H	IN1000259
Infiniti Q50 Red Sport 400/Sport, 14-17, w/o Object sensors	Bumper Cover, Front	IFB005NCQ	Pro Fortune	620224HD0H	IN1000258
Jeep Renegade, 15-17	Moulding, Wheel Opening R	AM-01012MARQ	Tong Yang	5XB64LXHAA	CH1291113
Lexus IS 250, 14-16, w/o F Sport	Moulding, Grille	TY-07566MAQ	Tong Yang	5271153041	LX1202106
Lexus IS 350, 14-16, w/o F Sport	Moulding, Grille	TY-07566MAQ	Tong Yang	5271153041	LX1202106
Mercedes-Benz C-Class C300, 15-16, Sedan, w/o AMG, w/o Luxury, w/o Surround View, w/ Active Park Ass	Bumper Cover, Front	BZ-04160BEQ	Tong Yang	2058800340649999	MB1000468
Mercedes-Benz C-Class C300, 15-16, Sedan, w/o AMG, w/o Luxury, w/Surround view, w/ Active Park Assis	Bumper Cover, Front	BZ-04160BFQ	Tong Yang	2058802040649999	MB1000511
Mercedes-Benz C-Class C300, 15-17, Sedan, w/o AMG, w/o Luxury, w/o Surround View, w/ Active Park Ass	Bumper Cover, Front	BZ-04160BEQ	Tong Yang	20588003409999	MB1000468
Mercedes-Benz C-Class C300, 15-17, Sedan, w/o AMG, w/o Luxury, w/o Surround View, w/o Active Park	Bumper Cover, Front	BZ-04160BHQ	Tong Yang	20588001409999	MB1000467
Mercedes-Benz C-Class C300, 15-17, Sedan, w/o AMG, w/o Luxury, w/Surround view, w/ Active Park Assis	Bumper Cover, Front	BZ-04160BFQ	Tong Yang	20588020409999	MB1000511
Mercedes-Benz C-Class C300, 17, Coupe, w/o Sport Pkg, w/o Surround View, w/Active Park Assist	Bumper Cover, Front	BZ-04160BEQ	Tong Yang	2058800340649999	MB1000468
Mercedes-Benz C-Class C300, 17, Coupe, w/o Sport Pkg, w/o Surround View, w/Active Park Assist	Bumper Cover, Front	BZ-04160BEQ	Tong Yang	20588003409999	MB1000468
Mercedes-Benz C-Class C300, 17, Coupe, w/o Sport Pkg, w/o Surround View, w/o Active Park Assist	Bumper Cover, Front	BZ-04160BHQ	Tong Yang	20588001409999	MB1000467
Mercedes-Benz C-Class C300, 17, Coupe, w/o Sport Pkg, w/Surround View, w/Active Park Assist	Bumper Cover, Front	BZ-04160BFQ	Tong Yang	2058802040649999	MB1000511
Mercedes-Benz C-Class C300, 17, Coupe, w/o Sport Pkg, w/Surround View, w/Active Park Assist	Bumper Cover, Front	BZ-04160BFQ	Tong Yang	20588020409999	MB1000511
Mercedes-Benz C-Class, 15-17, Sedan, w/ Surround View, w/o Active Park Assist	Bumper Cover, Front	BZ-04160BDQ	Tong Yang	20588019409999	MB1000510
Mercedes-Benz C-Class, 17, Coupe, w/ Surround View, w/o Active Park Assist	Bumper Cover, Front	BZ-04160BDQ	Tong Yang	20588019409999	MB1000510
Nissan Maxima S, 16-17	Bumper Cover, Rear	DS-04398BCQ	Tong Yang	850224RA0H	NI1100307
Nissan Maxima SV/SL/SR/Platinum, 16-17	Bumper Cover, Rear	DS-04398BDQ	Tong Yang	850224RBOH	NI1100308
Toyota Tacoma, 16-17, w/Fog lamps	Bumper Cover, Front	TY-04552BDQ	Tong Yang	5211904907	TO1000414
Toyota Tacoma, 16-17, w/o Fog lamps	Bumper Cover, Front	TY-04552BCQ	Tong Yang	5211904220	TO1000415

**NEW PARTS CAPA 301 STANDARD - LIGHTING**

<b>Application Description</b>	<b>Part Description</b>	<b>Manufacturer Number</b>	<b>Manufacturer</b>	<b>OEM Number</b>	<b>PartsLink Number</b>
BMW X5, 11-13, w/o Side view camera	Reflector, Kit	344-1420P-UC	DEPO	63147274433	BM1084103
BMW X5, 11-13, w/Side view camera	Reflector, Kit	344-1421P-UC	DEPO	63147274434	BM1084104
Ford Mustang Convertible/Coupe, 15-17	Headlamp Assy, R	K30-1162R-UCH2	DEPO	FR3Z13008J	FQ2519124
Ford Mustang Convertible/Coupe, 15-17	Headlamp Assy, L	K30-1162L-UCH2	DEPO	FR3Z13008K	FQ2518124

**NEW PARTS CAPA 301 STANDARD - LIGHTING**

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Ford Shelby GT350 Mustang, 16-17	Headlamp Assy, R	K30-1162R-UCH2	DEPO	FR3Z13008J	FO2519124
Ford Shelby GT350 Mustang, 16-17	Headlamp Assy, L	K30-1162L-UCH2	DEPO	FR3Z13008K	FO2518124
Honda Civic Coupe, 14-15	Taillamp R	317-19B2R-AC	DEPO	33500TS8A51	HO2801187
Honda Civic Coupe, 14-15	Taillamp L	317-19B2L-AC	DEPO	33550TS8A51	HO2800187
Mercedes-Benz Sprinter, 14-16, Halogen	Headlamp Assy, L	340-1151L-AC2	DEPO	9068202861	MB2502221
Mercedes-Benz Sprinter, 14-16, Halogen	Headlamp Assy, R	340-1151R-AC2	DEPO	9068202961	MB2503221
Mitsubishi Mirage, 14-17	Headlamp Assy, L	314-1148L-AC	DEPO	8301C693	MI2502164
Mitsubishi Mirage, 14-17	Headlamp Assy, R	314-1148R-AC	DEPO	8301C694	MI2503164
Subaru Legacy, 15-17, Halogen w/Chrome bezel	Headlamp Assy, R	320-1127R-AC1	DEPO	84001AL00A	SU2503151
Subaru Legacy, 15-17, Halogen, w/Chrome bezel	Headlamp Assy, L	320-1127L-AC1	DEPO	84001AL01A	SU2502151

**NEW PARTS CAPA 501 STANDARD - BUMPERS**

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Buick Enclave, 08-16	Bar, Impact	BKR3321A	Auto Power	22806759	GM1006657
Chevrolet Traverse, 09-16	Bar, Impact	BKR3321A	Auto Power	22806759	GM1006657
Ford Flex, 09-15	Bar, Reinforcement	FDR3417A	Auto Power	DG1Z17757A	FO1006255
Ford Taurus Police, 13-15	Bar, Reinforcement	FDR3417A	Auto Power	DG1Z17757A	FO1006255
Ford Taurus Police/SHO, 13-17	Absorber, Impact	FD2K613Q	Cobra King	DG1Z17787A	FO1170141
Ford Taurus SE/SEL/Limited, 10-12	Bar, Reinforcement	FDR3417A	Auto Power	DG1Z17757A	FO1006255
Ford Taurus SHO, 10-15	Bar, Reinforcement	FDR3417A	Auto Power	DG1Z17757A	FO1006255
Ford Taurus, 13-17	Absorber, Impact	FD2K613Q	Cobra King	DG1Z17787A	FO1170141
GMC Acadia Denali, 11-16	Bar, Impact	CVR3298A	Auto Power	22806758	GM1006658
GMC Acadia SL, 10-12 & 16	Bar, Impact	CVR3298A	Auto Power	22806758	GM1006658
GMC Acadia SLE 1/SLE 2/SLT 1/SLT 2, 13-15	Bar, Impact	CVR3298A	Auto Power	22806758	GM1006658
GMC Acadia SLE/SLT 1/SLT 2, 07-17	Bar, Impact	CVR3298A	Auto Power	22806758	GM1006658
Hyundai Accent, 12-16	Absorber, Energy	HN36-7001	Tran Hung	865801R000	HY1070131
Hyundai Accent, 12-16	Absorber, Energy	HY56124Q	Cobra King	865801R000	HY1070131
Kia Forte Sedan, 10-13	Absorber, Energy	KA1A613Q	Cobra King	866201M000	KI1170116
Lincoln MKS, 10-12, 3.5/3.7L Eng	Bar, Reinforcement	FDR3417A	Auto Power	DG1Z17757A	FO1006255
Lincoln MKT, 10-14	Bar, Reinforcement	FDR3417A	Auto Power	DG1Z17757A	FO1006255
Nissan Frontier, 05-16, w/o Rear object sensors	Bar, Face	NI1102153DSC	PBSI-DS	850309BF0A	NI1102153
Nissan Frontier, 05-16, w/o Rear object sensors	Bar, Face	NI1102154DSC	PBSI-DS	850309BF1D	NI1102154
Nissan Frontier, 13-16, w/Rear object sensors	Bar, Face	NI1102156DSC	PBSI-DS	850309BF1E	NI1102156
Nissan Frontier, 13-16, w/Rear object sensors, Chrome	Bar, Face	NI1102157DSC	PBSI-DS	850309BF0B	NI1102157
Nissan Versa Sedan, 12-17	Bar, Reinforcement	NI1006240DSC	PBSI-DS	620303BA0A	NI1006240
Toyota Avalon, 13-17.	Absorber, Energy	TA9D613Q	Cobra King	5261507020	TO1170142
Toyota Avalon, 13-17; Hybrid	Absorber, Energy	TA9D613Q	Cobra King	5261507020	TO1170142
Toyota Camry Hybrid, 15-16	Bar, Reinforcement	TYR2607A	Auto Power	5202106130	TO1006237
Toyota Camry, 15-16	Bar, Reinforcement	TYR2607A	Auto Power	5202106130	TO1006237
Toyota Corolla, 14-17	Bar, Reinforcement	TO1006249DSC	PBSI-DS	5202102240	TO1006249
Toyota Highlander Hybrid, 14-16	Absorber, Energy	TA2R124Q	Cobra King	5.2611E+96	TO1070181
Toyota Highlander, 14-16	Absorber, Energy	TA2R124Q	Cobra King	5.2611E+96	TO1070181

**DECERTIFICATIONS**

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

**CAPA 101 STANDARD - METALS**

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>	
FD-03017AQ	Ford Fusion, 06-09	Radiator Support	Tong Yang	10/16A	6E5Z16138A	FO1225184
S0471H000AS	Honda Ridgeline, 06-14	Hood	Jui Li	10/16A	60100SJCA90ZZ	HO1230147
FD-03017AQ	Lincoln Zephyr, 06	Radiator Support	Tong Yang	10/16A	6E5Z16138A	FO1225184
FD-03017AQ	Mercury Milan, 06-09	Radiator Support	Tong Yang	10/16A	6E5Z16138A	FO1225184
SB30093AH	Subaru Forester, 09-13	Radiator Support	Hui Yih	09/16A	53010SC0019P	SU1225139
DJ-CA15401	Toyota Camry Hybrid, 15-17	Hood	Da Juane	10/16A	5330106160	TO1230234
DJ-CA15401	Toyota Camry, 15-17	Hood	Da Juane	10/16A	5330106160	TO1230234

**DECERTIFICATIONS**

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

**CAPA 201 STANDARD - PLASTICS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Y-TYBP297CA	Toyota Avalon Hybrid, 13-14 w/fog lamps	Bumper Cover, Front	Y.C.C.	01/17A	5211907910	TO1000396
Y-TYBP297CA	Toyota Avalon, 13-14, w/fog lamps	Bumper Cover, Front	Y.C.C.	01/17A	5211907910	TO1000396
Y-TYBP271CA	Toyota Corolla S/XRS, 09-10, (USA)	Bumper Cover, Rear	Y.C.C.	01/17A	5215902964	TO1100265

**CAPA 301 STANDARD - LIGHTING**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

**CAPA 501 STANDARD - BUMPERS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

**DELETED PARTS CAPA 101 STANDARD - METALS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
CV7600090-100C	Chevrolet Express Van, 96-02, composite head lamps	Radiator Support	AP-Procom	15034846	GM1225207
CV7600090-000C	Chevrolet Express Van, 96-02, w/sealed beam headlamps	Radiator Support	AP-Procom	15034820	GM1225206
CV7600090-100C	GMC Savana, 96-02, composite head lamps	Radiator Support	AP-Procom	15034846	GM1225207
CV7600090-000C	GMC Savana, 96-02, w/sealed beam headlamps	Radiator Support	AP-Procom	15034820	GM1225206
DT3520160-1L0C	Nissan Maxima, 02-03	Fender L	AP	631014Y930	NI1240181
DT9200150-B00C	Nissan Pickup, 93-97	Hood	AP	651001S730	NI1230108

**DELETED PARTS CAPA 201 STANDARD - PLASTICS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

**DELETED PARTS CAPA 301 STANDARD - LIGHTING**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

**DELETED PARTS CAPA 501 STANDARD - BUMPERS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

\*This report includes all new, decertified and deleted parts from August 14, 2017 through August 18, 2017.

All CAPA reports including the weekly update are available on the CAPA website at [www.capacertified.org](http://www.capacertified.org).

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at [debbie@capacertified.org](mailto:debbie@capacertified.org)