

NEW PARTS CAPA 101 STANDARD - METALS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
GMC Sierra 2500/3500, 15-16	Hood	CV-20135AQ	Tong Yang	23469917	GM1230447

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Chrysler 200 Sedan, 15-16	Bumper Cover, Applique	CR-04069MAQ	Tong Yang	68203080AC	CH1144109
Dodge Challenger, 15-17	Liner, Fender R	DGC3014BR-C	Great Bestcam	68175060AF	CH1249172
Dodge Challenger, 15-17	Liner, Fender L	DGC3014BL-C	Great Bestcam	68175061AF	CH124817
Dodge Challenger, 15-17	Liner, Fender R	DGC3014CR-C	Great Bestcam	68259092AC	CH1249173
Dodge Challenger, 15-17	Liner, Fender L	DGC3014CL-C	Great Bestcam	68259093AC	CH1248173
Dodge Charger, 15-16, w/o Hood Scoop; w/o Adaptive Cruise Control; w/o Police Pkg	Grille, Lower	DGCGR15FG7	Gordon	68214782AB	CH1036140
Honda Accord Sedan, 16-17	Moulding, Grille	HD-07210MAQ	Tong Yang	71180T2FA51	HO1210148
Honda Civic Coupe, 16-17	Moulding, Grille	HDM060NEQ	Pro Fortune	71125TBAA01	HO1210149
Honda Civic Sedan, 16-17	Moulding, Grille	HDM060NEQ	Pro Fortune	71125TBAA01	HO1210149
Hyundai Sonata, 14	Cover, Lower Rear	LG-70-175C	CHL	866913Q800	HY1195112
Hyundai Tuscon, 16-17, w/o Skid Plate	Bumper Cover, Front Lower	HN-04167BAQ	Tong Yang	86512D3000	HY1015104
Kia Optima, 16, Std Type	Bumper Cover, Front	KA-04115BBQ	Tong Yang	86511D5000	KI1000182
Lincoln Navigator, 09-14, w/parking sensors	Bumper Cover, Front	Y-LCBP005HCA	Y.C.C.	9L7Z17D957ACP	FO1000642
Lincoln Navigator, 09-14, w/parking sensors	Bumper Cover, Front	Y-LCBP005HCA	Y.C.C.	9L7Z17D957APTM	FO1000642
Mazda CX-3, 16-17	Bumper Cover, Rear	MZ-04170BBQ	Tong Yang	DDYL5022XABB	MA1100218
Mazda CX-3, 16-18	Bumper Cover, Rear	MZ-04170BBQ	Tong Yang	DDYL5022XDBB	MA1100218
Mercedes-Benz GLA-Class GLA250, 15-17, w/o Sport pkg, w/o Parktronic	Grille, Center Bumper	BZ-07140GAQ	Tong Yang	1568850822	MB1036155
Toyota Sienna Base/L/LE/XLE/Limited, 11-17, w/o park distance sensors	Bumper Cover, Rear	TYB156NCQ	Pro Fortune	5215908902	TO1100286
Toyota Sienna Base/L/LE/XLE/Limited, 11-17, w/park distance sensors	Bumper Cover, Rear	TYB156NDQ	Pro Fortune	5215908903	TO1100285

NEW PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Chrysler 300 Sedan, 12-14, w/Black Bezel, Halogen	Headlamp Assy, R	333-1193R-ACN2	DEPO	68085416AF	CH2503235
Chrysler 300 Sedan, 12-14, w/Black Bezel, Halogen	Headlamp Assy, L	333-1193L-ACN2	DEPO	68085417AF	CH2502235
Ford Mustang Shelby GT500, 13-14, Xenon	Headlamp Assy, R	20-9569-01-9	TYC Brother	DR3Z13008C	FO2519113
Ford Mustang Shelby GT500, 13-14, Xenon	Headlamp Assy, L	20-9570-01-9	TYC Brother	DR3Z13008D	FO2518113
Ford Mustang, 13-14, Xenon	Headlamp Assy, R	20-9569-01-9	TYC Brother	DR3Z13008C	FO2519113
Ford Mustang, 13-14, Xenon	Headlamp Assy, L	20-9570-01-9	TYC Brother	DR3Z13008D	FO2518113
Honda Accord Hybrid, 17	Headlamp Assy, R	317-1176R-ACN2B	DEPO	33100T2AA91	HO2503177
Honda Accord Hybrid, 17	Headlamp Assy, L	317-1176L-ACN2B	DEPO	33150T2AA91	HO2502177
Scion tC, 14-16	Headlamp Assy, R	328-1102R-UC2	DEPO	8113021180	SC2519109
Scion tC, 14-16	Headlamp Assy, L	328-1102L-UC2	DEPO	8117021180	SC2518109

NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Chevrolet Silverado, 15-16; 2500 HD	Bumper, Rear Assembly	GM1103182DSC	PBSI-DS	GM1103182	GM1103182
Chevrolet Silverado, 15-16; 2500 HD	Bumper, Rear Assembly	GM1103183DSC	PBSI-DS	GM1103183	GM1103183

NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Chevrolet Silverado, 15-16; 2500 HD	Bumper, Rear Assembly	GM1103184DSC	PBSI-DS	GM1103184	GM1103184
Chevrolet Silverado, 15-16; 3500 HD	Bumper, Rear Assembly	GM1103182DSC	PBSI-DS	GM1103182	GM1103182
Chevrolet Silverado, 15-16; 3500 HD	Bumper, Rear Assembly	GM1103183DSC	PBSI-DS	GM1103183	GM1103183
Chevrolet Silverado, 15-16; 3500 HD	Bumper, Rear Assembly	GM1103184DSC	PBSI-DS	GM1103184	GM1103184
GMC Sierra, 15-16; 2500 HD	Bumper, Rear Assembly	GM1103182DSC	PBSI-DS	GM1103182	GM1103182
GMC Sierra, 15-16; 2500 HD	Bumper, Rear Assembly	GM1103183DSC	PBSI-DS	GM1103183	GM1103183
GMC Sierra, 15-16; 2500 HD	Bumper, Rear Assembly	GM1103184DSC	PBSI-DS	GM1103184	GM1103184
GMC Sierra, 15-16; 3500 HD	Bumper, Rear Assembly	GM1103182DSC	PBSI-DS	GM1103182	GM1103182
GMC Sierra, 15-16; 3500 HD	Bumper, Rear Assembly	GM1103183DSC	PBSI-DS	GM1103183	GM1103183
GMC Sierra, 15-16; 3500 HD	Bumper, Rear Assembly	GM1103184DSC	PBSI-DS	GM1103184	GM1103184
Kia Soul, 14-16	Absorber, Impact	KA0F124Q	Cobra King	86520B2010	KI1070136
Toyota Tacoma, 16-17, w/o Parking Assist, Chrome	Cap, Bumper Rear R	TY-04553PARQ	Tong Yang	5215504020	TO1105131
Toyota Tacoma, 16-17, w/o Parking Assist, Chrome	Cap, Bumper Rear L	TY-04553PALQ	Tong Yang	5215604020	TO1104131
Toyota Tacoma, 16-17, w/Parking Assist, Chrome	Cap, Bumper Rear R	TY-04553PBRQ	Tong Yang	5215504050	TO1105132
Toyota Tacoma, 16-17, w/Parking Assist, Chrome	Cap, Bumper Rear L	TY-04553PBLQ	Tong Yang	5215604050	TO1104132

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
DJ-CV13401	Honda Civic Hybrid, 13	Hood	Da Juane	12/16A	60100TR3A80ZZ	HO1230171
DJ-CV13401	Honda Civic Hybrid, 13-15	Hood	Da Juane	12/16A	60100TR3A50ZZ	HO1230171
DJ-CV13401	Honda Civic Sedan, 13	Hood	Da Juane	12/16A	60100TR3A80ZZ	HO1230171
DJ-CV13401	Honda Civic Sedan, 13-15	Hood	Da Juane	12/16A	60100TR3A50ZZ	HO1230171
HYSF13HD1	Hyundai Santa Fe Sport, 13-17	Hood	Gordon	12/16A	664004Z000	HY1230157
HYSN06HD1	Hyundai Sonata, 06-10	Hood	Gordon	11/16A	664000A000	HY1230134
HYSN06HD1	Hyundai Sonata, 06-10	Hood	Gordon	11/16A	664003K010	HY1230134

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
CV-04095BDQ	GMC Sierra, 03-07, w/fog lamps	Bumper Cover, Front	Tong Yang	03/17A	12335963	GM1000684

CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

WEEKLY PARTS UPDATE

September 25, 2017

DELETED PARTS CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

*This report includes all new, decertified and deleted parts from September 18, 2017 through September 22, 2017.
 All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.
 If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at