

NEW PARTS CAPA 101 STANDARD - METALS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
BMW 7-Series (G11/G12), 16-17	Fender L	BM11162LLH	Hui Yih	41007427513	BM1240167
BMW 7-Series (G11/G12), 16-18	Fender R	BM11162LRH	Hui Yih	41007427514	BM1241167
Honda Accord, 17, Hybrid	Radiator Support	HD30178AH	Hui Yih	60400T3WA20ZZ	HO1225187
Nissan Altima Sedan, 16-17	Hood	NS50001Q	Cobra King	651009HS0A	NI1230210
Volkswagen Golf, 15-17	Bracket, H/Lamp Mounting L	V1S60116AL	Auto Power	5GM805931	VW2508101
Volkswagen Golf, 15-17	Bracket, H/Lamp Mounting R	V1S60116AR	Auto Power	5GM805932	VW2509101
Volkswagen Jetta Sedan, 11-17	Support, Center	V1S60119A	Auto Power	5C6805567B	VW1233106

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Acura TSX, 09-14, Sedan, 2.4L Eng	Grille, Center	HD9A017BQ	Cobra King	71107TLOG50	AC1036102
Acura TSX, 11-14, Sport Wagon	Grille, Center	HD9A017BQ	Cobra King	71107TLOG50	AC1036102
BMW M3 Sedan, 15-17, w/HL washers	Bumper Cover, Front	BM33-9977-WOSWH	Tran Hung	51118058824	BM1000409
BMW M3 Sedan, 15-17, w/o HL washers	Bumper Cover, Front	BM33-9977-WOSOH	Tran Hung	51118058822	BM1000408
BMW M4 Convertible/Coupe, 15-17, w/HL washers	Bumper Cover, Front	BM33-9977-WOSWH	Tran Hung	51118058824	BM1000409
BMW M4 Convertible/Coupe, 15-17, w/o HL washers	Bumper Cover, Front	BM33-9977-WOSOH	Tran Hung	51118058822	BM1000408
BMW X3 F25 X Line, 11-14, w/o M Pkg.	Cover, Lower	BM33-5117	Tran Hung	51117258578	BM1095112
Chevrolet Trax, 15-16	Grille, Lower	CV-07300GAQ	Tong Yang	94560931	GM1200727
Dodge Charger, 15-16	Liner, Fender Front R	DGC4014CR-C	Great Bestcam	68205936AE	CH1249171
Dodge Charger, 15-16	Liner, Fender Front L	DGC4014CL-C	Great Bestcam	68205937AE	CH1248171
Dodge Charger, 15-17 Police, R/T, R/T Road & Track, SE, SXT Model	Liner, Fender Front R	DGC4014CR-C	Great Bestcam	68205936AF	CH1249171
Dodge Charger, 15-17 Police, R/T, R/T Road & Track, SE, SXT Model	Liner, Fender Front L	DGC4014CL-C	Great Bestcam	68205937AF	CH1248171
Ford Focus, 15-16; SE	Grille, Assy	FD-07406GCCQ	Tong Yang	FM5Z8200AA	FO1200564
Ford Fusion Energi, 16-17	Reinforcement, Support	FD-03054AQ	Tong Yang	HP5Z8A284B	FO1225247
Ford Fusion Hybrid, 16-17	Reinforcement, Support	FD-03054AQ	Tong Yang	HP5Z8A284B	FO1225247
Ford Fusion, 16-17	Reinforcement, Support	FD-03054AQ	Tong Yang	HP5Z8A284B	FO1225247
Ford MKZ Hybrid, 17	Reinforcement, Support	FD-03054AQ	Tong Yang	HP5Z8A284B	FO1225247
Ford MKZ, 17	Reinforcement, Support	FD-03054AQ	Tong Yang	HP5Z8A284B	FO1225247
Ford Mustang Convertible/Coupe, 15-17, w/o Fog lamps	Cover, Fog Lamp Opng R	FD3G083ARQ	Cobra King	FR3Z17E810BA	FO1039153
Ford Mustang Convertible/Coupe, 15-17, w/o Fog lamps	Cover, Fog Lamp Opng L	FD3G083ALQ	Cobra King	FR3Z17E811BA	FO1038153
Honda Civic, 16-17; Coupe	Liner, Fender Assy R	HDC1014M1R-C	Great Bestcam	74101TBAA00	HO1249158
Honda Civic, 16-17; Coupe	Liner, Fender Assy L	HDC1014M1L-C	Great Bestcam	74151TBAA00	HO1248158
Honda Civic, 16-17; Sedan	Liner, Fender Assy R	HDC1014M1R-C	Great Bestcam	74101TBAA00	HO1249158
Honda Civic, 16-17; Sedan	Liner, Fender Assy L	HDC1014M1L-C	Great Bestcam	74151TBAA00	HO1248158
Honda CR-V, 15-16	Liner, Fender Assy R	HDC4014FR-C	Great Bestcam	74100T1WA00	HO1249173
Honda CR-V, 17	Liner, Fender R	LT-HDV003AR	Liantuoh	74100TLAA00	HO1249170
Honda CR-V, 17	Liner, Fender L	LT-HDV003AL	Liantuoh	74150TLAA00	HO1248170
Hyundai Elantra GT, 13-16	Bumper Cover, Rear	Y-HYBP043CA	Y.C.C.	86611A5000	HY1100196
Hyundai Tucson, 16, w/o Pedestrian recognition	Grille, Radiator	HN-07099GAQ	Tong Yang	86350D3000RAM	HY1200189
Jeep Renegade, 15-17, w/o Fog Lamps	Bumper Cover, Front	JP4000000-000C	AP-Procom	5XB40LXHAA	CH1015122
Lexus IS 250, 14	Moulding, Grille	LSM025NCQ	Pro Fortune	5271153060	LX1202105
Lexus IS 250, 14-15 W/F Sport Pkg	Moulding, Grille	LSM025NCQ	Pro Fortune	5271153061	LX1202105
Lexus IS 350, 14	Moulding, Grille	LSM025NCQ	Pro Fortune	5271153060	LX1202105
Lexus IS 350, 14-15 W/F Sport Pkg	Moulding, Grille	LSM025NCQ	Pro Fortune	5271153061	LX1202105
Subaru Legacy, 13-14	Bumper Cover, Front	SB-04060BBQ	Tong Yang	57704AJ13A	SU1000170
Toyota RAV-4, 13-17	Cover, Engine Under	LT-TYB006A	Liantuoh	514410R070	TO1228196
Toyota RAV4, 16-17	Cover, Side Support R	TYT215AR	Auto Power	521550R050	TO1143121
Toyota RAV4, 16-17; Hybrid	Cover, Side Support R	TYT215AR	Auto Power	521550R050	TO1143121
Toyota Sequoia, 08-16, w/o Headlamp Washer	Filler, Front Fender R	TA6B065RQ	Cobra King	539310C901	TO1243100
Toyota Sequoia, 08-16, w/o Headlamp Washer	Filler, Front Fender L	TA6B065LQ	Cobra King	539320C901	TO1242100
Toyota Tundra, 07-13	Filler, Front Fender R	TA6B065RQ	Cobra King	539310C901	TO1243100
Toyota Tundra, 07-13	Filler, Front Fender L	TA6B065LQ	Cobra King	539320C901	TO1242100
Volkswagen Tiguan, 09-10, w/HL washer w/Parking aid	Bumper Cover, Front	Y-VWBP027HCA	Y.C.C.	5N0807217EBGRU	VW1000224
Volkswagen Tiguan, 09-10, w/o HL washer w/Parking aid	Bumper Cover, Front	Y-VWBP027CA	Y.C.C.	5N0807217EAGRU	VW1000223

NEW PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Acura RDX, 16-17	Reflector, Bumper Rear R	327-2907R-UC	DEPO	33505TS8A52	HO1185110
Acura RDX, 16-17	Reflector, Bumper Rear L	327-2907L-UC	DEPO	33555TS8A52	HO1184110
BMW 3-Series F30 Sedan, 12-15, w/o M Sport	Lamp, Side Marker L	344-1418L-UC	DEPO	63147274521	BM2554102
BMW 3-Series F30 Sedan, 12-15, w/o M Sport	Lamp, Side Marker R	344-1418R-UC	DEPO	63147274522	BM2555102
BMW 3-Series F30H Hybrid Sedan, 13-15, w/o M Sport	Lamp, Side Marker R	344-1418R-UC	DEPO	63147274522	BM2555102
BMW 3-Series F30H Sedan Hybrid, 13-15, w/o M Sport	Lamp, Side Marker L	344-1418L-UC	DEPO	63147274521	BM2554102
BMW 3-Series F31 Wagon, 14-16, w/o M Sport	Lamp, Side Marker L	344-1418L-UC	DEPO	63147274521	BM2554102
BMW 3-Series F31 Wagon, 14-16, w/o M Sport	Lamp, Side Marker R	344-1418R-UC	DEPO	63147274522	BM2555102
Cadillac ATS Sedan, 15-18	Lamp, Side Marker L	332-1436L-AC	DEPO	23169181	GM2550200
Cadillac ATS Sedan, 15-18	Lamp, Side Marker R	332-1436R-AC	DEPO	23169182	GM2551200
Cadillac CTS Sedan, 14-16	Lamp, Side Marker L	332-1436L-AC	DEPO	23169181	GM2550200
Cadillac CTS Sedan, 14-16	Lamp, Side Marker R	332-1436R-AC	DEPO	23169182	GM2551200
Cadillac SRX, 14-16, Halogen	Headlamp Assy, L	20-9144-90-9	TYC Brother	23315408	GM2502432
Cadillac SRX, 14-16, Halogen	Headlamp Assy, R	20-9143-90-9	TYC Brother	23315409	GM2503432
Chevrolet Camaro Convertible/Coupe, 16-17	Lamp, Side Marker L	332-1436L-AC	DEPO	23169181	GM2550200
Chevrolet Camaro Convertible/Coupe, 16-17	Lamp, Side Marker R	332-1436R-AC	DEPO	23169182	GM2551200
Chevrolet Camaro, 16-17	Lamp, Rear Side Marker R	332-1436R-AC-R	DEPO	23126884	GM2860113
Chevrolet Camaro, 16-17	Lamp, Rear Side Marker L	332-1436L-AC-R	DEPO	23126885	GM2861113
Ford Expedition, 15-17, Projector type	Headlamp Assy, R	A30-1170R-AC	DEPO	FL1Z13008C	FO2503334
Ford Expedition, 15-17, Projector type	Headlamp Assy, L	A30-1170L-AC	DEPO	FL1Z13008F	FO2502334
Honda Accord EX/Touring, Sedan, 16-17	Headlamp Assy, R	20-9727-00-9	TYC Brother	33100T2AA81	HO2503169
Honda Accord EX/Touring, Sedan, 16-17	Headlamp Assy, L	20-9728-00-9	TYC Brother	33150T2AA81	HO2502169
Honda Civic Coupe, 14-15	Reflector, Bumper Rear R	327-2907R-UC	DEPO	33505TS8A52	HO1185110
Honda Civic Coupe, 14-15	Reflector, Bumper Rear L	327-2907L-UC	DEPO	33555TS8A52	HO1184110
Honda CR-V, 12-1515	Lamp, Fog R	19-6111-00-9	TYC Brother	33901T1WA11	HO2593140
Honda CR-V, 15	Lamp, Fog L	19-6112-00-9	TYC Brother	33950T1WA11	HO2592140
Honda CR-V, 15-16	Lamp, Fog R	19-6111-00-9	TYC Brother	33900T1WA11	HO2593140
Honda CR-V, 15-16	Lamp, Fog L	19-6112-00-9	TYC Brother	33951T1WA11	HO2592140
Hyundai Elantra Sedan, 17, w/DRL (USA)	Headlamp Assy, L	321-1160L-AC2	DEPO	92101F3010	HY2502210
Hyundai Elantra Sedan, 17, w/DRL (USA)	Headlamp Assy, R	321-1160R-AC2	DEPO	92102F3010	HY2503210
Mercedes-Benz C-Class C300/C350/C400/C63 AMG, 15	Headlamp Assy, L	20-9632-00-9	TYC Brother	2058202761	MB2502220
Mercedes-Benz C-Class C300/C350/C400/C63 AMG, 15	Headlamp Assy, R	20-9631-00-9	TYC Brother	2058202861	MB2503220
Mercedes-Benz C-Class C300/C350/C400/C63 AMG, 15-17	Headlamp Assy, L	20-9632-00-9	TYC Brother	2059067102	MB2502220
Mercedes-Benz C-Class C300/C350/C400/C63 AMG, 15-17	Headlamp Assy, R	20-9631-00-9	TYC Brother	2059067202	MB2503220
Mercedes-Benz E-Class Hybrid Sedan, 14	Taillamp L	340-1914L-AC	DEPO	2129060757	MB2804109
Mercedes-Benz E-Class Hybrid Sedan, 14	Taillamp R	340-1914R-AC	DEPO	2129060857	MB2805109
Mercedes-Benz E-Class Sedan, 14	Taillamp L	340-1914L-AC	DEPO	2129060757	MB2804109
Mercedes-Benz E-Class Sedan, 14	Taillamp R	340-1914R-AC	DEPO	2129060857	MB2805109
Toyota Avalon Hybrid, 13-15, on body	Taillamp R	11-6559-00-9	TYC Brother	8155007070	TO2805117
Toyota Avalon Hybrid, 13-15, on body	Taillamp L	11-6560-00-9	TYC Brother	8156007070	TO2804117
Toyota Avalon, 13-15, on body	Taillamp R	11-6559-00-9	TYC Brother	8155007070	TO2805117
Toyota Avalon, 13-15, on body	Taillamp L	11-6560-00-9	TYC Brother	8156007070	TO2804117

NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Dodge Pickup 1500/2500/3500, 04-06	Bumper, Rear Assembly	CH1103112DSC	PBSI-DS	CH1103112	CH1103112
Dodge Pickup, 02-03, New design	Bumper, Rear Assembly	CH1103108DSC	PBSI-DS	CH1103108	CH1103108
Dodge Pickup, 02-03, New design	Bumper, Rear Assembly	CH1103109DSC	PBSI-DS	CH1103109	CH1103109
Dodge Pickup, 02-09, New design	Bumper, Rear Assembly	CH1102351DSC	PBSI-DS	55077107AN	CH1102351
Dodge Pickup, 04-08	Bumper, Rear Assembly	CH1103111DSC	PBSI-DS	CH1103111	CH1103111
Ford Focus Sedan/Hatchback, 12-16	Reinforcement, Bumper Front	FD44127AH	Hui Yih	CP9Z17757A	FO1006260
Toyota Tacoma, 16-17, w/o Parking Assist, Chrome	Cap, Bumper Rear R	TYS150RFQ	Pro Fortune	5215504020	TO1105131
Toyota Tacoma, 16-17, w/o Parking Assist, Chrome	Cap, Bumper Rear L	TYS150LFQ	Pro Fortune	5215604020	TO1104131
Toyota Tacoma, 16-17, w/Parking Assist, Chrome	Cap, Bumper Rear R	TYS150REQ	Pro Fortune	5215504050	TO1105132
Toyota Tacoma, 16-17, w/Parking Assist, Chrome	Cap, Bumper Rear L	TYS150LEQ	Pro Fortune	5215604050	TO1104132

NEW PARTS CAPA 601 STANDARD - RADIATORS

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Chrysler Sebring Convertible, 01-06	Radiator	CU2323	Spectra Premium	5017619AA	CH3010117
Chrysler Sebring Sedan, 01-06	Radiator	CU2323	Spectra Premium	5017619AA	CH3010117
Chrysler Town & Country, 01-04, w/V6 engine	Radiator	CU2311	Spectra Premium	4809225AG	CH3010306
Dodge Caravan, 01-04, w/V6 engine	Radiator	CU2311	Spectra Premium	4809225AG	CH3010306
Dodge Pickup (New Style), 02-03, 3.7L/4.7L Eng	Radiator	CU2479	Spectra Premium	52028829AF	CH3010280
Dodge Stratus Sedan, 01-06	Radiator	CU2323	Spectra Premium	5017619AA	CH3010117

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
DGDN11HD1	Dodge Durango, 11-12	Hood	Gordon	01/17A	55369453AA	CH1230286
DGDN11HD1	Dodge Durango, 11-14	Hood	Gordon	01/17A	55369453AB	CH1230286
DGDN11HD1	Dodge Durango, 11-16	Hood	Gordon	01/17A	55369453AE	CH1230286
KASL10HD1	Kia Soul, 10-11	Hood	Gordon	04/17A	664002K010	KI1230124

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
BM3300870-210C	BMW 325 Sedan, 02-05, w/o Sport package	Bumper Cover, Rear	AP-Procom	11/16A	51127030591	BM1100134
BM3300870-210C	BMW 330 Sedan, 02-05, w/o Sport package	Bumper Cover, Rear	AP-Procom	11/16A	51127030591	BM1100134
Y-GMBP341CA	Chevrolet Camaro SS Convertible, 10-13, w/o tow hook	Bumper Cover, Front	Y.C.C.	01/17A	92236547	GM1000905
Y-GMBP341CA	Chevrolet Camaro SS Coupe, 10-15, w/o tow hook	Bumper Cover, Front	Y.C.C.	01/17A	92236547	GM1000905
Y-CRBP059CA	Chrysler Town & Country, 11-14, w/o headlamp washer	Bumper Cover, Front	Y.C.C.	05/17A	68088967AA	CH1000990
DG3610000-000C	Dodge Challenger, 08-10	Bumper Cover, Front	AP-Procom	11/16A	68043387AA	CH1000969
DG3610000-000C	Dodge Challenger, 08-10	Bumper Cover, Front	AP-Procom	11/16A	68043387AB	CH1000969
Y-FDBP081CA	Ford Fusion Hybrid, 10-12	Bumper Cover, Rear	Y.C.C.	01/17A	AE5Z17K835AACP	FO1100649
Y-FDBP081CA	Ford Fusion Hybrid, 10-12	Bumper Cover, Rear	Y.C.C.	01/17A	AE5Z17K835AAPTM	FO1100649
Y-FDBP081CA	Ford Fusion, 10-12	Bumper Cover, Rear	Y.C.C.	01/17A	AE5Z17K835AACP	FO1100649
Y-FDBP081CA	Ford Fusion, 10-12	Bumper Cover, Rear	Y.C.C.	01/17A	AE5Z17K835AAPTM	FO1100649
Y-FDBP109CA	Ford Mustang, 13-14	Bumper Cover, Front	Y.C.C.	07/17A	DR3Z17D957ABPTM	FO1000670
FD-04349BBQ	Ford Taurus, 10-12, w/o Push Button Start, w/o Rear Object Sensors	Bumper Cover, Rear	Tong Yang	05/17A	AG1Z17K835LAPTM	FO1100666
FD-04154BBQ	Ford Windstar, 99-03, w/o SE Sport	Bumper Cover, Rear	Tong Yang	08/13A	YF2Z17K835AA	FO1100287
FD-04154BBQ	Ford Windstar, 99-03, w/o SE Sport	Bumper Cover, Rear	Tong Yang	08/13A	YF2Z17K835BA	FO1100287
HD-04249BBQ	Honda Accord Sedan, 13-15	Bumper Cover, Front	Tong Yang	04/17A	04711T2AA90ZZ	HO1000288
Y-HYBP026CA	Hyundai Santa Fe, 13-16	Bumper Cover, Front	Y.C.C.	04/17A	86511B8000	HY1000199
KA-04084BBQ	Kia Rio5, 12-16	Bumper Cover, Front	Tong Yang	06/17A	865111W200	KI1000158

CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
NONE						

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
NONE						

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
GM1103179DSC	Chevrolet Silverado 1500, 14-15, w/Corner step, w/o Sensors, w/o Sensor harness	Bumper, Rear Assembly	PBSI-DS	12/16A	GM1103179	GM1103179
GM1103179DSC	GMC Sierra 1500, w/Corner step, w/o Sensors, w/o Sensor harness	Bumper, Rear Assembly	PBSI-DS	12/16A	GM1103179	GM1103179
TOOA2B030C	Toyota Camry, 02-04, USA built	Bar, Reinforcement	Forerunner	03/17A	52021AA020	TO1006186

CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

DELETED PARTS CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

CORRECTION

The following parts were listed as decertified on the October 16, 2017 Weekly Parts Update.
Upon further review, these parts were not decertified during the period covered by that report.

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
20-6755-00-9	Chevrolet Avalanche, 07-08	Headlamp Assy, R	TYC Brother	11211610	15950808	GM2503263
20-6755-00-9	Chevrolet Avalanche, 07-12	Headlamp Assy, R	TYC Brother	11211610	20760579	GM2503263
20-6755-00-9	Chevrolet Avalanche, 07-13	Headlamp Assy, R	TYC Brother	11211610	22853026	GM2503263
20-6755-00-9	Chevrolet Suburban, 07-08	Headlamp Assy, R	TYC Brother	11211610	15950808	GM2503263
20-6755-00-9	Chevrolet Suburban, 07-12	Headlamp Assy, R	TYC Brother	11211610	20760579	GM2503263
20-6755-00-9	Chevrolet Suburban, 07-14	Headlamp Assy, R	TYC Brother	11211610	22853026	GM2503263
20-6755-00-9	Chevrolet Tahoe Hybrid, 08-09	Headlamp Assy, R	TYC Brother	11211610	15950808	GM2503263
20-6755-00-9	Chevrolet Tahoe Hybrid, 08-12	Headlamp Assy, R	TYC Brother	11211610	20760579	GM2503263
20-6755-00-9	Chevrolet Tahoe Hybrid, 08-13	Headlamp Assy, R	TYC Brother	11211610	22853026	GM2503263
20-6755-00-9	Chevrolet Tahoe, 07-08	Headlamp Assy, R	TYC Brother	11211610	15950808	GM2503263
20-6755-00-9	Chevrolet Tahoe, 07-12	Headlamp Assy, R	TYC Brother	11211610	20760579	GM2503263
20-6755-00-9	Chevrolet Tahoe, 07-14	Headlamp Assy, R	TYC Brother	11211610	22853026	GM2503263
TOEA4B030C	Toyota Sienna, 04-10	Bar, Reinforcement	Forerunner	02/17A	52021AE010	TO1006194

*This report includes all new, decertified and deleted parts from October 30, 2017 through November 3, 2017.

All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org