

**NEW PARTS CAPA 101 STANDARD - METALS**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Chevrolet Camaro, 16-17	Fender R	CVCM16FR1	Gordon	23221296	GM1241399
Chevrolet Camaro, 16-17	Fender L	CVCM16FL1	Gordon	23221297	GM1240399
Kia Sportage, 17	Fender L	KA-10045AQ-LH	Tong Yang	66311D9000	KI1240150
Kia Sportage, 17	Fender R	KA-10045AQ-RH	Tong Yang	66321D9000	KI1241150
Lincoln MKC, 15-17	Radiator Support	LC-03001AQ	Tong Yang	EJ7Z8A284C	FO1225248
Toyota Prius, 16-17	Hood	TY-20250AQ	Tong Yang	5330147110	TO1230241
Volkswagen CC, 13-17	Fender L	CR-906ALQ	Chang Jung	3C8821021	VW1240140
Volkswagen CC, 13-17	Fender R	CR-906ARQ	Chang Jung	3C8821022	VW1241140
Volkswagen Golf Hatchback, 10-14	Support, Hood Lock	V1S60114A	Auto Power	5K0805567A	VW1233100
Volkswagen Golf Wagon, 10-13	Support, Hood Lock	V1S60114A	Auto Power	5K0805567A	VW1233100
Volkswagen Golf, 15-17	Support, Hood Latch	V1S60115A	Auto Power	5G0805567	VW1233105
Volkswagen GTI, 10-14	Support, Hood Lock	V1S60114A	Auto Power	5K0805567A	VW1233100
Volkswagen Jetta Hybrid, 13-16	Support, Center	V1S60118A	Auto Power	5C6805567	VW1233101
Volkswagen Jetta Sedan, 11-17	Support, Center	V1S60118A	Auto Power	5C6805567	VW1233101
Volkswagen Passat CC, 09-12	Fender L	CR-906ALQ	Chang Jung	3C8821021	VW1240140
Volkswagen Passat CC, 09-12	Fender R	CR-906ARQ	Chang Jung	3C8821022	VW1241140
Volvo XC60, 10-16	Fender L	CR-907ALQ	Chang Jung	31217975	VO1240121
Volvo XC60, 10-16	Fender R	CR-907ARQ	Chang Jung	31217976	VO1241121

**NEW PARTS CAPA 201 STANDARD - PLASTICS**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Chevrolet Suburban, 15, w/o Parking aid sensors	Bumper Cover, Front	Y-GMBP365ACA	Y.C.C.	23142975	GM1000973
Chevrolet Suburban, 15, w/Parking aid sensors	Bumper Cover, Front	Y-GMBP365CA	Y.C.C.	23142976	GM1000974
Chevrolet Suburban, 15-17, w/o Parking aid sensors	Bumper Cover, Front	Y-GMBP365ACA	Y.C.C.	23320625	GM1000973
Chevrolet Suburban, 15-17, w/Parking aid sensors	Bumper Cover, Front	Y-GMBP365CA	Y.C.C.	23320623	GM1000974
Chevrolet Tahoe, 15, w/Parking aid sensors	Bumper Cover, Front	Y-GMBP365CA	Y.C.C.	23142976	GM1000974
Chevrolet Tahoe, 15-16, w/o Parking aid sensors	Bumper Cover, Front	Y-GMBP365ACA	Y.C.C.	23142975	GM1000973
Chevrolet Tahoe, 15-17, w/Parking aid sensors	Bumper Cover, Front	Y-GMBP365CA	Y.C.C.	23320623	GM1000974
Ford Edge, 15-17	Bumper Cover, Front Lower	FD-04474BAQ	Tong Yang	FT4Z17D957AA	FO1015117
Ford Mustang Coupe/Convertible, 15-17	Liner, Fender Front R	FDM1014FR-C	Great Bestcam	FR3Z16102A	FO1249165
Ford Mustang Coupe/Convertible, 15-17	Liner, Fender Front L	FDM1014FL-C	Great Bestcam	FR3Z16103A	FO1248165
GMC Sierra, 16-17; 1500	Cover, Tow Hook L	CV05006-1AL	Auto Power	23243484	GM1038192
GMC Sierra, 16-17; 1500	Cover, Tow Hook R	CV05006-1AR	Auto Power	23243485	GM10391922
GMC Sierra, 16-17; 1500	Cover, Tow Hook Opening L	CV05006AL	Auto Power	23243486	GM1038193
GMC Sierra, 16-17; 1500	Cover, Tow Hook Opening R	CV05006AR	Auto Power	23243487	GM1039193
Honda Civic Sedan, 16-17	Bumper Cover, Rear	HD-04314BBQ	Tong Yang	04715TBAA00ZZ	HO1100296
Honda CR-V, 17	Grille	HD46174AH	Hui Yih	71127TLAA00	HO1207112
Hyundai Elantra Sedan, 17, USA built	Cover, Lower	HN-05019VAQ	Tong Yang	86612F3000	HY1195118
Hyundai Genesis, 15	Radiator Support	HN-03031AQ	Tong Yang	64101B1000	HY1225193
Jeep Renegade, 15-16	Bumper Cover, Front Upper	AM-04074BBQ	Tong Yang	5UX70TZZAA	CH1014122
Jeep Renegade, 15-16	Bumper Cover, Front Upper	JP4000000-100C	AP-Procom	5UX70TZZAA	CH1014122
Lexus RX 350, 16-17	Cover, Engine Under, R	LSE011RAQ	Pro Fortune	514410E120	LX1228149
Lexus RX 350, 16-17	Cover, Engine Under, L	LSE011LAQ	Pro Fortune	514430E030	LX1228150
Lexus RX 450h, 16-17	Cover, Engine Under, R	LSE011RAQ	Pro Fortune	514410E120	LX1228149
Lexus RX 450h, 16-17	Cover, Engine Under, L	LSE011LAQ	Pro Fortune	514430E030	LX1228150
Nissan Sentra, 16-17	Bumper Cover, Rear	DS-04412BCQ	Tong Yang	850223YU0J	NI1100312
Nissan Sentra, 16-17, Sport type	Bumper Cover, Rear	DS-04412BDQ	Tong Yang	850223YU4J	NI1100313
Toyota Prius, 16-17	Liner, Fender R	TYP4014ER-C	Great Bestcam	5387547070	TO1249207
Toyota Prius, 16-17	Liner, Fender L	TYP4014EL-C	Great Bestcam	5387647110	TO1248207
Volkswagen Tiguan, 09-11	Grille	VG-07110GAQ	Tong Yang	5N0853651C2ZZ	VW1200152
Volvo V60, 15-16	Bumper Cover, Front Assy	VV-04024BBQ	Tong Yang	39834053	

**NEW PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Ford Super Duty Pickup, 11-16	Liner, Fender R	FDS1014DR-C	Great Bestcam	BC3Z16054B	FO1249156
Ford Super Duty Pickup, 11-16	Liner, Fender L	FDS1014DL-C	Great Bestcam	BC3Z16055A	FO1248156

**NEW PARTS CAPA 301 STANDARD - LIGHTING**

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
BMW X5, 07-10	Reflector, Bumper Rear L	344-2906L-UC	DEPO	63217158949	BM1184106
BMW X5, 07-10	Reflector, Bumper Rear R	344-2906R-UC	DEPO	63217158950	BM1185106
Buick Enclave, 13-17, LED	Lamp, Park L	336-1608L-AC	DEPO	20956919	GM2520195
Buick Enclave, 13-17, LED	Lamp, Park R	336-1608R-AC	DEPO	20956920	GM2521195
Chevrolet Cruze, 11-16	Lamp, Fog R	19-5991-00-9	TYC Brother	95169825	GM2593300
Chevrolet Cruze, 15-16	Lamp, Fog L	19-5992-00-9	TYC Brother	95169824	GM2592300
Chevrolet Cruze, 16-17, on body	Taillamp R	11-6927-00-9	TYC Brother	84078119	GM2805124
Chevrolet Cruze, 16-17, on body	Taillamp L	11-6928-00-9	TYC Brother	84226228	GM2804124
Chevrolet Cruze, 16-18	Taillamp R	11-6927-00-9	TYC Brother	84226227	GM2805124
Chevrolet Cruze, 16-18, on body	Taillamp L	11-6928-00-9	TYC Brother	84078120	GM2804124
Honda HR-V, 16-17	Reflector, Bumper Rear R	317-2916R-UC	DEPO	33505T7SA01	HO1185109
Honda HR-V, 16-17	Reflector, Bumper Rear L	317-2916L-UC	DEPO	33555T7SA01	HO1184109
Hyundai Elantra, 17	Lamp, Back Up L	321-1320L-AC	DEPO	92403F3000	HY2802138
Hyundai Elantra, 17	Lamp, Back Up R	321-1320R-AC	DEPO	92404F3000	HY2803138

**NEW PARTS CAPA 501 STANDARD - BUMPERS**

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Hyundai Elantra Sedan, 11-16	Bar, Impact	HY1006140DSC	PBSI-DS	865303Y600	HY1006140
Kia Sportage, 17	Bracket, Bumper Rear L	KAT233AL	Auto Power	86641D9010	K11166107
Kia Sportage, 17	Bracket, Bumper Rear R	KAT233AR	Auto Power	86642D9010	K11167107
Scion xD, 08-14 (HSS)	Bar, Reinforcement	SC1106106DSC	PBSI-DS	5210552061	SC1106106

**NEW PARTS CAPA 601 STANDARD - RADIATORS**

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
NONE					

**DECERTIFICATIONS**

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

**CAPA 101 STANDARD - METALS**

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
CV-10038AQ-RH	Chevrolet Blazer, 92-94	Fender R	Tong Yang	06/16A	15998378	GM1241133
CV9700150-000C	Chevrolet Colorado, 04-11	Hood	AP	06/17A	88944095	GM1230319
CV-10038AQ-RH	Chevrolet Full Size Pickup C/K, 88-02, (Old Style)	Fender R	Tong Yang	06/16A	15998378	GM1241133
CV-10038AQ-RH	Chevrolet Suburban, 92-00	Fender R	Tong Yang	06/16A	15998378	GM1241133
CV-10038AQ-RH	Chevrolet Tahoe, 95-00	Fender R	Tong Yang	06/16A	15998378	GM1241133
CV9700150-000C	GMC Canyon, 04-11	Hood	AP	06/17A	88944095	GM1230319
CV-10038AQ-RH	GMC Full Size Pickup C/K, 88-02, (Old Style)	Fender R	Tong Yang	06/16A	15998378	GM1241133
CV-10038AQ-RH	GMC Suburban, 92-00	Fender R	Tong Yang	06/16A	15998378	GM1241133
CV-10038AQ-RH	GMC Yukon, 92-99, w/o Denali pkg	Fender R	Tong Yang	06/16A	15998378	GM1241133
KA-03005AQ	Kia Forte Hatchback, 11-13	Radiator Support	Tong Yang	08/16B	641011M000	K11225150
KA-03005AQ	Kia Forte Hatchback, 11-13	Radiator Support	Tong Yang	12/16A	641011M000	K11225150
KA-03005AQ	Kia Forte Koup, 10-13	Radiator Support	Tong Yang	08/16B	641011M000	K11225150
KA-03005AQ	Kia Forte Koup, 10-13	Radiator Support	Tong Yang	12/16A	641011M000	K11225150
KA-03005AQ	Kia Forte Sedan, 10-13	Radiator Support	Tong Yang	08/16B	641011M000	K11225150
KA-03005AQ	Kia Forte Sedan, 10-13	Radiator Support	Tong Yang	12/16A	641011M000	K11225150
TYHN11HD1	Toyota Highlander, 11-13	Hood	Gordon	06/17A	533010E080	TO1230222

**DECERTIFICATIONS**

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

**CAPA 201 STANDARD - PLASTICS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
CLB064NCQ	Chevrolet Cruze, 11-16, w/o RS Pkg, w/o Rear Object Sensor	Bumper Cover, Rear	Pro Fortune	08/17A	95016694	GM1100876
Y-FDBP077CA	Ford Fusion, 08-09, 2.3L eng	Bumper Cover, Rear	Y.C.C.	06/17A	8E5Z17K835GACP	FO1100592
Y-FDBP077CA	Ford Fusion, 08-09, 2.3L eng	Bumper Cover, Rear	Y.C.C.	06/17A	8E5Z17K835GAPTM	FO1100592
Y-HDBP196CA	Honda Accord Crosstour, 13-15	Bumper Cover, Front	Y.C.C.	06/17A	04711TP6A80ZZ	HO1014101
Y-HDBP199ACA	Honda Accord Sedan, 16-17, w/o Parking Sensors	Bumper Cover, Front	Y.C.C.	07/17A	71101T2FA50ZZ	HO1000302
Y-KABP016CA	Kia Optima SX, 12-13, USA built	Bumper Cover, Rear	Y.C.C.	05/17A	866114C200	KI1100172
TY-04349BCQ	Toyota Camry Base/LE/XLE, 10-11 (USA)	Bumper Cover, Front	Tong Yang	05/16B	5211906958	TO1000356
Y-TYBP224CA	Toyota Corolla, 98-02	Bumper Cover, Rear	Y.C.C.	07/17A	5215902903	TO1100185

**CAPA 202 STANDARD - NON-WOVEN FABRICS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

**CAPA 301 STANDARD - LIGHTING**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

**CAPA 501 STANDARD - BUMPERS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

**CAPA 601 STANDARD - RADIATORS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

**DELETED PARTS CAPA 101 STANDARD - METALS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

**DELETED PARTS CAPA 201 STANDARD - PLASTICS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

**DELETED PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					



# WEEKLY PARTS UPDATE

## November 13, 2017

[Report: P6]  
Weekly

### DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

### DELETED PARTS CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

### DELETED PARTS CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

\*This report includes all new, decertified and deleted parts from November 6, 2017 through November 10, 2017.

All CAPA reports including the weekly update are available on the CAPA website at [www.capacertified.org](http://www.capacertified.org).

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at [debbie@capacertified.org](mailto:debbie@capacertified.org)