

NEW PARTS CAPA 101 STANDARD - METALS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Acura TLX, 15-17	Fender L	CR-905ALQ	Chang Jung	60260TZ3A90ZZ	AC1240126
Acural TLX, 15-17	Fender R	CR-905ARQ	Chang Jung	60210TZ3A90ZZ	AC1241126
Chrysler Pacifica Hybrid, 17	Radiator Support	CR-03005AQ	Tong Yang	68292241AB	CH1225287
Chrysler Pacifica, 17	Radiator Support	CR-03005AQ	Tong Yang	68292241AB	CH1225287
Hyundai Tucson, 10-15	Hood	HN5010150-000C	AP	664002S001	HY1230144
Mazda CX-5, 16	Radiator Support	MZS60077A	Auto Power	KA0M53110	MA1225161
Mazda CX-5, 16	Radiator Support	MZS60077A	Auto Power	KD6153110A	MA1225161

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
BMW X5, 14-17; F15	Liner, Fender Front L	BMX5014A0L-C	Great Bestcam	51717290853	BM1248149
BMW X5, 14-17; F15	Liner, Fender Front R	BMX5014A0R-C	Great Bestcam	51717290854	BM1249149
Chevrolet Suburban, 15, w/o Parking aid sensors	Bumper Cover, Front	CVTH015FB1	Gordon	23142975	GM1000973
Chevrolet Suburban, 15, w/Parking aid sensors	Bumper Cover, Front	CVTH015FB2	Gordon	23142976	GM1000974
Chevrolet Suburban, 15-17, w/o Parking aid sensors	Bumper Cover, Front	CVTH015FB1	Gordon	23320625	GM1000973
Chevrolet Suburban, 15-17, w/Parking aid sensors	Bumper Cover, Front	CVTH015FB2	Gordon	23320623	GM1000974
Chevrolet Tahoe, 15, w/Parking aid sensors	Bumper Cover, Front	CVTH015FB2	Gordon	23142976	GM1000974
Chevrolet Tahoe, 15-16, w/o Parking aid sensors	Bumper Cover, Front	CVTH015FB1	Gordon	23142975	GM1000973
Chevrolet Tahoe, 15-17, w/Parking aid sensors	Bumper Cover, Front	CVTH015FB2	Gordon	23320623	GM1000974
Dodge Charger, 15-16, SRT 392, SRT Hellcat Model	Cover, Lower	DGCGR15FV2	Gordon	68225383AB	CH1195115
Dodge Charger, 15-17, R/T Scat Pack Model	Cover, Lower	DGCGR15FV2	Gordon	68225383AB	CH1195115
Dodge Charger, 15-18, Type 2 Daytona, Daytona 392, SRT 392, SRT Hellcat, R/T Scat Pack	Cover, Engine Under Lower	DGE008NAQ	Pro Fortune	68202632AC	CH1228130
Ford Edge Sport, 15, w/o Active park assist, w/Tow hook	Bumper Cover, Rear Lower	FDB132NDQ	Pro Fortune	FT4Z17K835NPTM	FO1115118
Ford Edge Sport, 15-16, w/Active Park Assist	Bumper Cover, Rear Lower	FDB132NHQ	Pro Fortune	FT4Z17K835GPTM	FO1115117
Ford Edge Sport, 15-16, w/Active Park Assist, w/o Tow Hook	Bumper Cover, Rear Lower	FDB132NFQ	Pro Fortune	FT4Z17K835FPTM	FO1115119
Ford Edge Sport, 15-16, w/o Active Park Assist, w/o Tow Hook	Bumper Cover, Rear Lower	FDB132NCQ	Pro Fortune	FT4Z17K835CPTM	FO1115116
Ford Transit Cargo Van, 15-17	Support, Center	FD-03046AQ	Tong Yang	BK3Z8A284C	FO1225246
Ford Transit Passenger Van, 15-17	Support, Center	FD-03046AQ	Tong Yang	BK3Z8A284C	FO1225246
GMC Yukon, 15	Bumper Cover, Front	GMYKN15FB1	Gordon	23142977	GM1000975
GMC Yukon/XL/Denali, 15-17	Bumper Cover, Front	GMYKN15FB1	Gordon	23320621	GM1000975
Honda Accord EX-L, 16-17, Sedan	Bumper Cover, Rear	HD-04305BBQ	Tong Yang	71501T2FA50ZZ	HO1100290
Honda Accord EX/LX, 16-17, Sedan	Bumper Cover, Rear	HD-04305BBQ	Tong Yang	71501T2FA50ZZ	HO1100290
Lexus RX 350, 16-17	Guard, Front Bumper	TY-05102VARQ	Tong Yang	524370E010	LX1047102
Lexus RX 350, 16-17	Guard, Front Bumper	TY-05102VALQ	Tong Yang	524380E010	LX1046102
Lexus RX 450h, 16-17	Guard, Front Bumper	TY-05102VARQ	Tong Yang	524370E010	LX1047102
Lexus RX 450h, 16-17	Guard, Front Bumper	TY-05102VALQ	Tong Yang	524380E010	LX1046102
Mazda 3, 14-17, Hatchback, Mexico Built w/Radar Cruise Control	Radiator Support	MZ-03011EQ	Tong Yang	BNP253110	
Mazda 3, 17-18, Sedan	Radiator Support	MZ-03011EQ	Tong Yang	BNP253110	
Mazda CX-5, 17, Auto Trans w/o Radar Cruise Control	Radiator Support	MZS60077-1A	Auto Power	K15753110	MA1225166
Mazda CX-5, 17, Auto Trans w/Radar Cruise Control	Radiator Support	MZS60077-2A	Auto Power	K12753110	MA1225167
Mini Cooper F55 Hardtop 4 Door, 15-17, Black	Grille, Lower	AT-07028GAQ	Tong Yang	51117301563	MC1036105
Mini Cooper F56 Hardtop HB, 14-17, w/o Chrome trim	Grille, Lower	AT-07028GAQ	Tong Yang	51117301563	MC1036105
Mini Cooper F57 Convertible, 16-17, w/o Chrome trim	Grille, Lower	AT-07028GAQ	Tong Yang	51117301563	MC1036105
Nissan Titan PRO-4X, 08-15	Liner, Fender R	NST1014CR-C	Great Bestcam	63830ZR00A	NI1249151
Nissan Titan PRO-4X, 11-15	Liner, Fender L	NST1014CL-C	Great Bestcam	63831ZR00A	NI248151
Nissan Titan S, 11-15	Liner, Fender R	NST1014BR-C	Great Bestcam	638307S000	NI1251126
Nissan Titan S, 11-15	Liner, Fender L	NST1014BL-C	Great Bestcam	638317S000	NI1250126
Nissan Titan SL/SV, 11-15	Liner, Fender R	NST1014CR-C	Great Bestcam	63830ZR00A	NI1249151
Nissan Titan SL/SV, 11-15	Liner, Fender L	NST1014CL-C	Great Bestcam	63831ZR00A	NI248151
Nissan Titan XE, 04-10	Liner, Fender R	NST1014BR-C	Great Bestcam	638307S000	NI1251126
Nissan Titan XE, 04-10	Liner, Fender L	NST1014BL-C	Great Bestcam	638317S000	NI1250126

NEW PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Kia Soul, 12-13	Liner, Fender L	KAS6014AL-C	Great Bestcam	868112K500	KI1248127
Kia Soul, 12-13	Liner, Fender R	KAS6014AR-C	Great Bestcam	868122K500	KI1249127

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Buick Regal eASSIST, 12-13	Headlamp Assy, R	336-1123R-AC	DEPO	22794766	GM2503353
Buick Regal eASSIST, 12-13	Headlamp Assy, L	336-1123L-AC	DEPO	22794767	GM2502353
Buick Regal, 11-13	Headlamp Assy, R	336-1123R-AC	DEPO	22794766	GM2503353
Buick Regal, 11-13	Headlamp Assy, L	336-1123L-AC	DEPO	22794767	GM2502353
Chevrolet Impala, 15-16	Headlamp Assy, R	20-9455-90-9	TYC Brother	23489574	GM2503417
Chevrolet Impala, 15-16, Halogen	Headlamp Assy, L	20-9456-90-9	TYC Brother	23489573	GM2502417
Chevrolet Impala, 15-17, Halogen	Headlamp Assy, R	20-9455-90-9	TYC Brother	23405239	GM2503417
Chevrolet Impala, 15-17, Halogen	Headlamp Assy, L	20-9456-90-9	TYC Brother	23405242	GM2502417
Ford F150 Pickup, 15-17	Headlamp Assy, R	20-9677-00-9	TYC Brother	FL3Z13008A	FO2503335
Ford F150 Pickup, 15-17	Headlamp Assy, L	20-9678-00-9	TYC Brother	FL3Z13008B	FO2502335
Ford Focus Sedan, 15-17, on luggage lid	Lamp, Back Up R	K30-1310R-AC	DEPO	F1EZ13404A	FO2803110
Ford Focus Sedan, 15-17, on luggage lid	Lamp, Back Up L	K30-1310L-AC	DEPO	F1EZ13405A	FO2802110
Mazda 5, 12-17	Headlamp Assy, R	20-9277-01-9	TYC Brother	CG36510K0E	MA2519139
Mazda 5, 12-17	Headlamp Assy, L	20-9278-01-9	TYC Brother	CG36510L0E	MA2518139
Toyota Tundra, 07-13	Headlamp Assy, R	20-6847-00-9	TYC Brother	811100C051	TO2503171
Toyota Tundra, 07-13	Headlamp Assy, L	20-6848-00-9	TYC Brother	811500C051	TO2502171
Toyota Yaris Hatchback CE/L/LE, 15-17	Headlamp, R	312-11F3R-UC2	DEPO	811300DA70	TO2503226
Toyota Yaris Hatchback CE/L/LE, 15-17	Headlamp, L	312-11F3L-UC2	DEPO	811700DA70	TO2502226

NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Buick Allure, 10	Bracket, Bumper L	BK45119LLH	Hui Yih	22865539	GM1066194
Buick Allure, 10	Bracket, Bumper R	BK45119LRH	Hui Yih	22865540	GM1067194
Buick LaCrosse, 10-16	Bracket, Bumper L	BK45119LLH	Hui Yih	22865539	GM1066194
Buick LaCrosse, 10-16	Bracket, Bumper R	BK45119LRH	Hui Yih	22865540	GM1067194
Buick Regal, 11-17	Bracket, Bumper L	BK45119LLH	Hui Yih	22865539	GM1066194
Buick Regal, 11-17	Bracket, Bumper R	BK45119LRH	Hui Yih	22865540	GM1067194
Chevrolet Malibu, 13-15	Bracket, Bumper L	BK45119LLH	Hui Yih	22865539	GM1066194
Chevrolet Malibu, 13-15	Bracket, Bumper R	BK45119LRH	Hui Yih	22865540	GM1067194
Chevrolet Malibu, 16, Limited	Bracket, Bumper R	BK45119LRH	Hui Yih	22865540	GM1067194
Chevrolet Malibu, 16, Limited	Bracket, Bumper L	BK45119LLH	Hui Yih	22865539	GM1066194
Ford F150 Pickup, 15-16, Chrome, w/o Rear Parking Aid	Bar, Face	FO1102380DSC	PBSI-DS	FL3Z17906A	FO1102380
Ford F150 Pickup, 15-16, Chrome, w/Rear Parking Aid	Bar, Face	FO1102381DSC	PBSI-DS	FL3Z17906B	FO1102381
Ford F150 Pickup, 15-16, w/o Rear Parking Aid	Bar, Face	FO1102382DSC	PBSI-DS	FL3Z17906CPTM	FO1102382
Ford F150 Pickup, 15-16, w/o Rear Parking Aid	Bar, Face	FO1102382DSC	PBSI-DS	FL3Z17906GCP	FO1102382
Ford F150 Pickup, 15-16, w/Rear Parking Aid	Bar, Face	FO1102383DSC	PBSI-DS	FL3Z17906DPTM	FO1102383
Hyundai Santa Fe, 17	Bracket, Bumper L	HNT238AL	Auto Power	86641B8000	HY1166124
Hyundai Santa Fe, 17	Bracket, Bumper R	HNT238AR	Auto Power	86642B8000	HY1167124
Nissan Sentra, 16-17	Absorber, Energy	NS30613Q	Cobra King	850903YU0A	NI1170157
Toyota RAV-4 Hybrid, 16-17	Absorber, Energy	TA5J124Q	Cobra King	526140R070	TO1070207
Toyota RAV-4, 16-17	Absorber, Energy	TA5J124Q	Cobra King	526140R070	TO1070207

NEW PARTS CAPA 601 STANDARD - RADIATORS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
FD9110090-000C	Ford Excursion, 00-05	Radiator Support	AP	10/15A	5C3Z16138AA	FO1225167
WL-372Q	Ford Excursion, 00-05	Radiator Support	William Precision	10/15A	5C3Z16138AA	FO1225167
FD9110090-000C	Ford Excursion, 00-05	Radiator Support	AP	10/15A	6C3Z16138AA	FO1225167
WL-372Q	Ford Excursion, 00-05	Radiator Support	William Precision	10/15A	6C3Z16138AA	FO1225167
FD9110090-000C	Ford F-Series Super Duty Pickup, 99-06	Radiator Support	AP	10/15A	5C3Z16138AA	FO1225167
WL-372Q	Ford F-Series Super Duty Pickup, 99-06	Radiator Support	William Precision	10/15A	5C3Z16138AA	FO1225167
FD9110090-000C	Ford F-Series Super Duty Pickup, 99-07	Radiator Support	AP	10/15A	6C3Z16138AA	FO1225167
WL-372Q	Ford F-Series Super Duty Pickup, 99-07	Radiator Support	William Precision	10/15A	6C3Z16138AA	FO1225167

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
TY-04403BCQ	Toyota Camry L/LE/XLE/Hybrid, 12-14	Bumper Cover, Rear	Tong Yang	05/17A	5215906961	TO1100296
TY-04403BCQ	Toyota Camry L/LE/XLE/Hybrid, 12-14	Bumper Cover, Rear	Tong Yang	11/16B	5215906961	TO1100296

CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
333-1181R-AC	Jeep Wrangler, 07-16	Headlamp Assy, R	DEPO	20130610	55078148AC	CH2503175
333-1181R-AC	Jeep Wrangler, 07-17	Headlamp Assy, R	DEPO	20130610	55078148AD	CH2503175

CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

DELETED PARTS CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
DS-20067AQ	Nissan Altima, 98-01	Hood	Tong Yang	F51009E030	NI1230151

DELETED PARTS CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

**WEEKLY PARTS UPDATE
November 27, 2017**

DELETED PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

*This report includes all new, decertified and deleted parts from November 20, 2017 through November 24, 2017.
 All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.
 If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org