

NEW PARTS CAPA 101 STANDARD - METALS

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Chevrolet Malibu, 16-18	Bar, Lower Tie	CVS60055A	Auto Power	22978216	GM1225333
Chevrolet Silverado 1500, 07-13, w/Locking tailgate, w/Rear view camera	Tailgate	CV-90022BQ	Tong Yang	20885078	GM1900130
Chevrolet Silverado 1500, 16-18	Hood	CVSR16HD1	Gordon	23392664	GM1230452
Chevrolet Silverado 2500 HD/3500 HD, 11-14, w/Locking tailgate, w/Rear view camera	Tailgate	CV-90022BQ	Tong Yang	20885078	GM1900130
GMC Sierra 2500 HD/3500 HD, 11-14, w/Locking tailgate, w/Rear view camera	Tailgate	CV-90022BQ	Tong Yang	20885078	GM1900130
GMC, Acadia, 17-17,	Radiator Support	CVS60235A	Auto Power	23407480	GM1225342
Honda Civic, 17-18, Hatchback	Beam, Bumper	HDA1161A	Auto Power	71150TGGAA00	HO1041108
Honda CR-V, 17	Fender R	HDCR17FR1	Gordon	60211TLAA00ZZ	HO1241193
Honda CR-V, 17	Fender L	HDCR17FL1	Gordon	60261TLAA00ZZ	HO1240193
Lexus NX 200t, 15-16	Fender R	LXNX15FR1	Gordon	5380178010	LX1241137
Lexus NX 200t, 15-16	Fender L	LXNX15FL1	Gordon	5380278010	LX1240137
Lexus NX 200t, 15-17	Fender R	LXNX15FR1	Gordon	5381178010	LX1241137
Lexus NX 200t, 15-17	Fender L	LXNX15FL1	Gordon	5381278010	LX1240137
Lexus NX 300h, 15-16	Fender R	LXNX15FR1	Gordon	5380178010	LX1241137
Lexus NX 300h, 15-16	Fender L	LXNX15FL1	Gordon	5380278010	LX1240137
Lexus NX 300h, 15-17	Fender R	LXNX15FR1	Gordon	5381178010	LX1241137
Lexus NX 300h, 15-17	Fender L	LXNX15FL1	Gordon	5381278010	LX1240137
Ram ProMaster Cargo Van, 14-17	Radiator Support	DG5500-11A-CP	Hong Ling	68100667AC	CH1225269

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
BMW 3-Series, 14-16; Gran Turismo F34	Bumper Cover, Rear	BMF3414RB1	Gordon	51128073074	BM1100329
BMW 3-Series, 14-17; Gran Turismo F34	Bumper Cover, Rear	BMF3414RB2	Gordon	51128073075	BM1100330
BMW X1 (F48), 16-17, w/M Pkg, w/o Park Distance Control	Bumper Cover, Rear	BMB068NCQ	Pro Fortune	51128067668	BM1100360
BMW X1 (F48), 16-18, w/M Pkg, w/Park Distance Control	Bumper Cover, Rear	BMB068NDQ	Pro Fortune	51128072774	BM1100361
Cadillac XTS, 13-17, w/o DRL, w/o PDC, w/o Collision, w/o Steering aid	Bumper Cover, Front	CD34-9909-OSH	Tran Hung	22914022	GM1000936
Chevrolet Cruze, 15, Exc LTZ; Upper; Matte Black; w/Chrome Mldg	Grille, Assy	CV-07307GAQ	Tong Yang	94516092	GM1200725
Chevrolet Cruze, 16, Limited, Exc LTZ; Upper; Matte Black; w/Chrome Mldg	Grille, Assy	CV-07307GAQ	Tong Yang	94516092	GM1200725
Chrysler 200 Convertible, 11-14	Grille, Lower	CS77017Q	Cobra King	68082051AB	CH1036118
Chrysler 200 Sedan, 11-14	Grille, Lower	CS77017Q	Cobra King	68082051AB	CH1036118
Dodge Challenger, 15-18, w/Fog Lamps	Bumper Cover, Front	DG-04143BBQ	Tong Yang	68258730AB	CH1000A20
Ford Focus, 12-14, Electric	Extension, Lower	FD-05126VAQ	Tong Yang	CP9Z17810B	FO1195152
Ford Focus, 12-14, Hatchback, SE, SEL, Titanium Model	Extension, Lower	FD-05126VAQ	Tong Yang	CP9Z17810B	FO1195152
Ford Focus, 12-14; Electric	Deflector, Lower Air	FDE013NAQ	Pro Fortune	CP9Z8310A	FO1228119
Ford Focus, 12-14; Hatchback	Deflector, Lower Air	FDE013NAQ	Pro Fortune	CP9Z8310A	FO1228119
Ford Focus, 12-14; Sedan	Deflector, Lower Air	FDE013NAQ	Pro Fortune	CP9Z8310A	FO1228119
Ford Focus, 15-17; Electric	Deflector, Lower Air	FDE013NAQ	Pro Fortune	CP9Z8310A	FO1228119
Ford Fusion Energi, 17-18	Panel, Front	FDS60075A	Auto Power	HS7Z16138A	FD1225239
Ford Fusion Hybrid, 17-18	Panel, Front	FDS60075A	Auto Power	HS7Z16138A	FD1225239
Ford Fusion, 17-18	Panel, Front	FDS60075A	Auto Power	HS7Z16138A	FD1225239
Ford SE/SEL Edge, 15-16	Bumper Cover, Rear Upper	FD-04484BBQ	Tong Yang	FT4Z17810APTM	FO1114105
Ford Titanium/Sport Edge, 15-16, w/Active Park Assist	Bumper Cover, Rear Upper	FD-04484BDQ	Tong Yang	FT4Z17810GPTM	FO1114106
Ford Titanium/Sport Edge, 15-16, w/o Active Park Assist	Bumper Cover, Rear Upper	FD-04484BBQ	Tong Yang	FT4Z17810APTM	FO1114105
Ford, Edge, 15-17, SE, SEL, Titanium Model	Grille, Center Bumper	FDN109NFQ	Pro Fortune	FT4Z17K945DA	FO1036166
Ford, Edge, 15-17, w/Adaptive Cruise Control w/o Immersion Heater, SE, SEL, Titanium Model	Grille, Center Bumper	FDN109NAQ	Pro Fortune	FT4Z17K945BA	FO1036165
Ford, Edge, 15-17, w/o Adaptive Cruise Control w/Immersion Heater, SE, SEL, Titanium Model	Grille, Center Bumper	FDN108NFQ	Pro Fortune	FT4Z17K945CA	FO1036164
Ford, Edge, 15-17, w/o Adaptive Cruise Control w/o Immersion Heater, SE, SEL, Titanium Model	Grille, Center Bumper	FDN108NAQ	Pro Fortune	FT4Z17K945AA	FO1036163
Honda Accord Sedan, 16-17, w/o Parking Sensors	Bumper Cover, Front	HD2820000-300C	AP-Procom	71101T2FA50ZZ	HO1000302
Honda Accord Sedan, 16-17, w/Parking Sensors	Bumper Cover, Front	HD2820000-200C	AP-Procom	71100T2FA70ZZ	HO1000303
Honda Civic, 09-11, Sedan, USA, Canada Built	Spoiler, Front	HD-07224GAQ	Tong Yang	71107SNEA50	HO1036127
Honda Pilot, 16-17	Liner, Fender R	HDP2014ER-C	Great Bestcam	74101TG7A00	HO1249162
Honda Pilot, 16-17	Liner, Fender L	HDP2014EL-C	Great Bestcam	74151TG7A00	HO1248162
Honda Ridgeline, 17	Liner, Fender R	HDP2014ER-C	Great Bestcam	74101TG7A00	HO1249162
Honda Ridgeline, 17	Liner, Fender L	HDP2014EL-C	Great Bestcam	74151TG7A00	HO1248162
Hyundai Elantra GT, 13-16	Bumper Cover, Front	HN-04159BBQ	Tong Yang	86511A5000	HY1000196

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Hyundai Elantra, 14-16, Sedan, USA Built	Bumper Cover, Rear Lower	HN-05018VAQ	Tong Yang	866123Y700	HY1195119
Hyundai Santa Fe, 17, Sport	Plate, Skid	HN-05023VAQ	Tong Yang	865654Z500	HY1095106
Kia Forte, 17; Sedan	Grille, Bumper	KA-07084GAQ	Tong Yang	86522B0010	KI1036134
Kia Optima Hybrid, 11-13	Liner, Fender Assy L	KII001LBQ	Pro Fortune	868112T100	KI1248134
Kia Optima Hybrid, 11-13	Liner, Fender Assy R	KII001RBQ	Pro Fortune	868122T100	KI1249134
Kia Optima SX, 11-13 (Korea)	Liner, Fender Assy L	KII001LBQ	Pro Fortune	868112T100	KI1248134
Kia Optima SX, 11-13 (Korea)	Liner, Fender Assy R	KII001RBQ	Pro Fortune	868122T100	KI1249134
Kia Sorento, 16-18	Radiator Support	KAS6998A	Auto Power	64101C6000	KI1225173
Kia Soul, 10-11, Type B	Bumper Cover, Rear	Y-KABP018CA	Y.C.C.	866112K050	KI1100149
Lincoln MKX, 11-15, Paint to Match, Thermoplastic	Bumper Cover, Rear Upper	LG-80-849C	CHL	BA1Z17810B	FO1114103
Lincoln MKX, 11-15, Thermoplastic	Bumper Cover, Rear Upper	LG-80-849C	CHL	BA1Z17810B	FO1114103
Lincoln MKX, 11-15, Thermoplastic, Paint to Match	Bumper Cover, Rear Upper	LG-80-849C	CHL	BA1Z17810BPTM	FO1114103
Mercedes-Benz GL-Class GL350 Blutec/GL450/GL550, 13-16, w/o AMG styling, w/o Parktronic	Bumper Cover, Front	BZ-04178BBQ	Tong Yang	16688527259999	MB1000523
Nissan Altima, 07-11; Hybrid	Bracket, Bumper Side R	NS55617RQ	Cobra King	85220JA01A	NI1167107
Nissan Altima, 07-11; Hybrid	Bracket, Bumper Side L	NS55617LQ	Cobra King	85221JA01A	NI1166107
Nissan Altima, 07-12; Sedan	Bracket, Bumper Side R	NS55617RQ	Cobra King	85220JA01A	NI1167107
Nissan Altima, 07-12; Sedan	Bracket, Bumper Side L	NS55617LQ	Cobra King	85221JA01A	NI1166107
Nissan Versa Note, 14-17	Cover, Engine Under Front	NSE024NAQ	Pro Fortune	626603VY0A	NI1228153
Ram Promaster City Cargo Van, 15-16	Bumper Cover, Front	FT-04074BCQ	Tong Yang	5YH04TZZAA	CH1000A30
Ram Promaster City Passenger Van, 15-16	Bumper Cover, Front	FT-04074BCQ	Tong Yang	5YH04TZZAA	CH1000A30
Toyota Prius, 16-17, C	Cover, Engine Under, R	TYE043RAQ	Pro Fortune	5144152310	TO1228221
Toyota Prius, 16-17, C	Cover, Engine Under, L	TYE043LAQ	Pro Fortune	5144252150	TO1228222
Toyota Prius, 16-17, C	Cover, Engine Under Front	TYE043NAQ	Pro Fortune	5145152031	TO1228223
Toyota Prius, 16-18, 17" Wheels	Cover, Outer R	TY-04586PBRQ	Tong Yang	5256547901	
Toyota Prius, 16-18, 17" Wheels	Cover, Outer L	TY-04586PBLQ	Tong Yang	5256647901	TO1104134
Toyota RAV-4 LE+/XLE/Limited, 16-17, No. 2	Grille, Lower Cover	TY-07646GAQ	Tong Yang	531130R060	TO1036166
Toyota RAV-4 LE/XLE/Limited/Platinum, 16-17, No. 2	Grille, Lower Cover	TY-07646GAQ	Tong Yang	531130R060	TO1036166
Toyota Sienna, 17, 2017 FWD SE Model	Cover, Engine Under Front	TYE047NAQ	Pro Fortune	5144108060	TO1228218
Toyota Sienna, 17, FWD Base, L, LE, XLE, Limited Model	Cover, Engine Under Front	TYE046NAQ	Pro Fortune	5144108050	TO1228217

NEW PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Chevrolet Suburban X88, 15-17, w/o off Road Pkg	Liner, Fender L	CVT2014BL-C	Great Bestcam	22806316	GM1248268
Chevrolet Suburban X88,15-17, w/o Off Road Pkg	Liner, Fender R	CVT2014BR-C	Great Bestcam	22806317	GM1249268
Chevrolet Tahoe, 15-17, X88, w/o Off Road Pkg, MAT, PP/Vacuum Form, OEM, PET/Thermo Form	Liner, Fender L	CVT2014BL-C	Great Bestcam	22806316	GM1248268
Chevrolet Tahoe, 15-17, X88, w/o Off Road Pkg, MAT, PP/Vacuum Form, OEM, PET/Thermo Form	Liner, Fender R	CVT2014BR-C	Great Bestcam	22806317	GM1249268

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Buick Enclave, 13-17	Reflector, Bumper Rear R	336-2902R-UC	DEPO	22870716	GM1185114
Buick Enclave, 13-17	Reflector, Bumper Rear L	336-2902L-UC	DEPO	22870717	GM1184114
Ford Super Duty Pickup, 11-16	Headlamp Assy, R	20-14147-00-9	TYC Brother	BC3Z13008E	FO2503290
Ford Super Duty Pickup, 11-16	Headlamp Assy, L	20-14148-00-9	TYC Brother	BC3Z13008F	FO2502290
Hyundai Elantra Sedan, 17, HID	Headlamp Assy, L	321-1160L-ACN2	DEPO	92101F2300	HY2502207
Hyundai Elantra Sedan, 17, HID	Headlamp Assy, R	321-1160R-ACN2	DEPO	92102F2300	HY2503207
Hyundai Elantra Sedan, 17-18, w/o Daytime Running Lamps USA Built	Headlamp Assy, L	321-1160L-ACN2	DEPO	92101F3000	HY2502206
Hyundai Elantra Sedan, 17-18, w/o Daytime Running Lamps USA Built	Headlamp Assy, R	321-1160R-ACN2	DEPO	92102F3000	HY2503206
Hyundai Elantra Sedan, 17-18, w/o DRL (Korea)	Headlamp Assy, L	321-1160L-ACD2	DEPO	92101F2040	HY2502203
Hyundai Elantra Sedan, 17-18, w/o DRL (Korea)	Headlamp Assy, R	321-1160R-ACD2	DEPO	92102F2040	HY2503203
Jeep Cherokee, 14-17, on body	Taillamp R	333-1966R-AC	DEPO	68102906AF	CH2805107
Jeep Cherokee, 14-17, on body	Taillamp L	333-1966L-AC	DEPO	68102907AF	CH2804107
Mazda CX-5, 13-15	Headlamp Assy, R	20-9309-01-9	TYC Brother	KD3151031D	MA2519146
Mazda CX-5, 13-15	Headlamp Assy, L	20-9310-01-9	TYC Brother	KD3151041D	MA2518146
Mazda CX-5, 13-16	Headlamp Assy, R	20-9309-01-9	TYC Brother	KJ0151031	MA2519146
Mazda CX-5, 13-16	Headlamp Assy, R	20-9309-01-9	TYC Brother	KJ0151031C	MA2519146
Mazda CX-5, 13-16	Headlamp Assy, L	20-9310-01-9	TYC Brother	KJ0151041	MA2518146

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Mazda CX-5, 13-16	Headlamp Assy, L	20-9310-01-9	TYC Brother	KJ0151041C	MA2518146
Mercedes-Benz CLA-Class, 14-17	Headlamp Assy, L	340-1142L-AC2	DEPO	1178200261	MB2502222
Mercedes-Benz CLA-Class, 14-17	Headlamp Assy, R	340-1142R-AC2	DEPO	1178204561	MB2503222
Scion iA, 16	Reflector, Bumper Rear R	328-2902R-UC	DEPO	52163WB002	TO1185109
Scion iA, 16	Reflector, Bumper Rear L	328-2902L-UC	DEPO	52164WB002	TO1184109

NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Ford Escape, 13-17, w/o Towing Pkg (UHSS)	Reinforcement, Bumper Rear	FO1106366DSC	PBSI-DS	CJ5Z17906A	FO1106366

NEW PARTS CAPA 601 STANDARD - RADIATORS

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
NONE					

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
FD-03031AQ	Ford Focus Sedan/Hatchback, 12-14	Radiator Support	Tong Yang 09/17A	CP9Z8A284A	FO1225214
FD-03031AQ	Ford Focus Sedan/Hatchback, 12-14	Radiator Support	Tong Yang 11/16A	CP9Z8A284A	FO1225214
FD-03031AQ	Ford Focus Sedan/Hatchback, 12-16	Radiator Support	Tong Yang 09/17A	CM5Z8A284A	FO1225214
FD-03031AQ	Ford Focus Sedan/Hatchback, 12-16	Radiator Support	Tong Yang 11/16A	CM5Z8A284A	FO1225214
HDCV12FR1	Honda Civic Coupe, 12-13	Fender R	Gordon 09/16A	60211TR6305ZZ	HO1241181
HDCV12FR1	Honda Civic Hybrid, 12-14	Fender R	Gordon 09/16A	60211TR6305ZZ	HO1241181
HDCV12FR1	Honda Civic Sedan, 12-15	Fender R	Gordon 09/16A	60211TR6305ZZ	HO1241181
HDCV12FR1	Honda Civic, 12-13	Fender R	Gordon 09/16A	60211TR0A90ZZ	HO1241181
HDCV12FR1	Honda Civic, 12-14	Fender R	Gordon 09/16A	60211TR6999ZZ	HO1241181

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
HDB083NBQ	Honda Civic Hybrid, 06-08	Bumper Cover, Front	Pro Fortune 01/16A	04711SNEA90ZZ	HO1000239
HDB083NBQ	Honda Civic Sedan, 06-08, 1.8L eng	Bumper Cover, Front	Pro Fortune 01/16A	04711SNEA90ZZ	HO1000239
TY-04238BEQ	Lexus RX 350, 07-09, w/o laser cruise control w/H/Lamp washer cover assy	Bumper Cover, Front	Tong Yang 04/15A	5211948935	LX1000198
LSB018NCQ	Lexus RX 350, 10-15, w/Parking Sensors	Bumper Cover, Rear	Pro Fortune 11/17A	521050E903	LX1100143
LSB037NDQ	Lexus RX 350, 13-15, w/o F Sport pkg	Bumper Cover, Front	Pro Fortune 11/16A	521190E916	LX1000248
LSB018NCQ	Lexus RX 450h, 10-15, w/Parking Sensors	Bumper Cover, Rear	Pro Fortune 11/17A	521050E903	LX1100143
LSB037NDQ	Lexus RX 450h, 13-15, w/o F Sport pkg, w/Parking assist	Bumper Cover, Front	Pro Fortune 11/16A	521190E916	LX1000248

CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
NONE					

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer</u> <u>Number</u>	<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Lot</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
NONE					

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

DELETED PARTS CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
S0141F100BS	Eagle Talon, 95-96, w/o Turbo	Fender L	Jui Li	MB959373	MI1240132
S0141F100AS	Eagle Talon, 95-96, w/Turbo	Fender L	Jui Li	MB959375	MI1240131
S0141F200AS	Eagle Talon, 95-96, w/Turbo	Fender R	Jui Li	MB959376	MI1241131
S0141F200BS	Eagle Talon, 95-98, w/o Turbo	Fender R	Jui Li	MB959374	MI1241132
S0141F100BS	Eagle Talon, 97-98	Fender L	Jui Li	MB959373	MI1240132
S0141F200BS	Eagle Talon, 97-98, w/Turbo	Fender R	Jui Li	MB959374	MI1241132
S0141F100BS	Mitsubishi Eclipse, 95-99, w/o side air dam	Fender L	Jui Li	MB959373	MI1240132
S0141F200BS	Mitsubishi Eclipse, 95-99, w/o side air dam	Fender R	Jui Li	MB959374	MI1241132
S0141F100AS	Mitsubishi Eclipse, 95-99, w/side air dam	Fender L	Jui Li	MB959375	MI1240131
S0141F200AS	Mitsubishi Eclipse, 95-99, w/side air dam	Fender R	Jui Li	MB959376	MI1241131
S0091F200AS	Nissan Altima, 93-97	Fender R	Jui Li	F31009B030	NI1241146
S0091F100AS	Nissan Altima, 93-97	Fender L	Jui Li	F31019B030	NI1240141
S0165H000AS	Toyota Camry, 92-96	Hood	Jui Li	5330106900	TO1230105
TY3600150-000C	Toyota Camry, 92-96	Hood	AP	5330106900	TO1230105

DELETED PARTS CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

*This report includes all new, decertified and deleted parts from February 5, 2018 through February 9, 2018.

All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org