

NEW PARTS CAPA 101 STANDARD - METALS

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Chrysler 200 Sedan, 15-16	Bracket, Support	CRS60086A	Auto Power	68247600AA	CH1222102
Chrysler 200 Sedan, 15-17	Bracket, Support	CRS60086A	Auto Power	68376692AA	CH1222102

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Cadillac XTS, 13, w/DRL, w/PDC, w/Collision, w/o Steering aid	Bumper Cover, Front	CDB025NCQ	Pro Fortune	22914024	GM1000937
Cadillac XTS, 13-17, w/o DRL, w/o PDC, w/o Collision, w/o Steering aid	Bumper Cover, Front	CDB025NEQ	Pro Fortune	22914022	GM1000936
Ford Pickup, 11-14	Deflector, Upper Air	FD7E099BQ	Cobra King	BL3Z19E525A	FO1224122
Honda CR-V, 17	Cover, Side R	HDS120RBQ	Pro Fortune	04712TLAA00ZZ	HO1117104
Honda CR-V, 17	Cover, Side L	HDS120LBQ	Pro Fortune	04717TLAA00ZZ	HO1116104
Hyundai Elantra Sedan, 17	Bumper Cover, Front	HY1000215	Micro Rim	86510F3000	HY1000215
Kia Forte; Sedan, 17-17	Radiator Support	KA-03029AQ	Tong Yang	64101B0000	KI1225183
Kia Forte5, 17, 1.6L Turbo Eng	Radiator Support	KA-03029AQ	Tong Yang	64101B0000	KI1225183
Kia Optima, 14-15, Korea Built	Liner, Fender Assy L	KII003LBQ	Pro Fortune	868112T500	KI1248132
Kia Optima, 14-15, Korea Built	Liner, Fender Assy R	KII003RBQ	Pro Fortune	868122T500	KI1249132
Kia Optima, 16-18, w/ Park Assist System (USA Built)	Bumper Cover, Rear	KA3530870-000C	AP-Procom	86610D5020	KI1100205
Kia Optima, 16-18, w/o Park Assist System (USA Built)	Bumper Cover, Rear	KA3530870-100C	AP-Procom	86611D5000	KI1100204
Nissan Rogue, 17, Korea Built	Grille, Bumper	DS16-9706	Tran Hung	622546FL0A	NI1036108
Nissan Rogue, 17, USA Built, Japan Built	Grille, Bumper	DS16-9706	Tran Hung	622546FL0A	NI1036108
Nissan Rogue, 17, Hybrid	Grille, Bumper	DS16-9706	Tran Hung	622546FL0A	NI1036108
Volkswagen CC, 13-17, 2.0L Eng	Cover, Engine Under Lower	VGE004NAQ	Pro Fortune	3C8825235	VW1228114
Volkswagen Passat CC, 09-12, 2.0L Eng	Cover, Engine Under Lower	VGE004NAQ	Pro Fortune	3C8825235	VW1228114
Volkswagen Passat, 06-10, 2.0L Eng	Cover, Engine Under Lower	VGE004NAQ	Pro Fortune	3C8825235	VW1228114

NEW PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
NONE					

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Hyundai Elantra Sedan, 17-18, w/DRL (Korea)	Headlamp Assy, R	321-1160R-ACB2	DEPO	92102F2050	HY2503204
Hyundai Elantra Sedan, 17-18, w/DRL (Korea)	Headlamp Assy, L	321-1160L-ACB2	DEPO	92101F2050	HY2502204

NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
Chevrolet Suburban, 00-06	Bumper, Rear Face Bar	GM1102384DSC	PBSI-DS	19121287	GM1102384
Chevrolet Tahoe, 01-06	Bumper, Rear Face Bar	GM1102384DSC	PBSI-DS	19121287	GM1102384
GMC Yukon XL 1500, 00-06	Bumper, Rear Face Bar	GM1102384DSC	PBSI-DS	19121287	GM1102384
GMC Yukon, 01-06	Bumper, Rear Face Bar	GM1102384DSC	PBSI-DS	19121287	GM1102384
Toyota Tacoma, 07-11	Bar, Reinforcement	TYR2237-1A	Auto Power	5213104010	TO1025102

NEW PARTS CAPA 601 STANDARD - RADIATORS

<u>Application</u> <u>Description</u>	<u>Part</u> <u>Description</u>	<u>Manufacturer</u> <u>Number</u>	<u>Manufacturer</u> <u>Number</u>	<u>OEM</u> <u>Number</u>	<u>PartsLink</u> <u>Number</u>
NONE					

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
DJ-FT09401	Honda Fit, 09, Sayama Built	Hood	Da Juane	02/17A	60100TK6A91ZZ	HO1230159
DJ-FT09401	Honda Fit, 09, Suzuka Built from VIN 9S005261	Hood	Da Juane	02/17A	60100TK6A91ZZ	HO1230159
DJ-FT09401	Honda Fit, 09, Suzuka Built, to VIN 9S005260	Hood	Da Juane	02/17A	60100TK6305ZZ	HO1230159
DJ-FT09401	Honda Fit, 09-14, Suzuka Built, to VIN 9S005260	Hood	Da Juane	02/17A	60100TK6A92ZZ	HO1230159
DJ-FT09401	Honda Fit, 10-13	Hood	Da Juane	02/17A	60100TK6A91ZZ	HO1230159
HN-03012AQ	Hyundai Elantra Sedan, 14-16, Korea built, From 11-1-13	Radiator Support	Tong Yang	05/17A	641013X003	HY1225180
HN-03012AQ	Hyundai Elantra, 10-13	Radiator Support	Tong Yang	05/17A	641013X000	HY1225169

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
HD-04117BBQ	Honda Accord Hybrid, 05	Bumper Cover, Rear	Tong Yang	10/17A	04715SDAA90ZZ	HO1100208
HD-04117BBQ	Honda Accord Sedan, 03-05	Bumper Cover, Rear	Tong Yang	10/17A	04715SDAA90ZZ	HO1100208
TY-04518BBQ	Toyota FJ Cruiser, 07-10, w/Rear Object Sensors	Bumper Cover, Rear	Tong Yang	06/17A	5215935220	TO1100250
TY-04399BBQ	Toyota Yaris Hatchback, 09-11	Bumper Cover, Front	Tong Yang	02/17B	5211952961	TO1000352

CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

DELETED PARTS CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

*This report includes all new, decertified and deleted parts from February 19, 2018 through February 23, 2018.
 All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.
 If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org