

NEW PARTS CAPA 101 STANDARD - METALS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Acura TLX, 15-17	Hood	HD9F001Q	Cobra King	60100TZ3A90ZZ	AC1230128
Ford Ranger, 12	Fender R	FD-10211AQ-RH	Tong Yang	AB392116015AE	
Ford Ranger, 12	Fender L	FD-10211AQ-LH	Tong Yang	AB392116016BA	
Honda Civic Hatchback, 17-18	Hood	HD-20117BQ	Tong Yang	60100TGGAA00ZZ	HO1230188
Hyundai Elantra Sedan, 17	Hood	S1269H000AS	Jui Li	66400F3000	HY1230168
Mercedes-Benz GLE-Coupe, 16-17; 292	Hood	BZ4A001Q	Cobra King	2928800057	MB1230145
Mercedes-Benz GLE-SUV, 16-17; 166	Hood	BZ4A001Q	Cobra King	2928800057	MB1230145

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Acura MDX, 14-17	Cover, Engine Under	HDE014NAQ	Pro Fortune	74111TZ5A00	AC1228117
Acura MDX, 17, Sport Hybrid	Cover, Engine Under	HDE014NAQ	Pro Fortune	74111TZ5A00	AC1228117
BMW X5 F15, 14-16	Fender L	BM33-4112-LH	Tran Hung	51657373541	BM1240157
BMW X5 F15, 14-16	Fender R	BM33-4112-RH	Tran Hung	51657373542	BM1241157
Chevrolet Silverado, 15-17, 2500 HD	Radiator Support	CVS60071A	Auto Power	23379154	GM1225365
Chevrolet Silverado, 15-17, 3500 HD	Radiator Support	CVS60071A	Auto Power	23379154	GM1225365
Ford Focus Sedan, 15-16	Bumper Cover, Rear	FD0630870-900C	AP-Procom	F1EZ17906DAPTM	FO1100713
GMC Acadia, 13-17	Liner, Fender Front R	CLI015RAQ	Pro Fortune	25849007	GM1249207
GMC Acadia, 13-17	Liner, Fender Front L	CLI015LAQ	Pro Fortune	25849011	GM1248207
GMC Sierra, 15-17, 2500 HD	Radiator Support	CVS60071A	Auto Power	23379154	GM1225365
GMC Sierra, 15-17, 3500 HD	Radiator Support	CVS60071A	Auto Power	23379154	GM1225365
Honda Pilot, 16-17	Cover, Engine Under	HDE014NAQ	Pro Fortune	74111TZ5A00	AC1228117
Honda Ridgeline, 17	Cover, Engine Under	HDE014NAQ	Pro Fortune	74111TZ5A00	AC1228117
Hyundai Accent Sedan, 14-17	Liner, Fender L	HYI005LAQ	Pro Fortune	868111R010	HY1248136
Hyundai Accent Sedan, 14-17	Liner, Fender R	HYI005RAQ	Pro Fortune	868121R010	HY1249136
Hyundai Accent, 13, Hatchback, 2013 From 6-10-13	Liner, Fender R	HYI005RAQ	Pro Fortune	868121R010	HY1249136
Hyundai Accent, 13-13, Hatchback, 2013 From 6-10-13	Liner, Fender L	HYI005LAQ	Pro Fortune	868111R010	HY1248136
Hyundai Accent, 13-14, Sedan, 2014 From 6-10-13	Liner, Fender L	HYI005LAQ	Pro Fortune	868111R010	HY1248136
Hyundai Accent, 13-14, Sedan, 2014 From 6-10-13	Liner, Fender R	HYI005RAQ	Pro Fortune	868121R010	HY1249136
Hyundai Accent, 14-17, Hatchback	Liner, Fender L	HYI005LAQ	Pro Fortune	868111R010	HY1248136
Hyundai Accent, 14-17, Hatchback	Liner, Fender R	HYI005RAQ	Pro Fortune	868121R010	HY1249136
Infiniti QX60, 16-17, Premium/Comfort Model	Bumper Cover, Front	LG-70-216C	CHL	620229NC3H	IN1000287
Infiniti QX60, 16-18	Bumper Cover, Front	LG-70-219C	CHL	620229NC0H	IN1000273
Infiniti QX60, 16-18	Bumper Cover, Front	LG-70-217C	CHL	620229NC1H	IN1000274
Infiniti QX60, 16-18, Base Model	Bumper Cover, Front	LG-70-218C	CHL	620229NC2H	IN1000286
Infiniti QX60, 16-18, Hybrid	Bumper Cover, Front	LG-70-219C	CHL	620229NC0H	IN1000273
Infiniti QX60, 16-18, Hybrid	Bumper Cover, Front	LG-70-217C	CHL	620229NC1H	IN1000274
Kia Optima, 16-18	Radiator Support	KAS60065A	Auto Power	64101D5000	KI1225180
Mercedes-Benz GLA-Class GLA250 (156), 15-17	Grille, Radiator	BZ-07156GAQ	Tong Yang	1568801200	MB1200188
Mitsubishi Outlander Sport, 16-17,	Bumper Cover, Front	MB14-9927	Tran Hung	6400H486	MI1000343
Nissan Maxima, 16-18	Liner, Fender Front R	NSM1014ER-C	Great Bestcam	638404RA1D	NI1249154
Nissan Maxima, 16-18	Liner, Fender Front L	NSM1014EL-C	Great Bestcam	638434RA1D	NI1248154
Saturn Outlook, 07-10	Liner, Fender Front R	CLI015RAQ	Pro Fortune	25849007	GM1249207
Saturn Outlook, 07-10	Liner, Fender Front L	CLI015LAQ	Pro Fortune	25849011	GM1248207
Toyota Avalon Hybrid, 13-15	Grille	TYN128NBQ	Pro Fortune	5310207011	TO1036146
Toyota Avalon, 13-15	Grille	TYN128NBQ	Pro Fortune	5310207011	TO1036146
Toyota RAV-4, 17-18, w/o Parking Sensors, Matte Black, Paint to Match, North America Built	Bumper Cover, Rear	TYB166NCQ	Pro Fortune	521690R900	TO1115112
Toyota RAV-4, 17-18, w/Parking Sensors, Matte Black, Paint to Match, North America Built	Bumper Cover, Rear	TYB166NDQ	Pro Fortune	521690R901	TO1115113
Toyota Scion xD, 08-14, Paint to Match	Bumper Cover, Front	LG-70-067C	CHL	5211952945	SC1000106
Toyota, C-HR, 18-18,	Bumper Cover, Rear Lower	TY5150810-000C	AP-Procom	52453F4010	TO1115111

NEW PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Acura TLX, 15-17	Lamp, Fog R	327-2009R-AC	DEPO	33900TZ3H01	AC2593113
Acura TLX, 15-17	Lamp, Fog L	327-2009L-AC	DEPO	33950TZ3H01	AC2592113
Ram ProMaster Cargo Van, 14-17	Reflector, Bumper Rear	334-2903N-UC	DEPO	68098863AA	CH1184101
Ram ProMaster Cargo Van, 14-17, w/DRL	Headlamp, R	334-1138R-ACN2	DEPO	68154588AF	CH2503291
Ram ProMaster Cargo Van, 14-17, w/DRL	Headlamp, R	334-1138R-ACN2	DEPO	68154588AG	CH2503291
Ram ProMaster Cargo Van, 14-17, w/DRL	Headlamp, R	334-1138R-ACN2	DEPO	68154588AH	CH2503291
Ram ProMaster Cargo Van, 14-17, w/DRL	Headlamp, L	334-1138L-ACN2	DEPO	68154589AF	CH2502291
Ram ProMaster Cargo Van, 14-17, w/DRL	Headlamp, L	334-1138L-ACN2	DEPO	68154589AG	CH2502291
Ram ProMaster Cargo Van, 14-17, w/DRL	Headlamp, L	334-1138L-ACN2	DEPO	68154589AH	CH2502291
Ram ProMaster Cargo Van, 14-18, w/DRL	Headlamp, R	334-1138R-ACN2	DEPO	68154588AI	CH2503291
Ram ProMaster Cargo Van, 14-18, w/DRL	Headlamp, L	334-1138L-ACN2	DEPO	68154589AI	CH2502291
Subaru WRX, 15-18	Lamp, Signal R	12-5355-01-9	TYC Brother	84912VA120	SU2533100
Subaru WRX, 15-18	Lamp, Signal L	12-5356-01-9	TYC Brother	84912VA130	SU2532100

NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Cadillac CT6, 16-18	Bar, Reinforcement	CDR3486A	Auto Power	84188268	GM1006694
Chevrolet Camaro, 16-17, Coupe	Reinforcement, Bumper Front	CVR3479A	Auto Power	23388456	GM1006691
Chevrolet Express Van, 03-14, 1500, 2WD	Bracket, Bumper L	CV43035ALH	Hui Yih	15753329	GM1066157
Chevrolet Express Van, 03-14, 1500, 2WD	Bracket, Bumper R	CV43035ARH	Hui Yih	15753330	GM1067157
Chevrolet Express Van, 03-14, 1500, AWD	Bracket, Bumper L	CV43035ALH	Hui Yih	15753329	GM1066157
Chevrolet Express Van, 03-14, 1500, AWD	Bracket, Bumper R	CV43035ARH	Hui Yih	15753330	GM1067157
Chevrolet Express Van, 03-14, 3500, AWD	Bracket, Bumper L	CV43035ALH	Hui Yih	15753329	GM1066157
Chevrolet Express Van, 03-14, 3500, AWD	Bracket, Bumper R	CV43035ARH	Hui Yih	15753330	GM1067157
Chevrolet Express Van, 03-17, 2500, 2WD, w/7300LB GVW	Bracket, Bumper L	CV43035ALH	Hui Yih	15753329	GM1066157
Chevrolet Express Van, 03-17, 2500, 2WD, w/7500LB GVW	Bracket, Bumper R	CV43035ARH	Hui Yih	15753330	GM1067157
Chevrolet Malibu Hybrid, 08-10	Reinf., Bumper Rear	SNR3294A	Auto Power	20895999	GM1106670
Chevrolet Malibu, 08-12	Reinf., Bumper Rear	SNR3294A	Auto Power	20895999	GM1106670
GMC Savana, 03-14, 1500, 2WD	Bracket, Bumper L	CV43035ALH	Hui Yih	15753329	GM1066157
GMC Savana, 03-14, 1500, 2WD	Bracket, Bumper R	CV43035ARH	Hui Yih	15753330	GM1067157
GMC Savana, 03-14, 1500, AWD	Bracket, Bumper L	CV43035ALH	Hui Yih	15753329	GM1066157
GMC Savana, 03-14, 1500, AWD	Bracket, Bumper R	CV43035ARH	Hui Yih	15753330	GM1067157
GMC Savana, 03-17, 2500, 2WD, w/7300LB, GVW	Bracket, Bumper L	CV43035ALH	Hui Yih	15753329	GM1066157
GMC Savana, 03-17, 2500, 2WD, w/7500LB GVW	Bracket, Bumper R	CV43035ARH	Hui Yih	15753330	GM1067157
GMC Sierra 1500, 14-15	Bracket, Bumper L	GC44141ALH	Hui Yih	22902345	GM1062109
GMC Sierra 1500, 14-15	Bracket, Bumper R	GC44141ARH	Hui Yih	22902346	GM1063109
Nissan Sentra, 13-18, 1.8 Eng	Bracket, Front Bumper L	DS45139ALH	Hui Yih	G51153SHMA	NI1066143
Saturn Aura Hybrid, 07-09	Reinf., Bumper Rear	SNR3294A	Auto Power	20895999	GM1106670
Saturn Aura, 07-10	Reinf., Bumper Rear	SNR3294A	Auto Power	20895999	GM1106670
Toyota Tundra, 14-15, w/o Towing Pkg, w/o Towing Hitch, w/o Parking Assist, Chrome	Bumper, Rear Assembly	TY50145AH	Hui Yih	TO1103119	TO1103119
Toyota Tundra, 14-17, w/o Towing pkg, w/o Towing hitch, w/Parking assist, Chrome	Bumper, Rear Assembly	TY50145BH	Hui Yih	TO1103120	TO1103120
Toyota Tundra, 14-18, Chrome, w/o Parking assist	End Cap, Bumper R	TYB7101AR	Auto Power	521120C040	TO1005184
Toyota Tundra, 14-18, Chrome, w/o Parking assist	End Cap, Bumper L	TYB7101AL	Auto Power	521130C040	TO1004184
Toyota Tundra, 14-18, Chrome, w/Parking assist	End Cap, Bumper L	TYB7101-1AL	Auto Power	521130C050	TO1004185

NEW PARTS CAPA 601 STANDARD - RADIATORS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
CV-20092AQ	GMC Sierra 1500 Hybrid, 09	Hood	Tong Yang	09/17A	25786290	GM1230359
CV-20092AQ	GMC Sierra 1500 Hybrid, 09-10	Hood	Tong Yang	09/17A	25848847	GM1230359
CV-20092AQ	GMC Sierra 1500 Hybrid, 09-11	Hood	Tong Yang	09/17A	20863104	GM1230359
CV-20092AQ	GMC Sierra, 07-09	Hood	Tong Yang	09/17A	25786290	GM1230359
CV-20092AQ	GMC Sierra, 07-10	Hood	Tong Yang	09/17A	25848847	GM1230359
CV-20092AQ	GMC Sierra, 07-11	Hood	Tong Yang	09/17A	20863104	GM1230359

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
HD-04173BBQ	Acura MDX, 04-06	Bumper Cover, Front	Tong Yang	11/17A	04711S3VA80ZZ	AC1000150
CV-04241PALQ	Chevrolet Silverado, 12-13, w/o Fog lamps, Chrome	Cap, Face Bar L	Tong Yang	08/16A	22796186	GM1004157
Y-HDBP147ACA	Honda Odyssey EX/EX-L/LX, 05-07	Bumper Cover, Front	Y.C.C.	07/17B	04711SHJA90ZZ	HO1000222
LX4610000-310C	Lexus RX 350, 10-12, Canada Built, w/o Premium Pkg, w/o Parking Assist	Bumper Cover, Front	AP-Procom	11/17A	521190E906	LX1000190
Y-MZBP151CA	Mazda CX-5, 13-15	Bumper Cover, Front	Y.C.C.	01/18A	KD4550031BB	MA1000236
SBG004NCQ	Subaru Forester, 11-13	Grille	Pro Fortune	09/17A	91121SC040	SU1200149
Y-TYBP257ACA	Toyota Corolla CE/LE, 05-08	Bumper Cover, Front	Y.C.C.	12/17A	5211902946	TO1000297
Y-TYBP257ACA	Toyota Corolla CE/LE, 05-08	Bumper Cover, Front	Y.C.C.	12/17A	5211902938	TO1000297
TYB130NBQ	Toyota Corolla, 14-16	Bumper Cover, Rear	Pro Fortune	12/17B	5215903901	TO1100309
TY-04285BBQ	Toyota Matrix Base, 05-08	Bumper Cover, Front	Tong Yang	10/17A	5211902953	TO1000294
TY-04285BBQ	Toyota Matrix XR, 05-08, w/o Spoiler	Bumper Cover, Front	Tong Yang	10/17A	5211902953	TO1000294
TY-04285BBQ	Toyota Matrix XRS, 05-06, w/o Spoiler	Bumper Cover, Front	Tong Yang	10/17A	5211902953	TO1000294
TY04592BDQ	Toyota Sienna Base/L/LE/XLE/Limited, 11-17, w/park distance sensors	Bumper Cover, Rear	TYG Products	18/02/10	5215908903	TO1100285

CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

WEEKLY PARTS UPDATE
June 4, 2018

DELETED PARTS CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

*This report includes all new, decertified and deleted parts from May 28, 2018 through June 1, 2018.

All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at jillian.rahal@intertek.com