

**NEW PARTS CAPA 101 STANDARD - METALS**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Chevrolet Camaro, 16-17, LT, Aluminum	Hood	CV-20137CQ	Tong Yang	23351135	GM1230444
Chevrolet Camaro, 16-17, LT, Aluminum	Hood	CV-20137CQ	Tong Yang	84149362	GM1230444
Chevrolet Camaro, 16-17. SS, Aluminum	Hood	CV-20137AQ	Tong Yang	84149361	GM1230445
Honda Accord, 13-15	Radiator Support	HD30138BH	Hui Yih	60400T2FA50ZZ	HO1225177
Kia Sportage, 17-18, AWD	Hood	KA-20045BQ	Tong Yang	66400D9100	KI1230141

**NEW PARTS CAPA 201 STANDARD - PLASTICS**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Acura RDX, 16-17, w/o parking sensors	Bumper Cover, Rear	ACB028NCQ	Pro Fortune	04715TX4A50ZZ	AC1114101
Acura RDX, 16-18, w/ Parking Sensors	Bumper Cover, Rear	ACB028NDQ	Pro Fortune	04715TX4A60ZZ	AC1114102
BMW X1, 16-18, F48, w/ Headlamp Washer, w/ Park Distance Control	Bumper Cover, Front	BM-04154BHQ	Tong Yang	51117453569	BM1014103
BMW X1, 16-18, F48, w/Headlamp Washer, w/o Park Distance Control	Bumper Cover, Front	BM-04154BFQ	Tong Yang	51117453565	BM1014102
BMW X1, 16-18, F48, w/o Headlamp Washer, w/Park Distance Control	Bumper Cover, Front	BM-04154BGQ	Tong Yang	51117453566	BM1014101
BMW X1, 16-18, F48, w/o Park Distance Control	Bumper Cover, Front	BM-04154BEQ	Tong Yang	51117453562	BM1014100
Chevrolet, Cruze, 16-17, Premier, Sedan, w/o RS Pkg	Grille, Center Bumper	CV-07315GAQ	Tong Yang	84063315	GM1036181
Chevrolet, Cruze, 16-18, L, LS, LT, Sedan, w/o RS Pkg	Grille, Center Bumper	CV-07314GAQ	Tong Yang	23504350	GM1036174
Chevrolet, Cruze, 16-18, Premier, Sedan, w/o RS Pkg	Grille, Center Bumper	CV-07315GAQ	Tong Yang	84189628	GM1036181
Chevrolet, Cruze, 17-18, H/B, w/o RS Pkg	Grille, Center Bumper	CV-07314GAQ	Tong Yang	23504350	GM1036174
Dodge Charger, 11	Valance, Rear	DG-05038VAQ	Tong Yang	68092615AA	CH1195112
Dodge Charger, 15-18	Shield, Splash	LT-DGB001A	Liantuoh	68214815AA	CH1228138
Dodge Charger, R/T, SE, SXT, 12-14	Valance, Rear	DG-05038VAQ	Tong Yang	68092615AA	CH1195112
Dodge Challenger SRT-8, 11-14	Valance, Front Bumper	DGP003NAQ	Pro Fortune	68109837AA	CH1095121
Ford Explorer, 16-17	Valance, Front Bumper	FDB147NAQ	Pro Fortune	FB5Z17D957AA	FO1095261
Ford Explorer, 16-17	Moulding, Bumper Center	FDN147NBQ	Pro Fortune	FB5Z8419APTM	FO1095262
Ford Explorer, 16-17, Police Model	Valance, Front Bumper	FDB147NAQ	Pro Fortune	FB5Z17D957AA	FO1095261
Ford Explorer, 16-17, Police Model	Valance, Lower Bumper	FDP144NBQ	Pro Fortune	FB5Z17K835EPTM	FO1195145
Ford Explorer, 16-17, Police Model	Moulding, Bumper Center	FDN147NBQ	Pro Fortune	FB5Z8419APTM	FO1095262
Ford Explorer, 16-17, w/o Towing Pkg	Valance, Lower Bumper	FDP146NBQ	Pro Fortune	FB5Z17K835CPTM	FO1195144
Ford Fusion Hybrid/Energi, 13-16	Deflector, Lower Air	FDE021NAQ	Pro Fortune	DS7Z8349B	FO1228124
Ford Fusion, 13-16	Deflector, Lower Air	FDE021NAQ	Pro Fortune	DS7Z8349B	FO1228124
Ford Fusion, 17-18	Panel, Front	FDS60101A	Auto Power	HS7Z16138C	FO1225241
Ford, Explorer, 16-17, Police Model, w/o Skid Plate 3.5L Turbo Eng	Valance, Lower Bumper	FDP147NBQ	Pro Fortune	FB5Z17626BA	FO1095269
Ford, Explorer, 16-17, w/o Skid Plate 2.3L Turbo Eng 4WD	Valance, Lower Bumper	FDP147NBQ	Pro Fortune	FB5Z17626BA	FO1095269
Ford, Explorer, 16-17, w/o Skid Plate 2.3L Turbo Eng FWD	Valance, Lower Bumper	FDP147NAQ	Pro Fortune	FB5Z17626AA	FO1095268
Ford, Explorer, 16-17, w/o Skid Plate 3.5L, 3.5L Turbo Eng w/o Towing Pkg	Valance, Lower Bumper	FDP147NAQ	Pro Fortune	FB5Z17626AA	FO1095268
Ford, Explorer, 16-17, w/o Skid Plate 3.5L, 3.5L Turbo Eng w/Towing Pkg	Valance, Lower Bumper	FDP147NBQ	Pro Fortune	FB5Z17626BA	FO1095269
Hyundai Santa Fe, 17-18	Liner, Fender L	HYI006LAQ	Pro Fortune	86811B8500	HY1248165
Hyundai Santa Fe, 17-18	Liner, Fender R	HYI006RAQ	Pro Fortune	86812B8500	HY1249165
Jeep, Renegade, 15-18	Grille	AM-07045GAQ	Tong Yang	5XB17LXHAA	CH1223105
Lexus IS 250, 14-16, w/o F sport pkg, From 5-13	Grille	LSG026NBQ	Pro Fortune	5311253051	LX1200175
Lexus IS 350, 14-16, w/o F sport pkg, From 5-13	Grille	LSG026NBQ	Pro Fortune	5311253051	LX1200175
Mercedes-Benz, E-Class, 17, 213, Sedan	Tie Bar, Upper	BZ-03011AQ	Tong Yang	2136206300	MB1225189
Mercedes-Benz, E-Class, 17, 213, Wagon	Tie Bar, Upper	BZ-03011AQ	Tong Yang	2136206300	MB1225189
Mini Cooper, 14-16, Hardtop HB (F56), w/Chrome Trim	Grille	AT-07027GAQ	Tong Yang	51137335529	MC1200105
Mini Cooper, 15-15, Hardtop 4 Door FSS, w/o Chrome Pkg, 2015 From 1-1	Grille	AT-07027GBQ	Tong Yang	51137300586	MC1200106
Mini Cooper, 15-15, Hardtop HB (F56), w/ATC 2015 From 1-15	Grille	AT-07027GBQ	Tong Yang	51137300586	MC1200106
Mini Cooper, 15-18, Hardtop 4 Door FSS, w/Chrome Pkg	Grille	AT-07027GAQ	Tong Yang	51137335529	MC1200105
Mini Cooper, 16-17, Conv (F57) w/Chrome Trim	Grille	AT-07027GAQ	Tong Yang	51137335529	MC1200105
Mini Cooper, 16-17, Conv (F57), w/o Chrome Trim, w/ATC	Grille	AT-07027GBQ	Tong Yang	51137300586	MC1200106
Mini Cooper, 16-18, Hardtop 4 Door FSS, w/o Chrome Pkg	Grille	AT-07027GBQ	Tong Yang	51137300586	MC1200106
Mini Cooper, 16-18, Hardtop HB (F56), w/o Chrome Trim, w/ATC	Grille	AT-07027GBQ	Tong Yang	51137300586	MC1200106
Nissan Armada, 04-07	Liner, Fender R	NST1014DR-C	Great Bestcam	638307S200	NI249107
Nissan Armada, 04-07	Liner, Fender L	NST1014DL-C	Great Bestcam	638317S200	NI1248107
Nissan Titan LE/SE, 04-10	Liner, Fender R	NST1014DR-C	Great Bestcam	638307S200	NI249107
Nissan Titan LE/SE, 04-10	Liner, Fender L	NST1014DL-C	Great Bestcam	638317S200	NI1248107
Nissan Versa Note, 17-18	Cover, Grille	NSM001NAQ	Pro Fortune	623209MEOH	NI1210110
Toyota Corolla, 17-19, Model, CE, L, LE, LE ECO, XLE	Bumper Cover, Front	TYB161NBQ	Pro Fortune	5211903907	TO1000423

**NEW PARTS CAPA 201 STANDARD - PLASTICS**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Volkswagen Golf GTI, 15-17, w/Parallel park assist	Bumper Cover, Rear	VG-04215BCQ	Tong Yang	5GM807417BGRU	VW1100205
Volkswagen Golf, 15-17, w/Parallel park assist	Bumper Cover, Rear	VG-04215BCQ	Tong Yang	5GM807417BGRU	VW1100205

**NEW PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

**NEW PARTS CAPA 301 STANDARD - LIGHTING**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
BMW X3 F25, 15-18, Halogen	Headlamp Assy, L	344-1151L-AC2	DEPO	63117334073	BM2518142
BMW X3 F25, 15-18, Halogen	Headlamp Assy, R	344-1151R-AC2	DEPO	63117334074	BM2519142
BMW X4 F26, 15-18, Halogen	Headlamp Assy, L	344-1151L-AC2	DEPO	63117334073	BM2518142
BMW X4 F26, 15-18, Halogen	Headlamp Assy, R	344-1151R-AC2	DEPO	63117334074	BM2519142
Honda Odyssey, 18, Elite, EX, EX-L, Touring	Lamp, Signal R	317-1638R-AC	DEPO	33300THRA01	HO2531131
Honda Odyssey, 18, Elite, EX, EX-L, Touring	Lamp, Signal L	317-1638L-AC	DEPO	33350THRA01	HO2530131
Honda Odyssey, 18, LX	Lamp, Signal R	317-1638R3AC	DEPO	33300THRA11	HO2531132
Honda Odyssey, 18, LX	Lamp, Signal L	317-1638L3AC	DEPO	33350THRA11	HO2530132
Hyundai Genesis Sedan, 11-13	Lamp, Fog L	321-2038L-AC	DEPO	922013M210	HY2592149
Hyundai Genesis Sedan, 11-13	Lamp, Fog R	321-2038R-AC	DEPO	922023M210	HY2593149
Hyundai Tucson, 16-18	Reflector, Bumper Rear L	17-5616-00-9	TYC Brother	92405D3050	HY1184116
Hyundai Tucson, 16-18	Reflector, Bumper Rear R	17-5615-00-9	TYC Brother	92406D3050	HY1185116

**NEW PARTS CAPA 501 STANDARD - BUMPERS**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Chevrolet Silverado 1500 Hybrid, 09-13, w/Rear object sensors, Paint to match	End Cap, Bumper L	CV51071BLH	Hui Yih	15891685	GM1103161
Chevrolet Silverado 1500 Hybrid, 09-13, w/Rear object sensors, Paint to match	End Cap, Bumper R	CV51071BRH	Hui Yih	15891686	GM1103161
Chevrolet Silverado 1500/2500/3500, 07-13, w/Rear object sensors, Paint to match	End Cap, Bumper L	CV51071BLH	Hui Yih	15891685	GM1103161
Chevrolet Silverado 1500/2500/3500, 07-13, w/Rear object sensors, Paint to match	End Cap, Bumper R	CV51071BRH	Hui Yih	15891686	GM1103161
Chevrolet Sonic, 17-18	Absorber, Energy	CV4Y124Q	Cobra King	94544457	GM1070315
Chevrolet Trax, 15-16	Absorber, Energy	CV4X124Q	Cobra King	94544507	GM1070308
Ford Taurus, 13-16	Bar, Reinforcement	FDR3418A	Auto Power	BG1Z17906A	FO1106368
GMC Sierra 1500 Hybrid, 09-13, w/Rear object sensors, Paint to match	End Cap, Bumper L	CV51071BLH	Hui Yih	15891685	GM1103161
GMC Sierra 1500 Hybrid, 09-13, w/Rear object sensors, Paint to match	End Cap, Bumper R	CV51071BRH	Hui Yih	15891686	GM1103161
GMC Sierra 1500/2500/3500, 07-13, w/Rear object sensors, Paint to match	End Cap, Bumper L	CV51071BLH	Hui Yih	15891685	GM1103161
GMC Sierra 1500/2500/3500, 07-13, w/Rear object sensors, Paint to match	End Cap, Bumper R	CV51071BRH	Hui Yih	15891686	GM1103161
Jeep Wrangler Std Duty, 07-15	Bar, Face	AM-04066BAQ	Tong Yang	1BD22RXFAD	CH1100979
Jeep Wrangler Std Duty, 07-18	Bar, Face	AM-04066BAQ	Tong Yang	1BD22RXFAE	CH1100979
Jeep Wrangler Std Duty, 16, Black	Bar, Face	AM-04066BAQ	Tong Yang	1BD22RXFAD	CH1100979
Jeep Wrangler Std Duty, 16, Black	Bar, Face	AM-04066BAQ	Tong Yang	1BD22RXFAE	CH1100979
Jeep Wrangler, 07-18, w/tow hook w/fog lamps	Bar, Face	AM-04035BAHQ	Tong Yang	1FN67RXFAA	CH1000900
Toyota Tacoma, 16-18, w/o Towing Hitch, w/o Parking Assist, Black	Bumper, Rear Assembly	TY50161CH	Hui Yih	TO1103125	TO1103125

**NEW PARTS CAPA 601 STANDARD - RADIATORS**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

**DECERTIFICATIONS**

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

**CAPA 101 STANDARD - METALS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
CDCT08HD1	Cadillac CTS Coupe/Wagon, 11-14	Hood	Gordon	06/16A	22789395	GM1230383
CDCT08HD1	Cadillac CTS Sedan, 08-13	Hood	Gordon	06/16A	22789395	GM1230383
CDCT08HD1	Cadillac CTS Sedan, 08-03/31/09	Hood	Gordon	06/16A	25885609	GM1230383
FDS6785A	Ford C-Max, 13-17, Energi	Radiator Support	Auto Power	03/18A	CJ5Z8A284A	FO1225216
FDS6785A	Ford C-Max, 13-18, Hybrid	Radiator Support	Auto Power	03/18A	CJ5Z8A284A	FO1225216
FDS6785A	Ford Escape, 13-18	Radiator Support	Auto Power	03/18A	CJ5Z8A284A	FO1225216
FD-03031AQ	Ford Focus Sedan/Hatchback, 12-16	Radiator Support	Tong Yang	06/18A	CM5Z8A284A	FO1225214
FD-03031AQ	Ford Focus, 14-18	Radiator Support	Tong Yang	06/18A	CM5Z8A284ACP	FO1225214
FD-03031AQ	Ford Focus, 14-18, Hybrid	Radiator Support	Tong Yang	06/18A	CM5Z8A284ACP	FO1225214
FD-03031AQ	Ford Focus Sedan/Hatchback, 12-14	Radiator Support	Tong Yang	06/18A	CP9Z8A284A	FO1225214

**CAPA 201 STANDARD - PLASTICS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
HDB084NBQ	Honda Civic Hybrid, 06-11	Bumper Cover, Rear	Pro Fortune	02/18A	04715SNAA90ZZ	HO1100235
HDB084NBQ	Honda Civic Sedan, 06-11, 1.8L eng	Bumper Cover, Rear	Pro Fortune	02/18A	04715SNAA90ZZ	HO1100235
TYB137NBQ	Toyota 4Runner, 14-17, w/Chrome	Bumper Cover, Front	Pro Fortune	03/18A	5211935913	TO1000407
DS-04400BBQ	Nissan Altima Sedan, 16-17, w/o Distance sensors	Bumper Cover, Front	Tong Yang	03/18A	620229HS0H	NI1000311
DGB068NCQ	Dodge Charger, 11, w/o Parking Sensor	Bumper Cover, Rear	Pro Fortune	12/16A	68092608AA	CH1100962
DGB068NCQ	Dodge Charger, 12-14, Type 1 w/o parking sensor	Bumper Cover, Rear	Pro Fortune	12/16A	68092608AA	CH1100962
DGB068NCQ	Dodge Charger, 11-14, w/o Parking Sensor	Bumper Cover, Rear	Pro Fortune	12/16A	68092608AB	CH1100962
DGB068NCQ	Dodge Charger, 12-14, Type 1, w/o Parking sensor	Bumper Cover, Rear	Pro Fortune	12/16A	68092608AB	CH1100962
Y-HYBP023CA	Hyundai Genesis Coupe, 13-15	Bumper Cover, Front	Y.C.C.	05/17A	865112M300	HY1000197
CV-04106BAQ	Chevrolet Avalanche, 02	Bumper Cover, Front	Tong Yang	01/18A	88944057	GM1000648
MZ-04098BBQ	Mazda 3 Sedan, 07-09	Bumper Cover, Rear	Tong Yang	04/18A	BS4N50221CBB	MA1100192
FD-04395BDQ	Ford Edge, 11-14, w/Rear Object Sensors	Bumper Cover, Rear	Tong Yang	03/18A	BT4Z17810BPTM	FO1114101
DS-04354BBQ	Nissan Versa Note, 14-15	Bumper Cover, Front	Tong Yang	02/18A	FBM223VY0J	NI1000292

**CAPA 202 STANDARD - NON-WOVEN FABRICS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

**CAPA 301 STANDARD - LIGHTING**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

**CAPA 501 STANDARD - BUMPERS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

**CAPA 601 STANDARD - RADIATORS**

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

## WEEKLY PARTS UPDATE July 02, 2018

### DELETED PARTS CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

### DELETED PARTS CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

### DELETED PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

### DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

### DELETED PARTS CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

### DELETED PARTS CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

### CORRECTION

The following part was listed as certified on the June 25, 2018 Weekly Parts Update.  
Upon further review, this part was not certified during the period covered by that report.

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Toyota, Camry, 18-18, Hybrid, LE Model	Bumper Cover, Front	TY3830000-100C	AP-Procom	521190X936	TO1000438
Toyota, Camry, 18-18, L, LE Model	Bumper Cover, Front	TY3830000-100C	AP-Procom	521190X936	TO1000438

\*This report includes all new, decertified and deleted parts from June 25, 2018 through June 29, 2018.

All CAPA reports including the weekly update are available on the CAPA website at [www.capacertified.org](http://www.capacertified.org).

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at [jillian.rahal@intertek.com](mailto:jillian.rahal@intertek.com)