

NEW PARTS CAPA 101 STANDARD - METALS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Acura MDX, 14-15	Radiator Support	ACS6987A	Auto Power	60400TZ5A00ZZ	AC1225131
Acura MDX, 14-16	Radiator Support	ACS6987A	Auto Power	60400TZ5A01ZZ	AC1225131
Subaru Forester, 14-17, 2.0L/2.5L Eng	Hood	SUFS14HD1	Gordon	57229SG0009P	SU1230144
Mazda CX-5, 17	Member, Upper	MZS6762-1A	Auto Power	KB7W53150B	MA1225173

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Acura ILX, 16-17, w/o Adaptive Cruise Control	Grille	HD-07225GAQ	Tong Yang	71121TX6A51	AC1200129
Acura MDX, 14-17	Cover, Engine Under	LT-HDB002A	Liantuoh	74111TZ5A00	AC1228118
Acura MDX, 17, Sport Hybrid	Cover, Engine Under	LT-HDB002A	Liantuoh	74111TZ5A00	AC1228118
Chevrolet Camaro LS/LT, 14-15, w/o RS Pkg	Bumper Cover, Front	Y-GMBP360CA	Y.C.C.	22997718	GM1000965
Chevrolet Camaro LS/LT, 14-15, w/RS Pkg	Bumper Cover, Front	Y-GMBP360HCA	Y.C.C.	22997720	GM1000963
Honda Accord, 18, Sedan, EX, EX-L, LX, Sport Model	Bumper Cover, Front	HO1000314C	Grand HB	04711TVAA00ZZ	HO1000314
Honda Accord, 18, Touring Model	Bumper Cover, Front	HO1000315C	Grand HB	04711TVAA11ZZ	HO1000315
Honda Odyssey, 18-19	Shield, Splash	LT-HDB003A	Liantuoh	74111THRA00	HO1228154
Honda Pilot, 16-17	Cover, Engine Under	LT-HDB002A	Liantuoh	74111TZ5A00	AC1228118
Honda Ridgeline, 17	Cover, Engine Under	LT-HDB002A	Liantuoh	74111TZ5A00	AC1228118
Kia Optima, 16-18, Sport Type	Bumper Cover, Front	Y-KABP029CA	Y.C.C.	86511D5200	KI1000183
Lexus IS 250, 14-16, AWD	Cover, Engine Under Front	LSE015NAQ	Pro Fortune	5141053150	LX1228146
Lexus IS 250, 14-17, AWD	Cover, Engine Under Front	LSE015NAQ	Pro Fortune	5141053151	LX1228146
Lexus IS 250, 17, AWD, From 5-17	Cover, Engine Under Front	LSE015NAQ	Pro Fortune	5141053150	LX1228146
Lexus IS 250, 17, AWD, To 4-17	Cover, Engine Under Front	LSE015NAQ	Pro Fortune	5141053150	LX1228146
Lexus IS 250, 17-17, AWD, From 5-17	Cover, Engine Under Front	LSE015NAQ	Pro Fortune	5141053151	LX1228146
Lexus IS 250, 17-17, AWD, To 4-17	Cover, Engine Under Front	LSE015NAQ	Pro Fortune	5141053151	LX1228146
Lincoln MKX, 11-15, Paint to Match	Bumper Cover, Front Lower	LG-80-848C	CHL	BA1Z17D957A	FO1015114
Lincoln MKX, 11-15, Paint to Match	Bumper Cover, Front Lower	LG-80-848C	CHL	BA1Z17D957APTI	FO1015114
Nissan Pathfinder, 17-18	Moulding, Bumper Rear	DS-04438MAQ	Tong Yang	850729PF0A	NI1144108
Nissan Rogue Select, 13-15	Shield, Eng Splash R	NSE026RAQ	Pro Fortune	648384CL0A	NI1228157
Nissan Rogue Select, 13-15	Shield, Eng Splash L	NSE026LAQ	Pro Fortune	648394CL0A	NI1228158
Nissan Rogue, 13-15	Shield, Eng Splash R	NSE026RAQ	Pro Fortune	648384CL0A	NI1228157
Nissan Rogue, 13-15	Shield, Eng Splash L	NSE026LAQ	Pro Fortune	648394CL0A	NI1228158
Nissan Versa, 12-18	Bracket, Cover R	NS6D617RQ	Cobra King	852203BA0A	NI1133105
Nissan Versa, 12-18	Bracket, Cover L	NS6D617LQ	Cobra King	852213BA0A	NI1132105
Subaru Forester, 17-18	Moulding, Hood	SB-07064MBQ	Tong Yang	91121SG210	SU1235102
Subaru Forester, 17-18	Moulding, Hood	SB-07064MBQ	Tong Yang	91121SG211	SU1235102
Toyota, Corolla, 14-18	Seal, Rear Bumper Side R	TA1S617ARQ	Cobra King	5259102271	TO1183104
Toyota, Corolla, 14-18	Seal, Rear Bumper Side L	TA1S617ALQ	Cobra King	5259202261	TO1182104
Volvo XC90, 16-17, Hybrid, T8 Excellence Model, T8 Momentum Model w/o Park Assist Sensors Paint to Match	Spoiler, Rear Lower	VV27-8502	Tran Hung	398413344	VO1115106
Volvo XC90, 16-17, Hybrid, T8 Excellence Model, T8 Momentum Model w/Park Assist Sensors Paint to Match	Spoiler, Rear Lower	VV27-8502	Tran Hung	398413344	VO1115106
Volvo XC90, 16-18, T5 Inscription, T6 Inscription Model	Bumper Cover, Rear	VV27-8501	Tran Hung	39841897	

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Volvo XC90, 16-18, T5 Momentum, T6 Momentum Model	Bumper Cover, Rear	VV27-8501	Tran Hung	39841897	
Volvo XC90, 16-18, T5 R Design, T6 R Design Model	Bumper Cover, Rear	VV27-8501	Tran Hung	39841897	
Volvo XC90, 16-18, T6 First Edition Model	Bumper Cover, Rear	VV27-8501	Tran Hung	39841897	

NEW PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Honda HR-V, 16-18	Headlamp Assy, R	20-9701-00-9	TYC Brother	33100T7SA01	HO2503171
Honda HR-V, 16-18	Headlamp Assy, L	20-9702-00-9	TYC Brother	33150T7SA01	HO2502171
Chevrolet Malibu, 16, Type 1	Headlamp Assy, L	A35-1107L-AC2	DEPO	23350425	GM2502426
Chevrolet Malibu, 16, Type 1	Headlamp Assy, R	A35-1107R-AC2	DEPO	23350426	GM2503426
Chevrolet Malibu, 16-18, Type 1	Headlamp Assy, L	A35-1107L-AC2	DEPO	84217584	GM2502426
Chevrolet Malibu, 16-18, Type 1	Headlamp Assy, R	A35-1107R-AC2	DEPO	84217585	GM2503426
Chevrolet Malibu, 16-18, Type 1	Headlamp Assy, L	A35-1107L-AC2	DEPO	84324410	GM2502426
Chevrolet Malibu, 16-18, Type 1	Headlamp Assy, R	A35-1107R-AC2	DEPO	84324411	GM2503426
Honda Accord Sedan, 16-17, LED	Headlamp Assy, R	317-1179R-AC	DEPO	33100T2AA31	HO2503174
Honda Accord Sedan, 16-17, LED	Headlamp Assy, L	317-1179L-AC	DEPO	33150T2AA31	HO2502174
Honda Accord, 16-17, Sedan, LED	Headlamp Assy, L	317-1179L-AC	DEPO	33150T2AA32	HO2502174
Honda Accord, 16-17, Sedan, LED Type	Headlamp Assy, R	317-1179R-AC	DEPO	33100T2AA32	HO2503174
Hyundai Elantra Wagon, 10-12	Headlamp Assy, L	20-12124-90-9	TYC Brother	921012L152	HY2502162
Hyundai Elantra Wagon, 10-12	Headlamp Assy, R	20-12123-90-9	TYC Brother	921022L152	HY2503162
Toyota Camry, 18	Taillamp R	312-19ASR3AC	DEPO	8155006840	TO2805135
Toyota Camry, 18-18, SE Model	Taillamp R	312-19ASR3UC	DEPO	8155133710	TO2805139

NEW PARTS CAPA 301 STANDARD - LIGHTING EMC TESTED

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Lexus IS 250, 14-16	Headlamp, R	324-1117RMACM2	DEPO	8114553751	LX2519141
Lexus IS 250, 14-16	Headlamp, L	324-1117LMACM2	DEPO	8118553751	LX2518141
Toyota Camry, 18	Taillamp R	312-19ASR-AC	DEPO	8155006720	TO2805134
Toyota Prius V, 15	Taillamp R	11-6777-01-9	TYC Brother	8155147270	TO2801194
Toyota Prius V, 15	Taillamp L	11-6778-01-9	TYC Brother	8156147270	TO2800194
Toyota Prius V, 15-17	Taillamp R	11-6777-01-9	TYC Brother	8155147271	TO2801194
Toyota Prius V, 15-17	Taillamp R	11-6777-01-9	TYC Brother	8155147272	TO2801194
Toyota Prius V, 15-17	Taillamp L	11-6778-01-9	TYC Brother	8156117272	TO2800194
Toyota Prius V, 15-17	Taillamp L	11-6778-01-9	TYC Brother	8156147271	TO2800194
Toyota Prius V, 15-17	Taillamp L	11-6778-01-9	TYC Brother	8156147272	TO2800194

NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Cadillac CTS-V, 16-17, Sedan	Bar, Reinforcement	CDR3490A	Auto Power	23486730	
Cadillac CTS-V, 16-18, Sedan	Bar, Reinforcement	CDR3490A	Auto Power	23349757	
Chevrolet Equinox, 18	Bar, Reinforcement	CVR3536A	Auto Power	23462897	GM1106713
Chevrolet Express Van, 96-14, 1500	Bracket, Bumper L	CV56965ALH	Hui Yih	15979949	GM1166121
Chevrolet Express Van, 96-14, 1500	Bracket, Bumper R	CV56965ARH	Hui Yih	15979950	GM1167121
Chevrolet Express Van, 96-18, 2500	Bracket, Bumper L	CV56965ALH	Hui Yih	15979949	GM1166121
Chevrolet Express Van, 96-18, 2500	Bracket, Bumper R	CV56965ARH	Hui Yih	15979950	GM1167121
Chevrolet Express Van, 96-18, 3500	Bracket, Bumper L	CV56965ALH	Hui Yih	15979949	GM1166121
Chevrolet Express Van, 96-18, 3500	Bracket, Bumper R	CV56965ARH	Hui Yih	15979950	GM1167121

NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Chevrolet Silverado 1500, 14, w/Fog lamps, w/o Parking aid sensors, Black	Bar, Face	CVB7097-1APT	Auto Power	23138597	GM1002852
Chevrolet Silverado 1500, 14, w/o Fog lamps, w/o Parking aid sensors, Black	Bar, Face	CVB7097APT	Auto Power	22944858	GM1002854
Chevrolet Silverado 1500, 14-15, w/Fog lamps, w/o Parking aid sensors, Chrome	Bar, Face	CVB7097-1ACH	Auto Power	22944859	GM1002843
Chevrolet Silverado 1500, 14-15, w/Fog lamps, w/Parking aid sensors, Chrome	Bar, Face	CVB7097-2ACH	Auto Power	23173678	GM1002845
Chevrolet Silverado 1500, 14-15, w/Fog lamps, w/Parking aid sensors, PTM	Bar, Face	CVB7097-2APT	Auto Power	22944857	GM1002853
Chevrolet Silverado 1500, 14-15, w/o Fog lamps, w/o Parking aid sensors, Chrome	Bar, Face	CVB7097ACH	Auto Power	23173677	GM1002844
Ford Mustang, 15-16, Coupe	Absorber, Energy	FO1070192DSC	Grand HB	FR3Z17C882A	FO1070192
Ford Mustang, 15-17, Convertible	Absorber, Energy	FO1070192DSC	Grand HB	FR3Z17C882A	FO1070192
GMC Savana, 96-14, 1500	Bracket, Bumper L	CV56965ALH	Hui Yih	15979949	GM1166121
GMC Savana, 96-14, 1500	Bracket, Bumper R	CV56965ARH	Hui Yih	15979950	GM1167121
GMC Savana, 96-18, 2500	Bracket, Bumper L	CV56965ALH	Hui Yih	15979949	GM1166121
GMC Savana, 96-18, 2500	Bracket, Bumper R	CV56965ARH	Hui Yih	15979950	GM1167121
GMC Savana, 96-18, 3500	Bracket, Bumper L	CV56965ALH	Hui Yih	15979949	GM1166121
GMC Savana, 96-18, 3500	Bracket, Bumper R	CV56965ARH	Hui Yih	15979950	GM1167121
Honda Accord, 08-12, Sedan	Absorber, Energy	HO1070148DSC	Grand HB	71172TAOK00	HO1070148
Toyota Highlander Hybrid, 14-15	Reinf., Bumper Rear	TYR2689A	Auto Power	5.2171E+95	TO1106219
Toyota Highlander Hybrid, 15-16	Reinf., Bumper Rear	TYR2689A	Auto Power	5.2171E+85	TO1106219
Toyota Highlander, 14-15	Reinf., Bumper Rear	TYR2689A	Auto Power	5.2171E+95	TO1106219
Toyota Highlander, 15-16	Reinf., Bumper Rear	TYR2689A	Auto Power	5.2171E+85	TO1106219

NEW PARTS CAPA 601 STANDARD - RADIATORS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
TY-04402BBO	Toyota Camry Hybrid, 12-14	Bumper Cover, Front	Tong Yang	12/17A	5211906974	TO1000378
TY-04402BBO	Toyota Camry L/LE/XLE, 12-14	Bumper Cover, Front	Tong Yang	12/17A	5211906974	TO1000378
TY3820870-000C	Toyota Camry L/LE/XLE/Hybrid, 12-14	Bumper Cover, Rear	AP-Procom	12/17A	5215906961	TO1100296

CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						



WEEKLY PARTS UPDATE October 08, 2018

[Report: P6]
Weekly

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
11-6338-01-9	Subaru Forester, 09-13	Taillamp L	TYC Brother	05071810	84912SC131	SU2818102

CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

DELETED PARTS CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

*This report includes all new, decertified and deleted parts from September 29, 2018 through October 05, 2018.

All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at jillian.rahal@intertek.com