

**NEW PARTS CAPA 101 STANDARD - METALS**

<b>Application Description</b>	<b>Part Description</b>	<b>Manufacturer Number</b>	<b>Manufacturer</b>	<b>OEM Number</b>	<b>PartsLink Number</b>
Acura MDX, 14-15, w/o Lane Keep Assist	Liner, Fender L	HDA4014CL2-C	Great Bestcam	74151TZ5A00	AC1248131
Chevrolet Colorado, 15-17	Fender L	CR-911ALQ	Chang Jung	23354494	GM1240404
Chevrolet Colorado, 15-17	Fender L	CV9P002LQ	Cobra King	23354494	GM1240404
Kia Sedona, 15-16	Radiator Support	KAS60223A	Auto Power	64101A9000	KI1225172
Toyota Prius c, 18	Support, Hood Latch	TYS60282A	Auto Power	5320852906	TO1233132
Volvo XC60, 16-18, Hybrid	Bracket, Side L	VVS60300AL	Auto Power	31391623	VO1225112
Volvo XC60, 16-18, Hybrid	Bracket, Side R	VVS60300AR	Auto Power	31391624	VO1225113
Volvo XC60, 16-19	Bracket, Side L	VVS60300AL	Auto Power	31391623	VO1225112
Volvo XC60, 16-19	Bracket, Side R	VVS60300AR	Auto Power	31391624	VO1225113
Volvo XC60, 18, Plug-in	Bracket, Side L	VVS60300AL	Auto Power	313916231	VO1225112
Volvo XC60, 18-18, Plug-In	Bracket, Side L	VVS60300AL	Auto Power	31391623	VO1225112
Volvo XC60, 18-18, Plug-In	Bracket, Side R	VVS60300AR	Auto Power	31391624	VO1225113
Volvo XC60, 18-18, Plug-in	Bracket, Side R	VVS60300AR	Auto Power	313916249	VO1225113
Volvo XC60, 18-19	Bracket, Side L	VVS60300AL	Auto Power	31391623	VO1225112
Volvo XC60, 18-19	Bracket, Side L	VVS60300AL	Auto Power	313916231	VO1225112
Volvo XC60, 18-19	Bracket, Side R	VVS60300AR	Auto Power	31391624	VO1225113
Volvo XC60, 18-19	Bracket, Side R	VVS60300AR	Auto Power	313916249	VO1225113
Volvo XC90, 16-18, Hybrid	Bracket, Side L	VVS60300AL	Auto Power	313916231	VO1225112
Volvo XC90, 16-18, Hybrid	Bracket, Side R	VVS60300AR	Auto Power	313916249	VO1225113
Volvo XC90, 16-19	Bracket, Side L	VVS60300AL	Auto Power	313916231	VO1225112
Volvo XC90, 16-19	Bracket, Side R	VVS60300AR	Auto Power	313916249	VO1225113

**NEW PARTS CAPA 201 STANDARD - PLASTICS**

<b>Application Description</b>	<b>Part Description</b>	<b>Manufacturer Number</b>	<b>Manufacturer</b>	<b>OEM Number</b>	<b>PartsLink Number</b>
Volkswagen Jetta Hybrid, 15-17, w/o Parking assist	Bumper Cover, Front	VG1710000-300C	AP-Procom	5C6807217MGRU	VW1000220
Volkswagen Jetta Sedan, 15-17, w/o HL washer, w/o Parking assist	Bumper Cover, Front	VG1710000-300C	AP-Procom	5C6807217MGRU	VW1000220
Volkswagen Jetta, 15-17, Hybrid, w/o Parking assist	Bumper Cover, Front	VG1710000-300C	AP-Procom	5C6807217AGGRU	VW1000220
Volkswagen Jetta, 15-17, Sedan, w/o HL washer, w/o Parking assist	Bumper Cover, Front	VG1710000-300C	AP-Procom	5C6807217AGGRU	VW1000220
Toyota RAV-4, 13-18	Cover, Engine Under	TYE049NAQ	Pro Fortune	514410R070	TO1228196
Acura MDX, 14-15, w/Lane Keep Assist	Liner, Fender Assy R	HDA4014CR1-C	Great Bestcam	74101TZ5A10	AC1249132
Acura MDX, 14-15, w/Lane Keep Assist	Liner, Fender Assy L	HDA4014CL1-C	Great Bestcam	74151TZ5A10	AC1248132
Acura MDX, 14-15, w/o Lane Keep Assist	Liner, Fender R	HDA4014CR2-C	Great Bestcam	74101TZ5A00	AC1249131
Acura MDX, 16, w/o Lane Keep Assist	Liner, Fender Assy R	HDA4014CR1-C	Great Bestcam	74101TZ5A10	AC1249132
Acura MDX, 16, w/o Lane Keep Assist	Liner, Fender Assy L	HDA4014CL1-C	Great Bestcam	74151TZ5A10	AC1248132
Acura MDX, 17	Cover, Lower	AC13-5102	Tran Hung	71510TZ5A10	AC1115104
Acura MDX, 17, Sport, Hybrid	Moulding, Grille	HD-07234FAQ	Tong Yang	71121TZ5A00	AC1202109
Acura MDX, 17-18	Moulding, Grille	HD-07234FAQ	Tong Yang	71121TZ5A00	AC1202109
Audi, A4, 17-18, Sedan, w/o S-Line Pkg w/o Headlamp Washer w/Parking Aid w/o Parallel Park Assist	Bumper Cover, Front	AD-04066BDQ	Tong Yang	8W0807065NGRU	AU1000236
Chevrolet Cruze, Mexico Built, 17-18	Extension, Lower Cover	CLE008NAQ	Pro Fortune	84063312	GM1228152
Chevrolet Equinox, 16-17, LTZ, w/Dual Exh, w/Chrome Mldg, Textured	Bumper Cover, Rear L	LG-80-872C	CHL	23477052	GM1115123
Chevrolet Malibu, 16-18, w/o Park Sensors, w/o Cross-Traffic Alert, prime	Bumper Cover, Rear	LG-80-868C	CHL	84276886	GM1100979
Chevrolet Malibu, 16-18, w/Park Sensors, w/Blind Spot Detection, Prime	Bumper Cover, Rear	LG-80-867C	CHL	84276885	GM1100980
Chevrolet Malibu, 16-18, w/Park Sensors, w/Cross-Traffic Alert, prime	Bumper Cover, Rear	LG-80-867C	CHL	23352768	GM1100980
Chevrolet Malibu, 16-18, w/Park Sensors, w/Cross-Traffic Alert, w/Semi-Automatic Park Assist, prime	Bumper Cover, Rear	LG-80-866C	CHL	84276884	GM1100981
Ford Explorer, 16-17, Limited Model	Grille	FD-07419GBQ	Tong Yang	FB5Z8200AB	FO1200577
Ford Explorer, 16-17, Limited, Chrome/Silver Lining	Grille, Assy	FD-07419GDQ	Tong Yang	FB5Z8200AD	FO1200579
Ford Explorer, 16-17, Sport Model	Grille	FD-07419GAQ	Tong Yang	FB5Z8200BA	FO1200580
Ford Explorer, 16-17, XLT Model, w/o Appearance Pkg	Grille	FD-07419GCQ	Tong Yang	FB5Z8200AC	FO1200578
GMC Terrain, 16-17, Textured	Bumper Cover, Front Lower	LG-80-871C	CHL	84038114	GM1015126
Honda Civic, 17-18, Hatchback, EX, EX-L, LX Model	Grille, Bumper	LG-70-231C	CHL	71102TGGA00	HO1036128
Honda CR-V, 17-18, EX, EX-L, LX Model	Garnish, Rear Bumper	HD-04341MAQ	Tong Yang	71510TLAA10	HO1195114
Infiniti QX60, 15-17, Hybrid	Liner, Fender R	NSP1014GR-C	Great Bestcam	638409NB0A	NI1249161
Infiniti QX60, 15-17, Hybrid	Liner, Fender L	NSP1014GL-C	Great Bestcam	638419NB0A	NI1248161
Infiniti QX60, 15-18	Liner, Fender R	NSP1014GR-C	Great Bestcam	638409NB0A	NI1249161
Infiniti QX60, 15-18	Liner, Fender L	NSP1014GL-C	Great Bestcam	638419NB0A	NI1248161

**NEW PARTS CAPA 201 STANDARD - PLASTICS**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Lexus, RX 350, 16-18, w/o F Sport Pkg, w/Front View Camera	Grille, Radiator	LSG030NBQ	Pro Fortune	531110E180	LX1200181
Lexus, RX 350, 16-18, w/o Front View Camera, w/o F Sport Pkg	Grille, Assy	LSG030NFQ	Pro Fortune	531110E170	LX1200180
Lexus, RX 450h, 16-17, w/Front View Camera, w/o F Sport Pkg	Grille, Radiator	LSG030NBQ	Pro Fortune	531110E180	LX1200181
Lexus, RX 450h, 16-17, w/o Front View Camera, w/o F Sport Pkg	Grille, Assy	LSG030NFQ	Pro Fortune	531110E170	LX1200180
Mazda CX-5, 13-15	Stiffener, Bumper	LT-MZB004A	Liantuoh	KD53500S0A	MA1091100
Nissan Pathfinder, 15-18	Liner, Fender R	NSP1014GR-C	Great Bestcam	638409NBOA	NI1249161
Nissan Pathfinder, 15-18	Liner, Fender L	NSP1014GL-C	Great Bestcam	638419NBOA	NI1248161
Toyota C-HR, 18	Grille	TYG162NBQ	Pro Fortune	53111F4901	TO1200416
Toyota Highlander, 10-13, 3.5L Eng, USA Built	Cover, Engine Under	TYE051NAQ	Pro Fortune	514400E041	TO1228199
Volkswagen Passat, 12-18, 1.8L Turbo Eng	Cover, Engine Under L	VGE005NAQ	Pro Fortune	561825237D	VW1228121
Volkswagen Passat, 12-18, 2.0L Turbo Diesel Eng	Cover, Engine Under L	VGE005NAQ	Pro Fortune	561825237D	VW1228121
Volkswagen Passat, 12-18, 2.0L Turbo Gas Eng	Cover, Engine Under L	VGE005NAQ	Pro Fortune	561825237D	VW1228121
Volkswagen Passat, 12-18, 2.5L Eng	Cover, Engine Under L	VGE005NAQ	Pro Fortune	561825237D	VW1228121
Volkswagen Passat, 12-18, 3.6L Eng	Cover, Engine Under L	VGE005NAQ	Pro Fortune	561825237D	VW1228121

**NEW PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

**NEW PARTS CAPA 301 STANDARD - LIGHTING**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Ford XLT/Limited/Platinum Explorer, 16-17, HID	Headlamp Assy, R	20-9741-00-9	TYC Brother	FB5Z13008B	FO2519130
Ford XLT/Limited/Platinum Explorer, 16-17, LED	Headlamp Assy, L	20-9742-00-9	TYC Brother	FB5Z13008N	FO2518130
Honda Ridgeline, 17-19, w/o Park lamps	Lamp, Signal R	317-1637R3AC	DEPO	33300T6ZA11	HO2531130
Honda Ridgeline, 17-19, w/o Park lamps	Lamp, Signal L	317-1637L3AC	DEPO	33350T6ZA11	HO2530130
Honda Ridgeline, 17-19, w/Park lamps	Lamp, Signal R	317-1637R-AC	DEPO	33300T6ZA01	HO2531129
Honda Ridgeline, 17-19, w/Park lamps	Lamp, Signal L	317-1637L-AC	DEPO	33350T6ZA01	HO2530129
Hyundai Elantra Sedan, 17-18, w/DRL (Korea)	Headlamp Assy, R	20-9807-90-9	TYC Brother	92102F2050	HY2503204
Hyundai Elantra Sedan, 17-18, w/DRL (Korea)	Headlamp Assy, L	20-9808-90-9	TYC Brother	92101F2050	HY2502204
Jeep Grand Cherokee, 14-16, Black, STD Type	Headlamp Assy, R	333-1194R-ACN2	DEPO	68236108AE	CH2503308
Jeep Grand Cherokee, 14-16, Black, STD Type	Headlamp Assy, L	333-1194L-ACN2	DEPO	68236109AE	CH2502308

**NEW PARTS CAPA 301 STANDARD - LIGHTING**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>	<u>EMC Tested</u>
Nissan Maxima, 07-08, Xenon	Headlamp Assy, R	315-1168R-ACH6	DEPO	26010ZK40A	NI2503180	Y
Nissan Maxima, 07-08, Xenon	Headlamp Assy, L	315-1168L-ACH6	DEPO	26060ZK40A	NI2502180	Y

**NEW PARTS CAPA 501 STANDARD - BUMPERS**

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Ford Explorer, 11-15	Absorber, Energy	FO1170147DSC	Grand HB	BB5Z17E855A	FO1170147
Ford Explorer, 13-15, Police Model	Absorber, Energy	FO1170147DSC	Grand HB	BB5Z17E855A	FO1170147
Ford Truck Ranger, 98-11	Bar, Reinforcement	FO1006249DSC	PBSI-DS	6L5Z17757A	FO1006249
Lexus IS 200t, 14-16, w/F Sport Pkg	Reinforcement, Bumper Front	LX44148LAH	Hui Yih	5213153080	LX1006143
Lexus IS 200t, 14-16, w/o F Sport Pkg	Reinforcement, Bumper Front	LX44148LAH	Hui Yih	5213153080	LX1006143
Lexus IS 250, 14-16, w/F Sport Pkg	Reinforcement, Bumper Front	LX44148LAH	Hui Yih	5213153080	LX1006143
Lexus IS 250, 14-16, w/o F Sport Pkg	Reinforcement, Bumper Front	LX44148LAH	Hui Yih	5213153080	LX1006143
Lexus IS 300, 14-16, w/F Sport Pkg	Reinforcement, Bumper Front	LX44148LAH	Hui Yih	5213153080	LX1006143
Lexus IS 300, 14-16, w/o F Sport Pkg	Reinforcement, Bumper Front	LX44148LAH	Hui Yih	5213153080	LX1006143



# WEEKLY PARTS UPDATE

## November 05, 2018

[Report: P6]  
Weekly

### NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Lexus IS 350, 14-16, w/F Sport Pkg	Reinforcement, Bumper Front	LX44148LAH	Hui Yih	5213153080	LX1006143
Lexus IS 350, 14-16, w/o F Sport Pkg	Reinforcement, Bumper Front	LX44148LAH	Hui Yih	5213153080	LX1006143
Toyota Tundra, 14-15, w/Towing pkg, w/o Towing hitch, w/o Parking assist	Bumper, Rear Assembly	TY50144AH	Hui Yih	TO1103121	TO1103121
Toyota Tundra, 14-15, w/Towing pkg, w/o Towing hitch, w/Parking assist	Bumper, Rear Assembly	TY50144BH	Hui Yih	TO1103122	TO1103122

### NEW PARTS CAPA 601 STANDARD - RADIATORS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

### DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

### CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
DGDN11HD1	Dodge Durango, 11-12	Hood	Gordon	01/18A	55369453AA	CH1230286
DGDN11HD1	Dodge Durango, 11-14	Hood	Gordon	01/18A	55369453AB	CH1230286
DGDN11HD1	Dodge Durango, 11-17	Hood	Gordon	01/18A	55369453AE	CH1230286

### CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Y-HDBP168CA	Honda CR-V, 10-11	Bumper Cover, Rear	Y.C.C.	12/17A	04715SWAA80ZZ	HO1100263
TY04548BBQ	Toyota Sienna Base/L/LE, 11-17, 3.5L Eng	Bumper Cover, Front	TYG Products	18/05/17	5211908904	TO1000369
TY04548BBQ	Toyota Sienna XLE, 11-17, 3.5L Eng., w/o Limited pkg	Bumper Cover, Front	TYG Products	18/05/17	5211908904	TO1000369
TY04548BBQ	Toyota Sienna, 11-13, 2.7L Eng	Bumper Cover, Front	TYG Products	18/05/17	5211908904	TO1000369
LX4600000-600	Lexus RX 330, 04-06, USA built, w/HL washers w/Radar cruise control	Bumper Cover, Front	AP-Procom	06/18A	521190E902	LX1000141
LX4600000-600	Lexus RX 350, 07-09, USA built, w/HL washers w/Laser cruise control	Bumper Cover, Front	AP-Procom	06/18A	521190E902	LX1000141
TY3820870-200	Toyota Camry Hybrid, 15-17, w/o Park Assist	Bumper Cover, Rear	AP-Procom	10/17A	5215906989	TO1100315
TY3820870-200	Toyota Camry, 15-17, w/o Park Assist	Bumper Cover, Rear	AP-Procom	10/17A	5215906989	TO1100315
SB-04036BBQ	Subaru Legacy, 10-14	Bumper Cover, Rear	Tong Yang	12/17B	57704AJ06A	SU1100165
SB-04036BBQ	Subaru Legacy, 10-14	Bumper Cover, Rear	Tong Yang	10/17B	57704AJ06A	SU1100165
Y-DSBP248ACA	Nissan Altima Sedan, 16-18, w/o Distance sensors	Bumper Cover, Front	Y.C.C.	02/18A	620229HS0H	NI1000311
TY-07565MAQ	Toyota Tundra SR5/Limited/1794, 14-16	Hood Scoop Assy	Tong Yang	01/18A	761800C020	TO1231100
DS-04358BBQ	Nissan Rogue, 14	Bumper Cover, Rear	Tong Yang	11/17B	850224BA0H	NI1100295
DS-04358BBQ	Nissan Rogue, 14-16	Bumper Cover, Rear	Tong Yang	11/17B	850229TA0H	NI1100295
FD-04373BBQ	Ford Explorer, 11-15, w/o Parking Assist	Bumper Cover, Front Upper	Tong Yang	04/18A	BB5Z17D957ACP	FO1014109
FD-04373BBQ	Ford Explorer, 11-15, w/o Parking Assist	Bumper Cover, Front Upper	Tong Yang	04/18A	BB5Z17D957APTM	FO1014109

### CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						



# WEEKLY PARTS UPDATE November 05, 2018

[Report: P6]  
Weekly

## CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
18-5836-01-9	Chevrolet Avalanche, 02-06, w/body cladding	Lamp, Park/Signal L	TYC Brother	12181710	15077336	GM2520184
20-6804-91-9	Mazda 6 Sport, 06-08	Headlamp Assy, L	TYC Brother	05161610	GP7B510L0B	MA2502135

## CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

## CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

## DELETED PARTS CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

## DELETED PARTS CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

## DELETED PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

## DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

## DELETED PARTS CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

## DELETED PARTS CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

\*This report includes all new, decertified and deleted parts from October 27, 2018 through November 02, 2018.

All CAPA reports including the weekly update are available on the CAPA website at [www.capacertified.org](http://www.capacertified.org).

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at [jillian.rahall@intertek.com](mailto:jillian.rahall@intertek.com)