

**PUBLIC SAFETY NOTICE**

**Intertek Warns of Potential Safety-Related Issue with Reinforcement Bar Bearing a CAPA Quality Seal**

Published: April 20, 2022

The following is a notification from Intertek that the Auto Power Reinforcement Bar identified below bearing the CAPA certification mark (CAPA Quality Seal) have been determined to pose a potential safety hazard.

Product Description		Bar, Reinforcement					
Make	Model	Years	Details	AM Part Number	OEM Part Number	PartsLink Number	Country
Nissan	Frontier	2005-2019	Plastic, PTM bumper	NSR2508A	51010EA530	NI1006227	US
Nissan	Pathfinder	2005-2007	Plastic, PTM bumper	NSR2508A	51010EA530	NI1006227	US
Nissan	Pathfinder	2009-2009	To 9-08, Plastic, PTM bumper	NSR2508A	51010EA530	NI1006227	US
Nissan	Xterra	2007-2007	From 3-07, Plastic, PTM bumper	NSR2508A	51010EA530	NI1006227	US
Nissan	Xterra	2008-2010	Plastic, PTM bumper	NSR2508A	51010EA530	NI1006227	US
Nissan	Xterra	2011-2011	To 6-11, Plastic, PTM bumper	NSR2508A	51010EA530	NI1006227	US
Nissan	Xterra	2012-2015	Plastic, PTM bumper	NSR2508A	51010EA530	NI1006227	US
<b>Manufacturer</b>		Auto Power Enterprise Co., Ltd.					

<b>Number of Units</b>	200
<b>Lot Numbers</b>	02/21A
<b>Potential Hazard</b>	The material used to produce certified products may not be the same material used when certification was achieved. In instances where the same materials are not used, it may result in a product that does not meet CAPA requirements for comparable performance to the car company brand counterpart. To date, no complaints have been reported.
<b>Sold By</b>	Distributors of aftermarket parts
<b>What To Do</b>	Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Auto Power directly.