

PUBLIC SAFETY NOTICE

Intertek Warns of Potential Safety-Related Issue with Tie Bar, Upper Bearing a CAPA Quality Seal

Published: October 26, 2022

The following is a notification from Intertek that the Tong Yang Tie Bar, Upper identified below bearing the CAPA certification mark (CAPA Quality Seal) have been determined to pose a potential safety hazard.

Product Description		Tie Bar, Upper					
Make	Model	Years	Details	AM Part Number	OEM Part Number	PartsLink Number	Country
Mercedes-Benz	E-Class	2018-2022	Coupe	BZ-03011AQ	2136206300	MB1225189	US
Mercedes-Benz	E-Class	2017-2022	Sedan; E300, E350, E400, E450, E43, E53	BZ-03011AQ	2136206300	MB1225189	US
Mercedes-Benz	E-Class	2017-2021	Wagon; E400, E450, E53	BZ-03011AQ	2136206300	MB1225189	US
Mercedes-Benz	E-Class	2018-2022	Convertible	BZ-03011AQ	2136206300	MB1225189	US
Mercedes-Benz	CLS	2019-2022	N/A	BZ-03011AQ	2136206300	MB1225189	US
Manufacturer		Tong Yang					
Number of Units		128					
Lot Numbers		06/18A, 11/19A, 09/21A					
Potential Hazard		Mounting features too large for proper part installation in vehicle					
Sold By		Distributors of aftermarket parts					
What To Do		Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Tong Yang directly.					