

NEW PARTS CAPA 101 STANDARD - METALS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--------------------------------|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Kia Sorento, 14-15 | Radiator Support | KA-03017AQ | Tong Yang | 641011U500 | KI1225162 |

NEW PARTS CAPA 201 STANDARD - PLASTICS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| BMW 3-Series E90 Sedan, 09-11, Gas, w/o turbo, w/park distance control | Bumper Cover, Rear | BM-04089BBQ | Tong Yang | 51127202706 | BM1100217 |
| Dodge Dart, 13 | Bumper Cover, Front | DG0310000-000C | AP-Procom | 1TS71TZZAD | CH1000A09 |
| Dodge Dart, 13-14 | Cover, Upper Bumper | DG0310030-000C | AP-Procom | 1WC26TZZAB | CH1014106 |
| Dodge Dart, 13-15 | Bumper Cover, Front | DG0310000-000C | AP-Procom | 1TS71TZZAE | CH1000A09 |
| Dodge Dart, 13-15 | Cover, Upper Bumper | DG0310030-000C | AP-Procom | 1WC26TZZAC | CH1014106 |
| Fiat 500 POP/Sport/Lounge Hatchback, 12-14 | Moulding, Cover R | FT-07056MARQ | Tong Yang | 1SR90SZ0AA | FI1046100 |
| Fiat 500 POP/Sport/Lounge Hatchback, 12-14 | Moulding, Cover L | FT-07056MALQ | Tong Yang | 1SR91SZ0AA | FI1046100 |
| Fiat 500C POP/Lounge Convertible, 12-14 | Moulding, Cover R | FT-07056MARQ | Tong Yang | 1SR90SZ0AA | FI1046100 |
| Fiat 500C POP/Lounge Convertible, 12-14 | Moulding, Cover L | FT-07056MALQ | Tong Yang | 1SR91SZ0AA | FI1046100 |
| Ford Expedition, 07-14, Chrome | Grille | FD-07269GBQ | Tong Yang | 7L1Z8200BA | FO1200494 |
| Infiniti G25 Base/Journey, 11-12 | Cover, Center Grille | DS-07345GAQ | Tong Yang | 622541NF1A | IN1036100 |
| Infiniti G37 Base/Journey, 10-13, w/o Technology Pkg | Cover, Center Grille | DS-07345GAQ | Tong Yang | 622541NF1A | IN1036100 |
| Lexus LS 460 Base, 13-15, w/F sport pkg | Bumper Cover, Front | LSB045NBQ | Pro Fortune | 521195C907 | LX1000252 |
| Nissan Altima Coupe, 10 | Cover, Engine Under | NSE010NEQ | Pro Fortune | 75890ZX00E | NI1228149 |
| Nissan Altima Hybrid, 10 | Cover, Engine Under | NSE010NEQ | Pro Fortune | 75890ZX00E | NI1228149 |
| Nissan Altima Sedan, 09-10 | Cover, Engine Under | NSE010NEQ | Pro Fortune | 75890ZX00E | NI1228149 |
| Nissan Altima Sedan, 13-15 | Cover, Engine Under | NSE007NAQ | Pro Fortune | 758903TA0A | NI1228145 |
| Subaru Forester, 14, 2.5L Eng., Type 1 | Grille | SB-07049GAQ | Tong Yang | 91121SG040 | SU1200154 |
| Toyota Tacoma, 12-15 | Liner, Fender R | TYT2014FR-C | Great Bestcam | 5380504020 | TO1249175 |
| Toyota Tacoma, 12-15 | Liner, Fender L | TYT2014FL-C | Great Bestcam | 5380604020 | TO1248175 |

NEW PARTS CAPA 301 STANDARD - LIGHTING

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|---|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Ford Fusion Energi, 13-15 | Reflector, Rear R | 330-2907R-UC | DEPO | DS7Z13A565A | FO1185103 |
| Ford Fusion Energi, 13-15 | Reflector, Rear L | 330-2907L-UC | DEPO | DS7Z13A565B | FO1184103 |
| Ford Fusion Hybrid, 13-15 | Reflector, Rear R | 330-2907R-UC | DEPO | DS7Z13A565A | FO1185103 |
| Ford Fusion Hybrid, 13-15 | Reflector, Rear L | 330-2907L-UC | DEPO | DS7Z13A565B | FO1184103 |
| Ford Fusion, 13-15 | Reflector, Rear R | 330-2907R-UC | DEPO | DS7Z13A565A | FO1185103 |
| Ford Fusion, 13-15 | Reflector, Rear L | 330-2907L-UC | DEPO | DS7Z13A565B | FO1184103 |
| GMC Sierra 1500 Hybrid, 10-12, 2nd design | Taillamp L | 11-6224-90-9 | TYC Brother | 20840273 | GM2800250 |
| GMC Sierra 1500 Hybrid, 10-12, 2nd design | Taillamp R | 11-6223-90-9 | TYC Brother | 20840274 | GM2801250 |
| GMC Sierra 1500 SL/SLE/SLE 1/SLE 2/SLT/WT, 10-12, 2nd design | Taillamp L | 11-6224-90-9 | TYC Brother | 20840273 | GM2800250 |
| GMC Sierra 1500 SL/SLE/SLE 1/SLE 2/SLT/WT, 10-12, 2nd design | Taillamp R | 11-6223-90-9 | TYC Brother | 20840274 | GM2801250 |
| GMC Sierra 2500/3500 HD Series, 10-12, 2nd design, single rear wheels | Taillamp L | 11-6224-90-9 | TYC Brother | 20840273 | GM2800250 |
| GMC Sierra 2500/3500 HD Series, 10-12, 2nd design, single rear wheels | Taillamp R | 11-6223-90-9 | TYC Brother | 20840274 | GM2801250 |
| Hyundai Elantra Sedan, 14-15, w/o LED position (USA Built) | Headlamp Assy, L | 321-1149L-ACN2 | DEPO | 921013Y500 | HY2502187 |
| Hyundai Elantra Sedan, 14-15, w/o LED position (USA built) | Headlamp Assy, R | 321-1149R-ACN2 | DEPO | 921023Y500 | HY2503187 |
| Subaru Outback, 13-14 | Lamp, Fog R | 19-6093-00-9 | TYC Brother | 84501AJ09A | SU2593123 |
| Subaru Outback, 13-14 | Lamp, Fog L | 19-6094-00-9 | TYC Brother | 84501AJ10A | SU2592123 |
| Subaru Outback, 15, w/o Driver Assist System | Lamp, Fog R | 19-6093-00-9 | TYC Brother | 84501AJ09A | SU2593123 |

NEW PARTS CAPA 301 STANDARD - LIGHTING

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Subaru Outback, 15, w/o Driver Assist System | Lamp, Fog L | 19-6094-00-9 | TYC Brother | 84501AJ10A | SU2592123 |
| Toyota Highlander, 14-15 | Lamp, Daytime Running R | 312-1654R-AC | DEPO | 814300E020 | TO2563100 |
| Toyota Highlander, 14-15 | Lamp, Daytime Running L | 312-1654L-AC | DEPO | 814400E020 | TO2562100 |

NEW PARTS CAPA 501 STANDARD - BUMPERS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--------------------------------|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| SBS6681A | Subaru Legacy, 05-09 | Tie Bar, Upper | Auto Power | 07/13A | 53060AG00A9P | SU1225142 |
| SBS6681A | Subaru Outback, 05-09 | Tie Bar, Upper | Auto Power | 07/13A | 53060AG00A9P | SU1225142 |

CAPA 201 STANDARD - PLASTICS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--|---------------------------|---------------------|------------|-------------------|-------------------------|
| CV-04172BDQ | Chevrolet Cobalt LTZ/SS, 06-07, w/2.4L eng | Bumper Cover, Front | Tong Yang | 11/14A | 12336074 | GM1000827 |
| CV-04172BDQ | Chevrolet Cobalt Sport, 08 | Bumper Cover, Front | Tong Yang | 11/14A | 12336074 | GM1000827 |
| CLB064NCQ | Chevrolet Cruze, 11-15, w/o RS Pkg, w/o Rear Object Sensor | Bumper Cover, Rear | Pro Fortune | 11/14B | 95016694 | GM1100876 |
| Y-CRBP053CA | Chrysler 200 Sedan/Convertible, 11-12 | Bumper Cover, Front | Y.C.C. | 11/14A | 68082047AC | CH1000997 |
| Y-CRBP053CA | Chrysler 200 Sedan/Convertible, 11-13 | Bumper Cover, Front | Y.C.C. | 11/14A | 68082047AB | CH1000997 |
| Y-CRBP053CA | Chrysler 200 Sedan/Convertible, 11-14 | Bumper Cover, Front | Y.C.C. | 11/14A | 68082047AD | CH1000997 |
| HDB090NCQ | Honda Odyssey EX/EX-L/LX, 11-14 | Bumper Cover, Rear | Pro Fortune | 11/14A | 04715TK8A90ZZ | HO1100267 |
| Y-HYBP012CA | Hyundai Sonata, 09-10, paint to match | Bumper Cover, Front | Y.C.C. | 11/14A | 865110A700 | HY1000178 |
| KA5510000-010C | Kia Sorento, 11-13, w/o Sport Pkg | Bumper Cover, Front Upper | AP-Procom | 11/14A | 865111U000 | KI1000149 |
| LX2100870-000C | Lexus IS 250, 06-08, w/park distance sensors | Bumper Cover, Rear | AP-Procom | 11/14A | 5215953906 | LX1100128 |
| LX2100870-000C | Lexus IS 350, 06-08, w/park distance sensors | Bumper Cover, Rear | AP-Procom | 11/14A | 5215953906 | LX1100128 |
| Y-DSBP234CA | Nissan Maxima, 09-14 | Bumper Cover, Front | Y.C.C. | 11/14A | 620229N00H | NI1000258 |
| TY-04193BCQ | Toyota Corolla CE/LE, 03-04 | Bumper Cover, Front | Tong Yang | 11/14B | 5211902915 | TO1000240 |
| Y-TYBP265CA | Toyota Prius, 04-09 | Bumper Cover, Rear | Y.C.C. | 11/14A | 5215947903 | TO1100239 |

CAPA 301 STANDARD - LIGHTING

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| NONE | | | | | | |

CAPA 501 STANDARD - BUMPERS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| NONE | | | | | | |



WEEKLY PARTS UPDATE May 4, 2015

[Report: P6]
Weekly

DELETED PARTS CAPA 101 STANDARD - METALS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

DELETED PARTS CAPA 201 STANDARD - PLASTICS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

DELETED PARTS CAPA 301 STANDARD - LIGHTING

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

DELETED PARTS CAPA 501 STANDARD - BUMPERS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

*This report includes all new, decertified and deleted parts from April 27, 2015 through May 1, 2015.

All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org