



PUBLIC SAFETY NOTICE

Intertek Warns of Potential Safety-Related Issue with RH Headlamp Assembly Bearing a CAPA Quality Seal

Published: February 9, 2021

The following is a notification from Intertek that the DEPO RH Headlamp Assembly identified below bearing the CAPA certification mark (CAPA Quality Seal) has been determined to pose a potential safety hazard.

Product Description		Headlamp Assy, R					
Make	Model	Years	Details	AM Part Number	OEM Part Number	PartsLink Number	Country
Toyota	Corolla	2014-2016	N/A	312-11D7R-AC2	8111002E60	TO2503216	US
Manufacturer		DEPO Auto Parts Industrial Co., Ltd.					
Number of Units		3,249					
Lot Numbers		20200302, 20200309, 20200316, 20200323, 20200330, 20200406, 20200413, 20200420, 20200427, 20200511, 20200518, 20200629, 20200706, 20200727					
Potential Hazard		The projector lens for the low and high beam within the headlamp may vibrate while driving. If this vibration occurs, driver and oncoming traffic visibility may be impaired.					
Sold By		Distributors of aftermarket parts					
What To Do		Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact DEPO directly.					