



PUBLIC SAFETY NOTICE

Intertek Warns of Potential Safety-Related Issue with Right Headlamp Assembly Bearing a CAPA Quality Seal

Published: November 07, 2023

The following is a notification from Intertek that the TYC headlamp identified below bearing the CAPA certification mark (CAPA Quality Seal) has been determined to pose a potential safety hazard.

Product Description		Headlamp Assembly, R					
Make	Model	Years	Details	AM Part Number	OEM Part Number	PartsLink Number	Country
Jeep	Compass	17-21		20-9981-00-9	55112706AF	CH2503295	US
Manufacturer		TYC Brother Industrial Co., Ltd.					
Number of Units		980					
Lot Numbers		04042210, 05022210, 05162210, 06132210, 07042210, 07252210, 08082210					
Potential Hazard		The low beam function may become inoperable. If this were to occur, driver and oncoming traffic visibility would be impaired. To date, 4 complaints have been received.					
Sold By		Distributors of aftermarket parts					
What To Do		Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact TYC directly.					