

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
ARTL09FL1	Acura TL, 09-14	Fender L	Gordon	09/15A	60260TK4A90ZZ	AC1240121
DG-20056AQ-RH	Dodge Ram R1500 Pickup, 09	Fender R	San Wanpum	12/15A	68054338AA	CH1241269
DG9310160-OR0C	Dodge Ram R1500 Pickup, 09	Fender R	AP	12/15A	68054338AA	CH1241269
DG-20056AQ-RH	Dodge Ram R1500 Pickup, 09-11	Fender R	San Wanpum	12/15A	68054338AB	CH1241269
DG9310160-OR0C	Dodge Ram R1500 Pickup, 09-11	Fender R	AP	12/15A	68054338AB	CH1241269
DG-20056AQ-RH	Dodge Ram R1500 Pickup, 09-12	Fender R	San Wanpum	12/15A	68054338AC	CH1241269
DG9310160-OR0C	Dodge Ram R1500 Pickup, 09-12	Fender R	AP	12/15A	68054338AC	CH1241269
DG-20056AQ-RH	Dodge Ram R1500 Pickup, 09-12	Fender R	San Wanpum	12/15A	68054338AD	CH1241269
DG9310160-OR0C	Dodge Ram R1500 Pickup, 09-12	Fender R	AP	12/15A	68054338AD	CH1241269
DG-20056AQ-RH	Dodge Ram R1500 Pickup, 09-13	Fender R	San Wanpum	12/15A	68054338AE	CH1241269
DG9310160-OR0C	Dodge Ram R1500 Pickup, 09-13	Fender R	AP	12/15A	68054338AE	CH1241269
DG-20056AQ-RH	Dodge Ram R1500 Pickup, 09-15	Fender R	San Wanpum	12/15A	68054338AF	CH1241269
DG9310160-OR0C	Dodge Ram R1500 Pickup, 09-15	Fender R	AP	12/15A	68054338AF	CH1241269
DG-20056AQ-RH	Dodge Ram R1500 Pickup, 09-15	Fender R	San Wanpum	12/15A	68054338AG	CH1241269
DG9310160-OR0C	Dodge Ram R1500 Pickup, 09-15	Fender R	AP	12/15A	68054338AG	CH1241269
DG-20056AQ-RH	Dodge Ram R1500 Pickup, 09-15	Fender R	San Wanpum	12/15A	68054338AH	CH1241269
DG9310160-OR0C	Dodge Ram R1500 Pickup, 09-15	Fender R	AP	12/15A	68054338AH	CH1241269
DG-20056AQ-RH	Dodge Ram R1500 Pickup, 09-15	Fender R	San Wanpum	12/15A	68054338AI	CH1241269
DG9310160-OR0C	Dodge Ram R1500 Pickup, 09-15	Fender R	AP	12/15A	68054338AI	CH1241269
FD5120160-OR0C	Ford Escape Hybrid, 08-12	Fender R	AP	10/15A	8L8Z16005A	FO1241258
WL-466AQ-RH	Ford Escape Hybrid, 08-12	Fender R	William	10/15A	8L8Z16005A	FO1241258
FD5120160-OR0C	Ford Escape, 08-12	Fender R	AP	10/15A	8L8Z16005A	FO1241258
WL-466AQ-RH	Ford Escape, 08-12	Fender R	William	10/15A	8L8Z16005A	FO1241258
S1027F200AS	Honda Accord Hybrid, 14-15	Fender R	Jui Li	11/15A	60211T2FA90ZZ	HO1241185
S1027F100AS	Honda Accord Hybrid, 14-15	Fender L	Jui Li	09/15A	60261T2FA90ZZ	HO1240185
S1027F200AS	Honda Accord Sedan, 13-15	Fender R	Jui Li	11/15A	60211T2FA90ZZ	HO1241185
S1027F100AS	Honda Accord Sedan, 13-15	Fender L	Jui Li	09/15A	60261T2FA90ZZ	HO1240185
VW-10072AQ-LH	Volkswagen GLI Sedan, 11-15	Fender L	Tong Yang	11/15A	5C6821105	VW1240142
VW-10072AQ-LH	Volkswagen Jetta Hybrid, 13-15	Fender L	Tong Yang	11/15A	5C6821105	VW1240142
VW-10072AQ-LH	Volkswagen Jetta Sedan, 11-15	Fender L	Tong Yang	11/15A	5C6821105	VW1240142

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
CLB128NBQ	Cadillac Escalade, 07-14	Bumper Cover, Rear	Pro Fortune	01/16A	20951798	GM1100784
CLB128NBQ	Cadillac Escalade, 09-13, Hybrid	Bumper Cover, Rear	Pro Fortune	01/16A	20951798	GM1100784
CLB064NCQ	Chevrolet Cruze, 11-16, w/o RS Pkg, w/o Rear Object Sensor	Bumper Cover, Rear	Pro Fortune	11/15B	95016694	GM1100876
Y-GMBP329CA	Chevrolet Impala, 06-14, w/fog lamps	Bumper Cover, Front	Y.C.C.	11/15A	89025048	GM1000764
CV-04173BCQ	Chevrolet Tahoe, 07-11, w/o Off Road pkg, w/o object sensor	Bumper Cover, Rear	Tong Yang	09/15A	25830549	GM1100785
CV-04173BCQ	Chevrolet Tahoe, 07-14, w/o Off Road pkg, w/o object sensor	Bumper Cover, Rear	Tong Yang	09/15A	20951794	GM1100785
CV-04173BCQ	GMC Yukon, 07-11, w/o object sensor	Bumper Cover, Rear	Tong Yang	09/15A	25830549	GM1100785
CLB128NBQ	GMC Yukon, 07-13, Denali	Bumper Cover, Rear	Pro Fortune	01/16A	20951798	GM1100784
CV-04173BCQ	GMC Yukon, 07-14, w/o object sensor	Bumper Cover, Rear	Tong Yang	09/15A	20951794	GM1100785
CLB128NBQ	GMC Yukon, 09-13, Denali, Hybrid	Bumper Cover, Rear	Pro Fortune	01/16A	20951798	GM1100784
HDB080NBQ	Honda Accord Sedan, 06-07	Bumper Cover, Rear	Pro Fortune	09/15A	04715SDBA80ZZ	HO1100233
HD-04155BBQ	Honda Civic Coupe, 06-11	Bumper Cover, Rear	Tong Yang	05/15C	04715SVAA90ZZ	HO1100234
HN-04071BBQ	Hyundai Santa Fe, 07-09	Bumper Cover, Rear	Tong Yang	09/15B	866112B020	HY1100153
Y-HYBP005CA	Hyundai Sonata, 02-05	Bumper Cover, Front	Y.C.C.	11/15A	865603D030	HY1000139
HN-04088BBQ	Hyundai Sonata, 11-13, single exhaust	Bumper Cover, Rear	Tong Yang	01/16B	866103Q000	HY1100175
Y-HYBP017CA	Hyundai Sonata, 11-14	Bumper Cover, Front	Y.C.C.	11/15A	865113Q000	HY1000183
Y-KABP011HRC	Kia Sorento, 11-13, w/Parking Assistant	Bumper Cover, Rear	Y.C.C.	11/15A	866101U010	K11100154
DS-04306BBQ	Nissan Rogue S/SL/SV, 11-15	Bumper Cover, Front	Tong Yang	10/15A	620221VK0H	NI1000277

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
TY-04259BBQ	Scion iC, 05-10	Bumper Cover, Front	Tong Yang	04/15A	5211921906	SC1000103
TY-04259BBQ	Scion iC, 05-10	Bumper Cover, Front	Tong Yang	11/15A	5211921906	SC1000103
TY-04213BAQ	Toyota 4Runner Base, 03-09	Bumper Cover, Front	Tong Yang	12/13A	5211935050	TO1000259
TY-04213BAQ	Toyota 4Runner Sport, 03-09, Type 1	Bumper Cover, Front	Tong Yang	12/13A	5211935050	TO1000259
TY-04213BAQ	Toyota 4Runner SR5, 03-09	Bumper Cover, Front	Tong Yang	12/13A	5211935050	TO1000259
TY-04276BCQ	Toyota Camry Base, 08-09, (USA)	Bumper Cover, Front	Tong Yang	12/15A	5211906919	TO1000329
TY-04276BCQ	Toyota Camry CE, 07 (USA)	Bumper Cover, Front	Tong Yang	12/15A	5211906919	TO1000329
Y-TYBP269HCA	Toyota Camry Hybrid, 07-09	Bumper Cover, Front	Y.C.C.	10/15A	5211933943	TO1000327
TY-04276BCQ	Toyota Camry Hybrid, 07-09 (USA)	Bumper Cover, Front	Tong Yang	12/15A	5211906919	TO1000329
Y-TYBP249ACA	Toyota Camry LE/XLE, 02-04, (USA)	Bumper Cover, Front	Y.C.C.	09/14A	52119AA904	TO1000230
TY-04276BCQ	Toyota Camry LE/XLE, 07-09, (USA)	Bumper Cover, Front	Tong Yang	12/15A	5211906919	TO1000329
Y-TYBP249CA	Toyota Camry SE, 02-04 (USA)	Bumper Cover, Front	Y.C.C.	11/15A	52119AA905	TO1000231
TY-05046VBQ	Toyota Camry SE, 10-11 (USA)	Spoiler, Front	Tong Yang	10/15A	7685106906	TO1093120
TYB082NBQ	Toyota Camry, 02-06, (USA)	Bumper Cover, Rear	Pro Fortune	12/15A	52159AA903	TO1100203
Y-TYBP269HCA	Toyota Camry, 07-09, (Japan)	Bumper Cover, Front	Y.C.C.	10/15A	5211933943	TO1000327
Y-TYBP271ACA	Toyota Corolla Base/CE/L, 09-10, (USA)	Bumper Cover, Rear	Y.C.C.	08/15A	5215902963	TO1100264
Y-TYBP283HCA	Toyota Prius V, 12-14, w/LED HLamps and Pre-Collision System	Bumper Cover, Front	Y.C.C.	11/13A	5211947925	TO1000387
Y-VWBP015CA	Volkswagen GTI Gen 5, 06-07	Bumper Cover, Front	Y.C.C.	08/15A	1K0807217AGRU	VW1000161
Y-VWBP015CA	Volkswagen Jetta Gen 5, 05-10	Bumper Cover, Front	Y.C.C.	08/15A	1K0807217AGRU	VW1000161
Y-VWBP015CA	Volkswagen Jetta Wagon, 09-10	Bumper Cover, Front	Y.C.C.	08/15A	1K0807217AGRU	VW1000161
VW-04163BBQ	Volkswagen Passat, 12-15	Bumper Cover, Rear	Tong Yang	09/15B	561807421DGRU	VW1100192
VW-04163BBQ	Volkswagen Passat, 12-15	Bumper Cover, Rear	Tong Yang	09/15B	561807421GRU	VW1100192

CAPA 301 STANDARD - LIGHTING

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
NONE						

CAPA 501 STANDARD - BUMPER PARTS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
NONE						

*This report includes all decertifications from May 1, 2016 through May 31, 2016.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.