

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
DGPU09TG1	Dodge RAM R1500 Pick-Up, 10-12	Tailgate	Gordon	04/16A	68105727AC	CH1900129
DGPU09TG1	Dodge Ram R1500 Pick-Up, 10-12	Tailgate	Gordon	04/16A	68105727AE	CH1900129
DGPU09TG1	Dodge RAM R1500/R2500/R3500 Pick-Up, 10-13	Tailgate	Gordon	04/16A	68105727AB	CH1900129
DGPU09TG1	Dodge RAM R2500/R3500 Pick-Up, 10-13	Tailgate	Gordon	04/16A	68105727AC	CH1900129
DGPU09TG1	Dodge Ram R3500/R2500 Pick-up, 10-14	Tailgate	Gordon	04/16A	68105727AE	CH1900129
S0945H000AL	Ford F150 Pickup, 09-14	Hood	Jui Li	03/16A	9L3Z16612A	FO1230274
JP8210160-0L0C	Jeep Grand Cherokee Laredo, Limited, Overland, 11-13	Fender L	AP	03/16A	55369597AC	CH1240272
JP8210160-0L0C	Jeep Grand Cherokee Laredo/Limited/Overland, 11-13	Fender L	AP	03/16A	55369597AD	CH1240272
JP8210160-0L0C	Jeep Grand Cherokee Laredo/Limited/Overland, 11-13	Fender L	AP	03/16A	55369597AE	CH1240272
JP8210160-0L0C	Jeep Grand Cherokee SRT-8, 11-13	Fender L	AP	03/16A	55369597AD	CH1240272
JP8210160-0L0C	Jeep Grand Cherokee SRT-8, 11-13	Fender L	AP	03/16A	55369597AE	CH1240272
JP8210160-0L0C	Jeep Grand Cherokee SRT-8, 12-13	Fender L	AP	03/16A	55369597AC	CH1240272
JP8210160-0L0C	Jeep Grand Cherokee, 11	Fender L	AP	03/16A	55369597AB	CH1240272
JP8210160-0L0C	Jeep Grand Cherokee, 14-15	Fender L	AP	03/16A	55369597AC	CH1240272
JP8210160-0L0C	Jeep Grand Cherokee, 14-16	Fender L	AP	03/16A	55369597AD	CH1240272
JP8210160-0L0C	Jeep Grand Cherokee, 14-17	Fender L	AP	03/16A	55369597AE	CH1240272
SUFS14HD1	Subaru Forester, 14-17, 2.0L/2.5L Eng	Hood	Gordon	ALL	57229SG0009P	SU1230144
VWJT05FL1	Volkswagen Jetta Sedan Gen 5, 05-09	Fender L	Gordon	01/15A	1L5821021A	VW1240135
VWJT05FL1	Volkswagen Jetta Sedan Gen 5, 05-10	Fender L	Gordon	01/15A	1K5821021A	VW1240135
VWJT05FL1	Volkswagen Jetta Wagon, 09	Fender L	Gordon	01/15A	1K5821021A	VW1240135
VWJT05FL1	Volkswagen Jetta Wagon, 09	Fender L	Gordon	01/15A	1L5821021A	VW1240135

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
FD-04347BBQ	Ford Fusion Hybrid, 10-12	Bumper Cover, Front	Tong Yang	03/16A	AE5Z17D957BAPTM	FO1000650
FD-04347BBQ	Ford Fusion, 10-12	Bumper Cover, Front	Tong Yang	03/16A	AE5Z17D957BAPTM	FO1000650
HDB084NBQ	Honda Civic Hybrid, 06-11	Bumper Cover, Rear	Pro Fortune	03/16B	04715SNA90ZZ	HO1100235
HDB084NBQ	Honda Civic Sedan, 06-11, 1.8L eng	Bumper Cover, Rear	Pro Fortune	03/16B	04715SNA90ZZ	HO1100235
HD04230BBQ	Honda Odyssey EX/EX-L/LX, 11-16	Bumper Cover, Rear	TYG Products	16/05/22	04715TK8A90ZZ	HO1100267
TY-04238BEQ	Lexus RX 350, 07-09, w/o laser cruise control w/H/Lamp washer cover assy	Bumper Cover, Front	Tong Yang	02/15A	5211948935	LX1000198
MZ32014FL-C	Mazda 3 Hatchback, 12-13, 2.0/2.5L Eng	Liner, Fender L	Great Bestcam	02/15A	BFD156140	MA1248139
MZ32014FL-C	Mazda 3 Sedan, 12-13	Liner, Fender L	Great Bestcam	02/15A	BFD156140	MA1248139
MZ32014FL-C	Mazda 3, 10-11, 2.5L Eng	Liner, Fender L	Great Bestcam	02/15A	BFD156140	MA1248139
NSB108NBQ	Nissan Murano LE/Platinum/SL/SV, 11-14	Bumper Cover, Rear	Pro Fortune	03/16A	HEM221AA0H	NI1100263
NSB108NBQ	Nissan Murano, 09-10	Bumper Cover, Rear	Pro Fortune	03/16A	HEM221AA0H	NI1100263
Y-TYBP279ACA	Toyota Camry Base/LE/XLE, 10-11 (USA)	Bumper Cover, Front	Y.C.C.	01/16B	5211906958	TO1000356
TY2810000-100C	Toyota Corolla Base/CE/L, 09-10, w/o spoiler holes	Bumper Cover, Front	AP-Procom	03/16A	5211902990	TO1000343
TY8040870-100C	Toyota RAV-4, 13-15, w/o Parking sensors	Bumper Cover, Rear	AP-Procom	03/16A	521500R110	TO1100306
TY8040870-100C	Toyota RAV-4, 13-15, w/o Parking sensors	Bumper Cover, Rear	AP-Procom	06/16B	521500R110	TO1100306

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
20-6784-00-9	Subaru Forester, 05-06	Headlamp Assy, L	TYC Brother	6131610	84001SA471	SU2502119
20-6784-00-9	Subaru Forester, 07-08, w/o Sport Pkg	Headlamp Assy, L	TYC Brother	6131610	84001SA471	SU2502119
20-9421-00-9	Toyota RAV-4, 13	Headlamp Assy, R	TYC Brother	6271610	811100R040	TO2503217
20-9421-00-9	Toyota RAV-4, 13-15, (North America built)	Headlamp Assy, R	TYC Brother	6271610	811100R042	TO2503217



MONTHLY RECALL REPORT November 2016*

[Report: P8]
Monthly

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 501 STANDARD - BUMPER PARTS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

*This report includes all decertifications from October 1, 2016 through October 31, 2016.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.