

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
CV-10100AQ-LH	Chevrolet Impala Limited, 06-13	Fender L	Tong Yang	03/16A	89023525	GM1240326
CV-10100AQ-LH	Chevrolet Impala, 06-13	Fender L	Tong Yang	03/16A	89023525	GM1240326
S0525H000AL	Chrysler 300, 05	Hood	Jui Li	10/15B	5112136AC	CH1230244
S0525H000AL	Chrysler 300, 05	Hood	Jui Li	10/15B	5112136AD	CH1230244
S0525H000AL	Chrysler 300, 06-07	Hood	Jui Li	10/15B	5112136AG	CH1230244
S0525H000AL	Chrysler 300, 08-10	Hood	Jui Li	10/15B	5112136AH	CH1230244
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	02/16B	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	02/16B	CJ5Z8A284A	FO1225216
DS-20103AQ	Nissan Altima Coupe, 08-09	Hood	Tong Yang	02/16A	65100JA030	NI1230173
DS-20103AQ	Nissan Altima Hybrid, 07-09	Hood	Tong Yang	02/16A	65100JA00D	NI1230173
DS-20103AQ	Nissan Altima Sedan, 07-09	Hood	Tong Yang	02/16A	65100JA00D	NI1230173
DS-20103AQ	Nissan Altima Sedan/Hybrid, 07-09	Hood	Tong Yang	02/16A	65100JA030	NI1230173
TY-10276BQ-RH	Toyota Sienna, 11-14, w/antenna	Fender R	Tong Yang	05/16A	5381108050	TO1241235

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
DG-04126BCQ	Chrysler Town & Country, 11-14, w/o Blind spot sensor	Bumper Cover, Rear	Tong Yang	01/16A	68125724AA	CH1100969
DG-04126BCQ	Chrysler Town & Country, 11-16, Code MLA, w/o Blind spot sensor	Bumper Cover, Rear	Tong Yang	01/16A	68125724AB	CH1100969
DG-04126BCQ	Dodge Grand Caravan, 11-14, w/o Blind spot sensor	Bumper Cover, Rear	Tong Yang	01/16A	68125724AA	CH1100969
DG-04126BCQ	Dodge Grand Caravan, 11-16, Code MLA, w/o Blind spot sensor	Bumper Cover, Rear	Tong Yang	01/16A	68125724AB	CH1100969
HD-04168BAQ	Honda CR-V, 07-09	Bumper Cover, Rear	Tong Yang	07/16B	04715SWAA90	HO1100241
MZ32014FL-C	Mazda 3 Hatchback, 12-13, 2.0/2.5L Eng	Liner, Fender L	Great Bestcam	05/16A	BFD156140	MA1248139
MZ32014FL-C	Mazda 3 Sedan, 12-13	Liner, Fender L	Great Bestcam	05/16A	BFD156140	MA1248139
MZ32014FL-C	Mazda 3, 10-11, 2.5L Eng	Liner, Fender L	Great Bestcam	05/16A	BFD156140	MA1248139
TY04253BBQ	Toyota Camry, 02-06, (USA)	Bumper Cover, Rear	TYG Products	16/04/06	52159AA903	TO1100203
TY-04393BBQ	Toyota Highlander, 11-13	Bumper Cover, Rear Upper	Tong Yang	01/16A	521590E907	TO1100289
TY-05050VAQ	Toyota Tundra, 10-12	Panel, Valance Lower	Tong Yang	01/16A	539110C040	TO1095202
TY-05050VAQ	Toyota Tundra, 10-12	Panel, Valance Lower	Tong Yang	02/16A	539110C040	TO1095202
TY-05050VAQ	Toyota Tundra, 10-12	Panel, Valance Lower	Tong Yang	03/16A	539110C040	TO1095202
TY-05050VAQ	Toyota Tundra, 10-12	Panel, Valance Lower	Tong Yang	05/16A	539110C040	TO1095202
VW1700870-110C	Volkswagen Jetta Sedan , 05-10, Gen 5	Bumper Cover, Rear	AP-Procom	02/16A	1K5807417HGRU	VW1100175
VW1700870-110C	Volkswagen Jetta Sedan , 05-10, Gen 5	Bumper Cover, Rear	AP-Procom	03/16A	1K5807417HGRU	VW1100175

CAPA 301 STANDARD - LIGHTING

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
NONE						

CAPA 501 STANDARD - BUMPER PARTS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
NONE						

*This report includes all decertifications from January 1, 2017 through January 31, 2017.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.