

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
HD-20053AQ	Acura TL, 04-08	Hood	Tong Yang	03/18A	60100SEPA90ZZ	AC1230112
S0807H000AS	Acura TL, 04-08	Hood	Jui Li	03/18A	60100SEPA90ZZ	AC1230112
CVQN10FL1	Chevrolet Equinox, 10-11	Fender L	Gordon	10/17A	20859528	GM1240364
CVQN10FL1	Chevrolet Equinox, 10-17	Fender L	Gordon	10/17A	22846917	GM1240364
FD-03031AQ	Ford Focus Sedan/Hatchback, 12-14	Radiator Support	Tong Yang	11/17B	CP9Z8A284A	FO1225214
FD-03031AQ	Ford Focus Sedan/Hatchback, 12-16	Radiator Support	Tong Yang	11/17B	CM5Z8A284A	FO1225214
FD-03031AQ	Ford Focus, 14-18	Radiator Support	Tong Yang	11/17B	CM5Z8A284ACP	FO1225214
FD-03031AQ	Ford Focus, 14-18, Hybrid	Radiator Support	Tong Yang	11/17B	CM5Z8A284ACP	FO1225214
HDCV12FR1	Honda Civic Coupe, 12-13	Fender R	Gordon	05/17A	60211TR6305ZZ	HO1241181
HDCV12FR1	Honda Civic Hybrid, 12-14	Fender R	Gordon	05/17A	60211TR6305ZZ	HO1241181
HDCV12FR1	Honda Civic Sedan, 12-15	Fender R	Gordon	05/17A	60211TR6305ZZ	HO1241181
HDCV12FR1	Honda Civic, 12-13	Fender R	Gordon	05/17A	60211TR0A90ZZ	HO1241181
HDCV12FR1	Honda Civic, 12-14	Fender R	Gordon	05/17A	60211TR6999ZZ	HO1241181
KA5510150-000C	Kia Sorento, 11-15	Hood	AP	01/18A	664001U000	KI1230126

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
Y-GMBP339CA	Chevrolet Avalanche, 07-11, w/off road pkg	Bumper Cover, Front	Y.C.C.	01/18A	15946214	GM1000830
Y-GMBP339CA	Chevrolet Avalanche, 07-13, w/off road pkg	Bumper Cover, Front	Y.C.C.	01/18A	25830185	GM1000830
GMCIMPA-R06NEW	Chevrolet Impala LS/LT, 06-11	Bumper Cover, Rear	Micro Rim	C3817	19120960	GM1100735
GMCIMPA-R06NEW	Chevrolet Impala, 08, 50th Anniversary	Bumper Cover, Rear	Micro Rim	C3817	19120960	GM1100735
Y-GMBP339CA	Chevrolet Suburban, 07-10	Bumper Cover, Front	Y.C.C.	01/18A	15946214	GM1000830
Y-GMBP339CA	Chevrolet Suburban, 07-14	Bumper Cover, Front	Y.C.C.	01/18A	25830185	GM1000830
Y-GMBP339CA	Chevrolet Tahoe, 07-11, w/off-road pkg	Bumper Cover, Front	Y.C.C.	01/18A	15946214	GM1000830
Y-GMBP339CA	Chevrolet Tahoe, 07-14, w/off-road pkg	Bumper Cover, Front	Y.C.C.	01/18A	25830185	GM1000830
CV-04247BBQ	Chevrolet Traverse, 13-14	Bumper Cover, Front Upper	Tong Yang	09/17A	22899627	GM1014107
CV-04247BBQ	Chevrolet Traverse, 13-17	Bumper Cover, Front Upper	Tong Yang	09/17A	23328140	GM1014107
CR29-9915-WSH	Chrysler 300 Sedan, 11-12, w/Parking Sensor	Bumper Cover, Front	Tran Hung	04/17A	68127939AA	CH1000A01
CR29-9915-WSH	Chrysler 300 Sedan, 11-12, w/Parking Sensor	Bumper Cover, Front	Tran Hung	04/17A	68127939AD	CH1000A01
CR29-9915-WSH	Chrysler 300 Sedan, 11-14, w/Parking Sensor	Bumper Cover, Front	Tran Hung	04/17A	68127939AE	CH1000A01
DG-04141BBQ	Dodge Challenger, 11-14	Bumper Cover, Front	Tong Yang	11/17A	68109836AB	CH1000994
Y-CRBP029PGC	Dodge Dakota, 01, (USA) paint to match, w/o R/T, w/fog	Bumper Cover, Front	Y.C.C.	01/18A	5073221AA	CH1000925
Y-CRBP029PGC	Dodge Dakota, 03-04, paint to match, w/Fog Lamps	Bumper Cover, Front	Y.C.C.	01/18A	5073221AA	CH1000925
Y-CRBP029PGC	Dodge Durango, 03, w/fog lamps	Bumper Cover, Front	Y.C.C.	01/18A	5073221AA	CH1000925
FD-07223GAQ	Ford Excursion, 05, Chrome	Grille	Tong Yang	12/16A	5C3Z8200BAA	FO1200456
FD-07223GAQ	Ford Excursion, 05, Chrome	Grille	Tong Yang	12/16A	6C3Z8200BC	FO1200456
FD-07223GAQ	Ford F-Series Super Duty XLT/Lariat/Outlaw Pickup, 05, w/o Chrome Pkg	Grille	Tong Yang	12/16A	5C3Z8200BAA	FO1200456
FD-07223GAQ	Ford F-Series Super Duty XLT/Lariat/Outlaw Pickup, 05, w/o Chrome Pkg	Grille	Tong Yang	12/16A	6C3Z8200BC	FO1200456
FD-07363GAQ	Ford Taurus, 13-16	Grille, Outer	Tong Yang	08/17A	DG1Z8200SA	FO1202104
HDB083NBQ	Honda Civic Hybrid, 06-08	Bumper Cover, Front	Pro Fortune	01/18A	04711SNEA90ZZ	HO1000239
HDB083NBQ	Honda Civic Sedan, 06-08, 1.8L eng	Bumper Cover, Front	Pro Fortune	01/18A	04711SNEA90ZZ	HO1000239
Y-HDBP214CA	Honda Civic Sedan/Coupe, 16-18	Bumper Cover, Front	Y.C.C.	01/18A	04711TBAA00ZZ	HO1000306
Y-HYBP031CA	Hyundai Elantra Sedan, 14-15, Korea built	Bumper Cover, Rear	Y.C.C.	01/18A	866113X700	HY1100202
Y-HYGR017CPC	Hyundai Sonata, 11-12	Grille	Y.C.C.	07/17A	863503S100	HY1200154
IFB002NDQ	Infiniti FX35, 09-13, w/o Premium pkg	Bumper Cover, Rear	Pro Fortune	10/16A	HEM221CA0H	IN1100134
IFB002NDQ	Infiniti FX37, 09-13, w/o Premium pkg	Bumper Cover, Rear	Pro Fortune	10/16A	HEM221CA0H	IN1100134
IFB002NDQ	Infiniti QX70, 14, w/o Parking sensors	Bumper Cover, Rear	Pro Fortune	10/16A	HEM221CA0H	IN1100134
KA-04014BBQ	Kia Sportage, 05-07, w/Luxury Pkg.	Bumper Cover, Front	Tong Yang	10/17A	865111F001	KI1000130

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
LSB042NDQ	Lexus ES 350, 13-15, w/Parking sensors	Bumper Cover, Rear	Pro Fortune	05/16A	5215933953	LX1100161
LSB042NDQ	Lexus ES 350, 13-17, w/Parking sensors	Bumper Cover, Rear	Pro Fortune	05/16A	5215933943	LX1100161
LX2100000-010C	Lexus IS 250, 06-08, w/o pre collision; w/o headlamp washer	Bumper Cover, Front	AP-Procom	01/18A	5211953925	LX1000163
LX2100000-010C	Lexus IS 350, 06-08, w/o pre collision, w/o headlamp washer	Bumper Cover, Front	AP-Procom	01/18A	5211953925	LX1000163
MZ-04095BBQ	Mazda 6, 06-08, w/o turbo	Bumper Cover, Front	Tong Yang	06/17B	GPYA50031A	MA1000218
MZ-04095BBQ	Mazda 6, 06-08, w/o turbo	Bumper Cover, Front	Tong Yang	06/17B	GPYA50031ABB	MA1000218
Y-DSBP244CA	Nissan Versa Sedan, 12, (P)	Bumper Cover, Rear	Y.C.C.	08/16A	HEM223AN0H	NI1100284
Y-DSBP244CA	Nissan Versa Sedan, 12-16	Bumper Cover, Rear	Y.C.C.	08/16A	HEM223AN0J	NI1100284
TY-04402BBQ	Toyota Camry Hybrid, 12-14	Bumper Cover, Front	Tong Yang	01/17B	5211906974	TO1000378
TY-04402BBQ	Toyota Camry Hybrid, 12-14	Bumper Cover, Front	Tong Yang	07/17A	5211906974	TO1000378
TY-04402BBQ	Toyota Camry L/LE/XLE, 12-14	Bumper Cover, Front	Tong Yang	01/17B	5211906974	TO1000378
TY-04402BBQ	Toyota Camry L/LE/XLE, 12-14	Bumper Cover, Front	Tong Yang	07/17A	5211906974	TO1000378
Y-TYBP271HCA	Toyota Corolla, 09-10, (Japan)	Bumper Cover, Rear	Y.C.C.	01/18A	5215912934	TO1100268
TY-04442BBQ	Toyota RAV-4, 13-15, North America Built	Bumper Cover, Front	Tong Yang	11/17B	521190R911	TO1014101
VGB056NBQ	Volkswagen Jetta Hybrid, 13	Bumper Cover, Rear	Pro Fortune	12/16A	5C6807421GRU	VW1100189
VGB056NBQ	Volkswagen Jetta Sedan, 11-13, w/o Parking assist	Bumper Cover, Rear	Pro Fortune	12/16A	5C6807421GRU	VW1100189
VG0940000-200C	Volkswagen Passat, 12-15	Bumper Cover, Front	AP-Procom	08/17A	561807217BGRU	VW1000199
324-1102L-UC7	Lexus ES 350, 07-09, w/o HID	Headlamp Assy, L	DEPO	20170410	8117033670	LX2502134
GM1106663DSC	Chevrolet Impala, 06-16	Bar, Impact	PBSI-DS	11/17A	25865729	GM1106663
GM1106663DSC	Chevrolet Monte Carlo, 06-16	Bar, Impact	PBSI-DS	11/17A	25865729	GM1106663
FDB7081APT	Ford F250/F350 Pickup, 11-16, Paint to match	Bumper, Front	Auto Power	11/17A	BC3Z17757CPTM	FO1002417
FDB7081APT	Ford F450 Super Duty Pickup, 11-16, w/o Bumper end caps, Paint to match	Bumper, Front	Auto Power	11/17A	BC3Z17757CPTM	FO1002417

CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 501 STANDARD - BUMPER PARTS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

*This report includes all decertifications from May 1, 2018 through May 31, 2018.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at jillian.rahal@intertek.com.