

DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations, regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Decertification Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Decertified Part Reimbursement Program 4700 Broadmoor SE, Suite 200, Kentwood, MI 49512 or FAX (616) 245.5347.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
HDCV13HD1	Honda Civic Sedan, 13-15	Hood	Gordon	03/18A	60100TR3A50ZZ	HO1230171
S0993H000AS	Jeep Compass, 07-10	Hood	Jui Li	07/18A	5074926AF	CH1230253
LX1320150-000C	Lexus ES 300h, 13-18	Hood	AP	06/18A	5330133160	LX1230124
DT2020150-000C	Nissan Versa Sedan, 12-13	Hood	AP	05/18A	FEA009KAMA	NI1230188
S0975H000AS	Toyota Yaris Sedan, 07-12	Hood	Jui Li	05/18A	5330152251	TO1230205

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
HDB113NCQ	Honda Accord Sedan, 16-17, w/o Parking Sensors	Bumper Cover, Front	Pro Fortune	07/18A	71101T2FA50ZZ	HO1000302
Y-HYBP034CA	Hyundai Sonata, 14	Bumper Cover	Y.C.C.	03/18A	866113Q700	HY1100200
Y-HYBP034CA	Hyundai Sonata, 14	Bumper Cover	Y.C.C.	11/17A	866113Q700	HY1100200
Y-LXBP005CA	Lexus IS 350, 14-16, w/o Headlamp washer, w/Park	Bumper Cover, Front	Y.C.C.	08/17A	521195E913	LX1000263
DS-04358BBQ	Nissan Rogue, 14-16	Bumper Cover, Rear	Tong Yang	07/18B	850229TA0H	NI1100295
TY-04402BBQ	Toyota Camry L/LE/XLE, 12-14	Bumper Cover, Front	Tong Yang	12/17A	5211906974	TO1000378
TY3820870-000C	Toyota Camry L/LE/XLE/Hybrid, 12-14	Bumper Cover, Rear	AP-Procom	12/17A	5215906961	TO1100296
TYB119NBQ	Toyota Highlander, 11-13	Bumper Cover, Front	Pro Fortune	11/17A	521190E914	TO1000374
TY5910870-010C	Toyota Prius, 10-15	Bumper Cover, Rear	AP-Procom	10/17A	5215947916	TO1100280
TY8040870-100C	Toyota RAV-4, 13-15, w/o Parking sensors	Bumper Cover, Rear	AP-Procom	04/18A	521500R110	TO1100306

CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
11-6338-01-9	Subaru Forester, 09-13	Taillamp L	TYC Brother	5071810	84912SC131	SU2818102

CAPA 501 STANDARD - BUMPER PARTS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
JP44083AH	Dodge Nitro, 07-11	Crossmember, Lower	Hui Yih	12/17A	55360190AN	CH1006213
FD44138AH	Ford Fusion, 13-16, w/Towing Hook	Bar, Impact	Hui Yih	ALL	DG9Z5410852A	FO1006262
FD54138AH	Ford Fusion, 13-16	Bar, Impact	Hui Yih	ALL	DG9Z17906A	FO1106365
FD44138BH	Ford Fusion, 13-16, w/o Towing Hook	Bar, Impact	Hui Yih	ALL	DG9Z17757ACP	FO1006263
TY44101LAH	Toyota Prius, 12	Reinf., Bumper Front	Hui Yih	ALL	5202147012	TO1006221

CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

*This report includes all decertifications from October 1, 2018 through October 31, 2018.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at jillian.rahal@intertek.com.