

PUBLIC SAFETY NOTICE

**Intertek Warns of Potential Safety-Related Issue with
Left Back Up Lamps Bearing a CAPA Quality Seal**

Published: May 4, 2023

The following is a notification from Intertek that the DEPO back up lamps identified below bearing the CAPA certification mark (CAPA Quality Seal) have been determined to pose a potential safety hazard.

Product Description		Lamp, Back Up L					
Make	Model	Years	Details	AM Part Number	OEM Part Number	PartsLink Number	Country
Toyota	Venza	21-21	Hybrid	312-1339L-UC	8154148011	TO2882109	US
Manufacturer		DEPO Auto Parts Industrial Co., Ltd.					
Number of Units		210					
Lot Numbers		20211105, 20221021					
Potential Hazard		<p>Part does not meet the requirement for the effective projected luminous lens area for the LED turn signal function as identified in Federal Motor Vehicle Safety Standard 108; Lamps, reflective devices, and associated equipment.</p> <p>To date, no complaints have been received.</p>					
Sold By		Distributors of aftermarket parts					
What To Do		Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact DEPO directly.					